GIF++ test of BIL2 pack

Overall information

- Test performed up to now to 3 packages
- 2 BIL and 1 BIS
- Test system to be finalized to avoid manual scanning which can introduce systematic problems
- Gregorio is preparing a WINCC automatic procedure
- System used also as (supervised!) training of young RPC experts
- Atmospheric pressure effect can be automatically corrected or maybe better corrected ex post
- Data will be stored in a shared folder and inserted in the DB
- Expected data:
  - Initial and final scan with 3 sources + off
  - Monitoring of the currents
  - Measurement of plates resistance
- Today: report on the last BIL package made of 21 gas gaps

Conditioning trends

- Small effect of the pressure between initial (959 mbar) and final (953 mbar)
- Equivalent to about 0.6 % of the full voltage (36V)







Initial vs. final (first 16 gas gaps) source off





Comparison source off @6kV



- The higher tagged initial currents lowered
- A few increased, to be investigated in BB5
- The initial worst (21) was not properly monitored. To be retested in BB5
- We are still in the learning curve → we need to improve the standardization of the test performed by different people

Initial vs. final source filter 100 (first 16 gaps)





ADC problem for the gaps 17-21→ CAEN

- Trends monitored on CAEN currents
- Channel 11 is the last gas gap alone
- Was set
- Final scan to be repeated in BB5