
# Tuesday 08.04.2025

Published 07 04 2025, 17:00





1 2 3 4 5 low moderate considerable high very high




## Tuesday 08.04.2025

Published 07 04 2025, 17:00



#### **Danger Level 2 - Moderate**



#### The weather conditions fostered a strengthening of the snowpack.

As a consequence of falling temperatures, the avalanche activity has gradually decreased. The avalanche prone locations are to be found in particular at the base of rock walls and behind abrupt changes in the terrain and adjacent to ridgelines and in gullies and bowls. In addition the wind slabs must be taken into account.

The avalanches can be released by large loads.

In many places there is a danger of falling on the hard snow surface.

#### Snowpack

The weather conditions gave rise to consolidation of the snowpack. As a consequence of low temperatures a crust formed on the surface. The solar radiation will give rise as the day progresses to increasing moistening of the snowpack on sunny slopes.

### Tendency

The conditions remain wintry.



Friuli Venezia Giulia Page 2