









A



CABINET I/O



E.Triana
JOTEGO

Sheet: /
File: exterm.kicad_sch

Title: EXTERMINATION

Size: A3 Date: 29/08/2022
KiCad E.D.A. kicad-cl 7.0.8-7.0.8-ubuntu20.04.1



Rev: José Tejada G.
Id: 1/10

1 2 3 4 5 6 7 8

A

B

C

D

E

F




E.Triana
JOTEGO

Sheet: /capacitors/
File: capacitors.kicad_sch


Title: EXTERMINATION

Size: A3 Date: 29/08/2022
KiCad E.D.A. kicad-cli 7.0.8-7.0.8-ubuntu20.04.1

Rev: José Tejada G. Id: 2/10



1 2 3 4 5 6 7 8



E.Triana
JOTEGO


Sheet: /main/
File: main.kicad_sch

Title: EXTERMINATION


Size: A3 Date: 29/08/2022
KiCad E.D.A. kicad-cl 7.0.8-7.0.8-ubuntu20.04.1



Rev: José Tejada G.
Id: 3/10





The output signals (pin 55) **HBLK** (15.6KHz) and (pin 56) **VSYNC** (59.2 Hz) of the SetaX1-001, were simulated with the signal generator and an inverter. These were connected to the input pins of the Setax01-003 (pin 19 – 20), respectively. No logic signals are observed on the output pins (22–23) **HBLK** – **SYNC**, applying Jotego's instructions, given in this issue. It is concluded with Jotego that the Chip SetaX1-001 is broken.



Measures Seta X1-001:
 CLK_IN.....12MHz
 CLK_OUT.....11.07-12.01MHz
 VBLK.....59.2Hz
 VBLK.....59.3Hz
 HBLK2.....15.6kHz
 HBLK.....15.6kHz
 HBLK.....15.6kHz
 VSYNC.....59.2Hz

Observación: Pin 46 (HCO) does not correspond to the sequence of the HC[8..0] counter.



1 2 3 4 5 6 7 8

A

A

B

B

C

C

D


D

E

E

F

F



E.Triana
JOTEGO





Sheet: /watchdog/
File: watchdog.kicad_sch

Title: EXTERMINATION

Size: A3 | Date: 29/08/2022
KiCad E.D.A. kicad-cli 7.0.8-7.0.8-ubuntu20.04.1

Rev: José Tejada G.
Id: 6/10





E.Triana
JOTEGO





Sheet: /mcu/
File: mcu.kicad_sch

Title: EXTERMINATION

Size: A3 | Date: 29/08/2022
KiCad E.D.A. kicad-cli 7.0.8-7.0.8-ubuntu20.04.1

Rev: José Tejada G.
Id: 8/10





E.Triana
IOTEGO



Sheet: /gfx/gfx_rom/

File: gfx_rom.kicad_sch

Title: EXTERMINATION

Size: A3 Date: 29/08/2022
KiCad E.D.A. kicad-cli 7.0.8-7.0.8~ubuntu20.04.1

Rev: José Tejada G.