

TEST REPORT: 7191279319-CHM22-05-RC

Date: 01 JUN 2022

Tel: +65 6973 6171

Client's Ref: -

Email: Randy.CHIN@tuvsud.com

Note: This report is issued subject to the Testing and Certification Regulations of the TÜV SÜD Group and the General Terms and Conditions of Business of TÜV SÜD PSB Pte Ltd. In addition, this report is governed by the terms set out within this report.



PSB Singapore

Add value.
Inspire trust.

SUBJECT

Fungus Resistance Test

CLIENT

Bostik Findley (Malaysia) Sdn Bhd
Lot 112 & 113 Kawasan Perindustrian Senawang 70450
Seremban NSDK
Malaysia

Attn : Herman Chen

SAMPLE SUBMISSION DATE / TEST DATE

14 Mar 2022 / 05 Apr 2022

DESCRIPTION OF SAMPLE

One sample of sealant as below was submitted by the above company.

Sample Description	:	BOSTIK K&B S546
Nominal Dimensions	:	260 ml Cartridge
Brand Name	:	Bostik
Model Number	:	S546
Type of Material	:	Sealant
Composition	:	Silicone

The sealant was casted into 50 mm x 50 mm panels for the test.



Laboratory:
TÜV SÜD PSB Pte. Ltd.
15 International Business Park
TÜV SÜD @ IBP
Singapore 609937

Phone : +65-6778 7777
E-mail: info.sg@tuvsud.com
<https://www.tuvsud.com/sg>
Co. Reg : 199002667R

Regional Head Office:
TÜV SÜD Asia Pacific Pte. Ltd.
15 International Business Park
TÜV SÜD @ IBP
Singapore 609937
TÜV®

**METHOD OF TEST**

ASTM Designation : G21-15

‘Standard Practice for Determining Resistance of Synthetic Polymeric Materials to Fungi’.

1. The test fungi used were :

Aspergillus brasiliensis (ATCC 9642)
Penicillium funiculosum (ATCC 11797)
Chaetomium globosum (ATCC 6205)
Trichoderma virens (ATCC 9645)
Aureobasidium pullulans (ATCC 15233)

2. Three test specimens were prepared for the tests. Both sides of the test specimen were tested.
3. Incubation condition: 28-30°C for 28 days at not less than 85% relative humidity.
4. Viability controls were prepared using three pieces of sterilized filter paper (25mm by 25mm) on solidified nutrient-salts agar in separate petri dishes inoculated with the test fungi and incubated at the same conditions as the test specimens for 14 days.
5. Based on the standard, the test may be terminated in less than 28 days for samples exhibiting a growth rating of 2 or more.
6. The extent of fungal growth on the incubated test specimens were rated in accordance with the test method as follows :

Observed growth on specimens	Rating
None	0
Traces of growth (less than 10%)	1
Light growth (10 - 30%)	2
Moderate growth (30 - 60%)	3
Heavy growth (60% to complete coverage)	4



RESULTS

Inoculated test specimens	Observation of fungal growth on test specimens at the end of incubation period
<u>Sample:</u> BOSTIK K&B S546 # 1 # 2 # 3	Traces of growth (Rating 1) No fungal growth (Rating 0) Traces of growth (Rating 1)
<u>Viability controls</u> # 1 # 2 # 3	Heavy growth (Rating 4) Heavy growth (Rating 4) Heavy growth (Rating 4)

Remarks :

The above test results related to the sample(s) as received.

MS GERMAINE KHONG ZHI YU
TECHNICAL EXECUTIVE

MS CHEW WAN YU
EXECUTIVE MICROBIOLOGIST
MICROBIOLOGY
CHEMICAL & MATERIALS

APPENDIX




Figure 1: Observation of fungal growth on test specimens after incubation

Please note that this Report is issued under the following terms :

1. This report applies to the sample of the specific product/equipment given at the time of its testing/calibration. The results are not used to indicate or imply that they are applicable to other similar items. In addition, such results must not be used to indicate or imply that TÜV SÜD PSB approves, recommends or endorses the manufacturer, supplier or user of such product/equipment, or that TÜV SÜD PSB in any way "guarantees" the later performance of the product/equipment. Unless otherwise stated in this report, no tests were conducted to determine long term effects of using the specific product/equipment.
2. The sample/s mentioned in this report is/are submitted/supplied/manufactured by the Client. TÜV SÜD PSB therefore assumes no responsibility for the accuracy of information on the brand name, model number, origin of manufacture, consignment or any information supplied.
3. Nothing in this report shall be interpreted to mean that TÜV SÜD PSB has verified or ascertained any endorsement or marks from any other testing authority or bodies that may be found on that sample.
4. This report shall not be reproduced wholly or in parts and no reference shall be made by the Client to TÜV SÜD PSB or to the report or results furnished by TÜV SÜD PSB in any advertisements or sales promotion.
5. Unless otherwise stated, the tests were carried out in TÜV SÜD PSB Pte Ltd, 15 International Business Park TÜV SÜD @ IBP Singapore 609937.
6. The tests carried out by TÜV SÜD PSB and this report are subject to TÜV SÜD PSB's General Terms and Conditions of Business and the Testing and Certification Regulations of the TÜV SÜD Group.

Effective 26 January 2021

