

JoeSandbox Cloud BASIC



ID: 797228

Sample Name:

MASTER_Malware_Lab1.exe

Cookbook: default.jbs

Time: 18:01:12

Date: 02/02/2023

Version: 36.0.0 Rainbow Opal

Table of Contents

Table of Contents	2
Windows Analysis Report MASTER_Malware_Lab1.exe	5
Overview	5
General Information	5
Detection	5
Signatures	5
Classification	5
Process Tree	5
Malware Configuration	5
Yara Signatures	6
Sigma Signatures	6
Snort Signatures	6
Joe Sandbox Signatures	6
AV Detection	6
Persistence and Installation Behavior	6
Malware Analysis System Evasion	6
Lowering of HIPS / PFW / Operating System Security Settings	6
Mitre Att&ck Matrix	6
Behavior Graph	7
Screenshots	7
Thumbnails	7
Antivirus, Machine Learning and Genetic Malware Detection	8
Initial Sample	8
Dropped Files	8
Unpacked PE Files	9
Domains	9
URLs	9
Domains and IPs	9
Contacted Domains	9
URLs from Memory and Binaries	9
World Map of Contacted IPs	11
General Information	11
Warnings	11
Simulations	11
Behavior and APIs	11
Joe Sandbox View / Context	12
IPs	12
Domains	12
ASNs	12
JA3 Fingerprints	12
Dropped Files	12
Created / dropped Files	12
C:\ProgramData\USOPrivate\UpdateStore\updatestore51b519d5-b6f5-4333-8df6-e74d7c9ae4d4.xml (copy)	12
C:\ProgramData\USOPrivate\UpdateStore\updatestoretemp51b519d5-b6f5-4333-8df6-e74d7c9ae4d4.xml	12
C:\ProgramData\USOShared\Logs\UpdateSessionOrchestration.001.etl (copy)	13
C:\ProgramData\USOShared\Logs\UpdateSessionOrchestration_Temp.1.etl	13
C:\Users\Public\Public\Screens\screenshot.bmp	13
C:\Users\Public\Public\Screens\screenshot000.bmp	14
C:\Users\Public\Public\Screens\screenshot001.bmp	14
C:\Users\Public\Public\Screens\screenshot002.bmp	14
C:\Users\Public\Public\Screens\screenshot003.bmp	15
C:\Users\Public\Public\Screens\screenshot004.bmp	15
C:\Users\Public\Public\Screens\screenshot005.bmp	15
C:\Users\Public\Public\Screens\screenshot006.bmp	15
C:\Users\Public\Public\Screens\screenshot007.bmp	16
C:\Users\Public\Public\Screens\screenshot008.bmp	16
C:\Users\Public\Public\Screens\screenshot009.bmp	16
C:\Users\Public\Public\Screens\screenshot010.bmp	17
C:\Users\Public\Public\Screens\screenshot011.bmp	17
C:\Users\Public\Public\Screens\screenshot012.bmp	17
C:\Users\Public\Public\Screens\screenshot013.bmp	18
C:\Users\Public\Public\Screens\screenshot014.bmp	18
C:\Users\Public\Public\Screens\screenshot015.bmp	18
C:\Users\Public\Public\Screens\screenshot016.bmp	18
C:\Users\Public\Public\Screens\screenshot017.bmp	19
C:\Users\Public\Public\Screens\screenshot018.bmp	19
C:\Users\Public\Public\Screens\screenshot019.bmp	19
C:\Users\Public\Public\Screens\screenshot020.bmp	20
C:\Users\Public\Public\Screens\screenshot021.bmp	20
C:\Users\Public\Public\Screens\screenshot022.bmp	20

C:\Users\Public\Public\Screens\screenshot023.bmp	21
C:\Users\Public\Public\Screens\screenshot024.bmp	21
C:\Users\Public\Public\Screens\screenshot025.bmp	21
C:\Users\Public\Public\Screens\screenshot026.bmp	21
C:\Users\Public\Public\Screens\screenshot027.bmp	22
C:\Users\Public\Public\Screens\screenshot028.bmp	22
C:\Users\Public\Public\Screens\screenshot029.bmp	22
C:\Users\Public\Public\Screens\screenshot030.bmp	23
C:\Users\Public\Public\Screens\screenshot031.bmp	23
C:\Users\Public\Public\Screens\screenshot032.bmp	23
C:\Users\Public\Public\Screens\screenshot033.bmp	24
C:\Users\Public\Public\Screens\screenshot034.bmp	24
C:\Users\Public\Public\Screens\screenshot035.bmp	24
C:\Users\Public\Public\Screens\screenshot036.bmp	24
C:\Users\Public\Public\Screens\screenshot037.bmp	25
C:\Users\Public\Public\Screens\screenshot038.bmp	25
C:\Users\Public\Public\Screens\screenshot039.bmp	25
C:\Users\Public\Public\Screens\screenshot040.bmp	26
C:\Users\Public\Public\Screens\screenshot041.bmp	26
C:\Users\Public\Public\Screens\screenshot042.bmp	26
C:\Users\Public\Public\Screens\screenshot043.bmp	27
C:\Users\Public\Public\Screens\screenshot044.bmp	27
C:\Users\Public\Public\Screens\screenshot045.bmp	27
C:\Users\Public\Public\Screens\screenshot046.bmp	28
C:\Users\Public\Public\Screens\screenshot047.bmp	28
C:\Users\Public\Public\Screens\screenshot048.bmp	28
C:\Users\Public\Public\Screens\screenshot049.bmp	28
C:\Users\Public\Public\Screens\screenshot050.bmp	29
C:\Users\Public\Public\Screens\screenshot051.bmp	29
C:\Users\Public\Public\Screens\screenshot052.bmp	29
C:\Users\Public\Public\Screens\screenshot053.bmp	30
C:\Users\Public\Public\Screens\screenshot054.bmp	30
C:\Users\Public\Public\Screens\screenshot055.bmp	30
C:\Users\Public\Public\Screens\screenshot056.bmp	31
C:\Users\Public\Public\Screens\screenshot057.bmp	31
C:\Users\Public\Public\Screens\screenshot058.bmp	31
C:\Users\Public\Public\Screens\screenshot059.bmp	31
C:\Users\Public\Public\Screens\screenshot060.bmp	32
C:\Users\Public\Public\Screens\screenshot061.bmp	32
C:\Users\Public\Public\Screens\screenshot062.bmp	32
C:\Users\Public\Public\Screens\screenshot063.bmp	33
C:\Users\Public\Public\Screens\screenshot064.bmp	33
C:\Users\Public\Public\Screens\screenshot065.bmp	33
C:\Users\Public\Public\Screens\screenshot066.bmp	34
C:\Users\Public\Public\Screens\screenshot067.bmp	34
C:\Users\Public\Public\Screens\screenshot068.bmp	34
C:\Users\Public\Public\keylogs.txt	35
C:\Users\Public\Public\svchost.exe	35
C:\Users\Public\Public\svchost.exe:Zone.Identifier	35
C:\Users\user\AppData\Local\Packages\ActiveSync\LocalState\DiagOutputDir\SyncVerbose.etl	35
C:\Users\user\AppData\Local\Packages\ActiveSync\LocalState\DiagOutputDir\UnistackCircular.etl	36
C:\Users\user\AppData\Local\Packages\ActiveSync\LocalState\DiagOutputDir\UnistackCritical.etl	36
C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\SyncVerbose.etl.0001 (copy)	36
C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\UnistackCircular.etl.0001 (copy)	37
C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\UnistackCritical.etl.0001 (copy)	37
C:\Windows\Logs\waasmedic\waasmedic.20230203_020233_050.etl	37
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	38
C:\Windows\ServiceProfiles\NetworkService\AppData\Local\Microsoft\Windows\DeliveryOptimization\Logs\dosvc.20230203_020225_210.etl	38
\Device\ConDrv	38
Static File Info	39
General	39
File Icon	39
Static PE Info	39
General	39
Entrypoint Preview	39
Rich Headers	41
Data Directories	41
Sections	41
Resources	41
Imports	41
Possible Origin	42
Network Behavior	42
Statistics	43
Behavior	43
System Behavior	43
Analysis Process: MASTER_Malware_Lab1.exePID: 2560, Parent PID: 3452	43
General	43
File Activities	43

Analysis Process: conhost.exePID: 3076, Parent PID: 2560	43
General	43
Analysis Process: cmd.exePID: 5264, Parent PID: 2560	44
General	44
File Activities	44
Analysis Process: reg.exePID: 5256, Parent PID: 5264	44
General	44
File Activities	44
Registry Activities	44
Analysis Process: svchost.exePID: 628, Parent PID: 3452	44
General	44
File Activities	45
File Created	45
File Written	45
Analysis Process: conhost.exePID: 4788, Parent PID: 628	84
General	84
Analysis Process: cmd.exePID: 5500, Parent PID: 628	84
General	84
Analysis Process: reg.exePID: 5964, Parent PID: 5500	85
General	85
File Activities	85
Analysis Process: svchost.exePID: 732, Parent PID: 580	85
General	85
Analysis Process: svchost.exePID: 3512, Parent PID: 580	85
General	85
File Activities	86
Analysis Process: svchost.exePID: 2792, Parent PID: 580	86
General	86
File Activities	86
Analysis Process: svchost.exePID: 6140, Parent PID: 580	86
General	86
Registry Activities	86
Analysis Process: svchost.exePID: 5240, Parent PID: 580	87
General	87
Analysis Process: svchost.exePID: 4684, Parent PID: 3452	87
General	87
File Activities	87
File Created	87
File Written	87
Analysis Process: conhost.exePID: 4340, Parent PID: 4684	125
General	125
Analysis Process: cmd.exePID: 2384, Parent PID: 4684	125
General	125
Analysis Process: reg.exePID: 5444, Parent PID: 2384	125
General	125
File Activities	125
Analysis Process: svchost.exePID: 848, Parent PID: 580	125
General	126
File Activities	126
Registry Activities	126
Analysis Process: svchost.exePID: 6128, Parent PID: 580	126
General	126
Registry Activities	126
Analysis Process: svchost.exePID: 3020, Parent PID: 580	127
General	127
Analysis Process: MpCmdRun.exePID: 4600, Parent PID: 6128	127
General	127
File Activities	127
File Written	127
Analysis Process: conhost.exePID: 3012, Parent PID: 4600	129
General	129
Disassembly	129

Windows Analysis Report

MASTER_Malware_Lab1.exe

Overview

General Information

Sample Name:	MASTER_Malware_Lab1.exe
Analysis ID:	797228
MD5:	07b92f1473b82...
SHA1:	2d5fa5ca204e2...
SHA256:	ad9427b659a7...
Infos:	


Detection

Score:	88
Range:	0 - 100
Whitelisted:	false
Confidence:	100%

Signatures

Antivirus / Scanner detection for sub...
Multi AV Scanner detection for subm...
Antivirus detection for dropped file
Multi AV Scanner detection for drop...
Query firmware table information (lik...
Uses cmd line tools excessively to ...
Changes security center settings (n...
Drops PE files with benign system n...
Uses 32bit PE files
Found a high number of Window / U...
AV process strings found (often use...
Drops PE files

Classification



Process Tree

System is w10x64
MASTER_Malware_Lab1.exe (PID: 2560 cmdline: C:\Users\user\Desktop\MASTER_Malware_Lab1.exe MD5: 07B92F1473B82789F71A58EE8999C631)
conhost.exe (PID: 3076 cmdline: C:\Windows\system32\conhost.exe 0xffffffff -ForceV1 MD5: EA777DEEA782E8B4D7C7C33BBF8A4496)
cmd.exe (PID: 5264 cmdline: C:\Windows\system32\cmd.exe /c REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: F3BDBE3BB6F734E357235F4D5898582D)
reg.exe (PID: 5256 cmdline: REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: CEE2A7E57DF2A159A065A34913A055C2)
svchost.exe (PID: 628 cmdline: "C:\Users\Public\Public\svchost.exe" MD5: 07B92F1473B82789F71A58EE8999C631)
conhost.exe (PID: 4788 cmdline: C:\Windows\system32\conhost.exe 0xffffffff -ForceV1 MD5: EA777DEEA782E8B4D7C7C33BBF8A4496)
cmd.exe (PID: 5500 cmdline: C:\Windows\system32\cmd.exe /c REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: F3BDBE3BB6F734E357235F4D5898582D)
reg.exe (PID: 5964 cmdline: REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: CEE2A7E57DF2A159A065A34913A055C2)
svchost.exe (PID: 732 cmdline: C:\Windows\System32\svchost.exe -k LocalSystemNetworkRestricted -p -s NcbService MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 3512 cmdline: c:\windows\system32\svchost.exe -k unistacksvcgroup MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 2792 cmdline: c:\windows\system32\svchost.exe -k localService -p -s CDPSvc MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 6140 cmdline: c:\windows\system32\svchost.exe -k networkService -p -s DoSvc MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 5240 cmdline: C:\Windows\System32\svchost.exe -k NetworkService -p MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 4684 cmdline: "C:\Users\Public\Public\svchost.exe" MD5: 07B92F1473B82789F71A58EE8999C631)
conhost.exe (PID: 4340 cmdline: C:\Windows\system32\conhost.exe 0xffffffff -ForceV1 MD5: EA777DEEA782E8B4D7C7C33BBF8A4496)
cmd.exe (PID: 2384 cmdline: C:\Windows\system32\cmd.exe /c REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: F3BDBE3BB6F734E357235F4D5898582D)
reg.exe (PID: 5444 cmdline: REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe MD5: CEE2A7E57DF2A159A065A34913A055C2)
svchost.exe (PID: 848 cmdline: c:\windows\system32\svchost.exe -k netsvcs -p MD5: 32569E403279B3FD2EDB7EBD036273FA)
svchost.exe (PID: 6128 cmdline: c:\windows\system32\svchost.exe -k localServiceNetworkRestricted -p -s wscsvcs MD5: 32569E403279B3FD2EDB7EBD036273FA)
MpCmdRun.exe (PID: 4600 cmdline: "C:\Program Files\Windows Defender\mpcmdrun.exe" -wdenable MD5: A267555174BFA53844371226F482B86B)
conhost.exe (PID: 3012 cmdline: C:\Windows\system32\conhost.exe 0xffffffff -ForceV1 MD5: EA777DEEA782E8B4D7C7C33BBF8A4496)
svchost.exe (PID: 3020 cmdline: c:\windows\system32\svchost.exe -k wusvcs -p -s WaaSMedicSvc MD5: 32569E403279B3FD2EDB7EBD036273FA)
cleanup

Malware Configuration

⛔ No configs have been found

Yara Signatures

⛔ No yara matches

Sigma Signatures

⛔ No Sigma rule has matched

Snort Signatures

⛔ No Snort rule has matched

Joe Sandbox Signatures

AV Detection



- Antivirus / Scanner detection for submitted sample
- Multi AV Scanner detection for submitted file
- Antivirus detection for dropped file
- Multi AV Scanner detection for dropped file

Persistence and Installation Behavior



- Uses cmd line tools excessively to alter registry or file data
- Drops PE files with benign system names

Malware Analysis System Evasion



- Query firmware table information (likely to detect VMs)

Lowering of HIPS / PFW / Operating System Security Settings




- Changes security center settings (notifications, updates, antivirus, firewall)

Mitre Att&ck Matrix

Initial Access	Execution	Persistence	Privilege Escalation	Defense Evasion	Credential Access	Discovery	Lateral Movement	Collection	Exfiltration	Command and Control	Network Effects	Remote Service Effects	Impact
Valid Accounts	1 Windows Management Instrumentation	1 DLL Side-Loading	1 1 Process Injection	1 1 Masquerading	OS Credential Dumping	2 3 1 Security Software Discovery	Remote Services	Data from Local System	Exfiltration Over Other Network Medium	Data Obfuscation	Eavesdrop on Insecure Network Communication	Remotely Track Device Without Authorization	Modify System Partition

Initial Access	Execution	Persistence	Privilege Escalation	Defense Evasion	Credential Access	Discovery	Lateral Movement	Collection	Exfiltration	Command and Control	Network Effects	Remote Service Effects	Impact
Default Accounts	1 Command and Scripting Interpreter	1 Registry Run Keys / Startup Folder	1 DLL Side-Loading	1 Disable or Modify Tools	LSASS Memory	1 3 1 Virtualization/Sandbox Evasion	Remote Desktop Protocol	Data from Removable Media	Exfiltration Over Bluetooth	Junk Data	Exploit SS7 to Redirect Phone Calls/SMS	Remotely Wipe Data Without Authorization	Device Lockout
Domain Accounts	At (Linux)	Logon Script (Windows)	1 Registry Run Keys / Startup Folder	1 Modify Registry	Security Account Manager	1 Application Window Discovery	SMB/Windows Admin Shares	Data from Network Shared Drive	Automated Exfiltration	Steganography	Exploit SS7 to Track Device Location	Obtain Device Cloud Backups	Delete Device Data
Local Accounts	At (Windows)	Logon Script (Mac)	Logon Script (Mac)	1 3 1 Virtualization/Sandbox Evasion	NTDS	1 1 System Information Discovery	Distributed Component Object Model	Input Capture	Scheduled Transfer	Protocol Impersonation	SIM Card Swap		Carrier Billing Fraud
Cloud Accounts	Cron	Network Logon Script	Network Logon Script	1 1 Process Injection	LSA Secrets	Remote System Discovery	SSH	Keylogging	Data Transfer Size Limits	Fallback Channels	Manipulate Device Communication		Manipulate App Store Rankings or Ratings
Replication Through Removable Media	Launchd	Rc.common	Rc.common	1 DLL Side-Loading	Cached Domain Credentials	System Owner/User Discovery	VNC	GUI Input Capture	Exfiltration Over C2 Channel	Multiband Communication	Jamming or Denial of Service		Abuse Accessibility Features


Behavior Graph



Screenshots

Thumbnails

This section contains all screenshots as thumbnails, including those not shown in the slideshow.



Antivirus, Machine Learning and Genetic Malware Detection

Initial Sample

Source	Detection	Scanner	Label	Link
MASTER_Malware_Lab1.exe	49%	ReversingLabs	Win32.Trojan.Male x	
MASTER_Malware_Lab1.exe	56%	Virustotal		Browse
MASTER_Malware_Lab1.exe	100%	Avira	TR/Malex.pfzxh	

Dropped Files

Source	Detection	Scanner	Label	Link
C:\Users\Public\Public\svchost.exe	100%	Avira	TR/Malex.pfzxh	
C:\Users\Public\Public\svchost.exe	49%	ReversingLabs	Win32.Trojan.Male x	

Source	Detection	Scanner	Label	Link
C:\Users\Public\Public\svchost.exe	56%	Virustotal		Browse

Unpacked PE Files

 No Antivirus matches

Domains

 No Antivirus matches

URLs

Source	Detection	Scanner	Label	Link
http://https://%s.xboxlive.com	0%	URL Reputation	safe	
http://https://dynamic.t	0%	URL Reputation	safe	
http://https://%s.dnet.xboxlive.com	0%	URL Reputation	safe	
http://https://%s.dnet.xboxlive.com	0%	URL Reputation	safe	

Domains and IPs

Contacted Domains

 No contacted domains info

URLs from Memory and Binaries

Name	Source	Malicious	Antivirus Detection	Reputation
http://https://dynamic.t0.tiles.ditu.live.com/comp/gen.ashx	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://t0.ssl.ak.dynamic.tiles.virtualearth.net/odvs/gdv?pv=1&r=	svchost.exe, 0000000C.00000003.322748056.000001E0A9056000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.ditu.live.com/REST/v1/Routes/	svchost.exe, 0000000C.00000002.324142629.000001E0A903D000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.virtualearth.net/REST/v1/Routes/Driving	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://t0.ssl.ak.dynamic.tiles.virtualearth.net/comp/gen.ashx	svchost.exe, 0000000C.00000002.324142629.000001E0A903D000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.ditu.live.com/REST/v1/Traffic/Incidents/	svchost.exe, 0000000C.00000003.322303385.000001E0A905A000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324177574.000001E0A905C000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://t0.tiles.ditu.live.com/tiles/gen	svchost.exe, 0000000C.00000002.324160552.000001E0A904E000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.virtualearth.net/REST/v1/Routes/	svchost.exe, 0000000C.00000002.324142629.000001E0A903D000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://t0.ssl.ak.dynamic.tiles.virtualearth.net/odvs/gdi?pv=1&r=	svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.virtualearth.net/REST/v1/Routes/Walking	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.virtualearth.net/webservices/v1/LoggingService/LoggingService.svc/Log?	svchost.exe, 0000000C.00000003.322303385.000001E0A905A000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324177574.000001E0A905C000.00000004.00000020.00020000.00000000.sdmp	false		high

Name	Source	Malicious	Antivirus Detection	Reputation
http://t0.ssl.ak.dynamic.tiles.virtualearth.net/odvs/gd?pv=1&r=	svchost.exe, 0000000C.00000002.323991243.000001E0A9027000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324142629.000001E0A903D000.00000004.00000020.00020000.00000000.sdmp	false		high
https://dev.virtualearth.net/mapcontrol/HumanScaleServices/GetBubbles.ashx?n=	svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324149332.000001E0A9041000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://%s.xboxlive.com	svchost.exe, 0000000A.00000002.511910088.000001D7B123E000.00000004.00000020.00020000.00000000.sdmp	false	URL Reputation: safe	low
https://dev.ditu.live.com/mapcontrol/mapconfiguration.ashx?name=native&v=	svchost.exe, 0000000C.00000002.324160552.000001E0A904E000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.virtualearth.net/REST/v1/Locations	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
https://ecn.dev.virtualearth.net/mapcontrol/mapconfiguration.ashx?name=native&v=	svchost.exe, 0000000C.00000003.293771438.000001E0A9032000.00000004.00000020.00020000.00000000.sdmp	false		high
https://dev.virtualearth.net/mapcontrol/logging.ashx	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.ditu.live.com/mapcontrol/logging.ashx	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
https://dev.ditu.live.com/REST/v1/Imagery/Copyright/	svchost.exe, 0000000C.00000003.322303385.000001E0A905A000.00000004.00000020.00020000.00000000.sdmp	false		high
https://t0.ssl.ak.dynamic.tiles.virtualearth.net/odvs/gri?pv=1&r=	svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dynamic.api.tiles.ditu.live.com/odvs/gdi?pv=1&r=	svchost.exe, 0000000C.00000002.324177574.000001E0A905C000.00000004.00000020.00020000.00000000.sdmp	false		high
https://dev.virtualearth.net/REST/v1/JsonFilter/VenueMaps/data/	svchost.exe, 0000000C.00000003.322303385.000001E0A905A000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324177574.000001E0A905C000.00000004.00000020.00020000.00000000.sdmp	false		high
https://dev.virtualearth.net/REST/v1/Transit/Schedules/	svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324149332.000001E0A9041000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dynamic.t	svchost.exe, 0000000C.00000003.318005078.000001E0A9064000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324149332.000001E0A9041000.00000004.00000020.00020000.00000000.sdmp	false	URL Reputation: safe	unknown
https://dev.virtualearth.net/REST/v1/Routes/Transit	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://t0.ssl.ak.tiles.virtualearth.net/tiles/gen	svchost.exe, 0000000C.00000003.322712881.000001E0A9040000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dynamic.api.tiles.ditu.live.com/odvs/gdv?pv=1&r=	svchost.exe, 0000000C.00000003.322303385.000001E0A905A000.00000004.00000020.00020000.00000000.sdmp, svchost.exe, 0000000C.00000002.324177574.000001E0A905C000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://activity.windows.com	svchost.exe, 0000000A.00000002.511910088.000001D7B123E000.00000004.00000020.00020000.00000000.sdmp	false		high
http://www.bingmapsportal.com	svchost.exe, 0000000C.00000002.323936739.000001E0A9013000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://dev.ditu.live.com/REST/v1/Locations	svchost.exe, 0000000C.00000003.319329371.000001E0A9061000.00000004.00000020.00020000.00000000.sdmp	false		high
https://ecn.dev.virtualearth.net/REST/v1/Imagery/Copyright/	svchost.exe, 0000000C.00000002.324142629.000001E0A903D000.00000004.00000020.00020000.00000000.sdmp	false		high
http://https://%s.dnet.xboxlive.com	svchost.exe, 0000000A.00000002.511910088.000001D7B123E000.00000004.00000020.00020000.00000000.sdmp	false	- URL Reputation: safe - URL Reputation: safe	low

Name	Source	Malicious	Antivirus Detection	Reputation
http:// https://dev.ditu.live.com/REST/v1/JsonFilter/VenueMaps/data/	svchost.exe, 0000000C.00000003.322303385 .000001E0A905A000.00000004.00000020.0002 0000.00000000.sdmp, svchost.exe, 0000000 C.00000002.324177574.000001E0A905C000.00 000004.00000020.00020000.00000000.sdmp	false		high
http://https://dynamic.api.tiles.ditu.live.com/odvs/gd?pv=1&r=	svchost.exe, 0000000C.00000003.322303385 .000001E0A905A000.00000004.00000020.0002 0000.00000000.sdmp	false		high

World Map of Contacted IPs

 No contacted IP infos

General Information

Joe Sandbox Version:	36.0.0 Rainbow Opal
Analysis ID:	797228
Start date and time:	2023-02-02 18:01:12 +01:00
Joe Sandbox Product:	CloudBasic
Overall analysis duration:	0h 8m 3s
Hypervisor based Inspection enabled:	false
Report type:	light
Cookbook file name:	default.jbs
Analysis system description:	Windows 10 64 bit v1803 with Office Professional Plus 2016, Chrome 104, IE 11, Adobe Reader DC 19, Java 8 Update 211
Number of analysed new started processes analysed:	23
Number of new started drivers analysed:	0
Number of existing processes analysed:	0
Number of existing drivers analysed:	0
Number of injected processes analysed:	0
Technologies:	- HCA enabled - EGA enabled - HDC enabled - AMSI enabled
Analysis Mode:	default
Analysis stop reason:	Timeout
Sample file name:	MASTER_Malware_Lab1.exe
Detection:	MAL
Classification:	mal88.evad.winEXE@29/89@0/0
EGA Information:	Failed
HDC Information:	Failed
HCA Information:	- Successful, ratio: 100% - Number of executed functions: 0 - Number of non-executed functions: 0
Cookbook Comments:	Found application associated with file extension: .exe

Warnings

- Exclude process from analysis (whitelisted): SgrmBroker.exe - Excluded domains from analysis (whitelisted): fs.microsoft.com - Not all processes where analyz ed, report is missing behavior information - Report size getting too big, t oo many NtSetInformationFile calls found. - Report size getting too big, t oo many NtWriteFile calls found.

Simulations

Behavior and APIs

Time	Type	Description
18:02:06	API Interceptor	202x Sleep call for process: MASTER_Malware_Lab1.exe modified
18:02:09	Autostart	Run: HKCU\Software\Microsoft\Windows\CurrentVersion\Run Firewall C:\Users\Public\Public\svchost.exe

Time	Type	Description
18:02:17	Autostart	Run: HKCU64\Software\Microsoft\Windows\CurrentVersion\Run Firewall C:\Users\Public\Public\svchost.exe
18:02:24	API Interceptor	135x Sleep call for process: svchost.exe modified
18:03:35	API Interceptor	1x Sleep call for process: MpCmdRun.exe modified

Joe Sandbox View / Context

IPs

No context

Domains

No context

ASNs

No context

JA3 Fingerprints

No context

Dropped Files

No context

Created / dropped Files

C:\ProgramData\USOPrivate\UpdateStore\updatestore51b519d5-b6f5-4333-8df6-e74d7c9aead4.xml (copy)

Process:	C:\Windows\System32\svchost.exe
File Type:	XML 1.0 document, ASCII text, with very long lines (2494), with no line terminators
Category:	dropped
Size (bytes):	2494
Entropy (8bit):	5.230229221505206
Encrypted:	false
SSDEEP:	48:cAn/TLtGgzmqLeUp/B8H6rMSkC9+TyklSbs:pTLtf9zmQ7rVkgqSbs
MD5:	6E0F869D3D3BD21E43186115B0CD74DF
SHA1:	9BA7DB68CDAF7F6358A454EB9296E83E9CB9CB6C
SHA-256:	0471ED17C647021B27987587515E43530391228A8F15D17DDED47472F914BF5B
SHA-512:	E8F7A2ED0A28DFB9A7B32246A7A4A95D6E438FE5420C0F11C047633EA5E9AEAAAD2C1004D45D731066A54E2680567AF932850D5480654BA8D4BFE85AFB1BDAF9
Malicious:	false
Preview:	<?xml version="1.0" encoding="UTF-8"?><updateStore><sessionVariables><permanent><AUOptions dataType="3">1</AUOptions><AllowMUUpdateService dataType="3">0</AllowMUUpdateService><AreUpdatesPausedByPolicy dataType="11">False</AreUpdatesPausedByPolicy><AttentionRequiredReason dataType="19">0</AttentionRequiredReason><CurrentState dataType="19">1</CurrentState><FirstScanAttemptTime dataType="21">132399969272148706</FirstScanAttemptTime><FlightEnabled dataType="3">0</FlightEnabled><LastError dataType="19">0</LastError><LastErrorState dataType="19">0</LastErrorState><LastErrorStateType dataType="11">False</LastErrorStateType><LastMeteredScanTime dataType="21">132399969272304939</LastMeteredScanTime><LastScanAttemptTime dataType="21">132399969272148706</LastScanAttemptTime><LastScanDeferredReason dataType="19">1</LastScanDeferredReason><LastScanDeferredTime dataType="21">133051593686244000</LastScanDeferredTime><LastScanFailureError dataType="3">-2147023838</LastScanFailureError><LastScanFailu

C:\ProgramData\USOPrivate\UpdateStore\updatestoretemp51b519d5-b6f5-4333-8df6-e74d7c9aead4.xml

Process:	C:\Windows\System32\svchost.exe
File Type:	XML 1.0 document, ASCII text, with very long lines (2494), with no line terminators
Category:	dropped
Size (bytes):	2494
Entropy (8bit):	5.230229221505206

Encrypted:	false
SSDEEP:	48:cAn/TLtfGgzmqLeUp/B8H6rMSkC9+TyklSbs:pTLtf9zmQ7rVkgqSbs
MD5:	6E0F869D3D3BD21E43186115B0CD74DF
SHA1:	9BA7DB68CDAF7F6358A454EB9296E83E9CB9CB6C
SHA-256:	0471ED17C647021B27987587515E43530391228A8F15D17DDED47472F914BF5B
SHA-512:	E8F7A2ED0A28DFB9A7B32246A7A4A95D6E438FE5420C0F11C047633EA5E9AEAAAD2C1004D45D731066A54E2680567AF932850D5480654BA8D4BFE85AFB1BDAF9
Malicious:	false
Preview:	<?xml version="1.0" encoding="UTF-8"?><updateStore><sessionVariables><permanent><AUOptions dataType="3">1</AUOptions><AllowMUUpdateService dataType="3">0</AllowMUUpdateService><AreUpdatesPausedByPolicy dataType="11">False</AreUpdatesPausedByPolicy><AttentionRequiredReason dataType="19">0</AttentionRequiredReason><CurrentState dataType="19">1</CurrentState><FirstScanAttemptTime dataType="21">132399969272148706</FirstScanAttemptTime><FlightEnabled dataType="3">0</FlightEnabled><LastError dataType="19">0</LastError><LastErrorState dataType="19">0</LastErrorState><LastErrorStateType dataType="11">False</LastErrorStateType><LastMeteredScanTime dataType="21">132399969272304939</LastMeteredScanTime><LastScanAttemptTime dataType="21">132399969272148706</LastScanAttemptTime><LastScanDeferredReason dataType="19">1</LastScanDeferredReason><LastScanDeferredTime dataType="21">133051593686244000</LastScanDeferredTime><LastScanFailureError dataType="3">-2147023838</LastScanFailureError><LastScanFailu

C:\ProgramData\US0Shared\Logs\UpdateSessionOrchestration.001.etl (copy)	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	8192
Entropy (8bit):	3.7553248052032124
Encrypted:	false
SSDEEP:	96:7i8iv/iZxgZNnA8Z6uQZ2Z5k907HUuZbVZ+ZgEZwZeA3HZMTDZLpQ:7i8iv/c8NndOAnTob6d5MBLpQ
MD5:	6A5290D199C60BA00B831AF43CE84139
SHA1:	89C34056CF9631DB000E108D81C16181E2493C33
SHA-256:	F9BA0E11255941ACB9FDF04CBC0A4AE73F7CB021EAE50275502C11A5F78E6DC7
SHA-512:	3AB7066BFFA061988BF8712A96B0D2B5827D62DB0DC02EFBBCCCE39A20DCC5741B2978DAD06097629614F7DB9267FE56D698BF7593E6A5356E02BE9EC57EC182
Malicious:	false
Preview:	P...p.G.s7.....B.....Zb.K....(.....@t.z.r.e.s...d.I.I.,-2.1.2.....@t.z.r.e.s...d.I.I.,-2.1.1.....r.....p.G.s7.....Up.d.a.t.e.S.e.s.s.i.o.n.O.r.c.h.e.s.t.r.a.t.i.o.n...C:.\P.r.o.g.r.a.m.D.a.t.a.\U.S .O.S.h.a.r.e.d.\L.o.g.s.\U.p.d.a.t.e.S.e.s.s.i.o.n.O.r.c.h.e.s.t.r.a.t.i.o.n_1...e.t.l.....P.P.....P...p.G.s7.....

C:\ProgramData\US0Shared\Logs\UpdateSessionOrchestration_Temp.1.etl	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	8192
Entropy (8bit):	3.7553248052032124
Encrypted:	false
SSDEEP:	96:7i8iv/iZxgZNnA8Z6uQZ2Z5k907HUuZbVZ+ZgEZwZeA3HZMTDZLpQ:7i8iv/c8NndOAnTob6d5MBLpQ
MD5:	6A5290D199C60BA00B831AF43CE84139
SHA1:	89C34056CF9631DB000E108D81C16181E2493C33
SHA-256:	F9BA0E11255941ACB9FDF04CBC0A4AE73F7CB021EAE50275502C11A5F78E6DC7
SHA-512:	3AB7066BFFA061988BF8712A96B0D2B5827D62DB0DC02EFBBCCCE39A20DCC5741B2978DAD06097629614F7DB9267FE56D698BF7593E6A5356E02BE9EC57EC182
Malicious:	false
Preview:	P...p.G.s7.....B.....Zb.K....(.....@t.z.r.e.s...d.I.I.,-2.1.2.....@t.z.r.e.s...d.I.I.,-2.1.1.....r.....p.G.s7.....Up.d.a.t.e.S.e.s.s.i.o.n.O.r.c.h.e.s.t.r.a.t.i.o.n...C:.\P.r.o.g.r.a.m.D.a.t.a.\U.S .O.S.h.a.r.e.d.\L.o.g.s.\U.p.d.a.t.e.S.e.s.s.i.o.n.O.r.c.h.e.s.t.r.a.t.i.o.n_1...e.t.l.....P.P.....P...p.G.s7.....

C:\Users\Public\Public\Screens\screenshot.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.221117558239095
Encrypted:	false
SSDEEP:	98304:gLxleXAI6vKgK4qkVfISrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIj

MD5:	86558E92FA584C81D56C2AA48FD775F7
SHA1:	C68E99459D355F0C4EE8BB134BEAFB836D3EFE16
SHA-256:	35B061B7C71C47B61BD5C1A045D1E53A183054D7EDFD135F5B00F61C3D792AFC
SHA-512:	1C326316542811DEF84254E6DDCAB78F68D1E4C03FDC10379613EABCFDBEB9909872F0DFEB09D4076F34BF6FF829C5C20D3CD3C64C1D4D3FD3C642B0E7210DE
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot000.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAI6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot001.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAI6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot002.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAI6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false

Preview:	BMB.~.....B...(.....8.....~.....
----------	---

C:\Users\Public\Public\Screens\screenshot003.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot004.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot005.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot006.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66

Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot007.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot008.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot009.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD

SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot010.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfISrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot011.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfISrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot012.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfISrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F17F77ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot013.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217768203369236
Encrypted:	false
SSDEEP:	98304:gLxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:9YG90dhIJ
MD5:	A3EA2E73FE3F86F3EA834097A969E78B
SHA1:	9B5F2E01D29615AC1CFCD88935F2E05EBE036FAD
SHA-256:	A648A1000DB157793D1AE248DEDE6A307414F7444D93FDB07C142D7AF3F3D687
SHA-512:	AE55955C3DA15E113F177ADF7B589A917BC888CDAA77279E86789741EA7DD90BDF0E06C475E9DC09939E7A53434348F07B95F5AD62221F7A91964C4D3822C
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot014.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.228098935069598
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	4A6487EB853A62BA13ED907E17D6C38C
SHA1:	60DE98B9F3FD0F39A06B6B42C0C11DF45A11080E
SHA-256:	4EFBA6FB63E965F3B7D624DCE2CE61098B2D1CC6B64CFA39EBFE892D5113A1C7
SHA-512:	A1828FE42479608F6FA461157405AEE939FB328C181C2B1603015025D3EA69111D8147C2D65809CF38727F73B7FC4908ED8EBD5B9D2253458C79F4A93316A555
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot015.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot016.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787

Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot017.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot018.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot019.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954

SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot020.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot021.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot022.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSlrLfPLxWkh4+HxYNtxYRC++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot023.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC+++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot024.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC+++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot025.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	98304:9LxleXAl6vKgK4qkVfSIrLfPLxWkh4+HxYNtxYRC+++e3nuO2Buvkb5yJN6mi5Jl5:wYG90dhIJ
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot026.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped

Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot027.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot028.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot029.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.221102234090809
Encrypted:	false
SSDEEP:	
MD5:	04C82F2596FBAA18E6A4E0CB6FCCD75D

SHA1:	A9DDCE0215BE5FE391D1DB791ADE9F1B910809F2
SHA-256:	B0209ED881AEF9DD3CD3BA35A425BF30F302FF5ACAE5E754AA02ACC45F944658
SHA-512:	5D4B71CA610985649D868EFEB466C2EF58C16F0C023EC2E311E60E7C7070C7B8A734C4C7C6D9F532B2E89CF18D3658CF7318EED6E1B8741D7F19C1C14E112D83
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot030.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot031.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.221447740148902
Encrypted:	false
SSDEEP:	
MD5:	AB7EB8BB77800E29B01132EAB40576C0
SHA1:	FA67BEB4B07073AC9E63022C20B5D7FC83DECFCF
SHA-256:	CC4A914453FC65478A05DD4E73A950CD84C335B3BF44441A07ADDE7BEFB19257
SHA-512:	D320E6125B9F57DE14FEBCC31E241E620CCC3BBA8C12670C2C23E592F0607E9119C39F6ED2A4A081410298825345F1E998FCF0B682405F75F8E54007D2C4C82
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot032.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false

Preview:	BMB.~.....B...(.....8.....~.....
----------	---

C:\Users\Public\Public\Screens\screenshot033.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot034.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot035.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot036.bmp	
---	--

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot037.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot038.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot039.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787

Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot040.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot041.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot042.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954

SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot043.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot044.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot045.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot046.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot047.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot048.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot049.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped

Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot050.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.221408679682695
Encrypted:	false
SSDEEP:	
MD5:	C0C74D0B84CBEA80CFB335CB2CA8C437
SHA1:	E33B7A642FFE55BF10DCA5737328A2A901F4AC14
SHA-256:	08F9ECDD888E6432AA3BF57E463EFBC4F70C73687B15C1C412973516D6633C19
SHA-512:	4F0C24D05E0941B409C327EF72C42C7DDEBFF8208E50E9216DF8DB84056B69D3E56BF550B29A734D7D9FE013EA67B8694F279553C03CFA4DF29D1B62CB11554B
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot051.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot052.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520

SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot053.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot054.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~

C:\Users\Public\Public\Screens\screenshot055.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false

Preview:	BMB.~.....B...(.....8.....~.....
----------	---

C:\Users\Public\Public\Screens\screenshot056.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot057.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot058.bmp	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769400106787
Encrypted:	false
SSDEEP:	
MD5:	DB29ED5D33E174A6A6870FCBCC848520
SHA1:	20C24733DF8B5BB8CBA28000C71387407830A883
SHA-256:	877ED0E32D70B227567AB92D89E7580EC7096B45E550DC8E87D85CC2A3C23954
SHA-512:	6779A6454EC06DAAEF20FD14882BCA34F2770A9AEC4E89C6820549B17421A8D734B88B957CEDA51DAB3E4A9C16775D6C8C798051034AEF89826ADC670DBE937
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot059.bmp	
---	--

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.220773371957926
Encrypted:	false
SSDEEP:	
MD5:	C8B78E8DBD203579F4FE4D9310536F1F
SHA1:	9FF6E96193D25033442E19A45908FE8C9A97597F
SHA-256:	D7276DA57FFF0338E1B226B344DE86FEC5F01F109E589B2314663988308558B9
SHA-512:	31B777C42E4CF8F4EEA03CF6A92A57E0FAA200DDA9B8F7D8CC53E82063FBD9F9E3DFD109320DAA6444161ECB3B8AD7E1B08F28927A7577C9230552C7B6030E8D
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot060.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.2296226339111485
Encrypted:	false
SSDEEP:	
MD5:	C2BB83CAB978E593AF7480086AE4421B
SHA1:	0585E924CF407AAB0AEBF3430DE273895E16FD87
SHA-256:	458909BC79473DBD8D5B81701931F0A4556E1E6FFF19E0E9207B0E06A23EFA2D
SHA-512:	C44EFA25EB56464A724DE181AC0233D09B8C7BDA90A13ED2769F13904B67826CD116600D499D2E786664A073C7B76D2B57CF34EE9748CE1D5C3F2D2F960E13E4
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot061.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.225921621697788
Encrypted:	false
SSDEEP:	
MD5:	F8172BAAB31572E2B421F7F303386823
SHA1:	303827B4D73C3D3289AD2EB0FC7031EADD34BE05
SHA-256:	ECE3336CAF6F24135814453A6568E25D7FC58D691F1CDA460961DF60C314B1D7
SHA-512:	29EAE73D685BB02A0A667D19FDD510B366E46AF28F83102BC357C6B7B0834AC5561DCCA8235BB8181F687ACB274DF00FBBAD03D010571C9F8FC0141F523F6D7
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot062.bmp

Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769908125988

SHA-512:	1B14D292CBA3328FF56BAE803203F7343D8E9A197957110A233639DBCC2BBA30D00B716269A81D38DBB9E4355A57DD07A0C8D2498BDA4DF0806D0E9767530D28
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot066.bmp	
Process:	C:\Users\Public\Public\svchost.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.217769908125988
Encrypted:	false
SSDEEP:	
MD5:	473EEAD42BB2AC00D0AED2AB8C195797
SHA1:	FD3CA65702498290074B5DEA60EC33181B2B4F12
SHA-256:	BF8A321C1C34BF4E0CE3A14C866C94C63BB60AFECC38D975293F6A544D50FFD8
SHA-512:	1B14D292CBA3328FF56BAE803203F7343D8E9A197957110A233639DBCC2BBA30D00B716269A81D38DBB9E4355A57DD07A0C8D2498BDA4DF0806D0E9767530D28
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot067.bmp	
Process:	C:\Users\Public\Public\svchost.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	dropped
Size (bytes):	8294466
Entropy (8bit):	4.221408568096128
Encrypted:	false
SSDEEP:	
MD5:	414D0843A86BFFF5D40378380F20D565
SHA1:	DF2A46BA550AEA2A7F78657BD095DFD8E64CA37D
SHA-256:	0512233C8018FB1189CEBFD7A5FE4CA6761105565E69F33DCF4D8DDEA2EDBC11
SHA-512:	C07711666A49921317E51E01809CA0C983DBBC7630CE344B53EEA19B5051C2F23F27C8EF74A38372040FB2575E56E5E929F3442B3C90F6EDFB089EBC053D9D9F
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\Screens\screenshot068.bmp	
Process:	C:\Users\Public\Public\svchost.exe
File Type:	PC bitmap, Windows 3.x format, 1920 x 1080 x 32, 3 compression, image size 8294400, cbSize 8294466, bits offset 66
Category:	modified
Size (bytes):	8294466
Entropy (8bit):	4.217769908125988
Encrypted:	false
SSDEEP:	
MD5:	473EEAD42BB2AC00D0AED2AB8C195797
SHA1:	FD3CA65702498290074B5DEA60EC33181B2B4F12
SHA-256:	BF8A321C1C34BF4E0CE3A14C866C94C63BB60AFECC38D975293F6A544D50FFD8
SHA-512:	1B14D292CBA3328FF56BAE803203F7343D8E9A197957110A233639DBCC2BBA30D00B716269A81D38DBB9E4355A57DD07A0C8D2498BDA4DF0806D0E9767530D28
Malicious:	false
Preview:	BMB.~.....B...(.....8.....~.....

C:\Users\Public\Public\keylogs.txt	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	ASCII text, with very long lines (637), with no line terminators
Category:	dropped
Size (bytes):	637
Entropy (8bit):	3.330762844151229
Encrypted:	false
SSDEEP:	
MD5:	4A6B302891B1908800E8863321BE7320
SHA1:	C3C8D3C4106B085D3E24BB9F877A9DFBCE80F6BA
SHA-256:	7CF2E8ED183917B02CBACA1C5987E9B33ADFF0FFE7FE5E355C6E67BB171122B8
SHA-512:	0554A37992E3697CBABC3B408814E0CCE42EFAFDC8CBF7C68A73B12162F589E9DFE61BC467156C8C4A2B1A74C454F909870D13D2B84F82090D4F8D60F1F2526D
Malicious:	false
Preview:	**RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK** * *RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK**

C:\Users\Public\Public\svchost.exe:Zone.Identifier 	
Process:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
File Type:	ASCII text, with CRLF line terminators
Category:	dropped
Size (bytes):	26
Entropy (8bit):	3.95006375643621
Encrypted:	false
SSDEEP:	
MD5:	187F488E27DB4AF347237FE461A079AD
SHA1:	6693BA299EC1881249D59262276A0D2CB21F8E64
SHA-256:	255A65D30841AB4082BD9D0EEA79D49C5EE88F56136157D8D6156AEF11C12309
SHA-512:	89879F237C0C051EBE784D0690657A6827A312A82735DA42DAD5F744D734FC545BEC9642C19D14C05B2F01FF53BC731530C92F7327BB7DC9CDE1B60FB21CD64E
Malicious:	true
Preview:	[ZoneTransfer].....ZoneId=0

Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11013620174689967
Encrypted:	false
SSDEEP:	
MD5:	0588F1296F7F1FDDE141D2FDABB7FAD5
SHA1:	F82614257DFBFC1102827C0065D02E640BC5C2D2
SHA-256:	67AFFCF77687D7B552EE535F010B93DA6E4E39CCE3D5237241785E25EE810640
SHA-512:	9D310670835B1C3D119799FF219FF456C3329D2D154ABDC8BEC84946FA190C0DE3BF58C99224675BAB0D3D724B85F29D6B5BCB10C77B7A5367759924FCDBAD1
Malicious:	false
Preview:	q.Og.....B.....Zb.....@t.z.r.e.s...d.i.l.,-2.1.2.....@t.z.r.e.s...d.i.l.,-2.1.1.....r.....s7.....S.y.n.c.V.e.r.b.o.s.e...C.:\\U.s.e.r.s\\h.a.r.d.z\\.A.p.p.D.a.t.a\\.L.o.c.a.l\\.p.a.c. k.a.g.e.s\\.A.c.t.i.v.e.S.y.n.c\\.L.o.c.a.l.S.t.a.t.e\\.D.i.a.g.O.u.t.p.u.t.D.i.r\\.S.y.n.c.V.e.r.b.o.s.e...e.t.l.....P.P.....P.g.....

C:\Users\user\AppData\Local\Packages\ActiveSync\LocalState\DiagOutputDir\UnistackCircular.etl	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11262325110440781
Encrypted:	false
SSDEEP:	
MD5:	F2B61D630EEAE6EE4A8A6AA2A3AA9AE4
SHA1:	CE5BE05CED5C296CB1BC8C170E3423A21FDD3FDF
SHA-256:	316573276F52A5E6474CBD5252DD8F5259FE6447F7116516777364408630C6E5
SHA-512:	06E7523579C15B1B44813520458A5F3AE170189DE87F85CA8FC396C72AA904E561010BDD22418FF40F833BDBAE909509FE000C2208F195F7DA6751BAE1CF11DC
Malicious:	false
Preview:	*DLg.....B.....Zb.....@t.z.r.e.s...d.i.l.,-2.1.2.....@t.z.r.e.s...d.i.l.,-2.1.1.....r.....W.s7.....U.n.i.s.t.a.c.k.C.i.r.c.u.l.a.r...C.:\\U.s.e.r.s\\h.a.r.d.z\\.A.p.p.D.a.t.a\\.L.o.c.a. .l\\.p.a.c.k.a.g.e.s\\.A.c.t.i.v.e.S.y.n.c\\.L.o.c.a.l.S.t.a.t.e\\.D.i.a.g.O.u.t.p.u.t.D.i.r\\.U.n.i.s.t.a.c.k.C.i.r.c.u.l.a.r...e.t.l.....P.P.....gXlg.....

C:\Users\user\AppData\Local\Packages\ActiveSync\LocalState\DiagOutputDir\UnistackCritical.etl	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11238869034146516
Encrypted:	false
SSDEEP:	
MD5:	B7D4ED2C1879CCFD7BE7638A456C10BD
SHA1:	A1666AF4F9C327009DB7D1A469FEFA9096718728
SHA-256:	492153307D679C36C56836CAC97571DC76FDC0545C76F53E5F0B9BE89F937149
SHA-512:	0D3DF0158F91E63ABF4D1A0682F4A28C45D50E7338587E69683F0CC468AA483D8C39422E49175BC9C88760E081CF0BC2EF32BF1F253DE0D28EEFFD74C9F357C8
Malicious:	false
Preview:	lDg.....B.....Zb.....@t.z.r.e.s...d.i.l.,-2.1.2.....@t.z.r.e.s...d.i.l.,-2.1.1.....r.....s2.s7.....U.n.i.s.t.a.c.k.C.r.i.t.i.c.a.l...C.:\\U.s.e.r.s\\h.a.r.d.z\\.A.p.p.D.a.t.a\\.L.o.c.a. l\\.p.a.c.k.a.g.e.s\\.A.c.t.i.v.e.S.y.n.c\\.L.o.c.a.l.S.t.a.t.e\\.D.i.a.g.O.u.t.p.u.t.D.i.r\\.U.n.i.s.t.a.c.k.C.r.i.t.i.c.a.l...e.t.l.....P.P.....AtDg.....

C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\SyncVerbose.etl.0001 (copy)	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11013620174689967
Encrypted:	false

SSDEEP:	
MD5:	0588F1296F7F1FDDE141D2FDABB7FAD5
SHA1:	F82614257DFBFC1102827C0065D02E640BC5C2D2
SHA-256:	67AFFCF77687D7B552EE535F010B93DA6E4E39CCE3D5237241785E25EE810640
SHA-512:	9D310670835B1C3D119799FF219FF456C3329D2D154ABDC8BEC84946FA190C0DE3BF58C99224675BAB0D3D724B85F29D6B5BCB10C77B7A5367759924FCDBAD1
Malicious:	false
Preview:	q.Og.....B.....Zb.....@.t.z.r.e.s...d.i.l.l.,-2.1.2.....@.t.z.r.e.s...d.i.l.l.,-2.1.1.....r.....s7.....S.y.n.c.V.e.r.b.o.s.e...C:.\U.s.e.r.s\h.a.r.d.z\A.p.p.D.a.t.a\L.o.c.a.l\p.a.c.k.a.g.e.s\A.c.t.i.v.e.S.y.n.c.\L.o.c.a.l.S.t.a.t.e\D.i.a.g.O.u.t.p.u.t.D.i.r\S.y.n.c.V.e.r.b.o.s.e...e.t.l.....P.P.....P.g.....

C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\UnistackCircular.etl.0001 (copy)	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11262325110440781
Encrypted:	false
SSDEEP:	
MD5:	F2B61D630EEAE6EE4A8A6AA2A3AA9AE4
SHA1:	CE5BE05CED5C296CB1BC8C170E3423A21FDD3FDF
SHA-256:	316573276F52A5E6474CBD5252DD8F5259FE6447F7116516777364408630C6E5
SHA-512:	06E7523579C15B1B44813520458A5F3AE170189DE87F85CA8FC396C72AA904E561010BDD22418FF40F833BDBAE909509FE000C2208F195F7DA6751BAE1CF11DC
Malicious:	false
Preview:	*DLg.....B.....Zb.....@.t.z.r.e.s...d.i.l.l.,-2.1.2.....@.t.z.r.e.s...d.i.l.l.,-2.1.1.....r.....W.s7.....U.n.i.s.t.a.c.k.C.i.r.c.u.l.a.r...C:.\U.s.e.r.s\h.a.r.d.z\A.p.p.D.a.t.a\L.o.c.a.l\p.a.c.k.a.g.e.s\A.c.t.i.v.e.S.y.n.c.\L.o.c.a.l.S.t.a.t.e\D.i.a.g.O.u.t.p.u.t.D.i.r\U.n.i.s.t.a.c.k.C.i.r.c.u.l.a.r...e.t.l.....P.P.....gXLg.....

C:\Users\user\AppData\Local\packages\ActiveSync\LocalState\DiagOutputDir\UnistackCritical.etl.0001 (copy)	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	65536
Entropy (8bit):	0.11238869034146516
Encrypted:	false
SSDEEP:	
MD5:	B7D4ED2C1879CCFD7BE7638A456C10BD
SHA1:	A1666AF4F9C327009DB7D1A469FEFA9096718728
SHA-256:	492153307D679C36C56836CAC97571DC76FDC0545C76F53E5F0B9BE89F937149
SHA-512:	0D3DF0158F91E63ABF4D1A0682F4A28C45D50E7338587E69683F0CC468AA483D8C39422E49175BC9C88760E081CF0BC2EF32BF1F253DE0D28EEFFD74C9F357C8
Malicious:	false
Preview:	lDg.....B.....Zb.....@.t.z.r.e.s...d.i.l.l.,-2.1.2.....@.t.z.r.e.s...d.i.l.l.,-2.1.1.....r.....s2.s7.....U.n.i.s.t.a.c.k.C.r.i.t.i.c.a.l...C:.\U.s.e.r.s\h.a.r.d.z\A.p.p.D.a.t.a\L.o.c.a.l\p.a.c.k.a.g.e.s\A.c.t.i.v.e.S.y.n.c.\L.o.c.a.l.S.t.a.t.e\D.i.a.g.O.u.t.p.u.t.D.i.r\U.n.i.s.t.a.c.k.C.r.i.t.i.c.a.l...e.t.l.....P.P.....AtDg.....

C:\Windows\Logs\waasmedic\waasmedic.20230203_020233_050.etl	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	8192
Entropy (8bit):	2.73479418886721
Encrypted:	false
SSDEEP:	
MD5:	E15085C22E05811AD31FD41834C8E6AE
SHA1:	BEFBAC6963AA8510FF7F3AEC844B7EE284FFBFE4
SHA-256:	0A56893BBF725D0802C759DDD5BB7F87CDFEBF9A08D9AC9C304DCD467233ADD5

SHA-512:	5861906B0EB11D94D5CB726417B8A9470261DB0A2700EE82FF6812147D2EF945F9A5B9D56A5F387A8F6E6F9EA0A191BCE8E67E9A73E4248969B01D5ACCBDA72
Malicious:	false
Preview:	l.....E.....B.....s7..Zb.....@t.z.r.e.s...d.I.l.,-2.1.2.....@t.z.r.e.s...d.I.l.,-2.1.1.....WW.....J.*s7.....E.C.C.B.1.7.5.F.-1.E.B.2.-4.3.D.A.-B.F.B.5.-A.8.D.5.8.A.4.0.A.4.D.7...C. :\W.i.n.d.o.w.s\l.o.g.s\w.a.a.s.m.e.d.i.c\w.a.a.s.m.e.d.i.c...2.0.2.3.0.2.0.3_0.2.0.2.3.3_0.5.0...e.t.l.....P.P.....E.....9.B. .E.....17134.1.amd64fre.rs4_release.180410-1804.....5.@.E.....OYo."(s.O.....WaaSMedicSvc.pdb.....

C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	
Process:	C:\Program Files\Windows Defender\MpCmdRun.exe
File Type:	Unicode text, UTF-16, little-endian text, with CRLF line terminators
Category:	modified
Size (bytes):	10874
Entropy (8bit):	3.1652533662848836
Encrypted:	false
SSDEEP:	
MD5:	54F1BF0991F70FED43D36387452A38F7
SHA1:	91899AAD877A8895200CF8FAB5D832D9ECE994C5
SHA-256:	3A34AE9B6B493B7D4E07A0E0F9EED9B17776F1FC7F9C8E2E7702930A15844985
SHA-512:	5AA34C051A5864E1F3AEC29CE76F021A30AA0679E8B6799679547A4FA0D64D1377C1D7133D223434127531B2136186ABF10D5DA6389C383ADAC973A57E2D6BFF
Malicious:	false
Preview:	Mp.C.m.d.R.u.n.:.C.o.m.m.a.n.d. . L.i.n.e.: "C:\P.r.o.g.r.a.m. .F.i.l.e.s\W.i.n.d.o.w.s .D.e.f.e.n.d.e.r\m.p.c.m.d.r.u.n...e.x.e". -w.d.e.n.a.b.l.e.....S.t.a.r.t. .T.i.m.e.: ..T.h.u. ..J.u.n. ..2.7. ...2.0.1.9. .0. 1.:2.9.:4.9.....M.p.E.n.s.u.r.e.P.r.o.c.e.s.s.M.i.t.i.g.a.t.i.o.n.P.o.l.i.c.y.:.h.r. =. .0.x.1.....W.D.E.n.a.b.l.e.....E.R.R.O.R.:.M.p.W.D.E.n.a.b.l.e.(T.R.U.E). .f.a.i.l.e.d. . (8.0.0.7.0.4.E.C.).....M.p.C.m.d.R.u.n.:.E.n.d. .T.i.m.e.: ..T.h.u. ..J.u.n. ..2.7. ...2.0.1.9. .0.1.:2.9.:4.9.....

C:\Windows\ServiceProfiles\NetworkService\AppData\Local\Microsoft\Windows\DeliveryOptimization\Logs\dosvc.20230203_020225_210.etl	
Process:	C:\Windows\System32\svchost.exe
File Type:	data
Category:	dropped
Size (bytes):	8192
Entropy (8bit):	3.385861204139597
Encrypted:	false
SSDEEP:	
MD5:	358EC3485E09EDBCC34C8179ACE180EC
SHA1:	ECE173FB3CD3FFDA87B51F5FA9579DDBF81088FC
SHA-256:	CAEBA80E15D83DEDBD1CC473232163B8490241097AF4E41C59EB4CA1F99AD00D
SHA-512:	2BD995F47D8EDF5044C3AFB96EE7C66C1F793F9A328EDB62BEF82C71A5A0CE988A9343BDE6BB33C4CCEFADA5362A30A9C4DE7348C838E73730123407F4ED3558
Malicious:	false
Preview:	l.....D.....B.....Zb.....@t.z.r.e.s...d.I.l.,-2.1.2.....@t.z.r.e.s...d.I.l.,-2.1.1.....WW.....M5[s7.....8.6.9.6.E.A.C.4.-1.2.8.8.-4.2.8.8.-A.4.E.E.-4.9.E.E.4.3.1.B.0.A.D.9...C. :\W.i.n.d.o.w.s\S.e.r.v.i.c.e.P.r.o.f.i.l.e.s\N.e.t.w.o.r.k.S.e.r.v.i.c.e\AppData\Local\Microsoft\Windows\DeliveryOptimization\Logs\d. o.s.v.c...2.0.2.3.0.2.0.3_0.2.0.2.2.5_2.1.0...e.t.l.....P.P.....D.....

\Device\ConDrv	
Process:	C:\Users\Public\Public\svchost.exe
File Type:	ASCII text, with no line terminators
Category:	dropped
Size (bytes):	115
Entropy (8bit):	3.352411613911247
Encrypted:	false
SSDEEP:	
MD5:	5583F34A95FBA9FE0B88EC9222FB1E0F
SHA1:	AC1692818883B38D12D3635A87B197E7A64C157A
SHA-256:	F3BC649B37B527E54CBD115579D4326C77A21CE39EA7A4E920BE6B96F24CAC64
SHA-512:	522FA533C0B9B7CA24228B547E1A6BED26E42E6520E1C96FF44465C6389E36CF32166C493B5E459758CCA1A47918A77ABCDFAFB9C612F2B01ED6F7149F40425F
Malicious:	false
Preview:	**LEFT_CLICK** **RIGHT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **RIGHT_CLICK** **LEFT_CLICK** **LEFT_CLICK**

Static File Info

General

File type:	PE32 executable (console) Intel 80386, for MS Windows
Entropy (8bit):	6.220836733793725
TrID:	- Win32 Executable (generic) a (10002005/4) 99.96% - Generic Win/DOS Executable (2004/3) 0.02% - DOS Executable Generic (2002/1) 0.02% - Autodesk FLIC Image File (extensions: flc, fli, cel) (7/3) 0.00%
File name:	MASTER_Malware_Lab1.exe
File size:	40960
MD5:	07b92f1473b82789f71a58ee8999c631
SHA1:	2d5fa5ca204e2d31e6aaa5bcae12cec921f6da62
SHA256:	ad9427b659a7b77e08566627b82c21af23f35fa3047356113cfee764a890ad92
SHA512:	44d3ce9218778dc375faeeeb240a1b611978ab6083b041c0d6cd0f62d9bb901be5f155b1907f0d3c7c44a18a671c7ce915adba6499d0111f8f5a381645eb3c0d
SSDEEP:	768:fZiXwifv5il3eIIOb7clKo0FnQVu7Cx96+:fgk3eIIObBANqs+
TLSH:	5703F533BA0BC7B3EA1503F105756BA687EBB4240F5002C737845E7E25252DAAD77876
File Content Preview:	MZ.....@.....!..L!This program cannot be run in DOS mode....\$.....5=-.2ql.aq\aq.ax\$pa)\a.,.}\a.,.p\l.a.,.}\a.,.u\l.a*4.v\l.aq\l.a.-.s\l.a.-ap\l.a.-.p\l.aRichq\l.a.....PE.L..

File Icon

	
Icon Hash:	00828e8e8686b000

Static PE Info

General

Entrypoint:	0x4062e4
Entrypoint Section:	.text
Digitally signed:	false
Imagebase:	0x400000
Subsystem:	windows cui
Image File Characteristics:	EXECUTABLE_IMAGE, 32BIT_MACHINE
DLL Characteristics:	DYNAMIC_BASE, NX_COMPAT, TERMINAL_SERVER_AWARE
Time Stamp:	0x5F8C68C1 [Sun Oct 18 16:09:37 2020 UTC]
TLS Callbacks:	
CLR (.Net) Version:	
OS Version Major:	6
OS Version Minor:	0
File Version Major:	6
File Version Minor:	0
Subsystem Version Major:	6
Subsystem Version Minor:	0
Import Hash:	962e2dbbc5bb67a0f87fcd14de36453f

Entrypoint Preview

Instruction
call 00007F2628C19EB6h
jmp 00007F2628C19929h
push ebp
mov ebp, esp
mov eax, dword ptr [ebp+08h]
push esi
mov ecx, dword ptr [eax+3Ch]
add ecx, eax
movzx eax, word ptr [ecx+14h]
lea edx, dword ptr [ecx+18h]

Instruction
add edx, eax
movzx eax, word ptr [ecx+06h]
imul esi, eax, 28h
add esi, edx
cmp edx, esi
je 00007F2628C19ACBh
mov ecx, dword ptr [ebp+0Ch]
cmp ecx, dword ptr [edx+0Ch]
jc 00007F2628C19ABCh
mov eax, dword ptr [edx+08h]
add eax, dword ptr [edx+0Ch]
cmp ecx, eax
jc 00007F2628C19ABEh
add edx, 28h
cmp edx, esi
jne 00007F2628C19A9Ch
xor eax, eax
pop esi
pop ebp
ret
mov eax, edx
jmp 00007F2628C19AABh
push esi
call 00007F2628C1A3B4h
test eax, eax
je 00007F2628C19AD2h
mov eax, dword ptr fs:[00000018h]
mov esi, 0040B21Ch
mov edx, dword ptr [eax+04h]
jmp 00007F2628C19AB6h
cmp edx, eax
je 00007F2628C19AC2h
xor eax, eax
mov ecx, edx
lock cmpxchg dword ptr [esi], ecx
test eax, eax
jne 00007F2628C19AA2h
xor al, al
pop esi
ret
mov al, 01h
pop esi
ret
push ebp
mov ebp, esp
cmp dword ptr [ebp+08h], 00000000h
jne 00007F2628C19AB9h
mov byte ptr [0040B220h], 00000001h
call 00007F2628C1A1A3h
call 00007F2628C19E85h
test al, al
jne 00007F2628C19AB6h
xor al, al
pop ebp
ret
call 00007F2628C19E78h
test al, al
jne 00007F2628C19ABCh
push 00000000h

Instruction
call 00007F2628C19E6Dh
pop ecx
jmp 00007F2628C19A9Bh
mov al, 01h
pop ebp
ret
push ebp
mov ebp, esp
cmp byte ptr [0040B221h], 00000000h
je 00007F2628C19AB6h
mov al, 01h

Rich Headers	
Programming Language:	[IMP] VS2008 SP1 build 30729

Data Directories			
Name	Virtual Address	Virtual Size	Is in Section
IMAGE_DIRECTORY_ENTRY_EXPORT	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_IMPORT	0x95ac	0xf0	.rdata
IMAGE_DIRECTORY_ENTRY_RESOURCE	0xc000	0x1e0	.rsrc
IMAGE_DIRECTORY_ENTRY_EXCEPTION	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_SECURITY	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_BASERELOC	0xd000	0x7f0	.reloc
IMAGE_DIRECTORY_ENTRY_DEBUG	0x87e4	0x70	.rdata
IMAGE_DIRECTORY_ENTRY_COPYRIGHT	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_GLOBALPTR	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_TLS	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_LOAD_CONFIG	0x8858	0x40	.rdata
IMAGE_DIRECTORY_ENTRY_BOUND_IMPORT	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_IAT	0x8000	0x230	.rdata
IMAGE_DIRECTORY_ENTRY_DELAY_IMPORT	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_COM_DESCRIPTOR	0x0	0x0	
IMAGE_DIRECTORY_ENTRY_RESERVED	0x0	0x0	

Sections								
Name	Virtual Address	Virtual Size	Raw Size	Xored PE	ZLIB Complexity	File Type	Entropy	Characteristics
.text	0x1000	0x6244	0x6400	False	0.488125	data	6.297825159654746	IMAGE_SCN_CNT_CODE, IMAGE_SCN_MEM_EXECUTE, IMAGE_SCN_MEM_READ
.rdata	0x8000	0x286e	0x2a00	False	0.36551339285714285	data	4.981255823703229	IMAGE_SCN_CNT_INITIALIZE D_DATA, IMAGE_SCN_MEM_READ
.data	0xb000	0x59c	0x400	False	0.19140625	data	2.8760248433349993	IMAGE_SCN_CNT_INITIALIZE D_DATA, IMAGE_SCN_MEM_READ, IMAGE_SCN_MEM_WRITE
.rsrc	0xc000	0x1e0	0x200	False	0.529296875	data	4.701503258251789	IMAGE_SCN_CNT_INITIALIZE D_DATA, IMAGE_SCN_MEM_READ
.reloc	0xd000	0x7f0	0x800	False	0.86865234375	data	6.593452583866235	IMAGE_SCN_CNT_INITIALIZE D_DATA, IMAGE_SCN_MEM_DISCARDA BLE, IMAGE_SCN_MEM_READ

Resources					
Name	RVA	Size	Type	Language	Country
RT_MANIFEST	0xc060	0x17d	XML 1.0 document, ASCII text, with CRLF line terminators	English	United States

Imports


DLL	Import
KERNEL32.dll	AllocConsole, SetUnhandledExceptionFilter, GetModuleHandleW, InitializeSListHead, GetSystemTimeAsFileTime, GetCurrentThreadld, GetCurrentProcessld, CloseHandle, CreateFileA, SetFilePointer, GetModuleFileNameW, WriteFile, CopyFileW, IsDebuggerPresent, Sleep, GetCurrentProcess, TerminateProcess, IsProcessorFeaturePresent, QueryPerformanceCounter, UnhandledExceptionFilter
USER32.dll	GetDC, ShowWindow, FindWindowA, ReleaseDC, GetSystemMetrics, GetAsyncKeyState
GDI32.dll	CreateCompatibleBitmap, SelectObject, CreateCompatibleDC, GetDIBits, DeleteDC, DeleteObject, BitBlt
MSVCP140.dll	?id@?\$codecvt@DDU_Mbstatet@@@std@@@2V0locale@2@@A, ?_Fiopen@std@@@YAPAU_iobuf@@@PBDHH@Z, ?_Xlength_error@std@@@YAXPBD@Z, _Cnd_do_broadcast_at_thread_exit, _Thrd_id, _Thrd_join, ?_Osfx@?\$basic_ostream@DU?\$char_traits@D@std@@@std@@@QAEXXZ, ?_Getcat@?\$codecvt@DDU_Mbstatet@@@std@@@SAIPAPBVfacet@locale@2@PBV42@@@Z, ?sputn@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@QAE_JPBD_J@Z, ?put@?\$basic_ostream@DU?\$char_traits@D@std@@@std@@@QAEAAV12@D@Z, ?flush@?\$basic_ostream@DU?\$char_traits@D@std@@@std@@@QAEAAV12@XZ, ?_Getglobalocale@locale@std@@@CAPAV_Locimp@12@XZ, ?widen@?\$basic_ios@DU?\$char_traits@D@std@@@std@@@QBEDD@Z, ?unshift@?\$codecvt@DDU_Mbstatet@@@std@@@QBEEAAU_Mbstatet@@@PAD1AAPAD@Z, ???_basic_streambuf@DU?\$char_traits@D@std@@@std@@@IAE@XZ, ?getloc@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@QBE?AVlocale@2@XZ, ?_Init@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@IAEXXZ, ?in@?\$codecvt@DDU_Mbstatet@@@std@@@QBEEAAU_Mbstatet@@@PBD1AAPBDPAD3AAPAD@Z, ?out@?\$codecvt@DDU_Mbstatet@@@std@@@QBEEAAU_Mbstatet@@@PBD1AAPBDPAD3AAPAD@Z, ?_Pninc@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@IAEPADXZ, ?clear@?\$basic_ios@DU?\$char_traits@D@std@@@std@@@QAEXH_N@Z, ?setstate@?\$basic_ios@DU?\$char_traits@D@std@@@std@@@QAEXH_N@Z, ???_basic_ios@DU?\$char_traits@D@std@@@std@@@IAE@XZ, ???_basic_ostream@DU?\$char_traits@D@std@@@std@@@QAE@PAV?\$basic_streambuf@DU?\$char_traits@D@std@@@1@_N@Z, ???_basic_streambuf@DU?\$char_traits@D@std@@@std@@@UAE@XZ, ?showmanyc@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@MAE_JXZ, ?xsgetn@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@MAE_JPAD_J@Z, ?xsputn@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@MAE_JPBD_J@Z, ???_basic_ios@DU?\$char_traits@D@std@@@std@@@UAE@XZ, ???_basic_ostream@DU?\$char_traits@D@std@@@std@@@UAE@XZ, ??6?\$basic_ostream@DU?\$char_traits@D@std@@@std@@@QAEAAV01@P6AAAV01@AAV01@@@Z@Z, ?always_noconv@codecvt_base@std@@@QBE_NXZ, ??Bid@locale@std@@@QAEIXZ, ?cout@std@@@3V?\$basic_ostream@DU?\$char_traits@D@std@@@1@A, ?_Throw_Cpp_error@std@@@YAXH@Z, ???_Lockit@std@@@QAE@H@Z, ??1_Lockit@std@@@QAE@XZ, ?uncaught_exception@std@@@YA_NXZ, ?sputc@?\$basic_streambuf@DU?\$char_traits@D@std@@@std@@@QAEHD@Z
VCRUNTIME140.dll	memset, __current_exception_context, __current_exception, __except_handler4_common, memcpy, __CxxFrameHandler3, __std_exception_destroy, __std_exception_copy, __std_terminate, __CxxThrowException, memmove
api-ms-win-crt-stdio-l1-1-0.dll	ungetc, setvbuf, fgetpos, fwrite, fread, __p__commode, fsetpos, __get_stream_buffer_pointers, fgetc, _fseeki64, fclose, fflush, fputc, _set_fmode
api-ms-win-crt-runtime-l1-1-0.dll	_initterm_e, exit, _exit, terminate, __p__argc, _initterm, _cexit, _c_exit, _register_thread_local_exe_atexit_callback, __get_initial_narrow_environment, _initialize_narrow_environment, _configure_narrow_argv, _initialize_onexit_table, _register_onexit_function, _crt_atexit, _set_app_type, _controlfp_s, _seh_filter_exe, system, _invalid_parameter_noinfo_noreturn, _beginthreadex, __p__argv
api-ms-win-crt-file-system-l1-1-0.dll	_mkdir, _unlock_file, __access, _lock_file
api-ms-win-crt-heap-l1-1-0.dll	malloc, _callnewh, __set_new_mode, free
api-ms-win-crt-math-l1-1-0.dll	__setusermatherr
api-ms-win-crt-locale-l1-1-0.dll	_configthreadlocale

Possible Origin		
Language of compilation system	Country where language is spoken	Map
English	United States	

Network Behavior
Report size exceeds maximum size, go to the download page of this report and download PCAP to see all network behavior.

Statistics

Behavior



- MASTER_Malware_Lab1.exe
- conhost.exe
- cmd.exe
- reg.exe
- svchost.exe
- conhost.exe
- cmd.exe
- reg.exe
- svchost.exe
- svchost.exe
- svchost.exe
- svchost.exe
- svchost.exe
- svchost.exe
- conhost.exe
- cmd.exe
- reg.exe
- svchost.exe
- svchost.exe
- svchost.exe
- MpCmdRun.exe
- conhost.exe

Click to jump to process

System Behavior

Analysis Process: MASTER_Malware_Lab1.exe PID: 2560, Parent PID: 3452

General

Target ID:	0
Start time:	18:02:04
Start date:	02/02/2023
Path:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
Wow64 process (32bit):	true
Commandline:	C:\Users\user\Desktop\MASTER_Malware_Lab1.exe
Imagebase:	0x190000
File size:	40960 bytes
MD5 hash:	07B92F1473B82789F71A58EE8999C631
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language
Reputation:	low

File Activities

Analysis Process: conhost.exe PID: 3076, Parent PID: 2560

General

Target ID:	1
Start time:	18:02:04
Start date:	02/02/2023
Path:	C:\Windows\System32\conhost.exe
Wow64 process (32bit):	false
Commandline:	C:\Windows\system32\conhost.exe 0xffffffff -ForceV1
Imagebase:	0x7ff745070000
File size:	625664 bytes
MD5 hash:	EA777DEEA782E8B4D7C7C33BBF8A4496

Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language
Reputation:	high

Analysis Process: cmd.exe PID: 5264, Parent PID: 2560

General	
Target ID:	2
Start time:	18:02:04
Start date:	02/02/2023
Path:	C:\Windows\SysWOW64\cmd.exe
Wow64 process (32bit):	true
Commandline:	C:\Windows\system32\cmd.exe /c REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe
Imagebase:	0xb0000
File size:	232960 bytes
MD5 hash:	F3BDBE3BB6F734E357235F4D5898582D
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language
Reputation:	high

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

Analysis Process: reg.exe PID: 5256, Parent PID: 5264

General	
Target ID:	3
Start time:	18:02:04
Start date:	02/02/2023
Path:	C:\Windows\SysWOW64\reg.exe
Wow64 process (32bit):	true
Commandline:	REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe
Imagebase:	0x310000
File size:	59392 bytes
MD5 hash:	CEE2A7E57DF2A159A065A34913A055C2
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language
Reputation:	high

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

Registry Activities

Analysis Process: svchost.exe PID: 628, Parent PID: 3452

General	
Target ID:	4
Start time:	18:02:17

Imagebase:	0xb0000
File size:	232960 bytes
MD5 hash:	F3BDBE3BB6F734E357235F4D5898582D
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language
Reputation:	high

Analysis Process: reg.exe PID: 5964, Parent PID: 5500

General

Target ID:	7
Start time:	18:02:19
Start date:	02/02/2023
Path:	C:\Windows\SysWOW64\reg.exe
Wow64 process (32bit):	true
Commandline:	REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe
Imagebase:	0x310000
File size:	59392 bytes
MD5 hash:	CEE2A7E57DF2A159A065A34913A055C2
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language
Reputation:	high

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

Analysis Process: svchost.exe PID: 732, Parent PID: 580

General

Target ID:	8
Start time:	18:02:21
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	C:\Windows\System32\svchost.exe -k LocalSystemNetworkRestricted -p -s NcbService
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language

Analysis Process: svchost.exe PID: 3512, Parent PID: 580

General

Target ID:	9
Start time:	18:02:22
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k unistacksvcgroup
Imagebase:	0x7ff651c80000

File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

Old File Path	New File Path	Completion	Count	Source Address	Symbol
---------------	---------------	------------	-------	----------------	--------

File Path	Offset	Length	Value	Ascii	Completion	Count	Source Address	Symbol
-----------	--------	--------	-------	-------	------------	-------	----------------	--------

Analysis Process: svchost.exe PID: 2792, Parent PID: 580

General

Target ID:	10
Start time:	18:02:23
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k localservice -p -s CDPSvc
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Offset	Length	Completion	Count	Source Address	Symbol
-----------	--------	--------	------------	-------	----------------	--------

Analysis Process: svchost.exe PID: 6140, Parent PID: 580

General

Target ID:	11
Start time:	18:02:24
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k networkservice -p -s DoSvc
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Registry Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

Key Path	Name	Type	Old Data	New Data	Completion	Count	Source Address	Symbol
----------	------	------	----------	----------	------------	-------	----------------	--------

Analysis Process: svchost.exe PID: 5240, Parent PID: 580

General

Target ID:	12
Start time:	18:02:25
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	C:\Windows\System32\svchost.exe -k NetworkService -p
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Analysis Process: svchost.exe PID: 4684, Parent PID: 3452

General

Target ID:	13
Start time:	18:02:25
Start date:	02/02/2023
Path:	C:\Users\Public\Public\svchost.exe
Wow64 process (32bit):	true
Commandline:	"C:\Users\Public\Public\svchost.exe"
Imagebase:	0x1a0000
File size:	40960 bytes
MD5 hash:	07B92F1473B82789F71A58EE8999C631
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language

File Activities

File Created

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
C:\Users\Public\Public\svchost.exe	read data or list directory read attributes delete write dac synchronize generic read generic write	device sparse file	sequential only non directory file	object name collision	1	1A3240	CopyFileW
C:\Users\Public\Public\svchost.exe	read data or list directory read attributes delete write dac synchronize generic write	device sparse file	sequential only non directory file	object name collision	1	1A3240	CopyFileW

File Written

File Path	Offset	Length	Value	Ascii	Completion	Count	Source Address	Symbol
C:\Users\Public\Public\Screens\screenshot.bmp	0	14	42 4d 42 fd 7e 00 00 00 00 00 42 00 00 00	BMB~B	success or wait	1	1A597F	WriteFile
C:\Users\Public\Public\Screens\screenshot.bmp	14	40	28 00 00 00 fd 07 00 00 38 04 00 00 01 00 20 00 03 00 00 00 00 fd 7e 00 00 00 00 00 00 00 00 00 00 00	(8 ~	success or wait	1	1A59A1	WriteFile
C:\Users\Public\Public\Screens\screenshot.bmp	54	12	00 00 fd 00 00 fd 00 00 fd 00 00 00		success or wait	1	1A59FD	WriteFile

Analysis Process: conhost.exe PID: 4340, Parent PID: 4684

General

Target ID:	14
Start time:	18:02:26
Start date:	02/02/2023
Path:	C:\Windows\System32\conhost.exe
Wow64 process (32bit):	false
Commandline:	C:\Windows\system32\conhost.exe 0xffffffff -ForceV1
Imagebase:	0x7ff745070000
File size:	625664 bytes
MD5 hash:	EA777DEEA782E8B4D7C7C33BBF8A4496
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Analysis Process: cmd.exe PID: 2384, Parent PID: 4684

General

Target ID:	15
Start time:	18:02:26
Start date:	02/02/2023
Path:	C:\Windows\SysWOW64\cmd.exe
Wow64 process (32bit):	true
Commandline:	C:\Windows\system32\cmd.exe /c REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe
Imagebase:	0xb0000
File size:	232960 bytes
MD5 hash:	F3BDBE3BB6F734E357235F4D5898582D
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Analysis Process: reg.exe PID: 5444, Parent PID: 2384

General

Target ID:	16
Start time:	18:02:26
Start date:	02/02/2023
Path:	C:\Windows\SysWOW64\reg.exe
Wow64 process (32bit):	true
Commandline:	REG ADD "HKCU\SOFTWARE\Microsoft\Windows\CurrentVersion\Run" /V Firewall /t REG_SZ /F /D C:\Users\Public\Public\svchost.exe
Imagebase:	0x310000
File size:	59392 bytes
MD5 hash:	CEE2A7E57DF2A159A065A34913A055C2
Has elevated privileges:	false
Has administrator privileges:	false
Programmed in:	C, C++ or other language

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

Analysis Process: svchost.exe PID: 848, Parent PID: 580

General	
Target ID:	18
Start time:	18:02:29
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k netsvcs -p
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language

File Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

File Path		Access		Attributes		Options		Completion		Count	Source Address	Symbol
-----------	--	--------	--	------------	--	---------	--	------------	--	-------	----------------	--------

File Path						Completion		Count	Source Address	Symbol
-----------	--	--	--	--	--	------------	--	-------	----------------	--------

Old File Path		New File Path				Completion		Count	Source Address	Symbol
---------------	--	---------------	--	--	--	------------	--	-------	----------------	--------

File Path		Offset	Length	Value		Ascii		Completion		Count	Source Address	Symbol
-----------	--	--------	--------	-------	--	-------	--	------------	--	-------	----------------	--------

File Path				Offset		Length		Completion	Count	Source Address	Symbol
-----------	--	--	--	--------	--	--------	--	------------	-------	----------------	--------

Registry Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

Key Path					Completion	Count	Source Address	Symbol
Key Path	Name	Type	Old Data	New Data	Completion	Count	Source Address	Symbol

Analysis Process: svchost.exe

PID: 6128, Parent PID: 580

General

Target ID:	19
Start time:	18:02:32
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k localservicenetworkrestricted -p -s wscsvc
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Registry Activities

There is hidden Windows Behavior. Click on **Show Windows Behavior** to show it.

Key Path					Completion	Count	Source Address	Symbol
Key Path	Name	Type	Old Data	New Data	Completion	Count	Source Address	Symbol

Analysis Process: svchost.exe PID: 3020, Parent PID: 580

General

Target ID:	20
Start time:	18:02:32
Start date:	02/02/2023
Path:	C:\Windows\System32\svchost.exe
Wow64 process (32bit):	false
Commandline:	c:\windows\system32\svchost.exe -k wusvcs -p -s WaaSMedicSvc
Imagebase:	0x7ff651c80000
File size:	51288 bytes
MD5 hash:	32569E403279B3FD2EDB7EBD036273FA
Has elevated privileges:	true
Has administrator privileges:	true
Programmed in:	C, C++ or other language

Analysis Process: MpCmdRun.exe PID: 4600, Parent PID: 6128

General

Target ID:	21
Start time:	18:03:34
Start date:	02/02/2023
Path:	C:\Program Files\Windows Defender\MpCmdRun.exe
Wow64 process (32bit):	false
Commandline:	"C:\Program Files\Windows Defender\mpcmdrun.exe" -wdenable
Imagebase:	0x7ff76d380000
File size:	455656 bytes
MD5 hash:	A267555174BFA53844371226F482B86B
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

File Activities

File Path	Access	Attributes	Options	Completion	Count	Source Address	Symbol
-----------	--------	------------	---------	------------	-------	----------------	--------

File Written

File Path	Offset	Length	Value	Ascii	Completion	Count	Source Address	Symbol
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	9968	182	0d 00 0a 00 0d 00 0a 00 2d 00 0d 00 0a 00	----- ----- -----	success or wait	1	7FF76D3ABC96	WriteFile

File Path	Offset	Length	Value	Ascii	Completion	Count	Source Address	Symbol
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	10150	258	4d 00 70 00 43 00 6d 00 64 00 52 00 75 00 6e 00 3a 00 20 00 43 00 6f 00 6d 00 6d 00 61 00 6e 00 64 00 20 00 4c 00 69 00 6e 00 65 00 3a 00 20 00 22 00 43 00 3a 00 5c 00 50 00 72 00 6f 00 67 00 72 00 61 00 6d 00 20 00 46 00 69 00 6c 00 65 00 73 00 5c 00 57 00 69 00 6e 00 64 00 6f 00 77 00 73 00 20 00 44 00 65 00 66 00 65 00 6e 00 64 00 65 00 72 00 5c 00 6d 00 70 00 63 00 6d 00 64 00 72 00 75 00 6e 00 2e 00 65 00 78 00 65 00 22 00 20 00 2d 00 77 00 64 00 65 00 6e 00 61 00 62 00 6c 00 65 00 0d 00 0a 00 20 00 53 00 74 00 61 00 72 00 74 00 20 00 54 00 69 00 6d 00 65 00 3a 00 20 00 0e 20 54 00 68 00 75 00 20 00 0e 20 46 00 65 00 62 00 20 00 0e 20 30 00 32 00 20 00 0e 20 32 00 30 00 32 00 33 00 20 00 31 00 38 00 3a 00 30 00 33 00 3a 00 33 00 35 00 0d 00 0a 00 0d	MpCmdRun: Command Line: "C:\Program Files\Windows Defender\mpcmdrun.exe" -wdenable Start Time: Thu Feb 02 2023 18:03 :35	success or wait	1	7FF76D3ABC96	WriteFile
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	10408	86	4d 00 70 00 45 00 6e 00 73 00 75 00 72 00 65 00 50 00 72 00 6f 00 63 00 65 00 73 00 73 00 4d 00 69 00 74 00 69 00 67 00 61 00 74 00 69 00 6f 00 6e 00 50 00 6f 00 6c 00 69 00 63 00 79 00 3a 00 20 00 68 00 72 00 20 00 3d 00 20 00 30 00 78 00 31 00 0d 00 0a 00	MpEnsureProcessMitigati onPolicy: hr = 0x1	success or wait	1	7FF76D3ABC96	WriteFile
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	10494	20	57 00 44 00 45 00 6e 00 61 00 62 00 6c 00 65 00 0d 00 0a 00	WDEnable	success or wait	1	7FF76D3ABC96	WriteFile
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	10514	86	45 00 52 00 52 00 4f 00 52 00 3a 00 20 00 4d 00 70 00 57 00 44 00 45 00 6e 00 61 00 62 00 6c 00 65 00 28 00 54 00 52 00 55 00 45 00 29 00 20 00 66 00 61 00 69 00 6c 00 65 00 64 00 20 00 28 00 38 00 30 00 30 00 37 00 30 00 34 00 45 00 43 00 29 00 0d 00 0a 00	ERROR: MpWDEnable(TRUE) failed (800704EC)	success or wait	1	7FF76D3ABC96	WriteFile
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\MpCmdRun.log	10600	100	4d 00 70 00 43 00 6d 00 64 00 52 00 75 00 6e 00 3a 00 20 00 45 00 6e 00 64 00 20 00 54 00 69 00 6d 00 65 00 3a 00 20 00 0e 20 54 00 68 00 75 00 20 00 0e 20 46 00 65 00 62 00 20 00 0e 20 30 00 32 00 20 00 0e 20 32 00 30 00 32 00 33 00 20 00 31 00 38 00 3a 00 30 00 33 00 3a 00 33 00 35 00 0d 00 0a 00	MpCmdRun: End Time: Thu Feb 02 2023 18:03:35	success or wait	1	7FF76D3ABC96	WriteFile

File Path	Offset	Length	Value	Ascii	Completion	Count	Source Address	Symbol
C:\Windows\ServiceProfiles\LocalService\AppData\Local\Temp\ImpCmdRun.log	10700	174	2d 00 0d 00 0a 00	----- ----- -----	-success or wait	1	7FF76D3ABC96	WriteFile

Analysis Process: conhost.exe PID: 3012, Parent PID: 4600	
General	
Target ID:	22
Start time:	18:03:34
Start date:	02/02/2023
Path:	C:\Windows\System32\conhost.exe
Wow64 process (32bit):	false
Commandline:	C:\Windows\system32\conhost.exe 0xffffffff -ForceV1
Imagebase:	0x7ff745070000
File size:	625664 bytes
MD5 hash:	EA777DEEA782E8B4D7C7C33BBF8A4496
Has elevated privileges:	true
Has administrator privileges:	false
Programmed in:	C, C++ or other language

Disassembly
 No disassembly