
4T60-E



Condition: Poor or no TCC apply, work bore at TCC apply valve.