
## 4L60-E ('94)



**Condition:** Repeated 3-4 clutch failure, 2nd gear starts when hot due to low AFL psi. Rebuilt bad pump surface to rotor tolerance.

**Correction:** Needs good pump.