



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila
 (632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 20260511-02-KPM

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: CARAGA REGIONAL HOSPITAL ADDRESS: SURIGAO CITY
 SERVICE REQUESTED BY: DEPARTMENT: RADIOLOGY
 EQUIPMENT/MODEL: Shimadzu DR System SERIAL NO.: VEDBDX022

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT:

ACTIONS TAKEN

SCHEDULED PREVENTIVE MAINTENANCE UNDER WARRANTY - 2ND YEAR, 1ST VISIT

- Checked and cleaned the unit
- Checked connection of Flat Panel Detector, OK
- Checked SCU and Cradle charging, OK
- Accessed VIVIX_Setup, performed self-diagnosis, OK
- Discovered shock logs:
 - 03/09/2026, 19:08:51
 - 03/17/2026, 23:37:29
- Upon checking on the RAW image, no artifacts can be found
- Tested image acquisition, OK
- Checked connection of Hospital PACS, OK
- Tested image sending, OK
- Endorsed to end-user to freeup space of stored images on the Flat Panel detector

REMARKS/RECOMMENDATIONS

UNIT IN GOOD WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS


- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED


ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/11/2026	6:00PM	7:00PM	SALES INVOICE
			PURCHASE ORDER
			AS PER W.

SERVICED BY:


 D. NOPRE / K. MONTEVERDE
 NAME & SIGNATURE

ACKNOWLEDGED BY:


 LANDENDOEFER S. RIVAS, RRT
 NAME & SIGNATURE

CONTACT NO:

EMAIL ADD: crhradiologyfebruary2021@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting