Flood and debris situation report

Area and event date: 2026-08-26 | 85.30, 28.10, 85.42, 28.20

Mapped findings

	Strict	Default	Lenient
Detection area (ha)	25.62	28.47	73.77
Buildings inside	73	84	167
Buildings near	79	83	65
Road length intersecting detections (km)	2.69	3.16	6.09
Bridges near detections	3	4	6
Settlements affected	1	1	1
Settlements cut off	1	1	1
Settlements with degraded access	38	38	38
Settlements not assessable	66	66	66

Settlement access

Robust cut-off settlements: स्याप्रु बेसी

1. स्याप्रु बेसी

Reliability and limitations

Optical reliability: adequate. Valid optical pixels: 86.9%.

No new-water or disturbed-surface detections in the radar classification.


Mapped footprints are detections, not ground truth.

Data used

2026-08-12, 2026-10-01

- Copernicus Data Space Sentinel-1 GRD via Sentinel Hub Process API
- Copernicus Data Space Sentinel-2 L2A via Sentinel Hub Process API
- Sahayak run selection metadata

Mapped findings



- Contains modified Copernicus Sentinel data 2026.
- Produced using Copernicus WorldDEM-30 © DLR e.V. 2010-2014 and © Airbus Defence and Space GmbH 2014-2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
- © OpenStreetMap contributors (ODbL). Any published modified OSM data stays under ODbL.
- Educational prototype, not an operational tool.