बाढ़ और मलबा स्थिति रिपोर्ट

क्षेत्र और घटना की तारीख: 2026-08-26 | 85.30, 28.10, 85.42, 28.20

मानचित्र से प्राप्त निष्कर्ष

	कठोर	डिफ़ॉल्ट	विस्तृत
पहचान क्षेत्र (हेक्टेयर)	25.62	28.47	73.77
भीतर के भवन	73	84	167
पास के भवन	79	83	65
पहचान से प्रतिच्छेद सड़क (किमी)	2.69	3.16	6.09
पहचान के पास पुल	3	4	6
प्रभावित बस्तियाँ	1	1	1
संपर्क कटी बस्तियाँ	1	1	1
प्रभावित पहुँच वाली बस्तियाँ	38	38	38
आकलन संभव नहीं	66	66	66

बस्तियों तक पहुँच

सभी परिदृश्यों में कटे हुए बस्तियाँ: स्याप्रु बेसी

1. स्याप्रु बेसी

विश्वसनीयता और सीमाएँ

ऑप्टिकल विश्वसनीयता: adequate. वैध ऑप्टिकल पिक्सेल: 86.9%.

No new-water or disturbed-surface detections in the radar classification.


मानचित्रित क्षेत्र पहचान हैं, जमीनी सत्य नहीं।

उपयोग किए गए डेटा

2026-08-12, 2026-10-01

- Copernicus Data Space Sentinel-1 GRD via Sentinel Hub Process API
- Copernicus Data Space Sentinel-2 L2A via Sentinel Hub Process API
- Sahayak run selection metadata

मानचित्र से प्राप्त निष्कर्ष



- Contains modified Copernicus Sentinel data 2026.
- Produced using Copernicus WorldDEM-30 © DLR e.V. 2010-2014 and © Airbus Defence and Space GmbH 2014-2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
- © OpenStreetMap contributors (ODbL). Any published modified OSM data stays under ODbL.
- Educational prototype, not an operational tool.