



The mirrored reverse page does help

Page 284 contains Plate 12. Its visible ghost matches Plates 10 and 11 on the reverse of the leaf, page 283.

Original page 284



Page 283, mirrored and registered




Both pages were photographed while curved. The reference therefore needs a projective alignment plus a smooth local adjustment; mirroring alone is insufficient. Only the reverse reference moves. Plate 12 retains its accepted geometry.


Same cleanup, with and without the reverse reference

The threshold and contrast settings are identical. The added step estimates reverse-ink attenuation before the local paper normalization.


Rectified source



Earlier local cleanup



With mirrored reverse reference




The faint tank and wiring patterns diminish further. The reference is blurred to approximate transmission through paper, and its strength is fitted locally. The result remains a lossless grayscale master; no drawing geometry or lettering is reconstructed.


Ghost wiring near fine original lines

Enlarged identical source-coordinate crop; earlier local cleanup at left, paired correction at right.

Earlier local cleanup



With mirrored reverse reference




Compare the pale curved ghost inside the upper left body area. Original straight body edges, the control rod and lettering remain in their original pixel positions.


Control rods, leaders and small lettering

Enlarged identical source-coordinate crop; earlier local cleanup at left, paired correction at right.

Earlier local cleanup



With mirrored reverse reference




This enlargement checks genuine foreground intersections and weak context outlines. The correction divides by the estimated reverse-ink attenuation; it does not erase all ink wherever the reverse page is dark.


Darker mottling may also be reverse printing

Several clusters lie over inked battery and wiring regions. Localized ink penetration is plausible; the photographs cannot establish the physical cause.


Earlier local cleanup



Registered reverse printing



Current paired correction



Selected blank patches lose about 24-32% of their remaining mean ink after the earlier cleanup. The darker mottled patch changes by only about 4%. These are sample measurements, not a claim that all bleed-through is removed.

In three checked foreground regions, no previously dark pixel (gray below 120) became near-white (above 245). Mean changes at those dark pixels are about 1-2 gray levels out of 255. This supports the conservative setting but cannot prove every faint line is preserved.

The smooth transfer field handles the broad ghost but may underestimate intense local ink penetration. Removing all mottling would need stronger local evidence at original-line crossings. Plate 12 remains raster-preferred; sources and the previous cleanup are retained.

Registration evidence: the final whole-page fit correlation is 0.59, followed by 66 locally matched windows and a smoothed transfer field. This is fitting evidence, not a held-out validation score.