




Biaxial tension with crack propagation Comparison with Kamarei et al. (2026) Figs. 5 & 6



(d) Summary

	Glass	PU
σ_{bs} (MPa)	27.0	0.27
ε_{bs}	0.301×10^{-3}	0.0872
Fracture detected	Yes	Yes
Topo event	Step 68	Step 67
Model	Sharp crack + monitor	Sharp crack + monitor