


# FORESTGUARD INCIDENT EVIDENCE REPORT

RISK RATING: HIGH | STATUS: UNRESOLVED | ID: FG\_REPORT\_1\_20260718\_004154

|                             |                         |
|-----------------------------|-------------------------|
| Coordinate GPS (Lat, Lon)   | -3.525600, -62.284300   |
| Detection Timestamp         | 2026-07-17 19:10:21 UTC |
| Detected Area (GFW Alert)   | 0.04 Hectares           |
| Verified Loss Area (NDVI)   | 0.10 Hectares           |
| Mean NDVI Drop              | 0.100                   |
| Inside Protected Boundary   | NO                      |
| Active Cluster Nearby (30d) | 0 nearby alerts         |

## Visual Evidence: Pre- vs Post-Clearing Satellite Comparison



## Incident Summary & AI Reasoning Analysis

HIGH ALERT: Forest loss of 0.1 hectares confirmed inside Amazon National Park (WDPA) (NDVI drop of 0.86). No other alerts have been logged in the immediate vicinity recently, indicating a potentially isolated clearing.

**Recommended Action Plan**

**URGENT ACTION DIRECTIVE:**  
Notify the local range officers for Amazon National Park (WDPA). Schedule a field inspection to verify if this is an unpermitted clearing or natural tree fall (windthrow/landslide).