


FORESTGUARD INCIDENT EVIDENCE REPORT

RISK RATING: HIGH | STATUS: UNRESOLVED | ID: FG_REPORT_5_20260711_164732

Coordinate GPS (Lat, Lon)	-3.475013, -62.162936
Detection Timestamp	2026-07-11 11:17:31 UTC
Detected Area (GFW Alert)	8.14 Hectares
Verified Loss Area (NDVI)	7.33 Hectares
Mean NDVI Drop	7.330
Inside Protected Boundary	NO
Active Cluster Nearby (30d)	0 nearby alerts

Visual Evidence: Pre- vs Post-Clearing Satellite Comparison



Incident Summary & AI Reasoning Analysis

HIGH ALERT: Forest loss of 7.33 hectares confirmed inside Amazon National Park (WDPA) (NDVI drop of 0.16). No other alerts have been logged in the immediate vicinity recently, indicating a potentially isolated clearing.

Recommended Action Plan

URGENT ACTION DIRECTIVE:

Notify the local range officers for Amazon National Park (WDPA). Schedule a field inspection to verify if this is an unpermitted clearing or natural tree fall (windthrow/landslide).