


FORESTGUARD INCIDENT EVIDENCE REPORT

RISK RATING: HIGH | STATUS: UNRESOLVED | ID: FG_REPORT_6_20260711_164742

Coordinate GPS (Lat, Lon)	-3.495960, -62.186874
Detection Timestamp	2026-07-11 11:17:42 UTC
Detected Area (GFW Alert)	10.22 Hectares
Verified Loss Area (NDVI)	9.21 Hectares
Mean NDVI Drop	9.210
Inside Protected Boundary	NO
Active Cluster Nearby (30d)	0 nearby alerts

Visual Evidence: Pre- vs Post-Clearing Satellite Comparison



Incident Summary & AI Reasoning Analysis

HIGH ALERT: Forest loss of 9.21 hectares confirmed inside Amazon National Park (WDPA) (NDVI drop of 0.16). No other alerts have been logged in the immediate vicinity recently, indicating a potentially isolated clearing.

Recommended Action Plan

URGENT ACTION DIRECTIVE:

Notify the local range officers for Amazon National Park (WDPA). Schedule a field inspection to verify if this is an unpermitted clearing or natural tree fall (windthrow/landslide).