


FORESTGUARD INCIDENT EVIDENCE REPORT

RISK RATING: HIGH | STATUS: UNRESOLVED | ID: FG_REPORT_8_20260713_230439

Coordinate GPS (Lat, Lon)	-3.525600, -62.284300
Detection Timestamp	2026-07-13 17:34:38 UTC
Detected Area (GFW Alert)	0.04 Hectares
Verified Loss Area (NDVI)	0.10 Hectares
Mean NDVI Drop	0.100
Inside Protected Boundary	NO
Active Cluster Nearby (30d)	0 nearby alerts

Visual Evidence: Pre- vs Post-Clearing Satellite Comparison



Incident Summary & AI Reasoning Analysis

HIGH ALERT: Forest loss of 0.1 hectares confirmed inside Amazon National Park (WDPA) (NDVI drop of 0.16). No other alerts have been logged in the immediate vicinity recently, indicating a potentially isolated clearing.

Recommended Action Plan

URGENT ACTION DIRECTIVE:
Notify the local range officers for Amazon National Park (WDPA). Schedule a field inspection to verify if this is an unpermitted clearing or natural tree fall (windthrow/landslide).