

No. Laporan / Report No. : 23/MGS/53/II/2026

Revisi / Revision : R0

Tgl. Laporan / Report Date : 29 January 2026

Halaman/Pages : 1 dari 2

INFORMASI PROYEK / PROJECT INFORMATION

Nama Proyek / Project Name

BSI Candrian Waste Dump Extension Study

Lokasi Proyek / Location : Banyuwangi - JAWA TIMUR

No. PO / PO Number : PO-GQT-001

IDENTITAS KLIEN / CLIENT INFORMATION

Klien / Client : PT. GEOLAND QUATRO TECHNOLAB

Alamat / Address : Kab. Bandung - JAWA BARAT

INFORMASI CONTOH / SAMPLE INFORMATION

Kode Laboratorium / Laboratory Id.

26-001-DS-001

No. Contoh / Sample Id. :

Kedalaman / Depth (m) : #N/A

Jenis Contoh / Sample Type : Disturbed Sample

Deskripsi Tanah / Soil Description : Lanau Lempungan / Clayey Silt

Warna Tanah / Soil Color : Coklat / Brown

Tgl. Diterima / Date Received : 05 January 2026

Tgl. Pengujian / Date Tested : 06 January 2026

UJI KONSOLIDASI
CONSOLIDATION TEST

SNI 2812:2011

DATA BENDA UJI / SPECIMEN DATA

Tinggi Benda Uji / Specimen Height, cm	: 2,02
Diameter Benda Uji / Specimen Diameter, cm	: 5,05
Luas Permukaan Benda Uji / Specimen Area, cm ²	: 20,03
Volume Benda Uji / Specimen Volume, cm ³	: 40,46
Berat Jenis Tanah / Specific Gravity	: 2,68
Kadar Air Semula / Initial Moisture Content (%)	: 35,61
Angka pori semula / Initial Void Ratio, e ₀	: 0,97
Tinggi Padatan / Solid Height, H _s (cm)	: 1,03
Tahap Pembebanan / Loading Increment, kPa	: 25 - 50 - 100 - 200 - 400 - 800
Durasi Pembebanan / Loading Duration	: 1440 menit

HASIL PENGUJIAN / TEST RESULT

Pressure kPa	ΔH cm	H cm	Δe	e	t ₉₀ min	H _{Drainage} cm
25	0,00229	2,0177	0,002229	0,9643	3,24	1,01115
50	0,00321	2,0145	0,003125	0,9611	5,29	1,01275
100	0,00514	2,0094	0,005004	0,9561	4,84	1,01532
200	0,00664	2,0027	0,006464	0,9497	5,29	1,01864
400	0,00792	1,9948	0,007710	0,9420	4,84	1,02260
800	0,00968	1,9851	0,009424	0,9325	4,00	1,02744



PARAMETER HASIL UJI / TEST RESULT PARAMETERS

Tekanan Vertikal, kPa	Mv m ² /kN	Cv cm ² /s	k cm/s
25	0,0004629	0,004459914	2,02E-08
50	0,0006499	0,00274027	1,75E-08
100	0,0005217	0,003010268	1,54E-08
200	0,0003381	0,00272237	9,19E-09
400	0,0002024	0,003053591	6,06E-09
800	0,0001243	0,003729903	4,55E-09

Cc : 0,031
Cr : 0,0012
Pc : 230 kPa

GRAFIK

GRAFIK e-log P / e-log P Curve

SETTLEMENT VS $\sqrt{t}$ TIME (min^{1/2}) CURVE (TAYLOR METHOD)

Grafik Taylor untuk setiap tahap pembebanan disajikan pada lampiran. / Taylor plots for each loading increment are presented in the appendix.

DIUJI OLEH /
TESTED BY

RIZKI

Teknisi/Analisis

Tgl./Date : 28/01/26

DIPERIKSA OLEH /
CHECKED BY

NOUFAL

Koordinator Teknis

Tgl./Date : 28/01/26

DISETUJUI OLEH /
APPROVED BY

A.SUMARTADJI

Kepala Laboratorium

Tgl./Date : 28/01/26

SCAN FOR REPORT VERIFICATION

KETERANGAN /
NOTES

- Laporan hasil Uji ini hanya berlaku untuk contoh yang diuji
- Dilarang memperbanyak laporan tanpa ijin tertulis dari Laboratorium Mekanika Tanah PT. TERRAFORMA GEOTEKNIK INDONESIA.
- Laboratorium tidak bertanggung jawab atas kegiatan pengambilan dan transportasi contoh yang dilakukan oleh pihak lain.

- This test report applies only to the tested sample.
- This report shall not be reproduced except in full without written approval from PT. TERRAFORMA GEOTEKNIK INDONESIA Soil Mechanics Laboratory.
- The laboratory is not responsible for sampling, handling and sample transportation conducted by others.

23-MINEARTH-RM-LHU-CON-R0

No. Laporan / Report No. : 23/MGS/53/II/2026






Revisi / Revision : R0

Tgl. Laporan / Report Date : 29 January 2026

Halaman/Pages : 2 dari 2

LAMPIRAN / APPENDIX

SETTLEMENT VS $\sqrt{t}$ TIME ($\text{min}^{1/2}$) CURVE (TAYLOR METHOD)



**FOTO PENGUJIAN / TEST
PHOTOGRAPH**

**FOTO PENGUJIAN / TEST
PHOTOGRAPH**

CATATAN / NOTES :

DIUJI OLEH / TESTED BY  RIZKI Teknisi/Analisis Tgl./Date : 28/01/26	DIPERIKSA OLEH / CHECKED BY  NOUFAL Koordinator Teknis Tgl./Date : 28/01/26	DISETUJUI OLEH / APPROVED BY  A.SUMARTADJI Kepala Laboratorium Tgl./Date 28/01/26
--	--	---

SCAN FOR REPORT VERIFICATION

