UCL CASA 2025

Utilising IoT Sensors to Understand the Environmental Performance of NHS Eye Clinics

Yaman Kalaji, Duncan Wilson, and Steven Gray

Introduction



Pop-up eye clinics





Patient waiting space

Diagnosis cubicle

Aims and research question

Ophthalmology had **5.5 million** visits for 2020-21 (NHS Digital, 2021)

NHS waiting list in England has gone up to a record high at **7.75 million**(BBC News, 2023)



How to decrease patient backlog?

What are the clinic factors that affect patient backlog?


HERCULES Project

Phase 1: Tracking patients

at Brent Cross 1

On behalf of The HERCULES Consortium Funded by the NIHR Biomedical Research Centre at Moorfields Eye Hospital





Spatio-temporal visualisation of patient journeys




Ubisense Tracking tags

Ultra Wideband Time-Difference-of-Arrival (TDoA) and 2-axis Angle-of-Arrival (AoA)

Certain sections had 89% reduction in patient backlog





Single Glaucoma patient journey





HERCULES Project

Phase 2: Occupancy and Environmental performance at Brent Cross 2

On behalf of The HERCULES Consortium Funded by the NIHR Biomedical Research Centre at Moorfields Eye Hospital



Brent Cross 2 floorplan



Brent Cross 2 floorplan

Types of cubicles:

- 1. VA: Visual Acuity
- 2. VF: Visual Field
- 3. Photos
- 4. Scans
- Cataract VA
- 6. Consultants
- 7. Staff




Types of clinics:

- 1. Retina
- 2. Glaucoma
- 3. Cataract
- 4. Kerataconus



COACH - Connected Occupancy and Clinic Health





COACH Sensors

Wall/Ceiling mounting

Sensor holders

Main box






- Based on Arduino MKR Wifi 1010
- Custom PCB

3D Designed Using Fusion360









Temperature sensor affected by heat generated by other sensors

+2° to +3° above real temperature levels



Using rate of change (derivative of temperature)




Brent Cross, London

20Deployed Sensors


Wi-Fi connected ~50% Ceiling mounted ~50% Wall mounted




Since Feb/2024



Wall-mounted COACH




Ceiling-mounted COACH




Infrastructure

19



Grafana dashboard

Data collection challenges



mmWave radar affected by OCT fan

mmWave radar affected by OCT fan



1 affected cubicle was excluded



mmWave penetration

mmWave false positive caused by wall penetration



Higher movement detection threshold (>0.5)



Second sound sensor batch: +18 dBA above normal levels





Random CO2 sensors calibration





~400 to 500 PPM during nighttime (normal behaviour)

Initial results





What a normal day looks like | Utilisation



Cubicle utilisation on 12-4-2024

What a normal day looks like | Acoustics




Sound level average on 12-4-2024

What a normal day looks like | Temperature



Cubicle utilisation behaviour change




Opportunity for power usage reduction | Light levels



Light levels (Lux) on 12-4-2024

Sound levels exceed HTM* recommendation: 45 dBA





*Health
Technical
Memorandum
08-01: Acoustics

Courtesy of MD Hearing

Thank you for listening

Yaman Kalaji yaman.kalaji@ucl.ac.uk