P1 DROPPER SERUM BOTTLE - OWNER VISUAL REVIEW BOARD

PROVISIONAL_BEST_EFFORT_GEOMETRY_PILOT | geometry authority: PROVISIONAL_OWNER_MEASURED_PLUS_INFERRED | manufacturing authority: NOT_ESTABLISHED
owner approval: PENDING_VISUAL_REVIEW | GATE_2: BLOCKED | photographs are perspective + uncalibrated - NO calibrated overlay accuracy is claimed
photographs are never stretched: uniform scaling and whole-image crops only | THREAD_GEOMETRY_NOT_MODELLED | NOT_MANUFACTURING_AUTHORITATIVE
P1 V2 REVISION - V1 owner visual review: visual fidelity FAIL + material realism FAIL; V2 revises bulb/shoulder/collar/base + materials; V1 preserved at p1_pilot/2026-08-04/

OWNER PHOTOGRAPH



IMG_3120 - assembled product (crop of untouched original)

MATERIAL PREVIEW




corrected material preview (owner-corrected facts 2026-08-04)
bottle GLASS/MATTE/TRANSLUCENT ORANGE | collar+bulb PLASTIC/GLOSSY/ORANGE (bulb OPAQUE)

NEUTRAL GEOMETRY VALIDATION



three-quarter neutral render

OWNER PHOTOGRAPH



IMG_3123 - dropper assembly (crop)
pipette is hidden interior - excluded from renders (S5)

DIMENSION RECONCILIATION

field	owner	model/render
assembled height	114.3	114.28 (-0.02%)
body diameter	37.4	37.42 (+0.05%)
bottle height	91.6	91.6 exact
collar dia x h	21.4 x 16.5	exact, z 78.6-95.1
bulb dia x h	10.57 x 19.2	exact, top 114.3
neck dia	15.6	15.6 (thread 17.4 omitted)
wall end / shldr	66 / 69	A1 / A2 r=14.93
neck base	-	73.49 = 91.6-18.11
pipette (math)	88.74 x 6.9	tip 9.16, top 97.9

NEUTRAL GEOMETRY VALIDATION




front orthographic

NEUTRAL GEOMETRY VALIDATION



side orthographic

NEUTRAL GEOMETRY VALIDATION



top orthographic

NEUTRAL GEOMETRY VALIDATION



closure detail

NEUTRAL GEOMETRY VALIDATION



neck detail (thread statement inside)

COMPARISON



front reference (photo crop)
perspective, uncalibrated - visual juxtaposition only

COMPARISON



front render (same scale policy: fit-to-panel only)

COMPARISON



render silhouette (front)
silhouette from the RENDER only - photo silhouette not extracted (cluttered uncalibrated background)

INFERRED GEOMETRY

shoulder: V2 C2 smootherstep + fullness bias (VISUAL_ESTIMATE, MEDIUM; V1 cosine model owner-rejected)
bulb: V2 rounded capsule, TRUE hemispherical dome (VISUAL_ESTIMATE, MEDIUM; V1 conical cap owner-rejected)
neck finish: GL18/DIN 168 class (ONLINE_ANALOGOUS_REFERENCE, MEDIUM, NOT_EXACT_MATCH); pitch 3.0 from the DIN table
base bottom radius 2.5 + weighted settle; collar edge round 0.8; bottom glass 0.8 (GENERIC_RENDERING_DEFAULT, LOW)

OMITTED DETAILS


GL18-class thread geometry (S1) - statement stamped on views
collar knurling/ribs (S2); base embossing 50ml/46/dots (S3)
label artwork (S4, deferred); pipette in renders (S5, interior)

ASSUMPTIONS AWAITING OWNER ANSWERS

A1: 66 = straight-wall end? A2: 69 = point on shoulder
curve (model r=14.93)? A3: 18.11 neck landmark?
A4: 105 = bulb top to pipette tip?

COMPARISON


P1 V1 vs V2 FRONT SILHOUETTES - same pinned camera, aligned by construction (renders only, no photograph)
left: V1 (owner-rejected profiles) middle: V2 (revision) right: overlay - red=V1 only, blue=V2 only, dark=agreement



V1 vs V2 silhouettes (renders, aligned by construction)

COMPARISON

P1 OWNER PHOTO vs V2 - QUALITATIVE ONLY: the photograph is perspective and uncalibrated; NO accurate overlay is claimed



owner photo vs V2 (qualitative, uncalibrated)

evidence: docs/visual_quality/rbv/p1_pilot/2026-08-04 | contract p1_provisional_geometry/1.0 | meshes e7b0236deb66715e / 7175cb33d5cd7375 / 491a134981dd9506
visual review + pipeline validation only - NEVER supplier/manufacturing geometry