Project Name: Orange_NC_2010

Area Of Interest: Orange County

Producer: The Sanborn Map Company, Inc.

Date: 20100320 - 20100404

DELIVERY INFORMATION

Date: 20111107

POC: Gary Merrill, State Liaison

POC Information:

E-mail: glmerrill@usgs.gov Phone: 803-750-6124 Fax: 803-750-6181 720 Gracern Road

MS 509

Columbia, SC 29210-7651

PROJECT INFORMATION

Project size: 139 GB

Image Size: 10,000 X 10,000 pixels

Number of image files: 500

File Naming Convention: OC6i0_37_000_10972701_20100411R0.tif and .tfw

File Format Information: provided in TIFF (.TIF) format with associated world files (.TFW).

Metadata: Project level metadata was provided in .XML and .HTML format.

Applicable NGA Urban Area: 36 %

Quadrangle Information: 6 complete quads, 8 partial quads

Radiometry: 3 band, RGB

Coordinate System: State Plane and NAD 83

Pixel Resolution: 0.5-foot



Relative Horizontal Accuracy and Edge Alignment: All tiles were inspected for alignment issues. No significant misalignment issues were found along tile borders. Tile interiors were inspected for anomalies which are noted in an error file.

Horizontal Accuracy:

The 0.5' pixel GSD orthophotos were designed to meet ASPRS Class 2 horizontal accuracies at a design scale of 1:2400 (1'=200') where the limiting RMSE in either X or Y is not greater than 4.0'.

15 control points were within the imagery area. 13 of the 15 control points were used in resolution. Average RMSE is 3.411 feet. Class 2 ASPRS expected accuracy is 5.66 feet.

Bounding Coordinates:

WEST LONGITUDE = -79. 27129446 ° W NORTH LATITUDE = 36. 25025056 ° N EAST LONGITUDE = -78. 94913218 ° W SOUTH LATITUDE = 35. 85163383 ° N

Camera Information: Zeiss/Intergraph Digital Mapping Camera

REVIEW INFORMATION


General Observations: The imagery covers the entire extent of Orange County, North Carolina. The imagery is partly in Caswell, Person, Durham, Chatham, and Alamance counties in North Carolina. The imagery is partly in the Raleigh-Durham area of the 133 Cities Program. For your information there is a white line between two of the images. Images of the ends of the white line is provided in this report. The bounding coordinates are from the Global Mapper metadata.

Error File: An error shape file highlighting all noted errors is not included. No errors are being reported.

Project Outline:




Project/Quadrangle Area:





NGA





White Line from between images:

OC6i0_37_000_10986904_20100411R1.tif and OC6i0_37_000_10986903_20100411R1.tif From [1969996.91, 894994.86] to [1969996.91, 890024.52]







IMAGERY QUALITY ASSESSMENT SUMMARY REVIEWER

Summary Prepared By: Nan Aldridge

Date: 20130129