INSPECTION REPORT

INS-2026-00008 · Motor vehicle claim

APPROVED

Generated 30 Oct 2026, 19:17

Summary

INSURED
Johan Naidoo

CLAIM NUMBER
CLM-383573

VEHICLE
2015 Toyota Corolla Cross 1.8 · ND 420-191

INSURED VALUE
R 332 321.00

ASSESSOR
Thandi Nkosi

PRIORITY
low

ADDRESS
180 Umhlanga Rocks Drive, Umhlanga, Durban, 4319

COORDINATES
-29.72824, 31.08306

On-site evidence

STARTED
30 Oct 2026, 18:27

COMPLETED
30 Oct 2026, 19:17

SUBMITTED
30 Oct 2026, 19:17

DUE
03 Nov 2026, 05:00

DISTANCE FROM ADDRESS AT START
38 m (within geofence)

GPS TRAIL
4 points, 36 m covered

Checklist

1 item failed: Bodywork free of undeclared damage

Identification

VIN matches claim documents	**Pass**
Odometer reading	**123456 km**
Licence disc valid	**Pass**

Exterior

Bodywork free of undeclared damage	**Fail** Left rear door dented, paint scratched over 30 cm.
Windscreen condition	**Intact**
Head and tail lights working	**Pass**

Tyres

Tread depth front-left	**4.5 mm**
Tread depth front-right	**4.5 mm**
Tread depth rear-left	**4.5 mm**
Tread depth rear-right	**4.5 mm**
Spare wheel present	**Pass**

Interior and mechanical


Airbags	**Intact**

Engine starts	**Pass**
Interior notes	**Dent and scratches on the left rear door, consistent with the claim. Vehicle otherwise sound.**

Assessment

Outcome	**Repairable**
Estimated repair cost	**R 18 500.00**
Summary	**Dent and scratches on the left rear door, consistent with the claim. Vehicle otherwise sound.**

Damage (2)



1. MODERATE - Dent, left rear door
2. MINOR - Scuff on right front wing


Photos (10)



VIN plate
30 Oct 2026, 18:29 · -29.72814, 31.08306




Odometer display
30 Oct 2026, 18:30 · -29.72814, 31.08306




Front-left

30 Oct 2026, 18:31 · -29.72814, 31.08306




Front-right

30 Oct 2026, 18:32 · -29.72814, 31.08306




Rear-left

30 Oct 2026, 18:33 · -29.72814, 31.08306




Rear-right

30 Oct 2026, 18:34 · -29.72814, 31.08306




Bodywork free of undeclared damage

30 Oct 2026, 18:35 · -29.72814, 31.08306



Bodywork free of undeclared damage

30 Oct 2026, 18:36 · -29.72814, 31.08306




Windscreen condition
30 Oct 2026, 18:37 · -29.72814, 31.08306



Interior notes
30 Oct 2026, 18:38 · -29.72814, 31.08306

Client signature



Johan Naidoo · 30 Oct 2026, 19:17

Audit trail

30 Oct 2026, 19:17 assigned by Ayesha Moodley
30 Oct 2026, 19:17 started by Thandi Nkosi
30 Oct 2026, 19:17 submitted by Thandi Nkosi
30 Oct 2026, 19:17 approved by Ayesha Moodley - "Damage consistent with the claim. Approved for repair."
30 Oct 2026, 19:17 report generated - "Report for version 3 (254 KB)"