INSPECTION REPORT

INS-2026-00023 · Motor vehicle claim

APPROVED

Generated 30 Oct 2026, 19:38

Summary

INSURED
Bongani Mahlangu

CLAIM NUMBER
CLM-439792

VEHICLE
2017 Mercedes-Benz C200 · ND 748-530

INSURED VALUE
R 422 456.00

ASSESSOR
Thandi Nkosi

PRIORITY
normal

ADDRESS
111 Jan Hofmeyr Road, Westville, Durban, 3629

COORDINATES
-29.83718, 30.92816

On-site evidence

STARTED
30 Oct 2026, 18:48

COMPLETED
30 Oct 2026, 19:38

SUBMITTED
30 Oct 2026, 19:38

DUE
02 Nov 2026, 20:00

DISTANCE FROM ADDRESS AT START
38 m (within geofence)

GPS TRAIL
4 points, 36 m covered

Checklist

1 item failed: Bodywork free of undeclared damage

Identification

VIN matches claim documents	**Pass**
Odometer reading	**123456 km**
Licence disc valid	**Pass**

Exterior

Bodywork free of undeclared damage	**Fail** Left rear door dented, paint scratched over 30 cm.
Windscreen condition	**Intact**
Head and tail lights working	**Pass**

Tyres

Tread depth front-left	**4.5 mm**
Tread depth front-right	**4.5 mm**
Tread depth rear-left	**4.5 mm**
Tread depth rear-right	**4.5 mm**
Spare wheel present	**Pass**

Interior and mechanical


Airbags	**Intact**

Engine starts	**Pass**
Interior notes	**Dent and scratches on the left rear door, consistent with the claim. Vehicle otherwise sound.**

Assessment

Outcome	**Repairable**
Estimated repair cost	**R 18 500.00**
Summary	**Dent and scratches on the left rear door, consistent with the claim. Vehicle otherwise sound.**

Damage (2)



1. MODERATE - Dent, left rear door
2. MINOR - Scuff on right front wing


Photos (10)



VIN plate
30 Oct 2026, 18:50 · -29.83708, 30.92816




Odometer display
30 Oct 2026, 18:51 · -29.83708, 30.92816




Front-left

30 Oct 2026, 18:52 · -29.83708, 30.92816




Front-right

30 Oct 2026, 18:53 · -29.83708, 30.92816




Rear-left

30 Oct 2026, 18:54 · -29.83708, 30.92816




Rear-right

30 Oct 2026, 18:55 · -29.83708, 30.92816




Bodywork free of undeclared damage

30 Oct 2026, 18:56 · -29.83708, 30.92816



Bodywork free of undeclared damage

30 Oct 2026, 18:57 · -29.83708, 30.92816




Windscreen condition
30 Oct 2026, 18:58 · -29.83708, 30.92816



Interior notes
30 Oct 2026, 18:59 · -29.83708, 30.92816

Client signature



Bongani Mahlangu · 30 Oct 2026, 19:38

Audit trail

30 Oct 2026, 19:38 assigned by Ayesha Moodley
30 Oct 2026, 19:38 started by Thandi Nkosi
30 Oct 2026, 19:38 submitted by Thandi Nkosi
30 Oct 2026, 19:38 approved by Ayesha Moodley - "Damage consistent with the claim. Approved for repair."