LAB 8: Cross-Site-Request-Forgery attack Md Rony John Jay College of Criminal justice

Task 1: CSRF Attack using GET Request




Figure 1

Observation: We are using the inspect element of firefox to find out the user id of the attacker Boby. The user id is 43. This is from the member's page.




Figure 2

Observation: This is the LiveHTTPHeader when Boby adds Alice as his friend. He uses this as reference to construct the malicious url which adds him as a friend in Alice's account without Alice knowing.




Figure 4

Observation: Boby creates a blog post with the malicious url in the body. When Alice clicks on this url, Boby gets added into Alice's friends list.




Figure 5

Observation: Boby creates the blog post with the malicious url as can be observed from Figure 5.




Figure 6

Observation: Alice currently has no friends.

```
d-VirtualBox:~/Desktop$ cat index.html
<head>
Hack Part 1
</title>
.bouy/
;r>Sorry this site is temporaryily unavailable 
:img src = "http.csrflabelgg.com/action/friends/add?friend=428_elgg_ts 15099093188_elgg_token=gLJvfWngI3oq9_9zhB2z4Q" width= "1" hieg
 d@md-VirtualBox:~/Desktop$ sudo sevice apache2 restart
```

Figure 7

Observation: index.html code of the malicious url used by Boby to attack Alice can be observed.

CSI	RF	Lab	Site	9		
Activity	Blogs	Bookmarks	Files	Groups	More »	
Alice's friends						
Alice Boby						

Figure 8

Observation: We can see that after clicking on the malicious url, Boby gets added as Alice's friend.

Explanation: This is a Cross site request forgery attack where GET request is used to add Boby into Alice's friends list. Here we have a trusted site www.csrflabelgg.com, a user Alice logged into the trusted site and malicious website www.csrflabattacker.com created by Boby. So first, Boby has to find his own id so that he can add himself to Alice's friends list. He goes to the member's page, inspects the elements using firefox and finds his id. Next he constructs the malicious url so that he can generate the GET request that adds him to Alice's friend list. For this he adds someone to his friends list and captures that request using LiveHTTPHeaders. So, based on that, he recreates a url that adds himself into the friends list of Alice, and places it as a src attribute in the img tag of a malicious url that he created. He sends this webpage as contents of a blog. So, when Alice clicks on the link, Boby gets added as a friend. Here a request is sent from the malicious site to the elgg site posing as Alice. This is a cross site request forgery. To the elgg site, it gives an impression of Alice trying to add Boby as a friend. We use the img tag since the image is loaded when the page is opened but we set the size of image as really small.

Task 2: CSRF Attack using POST Request




Figure 9

Observation: Alice edits her own profile with the description "I support SEED project and observes it using liveHTTPHeaders so that she can craft the malicious request. We already know the id of Boby.




Figure 10

Observation: This is the screenshot of the LiveHTTPHeader when Alice modifies her profile.

md@md-VirtualBox:~/Desktop\$ sudo sevice apache2 restart

Figure 11

Observation: We modify index.html to craft the malicious url and figure 12 gives the code we used to modify the fields.




Blogs Add blog post ∓ ▲ Title Hack Part 2 Alice

I support SEED project! Excerpt Blogs Rookmarks Body Edit HTML Files Pages Wire posts http://www.csrflabattacker.com/ Latest comments No comments

Figure 13

Observation: Alice creates a blog post with the malicious url so that when Boby clicks on it, his description is modified.






Figure 14

Observation: This was before clicking on the malicious url.




Figure 15

Observation: Description on Boby's profile is modified after clicking on the link.

Explanation: Since data must be sent, we use a POST request for this attack. This is a Cross site request forgery attack where POST request is used to modify contents of Boby's profile. Here we have a trusted site www.csrflabelgg.com, a user Boby logged into the trusted site and malicious website www.csrflabattacker.com created by Alice. So first, Alice has to find Boby's id so that she can modify the contents of this profile. She goes to the member's page, inspects the elements using firefox and finds his id. Next she should construct the url so that she can generate the POST request that modifies the profile of Boby. She changes the brief description in her profile and captures that request using LiveHTTPHeaders. Now, she creates a webpage that sends a POST request to the server which recreates the form submission of the profile page with changed contents. She sends this webpage as contents of a blog. So, when Boby clicks on the link, the contents of the profile are changed. Here a request is sent from the malicious site to the elgg site posing as Boby. This is a cross site request forgery. To the elgg site, the request appears as though Boby is trying to modify his own page.

- 1. Alice can find Boby's id by inspecting the members page of the elgg site using firebug.
- 2. Alice cannot launch this attack with anybody who visits her malicious webpage since the user id of every user is different and only when the user id of the logged in user and the user id specified in the webpage match, the attack can be successful. The attack takes place if the user id

specified in the webpage has an active session with elgg and visits this webpage and by changing this user id, we can perform the attack on other users too.

Task 3: Implementing a countermeasure for Elgg

Figure 16

Observation: We turn on the countermeasure of elgg against CSRF by commenting out true in the above code.

Figure 17

```
root@VM:/var/www/CSRF/Elgg/vendor/elgg/elgg/engine/classes/Elgg# subl ActionsService.php
root@VM:/var/www/CSRF/Elgg/vendor/elgg/elgg/engine/classes/Elgg# cd /var/www/CSRF
root@VM:/var/www/CSRF# ls
Attacker
root@VM:/var/www/CSRF# cd Attacker
root@VM:/var/www/CSRF/Attacker# ls
index.html
root@VM:/var/www/CSRF/Attacker# sudo subl index.html
root@VM:/var/www/CSRF/Attacker#
```

Figure 18



Figure 19




Figure 20

Observation: Tried to perform the attack again with the countermeasure turned on, but it failed. We modified the code and added the values to fields elgg_token and timestamp, that time when we click on the link, our attack is still not successful. We can see that the description is not modified.

Explanation: The counter measure is to send two fields, timestamp and a unique token along with each request. When the countermeasure is turned on, it compares these values. It compares and checks if these values are valid in the current valid session with the user. The secret token validation fails if we perform the attack when the countermeasure is turned on because it identifies it as a cross site request and not a request from the user.

Refarence:

- http://www.cis.syr.edu/~wedu/seed/Labs/Attacks_CSRF/CSRF.pdf
- http://www.cis.syr.edu/~wedu/seed/Labs/Attacks_CSRF/
- 3. https://youtu.be/iY74zUB6Mpk
- 4. https://www.cybrary.it/video/part-6-csrf-lab-solution/

,