
# YZNCMSv1.4.2 background management system has storage XSS vulnerability

## **Vulnerability location**

/admin/index/index.html

### **POC**

Login background




#### Click the Modify button




xss payload is injected in the configured remarks

<script>alert('XSS')</script>



#### The database was successfully injected



#### Updated web page xss vulnerability verification succeeded

