RIVERTON POLICE DEPARTMENT

Traffic Division · 1 Civic Plaza, Riverton · Records (555) 010-2100

Form RPD-TC-1 (rev. 07/2024)
Report No. RPD-26-018842

TRAFFIC CRASH REPORT

Investigated at scene · Reportable crash — injury

CRASH IDENTIFICATION					
REPORT NUMBER RPD-26-018842	DATE OF CRASH 02/06/2026	DAY OF WEEK Friday	TIME (APPROX.) 07:10	TIME NOTIFIED 07:11	TIME ARRIVED 07:16
TIME CLEARED 08:24	BEAT / UNIT Beat 4 · Car 412	LOCATION (ON STREET / AT INTERSECTING STREET) Maple Hollow Rd at Birch Ave		CITY / COUNTY Riverton	INTERSECTION TYPE Four-way
TRAFFIC CONTROL All-way stop	CONTROL FUNCTIONING Yes	POSTED SPEED 25 mph	CRASH TYPE Angle	WEATHER Clear	LIGHT CONDITION Dawn
ROAD SURFACE Dry asphalt	NO. OF UNITS 3 (1 parked)	FATAL / INJURED 0 / 1 (C)	HIT AND RUN No	PHOTOGRAPHS Yes — 14	STATEMENTS D1, D2, W1

UNIT 1 — DRIVER & VEHICLE					
DRIVER NAME SMITH, Robert		DATE OF BIRTH 07/19/1979	SEX M	PHONE (555) 010-6630	DRIVER LICENSE / CLASS S530-4419-7731 C
ADDRESS 118 Larkspur Ln, Riverton		YEAR 2017	MAKE / MODEL Chevrolet Silverado 1500		BODY / COLOR Pickup · black
PLATE RKT-4471	OWNER Same as driver	INSURANCE COMPANY / POLICY NO. Keystone Mutual Insurance · KMI-PA-7731045		DIRECTION / ROAD North · Birch Ave	PRE-CRASH ACTION Straight ahead
EST. SPEED / POSTED 25–30 / 25	CONTRIBUTING (CODE) 04 Disregarded stop sign	DAMAGE AREA / SEVERITY Front, front-right · moderate		AIRBAG Not deployed	REMOVED Driven from scene

UNIT 2 — DRIVER & VEHICLE					
DRIVER NAME ALVAREZ, Kevin		DATE OF BIRTH 11/03/1988	SEX M	PHONE (555) 010-5172	DRIVER LICENSE / CLASS A417-2203-8851 C
ADDRESS 47 Fenwick St, Riverton		YEAR 2021	MAKE / MODEL Ford Escape		BODY / COLOR SUV · silver
PLATE HMV-2318	OWNER Same as driver	INSURANCE COMPANY / POLICY NO. Harbor Point Insurance · HPA-4402917		DIRECTION / ROAD East · Maple Hollow Rd	PRE-CRASH ACTION Stopped, then straight
EST. SPEED / POSTED ~10 / 25	CONTRIBUTING (CODE) 00 None	DAMAGE AREA / SEVERITY Right side (front pass. door) · disabling; left side (2nd impact)		AIRBAG Deployed — right side	REMOVED Towed — to Eastline Auto Body


UNIT 3 — PARKED VEHICLE (UNOCCUPIED)					
OWNER NAME / ADDRESS DOE, John · 2214 Maple Hollow Rd, Riverton		YEAR 2019	MAKE / MODEL Honda Civic LX	BODY / COLOR Sedan · blue	PLATE JLD-9026
INSURANCE COMPANY / POLICY NO. Bluewater Auto Insurance · BWA-209-66184		PARKED LOCATION East curb, Birch Ave, N of intersection, facing north		DAMAGE / SEVERITY Left side · disabling	REMOVED Towed — Riverton Towing

Persons involved

Unit	Seat	Name	DOB	Address	Restraint	Airbag	Eject.	Injury	EMS / transport
1	Driver	Robert Smith	07/19/1979	118 Larkspur Ln, Riverton	Lap/shoulder belt used	Not depl.	No	O – no injury	None
2	Driver	Kevin Alvarez	11/03/1988	47 Fenwick St, Riverton	Lap/shoulder belt used	Depl. — side	No	O – no injury	None
2	Front right	John Doe	08/14/1991	2214 Maple Hollow Rd, Riverton	Lap/shoulder belt used	Depl. — side	No	C – possible injury, complaint of neck pain	RFD Medic 7 · refused (RF-26-0206-114)

WITNESS		
NAME CALLOWAY, Ruth	ADDRESS 2209 Maple Hollow Rd, Riverton	PHONE (555) 010-3147
LOCATION AT TIME OF CRASH / STATEMENT On foot, SW corner of intersection · written statement taken 07:40 (attached, W1)		

Collision diagram



Dashed outline = position before impact · solid outline = final rest · ⊗ = point of impact · red octagon = stop sign (all-way) · W = witness · 1 = Silverado, 2 = Escape, 3 = Civic (parked)

Narrative

On 02/06/2026 at approx. 0710 hrs I was dispatched to a two-vehicle crash with a parked vehicle struck at Maple Hollow Rd and Birch Ave, an all-way stop intersection. Arrived 0716. All stop signs present and unobstructed.

Unit 2 (Ford Escape, driver Alvarez) was eastbound on Maple Hollow Rd. D2 stated he stopped at the stop sign, saw no one at the other approaches, and proceeded. Unit 1 (Chevrolet Silverado, driver Smith) was northbound on Birch Ave. D1 stated he "thought the other car was going to wait" and did not recall whether he stopped. W1 (Calloway), on foot at the SW corner, stated Unit 2 came to a complete stop and Unit 1 did not slow down.

Unit 1 failed to stop at the stop sign for northbound traffic and struck Unit 2's front passenger door in the SE quadrant of the intersection. The impact pushed Unit 2 north into Unit 3 (Honda Civic, unoccupied), legally parked at the east curb of Birch Ave. No skid marks from Unit 1 located before the POI. Debris field in the NE quadrant.

P1 (Doe), front-right passenger of Unit 2, complained of neck pain; evaluated by RFD Medic 7 and refused transport. Residential doorbell camera at 2214 Maple Hollow Rd (NE corner) faces the intersection; owner advised to preserve the recording. D1 cited (below).

CITATIONS / ENFORCEMENT		
PERSON CITED	VIOLATION	CITATION NO.
Unit 1 — Robert Smith	Failure to stop at stop sign	R-552310

T. Garner #2217

Investigating officer: Officer Thomas Garner #2217 · 02/06/2026

L. Pruitt

Reviewed: Sgt. Lydia Pruitt #1904 · 02/07/2026

CERTIFIED TRUE COPY · RPD RECORDS DIVISION
ISSUED 02/18/2026 · FEE $25.00 PAID