RIVERTON POLICE DEPARTMENT

Traffic Division · 1 Civic Plaza, Riverton · Records (555) 010-7100

Form RPD-TC-1 (rev. 07/2024)
Report No. RPD-26-018842

TRAFFIC CRASH REPORT

Investigated at scene · Reportable crash — injury

CRASH IDENTIFICATION

REPORT NUMBER	DATE OF CRASH	DAY OF WEEK	TIME (APPROX.)	TIME NOTIFIED	TIME ARRIVED
RPD-26-018842	02/06/2026	Friday	07:10	07:11	07:16

TIME CLEARED	BEAT / UNIT	LOCATION (ON STREET / AT INTERSECTING STREET)	CITY / COUNTY	INTERSECTION TYPE
08:24	Beat 4 · Car 412	Maple Hollow Rd at Birch Ave	Riverton	Four-way

TRAFFIC CONTROL	CONTROL FUNCTIONING	POSTED SPEED	CRASH TYPE	WEATHER	LIGHT CONDITION
All-way stop	Yes	25 mph	Angle	Clear	Dawn

ROAD SURFACE	NO. OF UNITS	FATAL / INJURED	HIT AND RUN	PHOTOGRAPHS	STATEMENTS
Dry asphalt	3 (1 parked)	0 / 1 (C)	No	Yes — 14	D1, D2, W1

UNIT 1 — DRIVER & VEHICLE

DRIVER NAME	DATE OF BIRTH	SEX	PHONE	DRIVER LICENSE / CLASS
SMITH, Robert	07/19/1979	M	(555) 010-6630	S530-4419-7731 C

ADDRESS	YEAR	MAKE / MODEL	BODY / COLOR
118 Larkspur Ln, Riverton	2017	Chevrolet Silverado 1500	Pickup · black

PLATE	OWNER	INSURANCE COMPANY / POLICY NO.	DIRECTION / ROAD	PRE-CRASH ACTION
RKT-4471	Same as driver	Keystone Mutual Insurance · KMI-PA-7731045	North · Birch Ave	Straight ahead

EST. SPEED / POSTED	CONTRIBUTING (CODE)	DAMAGE AREA / SEVERITY	AIRBAG	REMOVED
25–30 / 25	04 Disregarded stop sign	Front, front-right · moderate	Not deployed	Driven from scene

UNIT 2 — DRIVER & VEHICLE

DRIVER NAME	DATE OF BIRTH	SEX	PHONE	DRIVER LICENSE / CLASS
ALVAREZ, Kevin	11/03/1988	M	(555) 010-5172	A417-2203-8851 C

ADDRESS	YEAR	MAKE / MODEL	BODY / COLOR
47 Fenwick St, Riverton	2021	Ford Escape	SUV · silver

PLATE	OWNER	INSURANCE COMPANY / POLICY NO.	DIRECTION / ROAD	PRE-CRASH ACTION
HMV-2318	Same as driver	Harbor Point Insurance · HPA-4402917	East · Maple Hollow Rd	Stopped, then straight

EST. SPEED / POSTED	CONTRIBUTING (CODE)	DAMAGE AREA / SEVERITY	AIRBAG	REMOVED
~10 / 25	00 None	Right side (front pass. door) · disabling; left side (2nd impact)	Deployed — right side	Towed — to Eastline Auto Body

UNIT 3 — PARKED VEHICLE (UNOCCUPIED)

OWNER NAME / ADDRESS	YEAR	MAKE / MODEL	BODY / COLOR	PLATE
DOE, John · 2214 Maple Hollow Rd, Riverton	2019	Honda Civic LX	Sedan · blue	JLD-9026


INSURANCE COMPANY / POLICY NO.	PARKED LOCATION	DAMAGE / SEVERITY	REMOVED
Bluewater Auto Insurance · BWA-209-66184	East curb, Birch Ave, N of intersection, facing north	Left side · disabling	Towed — Riverton Towing

Persons involved

Unit	Seat	Name	DOB	Address	Restraint	Airbag	Eject.	Injury	EMS / transport
1	Driver	Robert Smith	07/19/1979	118 Larkspur Ln, Riverton	Lap/shoulder belt used	Not depl.	No	O – no injury	None
2	Driver	Kevin Alvarez	11/03/1988	47 Fenwick St, Riverton	Lap/shoulder belt used	Depl. — side	No	O – no injury	None
2	Front right	John Doe	08/14/1991	2214 Maple Hollow Rd, Riverton	Lap/shoulder belt used	Depl. — side	No	C – possible injury, complaint of neck pain	RFD Medic 7 · refused (RF-26-0206-114)

WITNESS		
NAME CALLOWAY, Ruth	ADDRESS 2209 Maple Hollow Rd, Riverton	PHONE (555) 010-3147
LOCATION AT TIME OF CRASH / STATEMENT On foot, SW corner of intersection · written statement taken 07:40 (attached, W1)		

Collision diagram



Dashed outline = position before impact · solid outline = final rest · ⊗ = point of impact · red octagon = stop sign (all-way) · W = witness · 1 = Silverado, 2 = Escape, 3 = Civic (parked)

Narrative

On 02/06/2026 at approx. 0710 hrs I was dispatched to a two-vehicle crash with a parked vehicle struck at Maple Hollow Rd and Birch Ave, an all-way stop intersection. Arrived 0716. All stop signs present and unobstructed.

Unit 2 (Ford Escape, driver Alvarez) was eastbound on Maple Hollow Rd. D2 stated he stopped at the stop sign, saw no one at the other approaches, and proceeded. Unit 1 (Chevrolet Silverado, driver Smith) was northbound on Birch Ave. D1 stated he "thought the other car was going to wait" and did not recall whether he stopped. W1 (Calloway), on foot at the SW corner, stated Unit 2 came to a complete stop and Unit 1 did not slow down.

Unit 1 failed to stop at the stop sign for northbound traffic and struck Unit 2's front passenger door in the SE quadrant of the intersection. The impact pushed Unit 2 north into Unit 3 (Honda Civic, unoccupied), legally parked at the east curb of Birch Ave. No skid marks from Unit 1 located before the POI. Debris field in the NE quadrant.

P1 (Doe), front-right passenger of Unit 2, complained of neck pain; evaluated by RFD Medic 7 and refused transport. Residential doorbell camera at 2214 Maple Hollow Rd (NE corner) faces the intersection; owner advised to preserve the recording. D1 cited (below).

CITATIONS / ENFORCEMENT		
PERSON CITED	VIOLATION	CITATION NO.
Unit 1 — Robert Smith	Failure to stop at stop sign	R-552310

T. Garner #2217

Investigating officer: Officer Thomas Garner #2217 · 02/06/2026

L. Pruitt

Reviewed: Sgt. Lydia Pruitt #1904 · 02/07/2026

CERTIFIED TRUE COPY · RPD RECORDS DIVISION
ISSUED 02/18/2026 · FEE $25.00 PAID