


# Recovery slot geometry, same pad



worst edge clearance 0.523 m = exactly one airframe radius:  
no overhang at the nominal slot, and no margin beyond it