


Figure 2 – *Examples of landslides and other slope processes inventoried from Google Earth*

In Figure 2 above, red polygons delineate the landslides. Small white arrows locate the landslide headscarps, i.e. the landslide source areas. Large white arrows indicate the north. a) Old large deep-seated landslide in Bishenyi sub-catchment, Jan. 2021 (-1.958, 29.948°). b) Old large deep-seated landslide in Kamembe-Gihundwe sub-catchment, Sept. 2020 (-2.454, 28.912°). c) Old large deep-seated landslides in Kamembe-Gihundwe sub-catchment, Sept.2020 (-2.502, 29.906°). d) Recent flow landslides (mixture of flow slides and earthflows) in Bishenyi sub-catchment, January, 2021 (-2.000°, 29.939°). e) Deep-seated landslide, probably associated with soil creep in Rwabayanga sub-catchment, July. 2018 (-2.602°, 29.718°). f) Active gully associated with a road in the Rwabayanga sub-catchment. Note the vegetation free gully features as well as the colluvium deposit downslope (clear sediment) that attest the activity of the system, July 2018 (-2.602°, 29.739°).