- Deep-seated landslides. These processes are of the slide and earthflow types. Although it was not directly observed here in the field, these landslides are known to occur in all types of slope material, whether it is in highly weathered mobile regolith, or, at the other extreme of the weathering process, into fresh bedrock (Dille et al., 2019; Dewitte et al., 2021; Kubwimana et al., 2021).
- Shallow landslides. These landslides were not identified directly from the analysis of the Google Earth images in the four watersheds, but it is known that they can occur in the region at any time, especially during rainfall events. This is for these landslides that the landside hazard and risk analysis was carried out. In the region of western Rwanda, these landslides are commonly of the slide and avalanche types (Depicker et al., 2021). They mostly occur in regolith material and the degree of weathering of the material where they develop is variable (Kubwimana et al., 2021).
- In addition to these slope failures processes, soil creep is also known to occur on the hillslopes, affecting the regolith layer. This process can produce colluvium slopes where landslides can also take place.
- Gully erosion is also observed. Gully erosion is a process that is not due to gravity and it is not considered as a landslide process. Nevertheless, gully erosion is frequently associated with landsliding, either in cause or in consequence of it.




Figure 10: *Framework for landslide risk management. Adapted from Fell et al. (2008).*