Walkaround evidence sheet

Two walkaround videos of one rental car, compared panel by panel. Code decides every verdict; a model answer can only lower one.

evidence support, not legal advice

Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

run id	`eval_nhtsa15759_r6`
app commit	`f24ae02c6e4645e19aca16b69310c377db1c5bcd`
config hash	`3fb220014a1d9911b5fd97f330fad75c426f3c5827c1a1a0e1bc3e1cb2506b7e`
events head hash	`2267706887a6372b09cebd2df8f9ec7814cd795ca3b087bc2889177fff522be7`
rental agreement number	_____ (fill in)
plate	plate blurred

The three clocks

sealed at	first model call at	sealed after the camera time
2026-11-01T07:15:35.289Z	**2026-11-01T07:15:53Z**	**camera time not present**

Originals

walk	file	bytes	sha256	camera says	received	hash on your phone = hash on receipt	proven to exist by
pickup	t15759_pre.mp4	36444009	0f612417615726cf0bc5d0662a5373cdf92cd2defc7329e063685580a2fd04ed	not present	2026-11-01T07:15:35.071Z	match	2026-11-01T07:15:41Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)
return	t15759_post.mp4	58523935	a157a4a7483b7540d1f4e133c1b69d7f51deeca9360336e96004e64fea2a7fed	not present	2026-11-01T07:15:35.136Z	match	2026-11-01T07:15:41Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)

Privacy

Processed with Meta's Model API in Standard mode, which Meta's documentation says is not used to train Meta models. Uploads were set to expire after one hour and were deleted by Walkaround when the run ended. Model requests were sent with storage off. Meta's terms allow it to retain content for abuse review and legal reasons; Walkaround does not control that. SAM 3.1 saw the unblurred proxy for the length of one segmentation pass to find the plates and faces it then blurred. For the

second look, two blurred crops per look were sent to Muse Spark Open on Baseten, a company separate from Meta; no video went there.

Files API upload deleted: 2026-11-01T07:19:49.948Z. Stored responses deleted: none stored or not yet. Quarantine (unblurred originals) deleted: 2026-11-01T07:19:49.948Z.

What to do with this sheet

1. Start with the dated pickup frames in this sheet: the camera says not present, the file was received 2026-11-01T07:15:35.071Z, and the file hashes (0f6124176157, a157a4a7483b) are on page 1 and in the sealed manifest.
2. Ask the company in writing for the full damage report, the repair estimate and every image it holds for this rental, including the pickup inspection images; Hertz says customers can request more images.
3. Get an alternative written estimate from a body shop within 10 business days; card network rules compare two quotes (Visa Core Rules Table 5-19; Amex allows up to 115% of the estimate).
4. If the company does not answer, escalate to a named executive and file a complaint with your state consumer protection office; the one sourced renter win came by executive escalation with the company's own scans.
5. Last, the card dispute, with its clocks: 60 days from the statement under Regulation Z 1026.13, 120 days under Visa's rules, and the $50 cap of 15 USC 1666i; a dispute does not stop collections, so keep the paper trail.

Coverage per walk

pickup

- left front door: filmed, 4.5 s
- left rear door: filmed, 4.6 s
- right front door: filmed, 5.8 s
- right rear door: filmed, 5.0 s
- left front fender: not_filmed
- left rear fender: not_filmed
- right front fender: not_filmed
- right rear fender: not_filmed
- hood: filmed, 14.7 s
- roof: glimpsed, 5.0 s
- trunk lid: not_filmed
- front bumper: filmed, 5.0 s
- rear bumper: filmed, 5.0 s
- left front wheel: filmed, 4.5 s
- left rear wheel: filmed, 4.5 s
- right front wheel: filmed, 5.0 s
- right rear wheel: glimpsed, 4.9 s
- headlights: glimpsed, 5.1 s
- tail lights: glimpsed, 5.0 s
- mirrors: not_filmed
- windshield: filmed, 10.1 s
- rear window: filmed, 5.1 s
- missing at pickup: right front wheel, right rear wheel, rear bumper, right front door, right rear door, left front fender, left rear fender, right front fender, right rear fender, roof, trunk lid, headlights, tail lights, mirrors, rear window
- top-up asked: Film these again, in this order: right front wheel (not filmed); right rear wheel (not filmed); rear bumper (glimpsed, 3.7 s); right front door (glimpsed, 5.0 s); right rear door (not filmed); left front fender (not filmed); left rear fender (not filmed); right front fender (not filmed); right rear fender (not filmed); roof (glimpsed, 8.6 s); trunk lid (not filmed); headlights (glimpsed, 10.0 s); tail lights (glimpsed, 3.7 s); mirrors (glimpsed, 5.0 s); rear window (not filmed). The app then re-runs 13 of 16 nouns: wheel, bumper, car door, fender, roof, trunk lid, headlight, tail light, side mirror, rear window, car, license plate, face. Also film the odometer once.

return


- left front door: filmed, 13.7 s
- left rear door: filmed, 13.7 s
- right front door: glimpsed, 5.0 s
- right rear door: not_filmed
- left front fender: not_filmed
- left rear fender: not_filmed
- right front fender: not_filmed
- right rear fender: not_filmed
- hood: filmed, 15.0 s
- roof: glimpsed, 8.6 s
- trunk lid: not_filmed
- front bumper: filmed, 10.0 s
- rear bumper: glimpsed, 3.7 s
- left front wheel: filmed, 5.0 s
- left rear wheel: filmed, 8.7 s
- right front wheel: not_filmed
- right rear wheel: not_filmed
- headlights: glimpsed, 10.0 s
- tail lights: glimpsed, 3.7 s
- mirrors: glimpsed, 5.0 s
- windshield: filmed, 13.1 s
- rear window: not_filmed

left front door

coverage: pickup 4.5 s (filmed); return 13.7 s (filmed)



pickup: video time 0.33 s



return: video time 13.80 s; marks return_left_front_door_kf1_m1, return_left_front_door_kf2_m1, return_left_front_door_kf2_m2, return_left_front_door_kf2_m3

how it was checked: compared on keyframes pickup_left_front_door_kf1 with return_left_front_door_kf1, the first pair tried

Verdicts

marks	verdict	rule ids	distance	detail
return_left_front_door_kf1_m1 dent L	new or unseen	L2	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark the second look compared this mark with the same spot in the pickup walk and said different, so the label stands
return_left_front_door_kf2_m1 dent L	needs your eye	L4, L2, K15	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark return view flagged glare: could be a reflection
return_left_front_door_kf2_m2 dent L	needs your eye	L4, L2, K15	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark return view flagged glare: could be a reflection
return_left_front_door_kf2_m3 dent M	needs your eye	L4, L2, K15	no pair	Stays Put: drift 0.08, b1 0.00, b2 0.00, not panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark return view flagged glare: could be a reflection

L2 new or unseen: d is None for a return mark: new_or_unseen
L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
K15 view flagged: Muse Spark flagged the pickup or return view of the panel wet, dirty or glare, so a mark seen in one walk only may be dirt, water or a reflection, or may have been hidden in the other walk; a mark in the same place in both walks keeps its label with a note

---

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

`0f6124176157/a157a4a7483b`

left rear door

coverage: pickup 4.6 s (filmed); return 13.7 s (filmed)



pickup: video time 0.40 s



return: video time 13.87 s; marks return_left_rear_door_kf1_m1, return_left_rear_door_kf1_m2

how it was checked: not compared: none of the 2 keyframe pairs passed every gate; tried: pickup_left_rear_door_kf2 with return_left_rear_door_kf1 (G4 mask IoU 0.70); pickup_left_rear_door_kf1 with return_left_rear_door_kf1 (G4 mask IoU: panel axes disagree); outline changed in place (L7): keyframes pickup_left_rear_door_kf2 with return_left_rear_door_kf1, IoU 0.70, box aspect ratios 0.988 and 0.988 (0.0% apart), largest blob 64% of the mask difference

Verdicts

marks	verdict	rule ids	distance	detail
`return_left_rear_door_kf1_m1, return_left_rear_door_kf1_m2` `dent L`	needs your eye	L7, G4	no pair	Stays Put: no track (SAM did not follow the mark through the clip)

L7 outline changed in place: G4 alone failed on every keyframe pair tried, the best whitened mask IoU is from 0.5 to under 0.7, the two keyframes' box aspect ratios agree within 2% and the largest blob of the mask difference holds at least half of it: the panel may be reshaped, so needs your eye; never already there or new
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

right front door

coverage: pickup 5.8 s (filmed); return 5.0 s (glimpsed)



pickup: video time 8.80 s



return: video time 24.53 s; marks return_right_front_door_kf2_m1

how it was checked: not compared: keyframes pickup_right_front_door_kf2 with return_right_front_door_kf1 (G1 not filmed, G4 mask IoU 0.61, G9 mask definition differs); G1 is a panel gate, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
`return_right_front_door_kf2_m1` `reflection S`	**not comparable**	L6, G1, G4, G9	no pair	Stays Put: drift 0.13, b1 0.00, b2 0.04, not panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G9 mask definition differs: window_subtracted differs between the paired keyframes


---

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157
/
a157a4a7483b

right rear door

coverage: pickup 5.0 s (filmed); return 0.0 s (not_filmed)



pickup: video time 9.80 s; marks pickup_right_rear_door_kf1_m1, pickup_right_rear_door_kf2_m1

no return frame for this panel

Verdicts


marks	verdict	rule ids	distance	detail
`pickup_right_rear_door_kf1_m1, pickup_right_rear_door_kf2_m1` `dent L`	**not comparable**	L6, G1	no pair	Stays Put: no track (SAM did not follow the mark through the clip)

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

hood

coverage: pickup 14.7 s (filmed); return 15.0 s (filmed)



pickup: video time 14.73 s



return: video time 22.73 s

how it was checked: compared on keyframes pickup_hood_kf1 with return_hood_kf2, the first pair tried

No marks compared on this panel.

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

roof

coverage: pickup 5.0 s (glimpsed); return 8.6 s (glimpsed)



pickup: video time 5.73 s



return: video time 27.80 s

how it was checked: not compared: keyframes pickup_roof_kf2 with return_roof_kf3 (G1 not filmed, G4 mask IoU: not measured, G6 side uncertain); G1 and G6 are panel gates, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G4, G6	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G6 side uncertain: side_uncertain, or front_sign null, on either walk


Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157 / a157a4a7483b

front bumper



pickup: video time 15.07 s



return: video time 24.33 s; marks return_front_bumper_kf3_m1

coverage: pickup 5.0 s (filmed); return 10.0 s (filmed)

how it was checked: not compared: none of the 6 keyframe pairs passed every gate; tried: pickup_front_bumper_kf2 with return_front_bumper_kf1 (G4 mask IoU 0.62); pickup_front_bumper_kf1 with return_front_bumper_kf1 (G4 mask IoU 0.62); pickup_front_bumper_kf1 with return_front_bumper_kf2 (G4 mask IoU 0.61); pickup_front_bumper_kf2 with return_front_bumper_kf2 (G4 mask IoU 0.61); pickup_front_bumper_kf1 with return_front_bumper_kf3 (G4 mask IoU 0.60); pickup_front_bumper_kf2 with return_front_bumper_kf3 (G4 mask IoU 0.60); not called reshaped: keyframes pickup_front_bumper_kf1 with return_front_bumper_kf1, IoU 0.62, box aspect ratios 3.375 and 8.569 (60.6% apart), largest blob 41% of the mask difference

Verdicts

marks	verdict	rule ids	distance	detail
`return_front_bumper_kf3_m1` `chip S`	**not comparable**	L6, G4	no pair	Stays Put: no track (SAM did not follow the mark through the clip)

L6 not comparable: a G rule failed for the panel; both best frames still show
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

rear bumper



pickup: video time 6.20 s; marks pickup_rear_bumper_kf1_m1, pickup_rear_bumper_kf1_m2, pickup_rear_bumper_kf1_m3, pickup_rear_bumper_kf3_m1



return: video time 0.13 s

coverage: pickup 5.0 s (filmed); return 3.7 s (glimpsed)

how it was checked: not compared: keyframes pickup_rear_bumper_kf1 with return_rear_bumper_kf1 (G1 not filmed, G4 mask IoU 0.64); G1 is a panel gate, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_rear_bumper_kf1_m1, pickup_rear_bumper_kf1_m2, pickup_rear_bumper_kf1_m3, pickup_rear_bumper_kf3_m1` `scuff S`	**not comparable**	L6, G1, G4	no pair	Stays Put: drift 0.02, b1 0.00, b2 0.03, not panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26).

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

left front wheel



pickup: video time 0.47 s



return: video time 13.93 s

coverage: pickup 4.5 s (filmed); return 5.0 s (filmed)


how it was checked: compared on keyframes pickup_left_front_wheel_kf1 with return_left_front_wheel_kf3, the first pair tried

No marks compared on this panel.

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157 / a157a4a7483b

left rear wheel



pickup: video time 2.13 s



return: video time 13.87 s


coverage: pickup 4.5 s (filmed); return 8.7 s (filmed)

how it was checked: compared on keyframes pickup_left_rear_wheel_kf1 with return_left_rear_wheel_kf1, the first pair tried

No marks compared on this panel.

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

right front wheel



pickup: video time 9.53 s

no return frame for this panel

coverage: pickup 5.0 s (filmed); return 0.0 s (not_filmed)


Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

right rear wheel



no return frame for this panel

pickup: video time 12.27 s

coverage: pickup 4.9 s (glimpsed); return 0.0 s (not_filmed)

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk


Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

headlights

coverage: pickup 5.1 s (glimpsed); return 10.0 s (glimpsed)



pickup: video time 19.07 s



return: video time 23.67 s

how it was checked: not compared: keyframes pickup_headlights_kf3 with return_headlights_kf1 (G1 not filmed, G4 mask IoU 0.58); G1 is a panel gate, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G4	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157 / a157a4a7483b

tail lights

coverage: pickup 5.0 s (glimpsed); return 3.7 s (glimpsed)



pickup: video time 4.53 s



return: video time 2.73 s

how it was checked: not compared: keyframes pickup_tail_lights_kf1 with return_tail_lights_kf2 (G1 not filmed); G1 is a panel gate, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157 / a157a4a7483b

mirrors

coverage: pickup 0.0 s (not_filmed); return 5.0 s (glimpsed)

no pickup frame for this panel



return: video time 26.00 s

Verdicts


marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G6	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G6 side uncertain: side_uncertain, or front_sign null, on either walk


Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

windshield

coverage: pickup 10.1 s (filmed); return 13.1 s (filmed)



pickup: video time 7.53 s



return: video time 23.67 s; marks return_windshield_kf2_m1

how it was checked: compared on keyframes pickup_windshield_kf1 with return_windshield_kf3, the first pair tried

Verdicts


marks	verdict	rule ids	distance	detail
return_windshield_kf2_m1 reflection S	needs your eye	L4, L2, K15, K2, K4	no pair	Stays Put: drift 0.08, b1 0.04, b2 0.17, panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark return view flagged glare: could be a reflection; pickup view flagged glare: could have hidden the mark

L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
L2 new or unseen: d is None for a return mark: new_or_unseen
K15 view flagged: Muse Spark flagged the pickup or return view of the panel wet, dirty or glare, so a mark seen in one walk only may be dirt, water or a reflection, or may have been hidden in the other walk; a mark in the same place in both walks keeps its label with a note
K2 single frame: the mark appears in 1 of 3 keyframes while the other two were complete and sharp
K4 uncertain type: type dirt, reflection or unsure

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

rear window

coverage: pickup 5.1 s (filmed); return 0.0 s (not_filmed)



pickup: video time 5.73 s

no return frame for this panel

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

Panels without frames

panel	coverage
left front fender	pickup: not_filmed (0.0 s); return: not_filmed (0.0 s)
left rear fender	pickup: not_filmed (0.0 s); return: not_filmed (0.0 s)
right front fender	pickup: not_filmed (0.0 s); return: not_filmed (0.0 s)
right rear fender	pickup: not_filmed (0.0 s); return: not_filmed (0.0 s)
trunk lid	pickup: not_filmed (0.0 s); return: not_filmed (0.0 s)

Not comparable

panel	rule ids	why
right front door	G1, G4, G9	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G9 mask definition differs: window_subtracted differs between the paired keyframes
right rear door	G1	G1 not filmed: the panel is not 'filmed' in either walk
roof	G1, G4, G6	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G6 side uncertain: side_uncertain, or front_sign null, on either walk
front bumper	G4	G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
rear bumper	G1, G4	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
right front wheel	G1	G1 not filmed: the panel is not 'filmed' in either walk
right rear wheel	G1	G1 not filmed: the panel is not 'filmed' in either walk
headlights	G1, G4	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
tail lights	G1	G1 not filmed: the panel is not 'filmed' in either walk
mirrors	G1, G6	G1 not filmed: the panel is not 'filmed' in either walk G6 side uncertain: side_uncertain, or front_sign null, on either walk
rear window	G1	G1 not filmed: the panel is not 'filmed' in either walk

Method and limits

Every verdict on the panel pages was decided by code from the numbers below. The thresholds were frozen into this run under config hash `3fb220014a1d9911b5fd97f330fad75c426f3c5827c1a1a0e1bc3e1cb2506b7e`. Rebuilding the derived files from the stored model answers and these thresholds gives the same bytes when the line below says so.

rebuild	event chain verified to the head on page 1 and any original still in quarantine re-hashed at sheet time; run walkaround verify to compare a rebuild
storage	Model requests were sent with storage off and the models accepted it; nothing was kept after the run. Files API upload deleted: 2026-11-01T07:19:49.948Z; quarantine deleted: 2026-11-01T07:19:49.948Z.
Hertz thresholds	Example thresholds Hertz published (REV 7.2025), illustrative only, quoted from its Damage Charges support page saved 2026-10-26: a body scratch is billable when it cannot be covered by a credit card (2 in x 3.5 in), or when scratches over 1 in together exceed that area; a dent with a diameter over 1 in, or multiple dents; a wheel, rim or hubcap scratch or scuff over 1 in; any crack or chip in glass. Paint transfer or scuffs that do not break the paint are listed as Ordinary Wear and not charged.

Eval numbers

No eval run is attached to this sheet; the README carries the eval tables with their N.

Calibration

tau_pre (already there below)	`0.4`
tau_eye (needs your eye below)	`0.8`
tau_fix (Stays Put fixed below)	`0.08`
sigma_frame / sigma_spark / sigma_view / sigma_within	`None / 0.117 / 0.065284 / 0.133981`
calibrated	no: tau_pre hit its cap, so the matcher is not calibrated for this run

Model calls (from runs/ledger.jsonl)

kind	calls	dollars	quantity
sam_image	142	0.3550	142 images
sam_video	45	2.8706	14353 frames
spark	69	0.2562	112696 tokens
spark_open	1	0.0030	1676 tokens
total	257	3.4848	

What was blurred

- pickup: SAM image checks on 37 keyframes found a plate on 28 and faces on 0; the display proxy was pixelated from the plate and face tracks
- return: SAM image checks on 32 keyframes found a plate on 20 and faces on 0; the display proxy was pixelated from the plate and face tracks

What was deleted and when

kind	target	sha256	bytes	deleted at	reason	receipt

file	media/pickup.proxy.mp4	b36d4268e449	2537618	2026-11-01T07:17:17Z	unblurred proxy deleted at blur.done	
file	media/return.proxy.mp4	76a88ee931e6	4935793	2026-11-01T07:17:20Z	unblurred proxy deleted at blur.done	
files_api	file-1121944830247907	b36d4268e449		2026-11-01T07:19:49.948Z	run end (pickup proxy)	{'deleted': True, 'id': 'file-1121944830247907', 'object': 'file'}
files_api	file-28656829494008439	76a88ee931e6		2026-11-01T07:19:49.948Z	run end (return proxy)	{'deleted': True, 'id': 'file-28656829494008439', 'object': 'file'}
quarantine	quarantine/pickup.orig	0f6124176157	36444009	2026-11-01T07:19:49.948Z	run end	
quarantine	quarantine/return.orig	a157a4a7483b	58523935	2026-11-01T07:19:49.948Z	run end	

What the seal does not prove

- which car was filmed, unless the plate was kept on this sheet at the renter's request
- that the walk was not staged before the upload; the seal dates the bytes, not the events in them
- anything about the pickup condition when the seal was made after the return

The seal is offered as a process record under FRE 901(b)(9): the same inputs through the same code give the same output, and the method page states that code's inputs.

Thresholds frozen into this run

claim.align_landmark_fit	False
claim.dark_v_max	0.15
claim.drawn_box_inside_saturated_max	0.1
claim.drawn_box_perimeter_saturated_min	0.3
claim.drawn_box_saturation_min	0.5
claim.full_panel_area_min	0.03
claim.full_panel_border_max	0.15
claim.landmark_fit_min_landmarks	3
claim.landmark_fit_residual_max_frac	0.1
claim.low_res_px	480
claim.on_panel_frac	0.025
claim.passenger_side_is	right
claim.photo_flag_caps_one_walk_only	True
claim.r_claim_full_panel	0.1
claim.r_claim_two_landmarks	0.2
claim.roi_pad_frac	0.25
claim.roi_region_max_panel_frac	0.4

claim.sam_vote_requests	14
claim.scanner_style_saturation_max	0.08
claim.view_flag_caps	True
cost.d1_budget_usd	25
cost.pair_estimate_usd_10fps	4.9
cost.pair_estimate_usd_15fps	6.2
cost.pickup_check_estimate_usd	2.6
cost.sam_image_usd	0.0025
cost.sam_video_min_frames	50
cost.sam_video_usd_per_frame	0.0002
cost.voice_usd_per_hour	0.18
coverage.area_only_box_area_frac_min	0.01
coverage.c_present_floor	0.5
coverage.filmed_area_frac_min	0.03
coverage.filmed_completeness_min	0.85
coverage.filmed_sharpness_rel_min	0.4
coverage.glimpsed_c_percentile	25
coverage.odometer_ask_once	True
coverage.topup_order	['wheels', 'lower_bumpers', 'rest']
dedup.cluster_radius_units	0.2
dedup.collinear_angle_deg	10
dedup.collinear_gap_units	0.1
dedup.count_mode_new_point_min_units	0.1
dedup.droplet_max_size_units	0.03
dedup.droplet_min_marks	8
dedup.group_min_marks	3
dedup.group_radius_units	0.5
dedup.road_spray_band_bottom_frac	0.25
dedup.road_spray_min_marks	3
dedup.small_mark_px	12
dedup.small_mark_units	0.03
eval.billable_buckets_mm	[10, 20, 25.4]
eval.false_mark_radius_units	0.35
eval.recall_radius_units	0.25
eval.report_pairs	['p2xr2', 'cross', 'multi_day']
eval.threshold_fit_pairs	['pseudo', 'p1xr1']
geometry.bumper_arc_fallback_tau_factor	1.5
geometry.carried_moments_check_frames	5
geometry.carried_moments_residual_max_units	0.02
geometry.hood_depth_thirds	3
geometry.perspective_residual_center_max	0.08
geometry.perspective_residual_corner_max	0.25
geometry.unit_cm_along_door	35
geometry.unit_cm_vertical_door	29
geometry.whiten_affine_invariance_tol	1e-06
matching.band_radius_factor	0.5
matching.chance_match_density_formula	pi * tau_pre^2 / 12 * mark_density
matching.cm_per_unit_for_print	35

matching.compatible_types	['scratch', 'scuff', 'chip']
matching.counter_looks_max	8
matching.hood_mask_iou_min	0.8
matching.margin_min_tau_pre_factor	0.5
matching.mask_iou_min	0.7
matching.next_keyframe_pair	True
matching.one_walk_counter_look	True
matching.pseudo_pair_percentile	90
matching.pseudo_pair_share_min	0.9
matching.ratio_test_min	1.5
matching.reshape_aspect_tol	0.02
matching.reshape_blob_share_min	0.5
matching.reshape_iou_min	0.5
matching.reshape_open_px	5
matching.reshaped_panel	True
matching.sharpness_rel_min	0.4
matching.sigma_spark	0.117
matching.size_cost_factor	0.1
matching.tau_eye_factor	2.0
matching.tau_pre0_floor	0.25
matching.tau_pre0_sigma_factor	3.535534
matching.tau_pre_cap	0.4
matching.tight_pair_k5	True
matching.tight_pair_second_look	True
matching.type_cost_compatible	0.1
matching.type_cost_incompatible	0.4
matching.wheel_min_marks_for_shift	2
matching.wheel_radius_tolerance	0.1
matching.wheel_size_factor_max	2.0
media.anchor_clip_frames	180
media.anchor_clip_half_window_s	6.0
media.chunk_bytes	8388608
media.chunk_route_max_body_bytes	9437184
media.chunks_in_flight	3
media.clip_crf	18
media.clip_frames	91
media.clip_half_window_s	1.5
media.clip_prompt_frame	45
media.clip_size_px	1008
media.files_expires_after_s	3600
media.inline_data_url_max_bytes	52428800
media.other_route_max_body_bytes	1048576
media.proxy_codec	libx264
media.proxy_crf	20
media.proxy_fps	15
media.proxy_fps_fallbacks	[10, 30]
media.proxy_max_edge	960
media.proxy_preset	medium

media.source_fps_assumed	30
media.upload_max_bytes	1073741824
media.upload_warn_bytes	524288000
media.wav_rate	24000
nouns.d1_text_prompts	['scuff']
nouns.door_handle_image_requests_per_pair	24
nouns.image_only	['door handle']
nouns.lanes	['car', 'license plate', 'face', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window']
nouns.never_prompt	['front bumper', 'rear bumper']
nouns.privacy	['license plate', 'face']
nouns.topup_always	['car', 'license plate', 'face']
nouns.voice_keywords	['car', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window', 'scuff', 'scratch', 'chip', 'dent', 'crack', 'tape', 'odometer']
orchestrator.baseten_rpm	30
orchestrator.baseten_semaphore	1
orchestrator.caps_if_no_card_ceiling.pair_runs_per_day	0
orchestrator.caps_if_no_card_ceiling.pickup_runs_per_day	3
orchestrator.daily_card_ceiling_cents	5000
orchestrator.decode_workers	2
orchestrator.health_probe_failures_to_pause	3
orchestrator.health_probe_interval_s	300
orchestrator.judging_card_ceiling_cents	5000
orchestrator.max_concurrent_runs	2
orchestrator.media_workers	2
orchestrator.pair_runs_per_day	1
orchestrator.pdf_timeout_s	60
orchestrator.pickup_runs_per_day	6
orchestrator.priority_wave_size	6
orchestrator.queue_eta_from_last_runs	3
orchestrator.rate_limit_backoff_base_s	0.5
orchestrator.rate_limit_retries	6
orchestrator.replay_fixed_total_s_estimate	35
orchestrator.replay_recorded_delay_cap_ms	2000
orchestrator.request_retries	1
orchestrator.request_timeout_s	240
orchestrator.run_deadline_s	720
orchestrator.run_spend_ceiling_cents	800
orchestrator.sam_image_semaphore	16
orchestrator.sam_video_semaphore_global	32
orchestrator.sam_video_semaphore_per_run	16
orchestrator.spark_semaphore	12
orchestrator.sse_ping_s	15
orchestrator.sweeper_interval_s	3600
orchestrator.volume_min_free_bytes	524288000

panels.anchor_absorb_iou_min	0.5
panels.anchor_max_frames_per_panel	3
panels.anchor_negative_point_seam_offset_box_widths	0.1
panels.anchor_pass_coverage_below	0.7
panels.area_floor_default	0.02
panels.area_floor_small	0.005
panels.border_frac_keyframe_max	0.15
panels.c_floor	None
panels.car_box_containment_min	0.8
panels.car_mask_containment_min	0.8
panels.crop_long_edge_px	1280
panels.crop_pad_frac	0.1
panels.direction_min_px_per_frame	2.0
panels.direction_phase_corr	False
panels.fast_mask_decode	True
panels.fragment_gap_split_frames	2.5
panels.fragment_gap_split_s	0.5
panels.fragment_min_frames	2
panels.fragment_min_s	0.5
panels.glare_s_max	40
panels.glare_v_min	250
panels.keyframe_box_pass_candidates	9
panels.keyframe_decode_budget_s_per_video	60
panels.keyframe_min_gap_s	0.5
panels.keyframe_panels_in_flight	4
panels.keyframe_score_exponents.area	1.0
panels.keyframe_score_exponents.completeness	1.0
panels.keyframe_score_exponents.frontality	1.0
panels.keyframe_score_exponents.one_minus_glare	1.0
panels.keyframe_score_exponents.sharpness	1.0
panels.keyframe_top_k	3
panels.keyframe_top_k_under_budget	2
panels.merge_area_ratio	[0.6, 1.6]
panels.merge_aspect_tolerance	0.2
panels.merge_gap_max_s	1.0
panels.merge_pred_dist_box_widths	0.5
panels.prompt_box_pad_px	2
panels.side_vote_margin_min	1
panels.side_vote_weights.R1	2
panels.side_vote_weights.R2	1
panels.side_vote_weights.R3	1
panels.side_vote_weights.R4	1
panels.small_nouns	['side mirror', 'headlight', 'tail light', 'license plate', 'face']
panels.twin_check.adjacent_lid_sizes	0.25
panels.twin_check.margin_min	3
panels.twin_check.min_frames	5
panels.twin_check.mirror_far_lid_sizes	1.5
panels.twin_check.mirror_near_lid_sizes	1.0

panels.twin_check.neighbour_majority	2.0
panels.twin_check.neighbour_share_min	0.5
panels.twin_check.photo_margin_min	2
panels.twin_check.plate_inside_min	0.8
panels.twin_check.plate_share_min	0.5
panels.twin_check.presence_margin	0.4
panels.twin_check.weights.glass	1
panels.twin_check.weights.lights	1
panels.twin_check.weights.mirror	2
panels.twin_check.weights.plate	2
privacy.box_blocks_across	4
privacy.files_delete_retries	3
privacy.image_check_nouns	['license plate', 'face']
privacy.image_checks_in_flight	16
privacy.keep_plate_default	False
privacy.pixel_block_px_at_4k	20
privacy.run_retention_hours	24
privacy.track_box_dilation_frac	0.1
privacy.track_box_dilation_px	24
privacy.track_box_union_s	0.1
privacy.track_carry_fit_s	0.4
privacy.track_carry_grow_per_s	0.5
privacy.track_carry_s	3.0
privacy.track_carry_speed_max_frac_per_s	1.0
privacy.track_flow_cover_max_frac	0.1
privacy.track_flow_cover_path	True
privacy.track_flow_grow_per_s	0.2
privacy.track_gap_bridge_s	0.5
privacy.unblurred_temp_max_minutes	30
ruler.axis_tilt_correction_max_deg	30
ruler.body_scuff_ordinary_wear	True
ruler.bound_px_per_side	2
ruler.camera_hfov_deg	70
ruler.d1_plate_wheel_ppi_agreement	0.15
ruler.mark_min_px	8
ruler.plate_c_min	0.5
ruler.plate_hw_min	0.35
ruler.plate_long_side_in	12
ruler.plate_min_px	60
ruler.plate_tilt_max_deg	30
ruler.ruler_max_distance_m	0.6
ruler.threshold_body_scratch_in	3.5
ruler.threshold_dent_in	1.0
ruler.threshold_wheel_in	1.0
ruler.tire_diameter_formula	D = 2 * (SW * AR / 2540 + RD / 2)
ruler.view_flag_sizes	True
ruler.wheel_c_min	0.5
ruler.wheel_min_px	120

sheet.footage_credit	True
spark.confidence_levels	['low', 'medium', 'high']
spark.d1_jaccard_pass	0.7
spark.d1_sigma_pass_frac_of_crop_width	0.02
spark.effort	low
spark.grid	1000
spark.grid_slack	20
spark.image_long_edge_px	1280
spark.input_tokens_per_1280_crop_estimate	1400
spark.jpeg_quality	90
spark.landmarks.bumper	['plate_corner_tl', 'plate_corner_tr', 'plate_corner_bl', 'plate_corner_br', 'fog_lamp', 'grille_corner', 'sensor']
spark.landmarks.door	['handle', 'lock', 'mirror_base', 'window_front_corner', 'window_rear_corner', 'wheel_arch', 'lower_trim', 'badge']
spark.landmarks.hood	['badge', 'washer_nozzle', 'front_corner_left', 'front_corner_right']
spark.landmarks.wheel	['hub', 'rim_lip', 'valve']
spark.landmarks_max	4
spark.mark_types	['scratch', 'scuff', 'chip', 'dent', 'crack', 'dirt', 'reflection', 'unsure']
spark.max_output_tokens	4000
spark.model	muse-spark-1.3
spark.retry_max_output_tokens	8000
spark.schema_names	['marks_v1', 'count_v1', 'look_v1', 'seed_v1', 'claim_name_v1', 'timeline_v1', 'note_prefill_v1']
spark.schema_retry_count	1
spark.second_look_engine	spark_open
spark.second_looks_per_pair_max	25
spark.size_classes	['S', 'M', 'L']
spark.store	False
spark.stream_when_expected_over_s	30
staysput.b1_floor	0.15
staysput.b2_floor	0.05
staysput.cap_enabled	False
staysput.check_box_covered_min	0.9
staysput.clip_blur_dilation_frac	0.3
staysput.clip_frames_max	181
staysput.control_blob_max_frac	0.15
staysput.control_blob_min_px	9
staysput.curvature_boundary_units	0.15
staysput.d1_pass_box_share	0.8
staysput.d1_pass_drift_max	0.08
staysput.d1_reflection_drift_min	0.16
staysput.highlight_s_percentile	10
staysput.highlight_v_percentile	95
staysput.max_clips_per_walk	16
staysput.max_objects_per_clip	16
staysput.min_bbox_px_at_4k	12

staysput.min_drift_frames	10
staysput.neighbour_dedupe_iou	0.5
staysput.neighbour_fixed_below	1.5
staysput.neighbour_handle_half_h_frac	0.02
staysput.neighbour_handle_half_w_frac	0.08
staysput.neighbour_mark_min_clip_px	16
staysput.neighbour_near_half_window_s	0.5
staysput.neighbour_part_max_window_frac	0.5
staysput.neighbour_residual_floor_px	0.5
staysput.neighbour_sliding_above	2.5
staysput.neighbour_track_share_min	0.8
staysput.neighbour_window_margin	1.15
staysput.neighbour_window_max_growth	2.0
staysput.neighbour_window_max_panel_frac	1.5
staysput.neighbours_enabled	True
staysput.neighbours_max	12
staysput.neighbours_min	4
staysput.neighbours_target	6
staysput.no_track_box_share_below	0.8
staysput.panned_inconclusive_share_caption_threshold	0.5
staysput.reflection_control_from_hood_glare	True
staysput.sign_agreement_min	0.8
staysput.sign_pair_gap_frames	5
staysput.sign_pairs_min	8
staysput.sign_panel_dx_min_px_per_frame	2.0
staysput.sliding_factor	2.0
staysput.tau_fix_floor	0.08
staysput.tau_fix_sigma_factor	3.0
staysput.window_frac_of_panel_width	0.3
staysput.window_mark_margin	1.5
staysput.window_min_px	400
staysput.window_share_overlap_min	0.5
voice.chip_min_ms	100
voice.max_audio_s	600
voice.max_body_bytes	33554432
voice.mode	ENDPOINTING
voice.model	muse-voice-transcribe-1.0
voice.modes_allowed	['PUSH_TO_TALK', 'ENDPOINTING', 'DIARIZATION']
voice.pin_fallback	turn_start_panel
voice.seeds_per_walk_max	16

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

Appendix A certification

```
Renter's certification

I, [name], state that:
1. I recorded the videos listed below myself, at pickup on [date] and at return on [date], of the vehicle
under
   rental agreement [number].
2. I uploaded them to Walkaround without editing them, and the sha256 hashes on page 1 match the files on
my phone.
3. I understand this sheet is evidence support, not legal advice, and that it was produced by code from
my videos.

- pickup: t15759_pre.mp4 (sha256 0f6124176157...)
- return: t15759_post.mp4 (sha256 a157a4a7483b...)

Signed: _____________________   Date: ____________

This is a signed statement, not a notarized affidavit.
```

Appendix B glossary

```
Glossary

already there: the same mark was found at pickup within tau_pre of its return position (rule L3).
needs your eye: a human should look; the pair sat in the band between tau_pre and tau_eye, or a cap (K1
to K15) applied (L4).
new or unseen: a return mark with no pickup mark near it; new, or not filmed at pickup (L2).
not seen at return: a pickup mark with no return mark near it (L1).
not comparable: a panel gate failed (G1, G3 to G10); both best frames still show with the reason (L6).
view flagged: Muse Spark said a frame shows water, dirt or glare. That is a model's judgment, so it no
longer blocks a panel (gate G2 did that until Oct 31). A mark seen in one walk only is capped at needs
your eye (K15); a mark in the same place in both walks keeps its label, with a note.
tight pair: a pair inside tau_pre is already there because the mark sits in the same place in both walks,
whatever Muse Spark called it. So Spark's type (dirt, reflection or unsure, K4), the two types
disagreeing (K5) and its low confidence (K12) are notes on that pair, and the second look compares the
two crops and may lower it (K7). If the second look gives no answer, K4, K5 and K12 cap the pair at needs
your eye as before. A mark seen in one walk only, or a pair in the band, keeps them as caps.
keyframe pair: each panel is compared on one pickup keyframe and one return keyframe. When that pair
fails a gate of the pair (G3, G4, G5, G8 or G9), the panel's other keyframe pairs are tried in a fixed
order (clean views first, then the two keyframe scores, then keyframe number) and the first that passes
every gate is used. The panel page says which pair was used and what each pair tried failed. G1, G6, G7
and G10 belong to the panel, so no other pair can pass them.
outline changed in place: a panel that fails only the mask IoU gate (G4) on every keyframe pair tried,
with the best IoU from 0.5 to under 0.7, is needs your eye (L7) instead of not comparable when the two
keyframes' box shapes agree within 2% and the outline difference sits in one place (its largest blob
holds at least half of it). A turned camera changes the box shape or spreads the difference along the
whole outline; a crushed panel does neither. No marks are compared, so it never says already there or
new.
counter-look: a mark seen in one walk only would be new or unseen (or not seen at return) on distance
alone. If no cap already lowers it, the second look is shown the mark in its own walk and the other
walk's view of the same panel with the spot where it would sit outlined (carried through the panel
frame). If the look says the same mark shows there, or is unsure, it is needs your eye (K16, the other
walk may show it); if it says different, or gives no answer, the label stands. A model can only lower a
label.
units: panel-normalized distance; 1 unit is about 35 cm along a door (the about-cm beside it uses that).
tau_pre, tau_eye: the two distance thresholds, calibrated from the run's own repeat frames; printed on
the method page.
Stays Put: a check that a mark moves with the panel through a short clip; a reflection slides, a scratch
stays put.
sha256: the fingerprint of a file; one changed byte changes it.
sealed: the manifest of hashes was written and offered for time stamping before any model saw the video.
config hash: the fingerprint of every threshold the code used; it changes when a threshold changes.
rule id: the row of the decision table that produced a label; G gates a panel, K caps a mark, L names a
label, E is a claim exit.
```

Appendix C verify it yourself

```
Verify it yourself (5 steps; none needs Walkaround's server)

1. Hash the video file on your phone or computer and compare it with page 1:
   shasum -a 256 <your video file>     (Linux: sha256sum <your video file>)
   pickup: 0f612417615726cf0bc5d0662a5373cdf92cd2defc7329e063685580a2fd04ed
   return: a157a4a7483b7540d1f4e133c1b69d7f51deeca9360336e96004e64fea2a7fed
2. Read the OpenTimestamps proof (pip install opentimestamps-client):
   ots info bundle/manifest.json.ots
3. Verify it against the Bitcoin block, or drop the .ots file on https://opentimestamps.org :
   ots verify bundle/manifest.json.ots
4. Verify the RFC 3161 token from freetsa (2026-11-01T07:15:41Z) with freetsa's certificates (download
https://freetsa.org/files/cacert.pem and https://freetsa.org/files/tsa.crt):
   openssl ts -verify -data bundle/manifest.json -in bundle/manifest.json.tsr -CAfile cacert.pem -
untrusted tsa.crt
5. Re-hash every file in the bundle and rebuild the derived files from the stored model answers:
   walkaround verify eval_nhtsa15759_r6
```

Letter: write to the company first

```
Write to the company first

[date]

To: [rental company], damage claims
Re: rental agreement [number], picked up [date], returned [date]

I received a damage charge of [amount] for [description]. Before anything else I ask for the full damage
report,
the written repair estimate and every photograph or scan the company holds for this rental, including the
pickup
inspection images. Hertz's own support page says customers can request more images.

I recorded a walkaround video at pickup and at return. The files were hashed and sealed before any
analysis:
- pickup: t15759_pre.mp4, 36444009 bytes, sha256
0f612417615726cf0bc5d0662a5373cdf92cd2defc7329e063685580a2fd04ed, camera time not present, received 2026-
11-01T07:15:35.071Z
- return: t15759_post.mp4, 58523935 bytes, sha256
a157a4a7483b7540d1f4e133c1b69d7f51deeca9360336e96004e64fea2a7fed, camera time not present, received 2026-
11-01T07:15:35.136Z
- sealed at 2026-11-01T07:15:35.289Z
- Walkaround run eval_nhtsa15759_r6; the panel-by-panel evidence sheet is attached
- the frames on the sheet: Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759,
15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-
multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA
does not endorse this project. Plates and faces blurred.

The attached sheet shows the panel in question at pickup and at return with the marks drawn on both
frames. The
sheet is evidence support, not legal advice, and I ask that it be read next to your own images.

If the charge stands after you have reviewed it, I will obtain an alternative written estimate within 10
business
days. Card network rules (Visa Core Rules 13.3 and 13.5; 15 USC 1666i) require that I first try to
resolve the
charge with you; this letter is that attempt. Please reply within 14 days to [email].

[name]
```

Walkaround run eval_nhtsa15759_r6. Crash test photos and video: NHTSA Vehicle Crash Test Database, tests 15759, 15637 and 15641, https://nrd.api.nhtsa.dot.gov/nhtsa/vehicle/api/v1/vehicle-database-test-results/get-multimedia-files/15759 (same path for the others), public information under NHTSA's terms of use. NHTSA does not endorse this project. Plates and faces blurred.

0f6124176157 / a157a4a7483b