Walkaround evidence sheet

Two walkaround videos of one rental car, compared panel by panel. Code decides every verdict; a model answer can only lower one.

evidence support, not legal advice

This run's verdicts recomputed on Nov 2, 2026 with this version's rules (code d44edde) from the model answers stored on Nov 2, 2026 by run hero_focus5; no new model calls.

Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

run id	`hero_focus5b`
app commit	`d44edde7dee1e2fa2a0eeeba11abe5d0e8210775`
config hash	`f9bb1ca339d97887886fe182bb4dd4a02f079cfd799565057148412f8277a775`
events head hash	`cf9ed4b1714e80a397ea8af8c1d2e81a34e39a10b3ba8aacdc7c165a9a87e682`
rental agreement number	_____ (fill in)
plate	plate blurred

The three clocks

sealed at
2026-11-02T23:42:53.709Z

first model call at
2026-11-02T23:43:16Z

sealed after the camera time
sealed 236 minutes after the camera time

Originals

walk	file	bytes	sha256	camera says	received	hash on your phone = hash on receipt	proven to exist by
pickup	IMG_2678.mov	58008058	`0b1d3a373eeccd030eb8cc1eeadfa408d929a48cbabcf2f90481923bf4eca2cf`	2026-11-02T19:46:29Z	2026-11-02T23:42:53.536Z	match	2026-11-02T23:42:57Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)
return	IMG_2679.mov	37568726	`cc683f02ad13d63d148fb5568724560f5c35e3d15202edcf7a21609cc23024f3`	2026-11-02T19:50:42Z	2026-11-02T23:42:53.575Z	match	2026-11-02T23:42:57Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)

Privacy

Processed with Meta's Model API in Standard mode, which Meta's documentation says is not used to train Meta models. Uploads were set to expire after one hour and were deleted by Walkaround when the run ended. Model requests were sent with storage off. Meta's terms allow it to retain content for abuse review and legal reasons; Walkaround does not control that. SAM 3.1 saw the unblurred proxy for the length of one segmentation pass to find the plates and faces it then blurred. For the second look, two blurred crops per look were sent to Muse Spark Open on Baseten, a company separate from Meta; no video went there.

Files API upload deleted: 2026-11-02T23:55:14.219Z. Stored responses deleted: none stored or not yet. Quarantine (unblurred originals) deleted: 2026-11-02T23:55:14.219Z.

What to do with this sheet

1. Start with the dated pickup frames in this sheet: the camera says 2026-11-02T19:46:29Z, the file was received 2026-11-02T23:42:53.536Z, and the file hashes (0b1d3a373eec, cc683f02ad13) are on page 1 and in the sealed manifest.
2. Ask the company in writing for the full damage report, the repair estimate and every image it holds for this rental, including the pickup inspection images; Hertz says customers can request more images.
3. Get an alternative written estimate from a body shop within 10 business days; card network rules compare two quotes (Visa Core Rules Table 5-19; Amex allows up to 115% of the estimate).
4. If the company does not answer, escalate to a named executive and file a complaint with your state consumer protection office; the one sourced renter win came by executive escalation with the company's own scans.
5. Last, the card dispute, with its clocks: 60 days from the statement under Regulation Z 1026.13, 120 days under Visa's rules, and the $50 cap of 15 USC 1666i; a dispute does not stop collections, so keep the paper trail.

Coverage per walk

pickup

- left front door: filmed, 16.5 s
- left rear door: filmed, 15.9 s
- right front door: filmed, 24.8 s
- right rear door: filmed, 23.1 s
- left front fender: filmed, 15.5 s
- left rear fender: not_filmed
- right front fender: filmed, 8.9 s
- right rear fender: filmed, 12.7 s
- hood: filmed, 38.3 s
- roof: glimpsed, 3.1 s
- trunk lid: filmed, 10.3 s
- front bumper: filmed, 33.1 s
- rear bumper: filmed, 11.3 s
- left front wheel: filmed, 15.5 s
- left rear wheel: not_filmed
- right front wheel: filmed, 8.9 s
- right rear wheel: filmed, 12.7 s
- headlights: filmed, 33.3 s
- tail lights: filmed, 11.7 s
- mirrors: filmed, 31.1 s
- windshield: filmed, 40.9 s
- rear window: filmed, 12.0 s
- missing at pickup: right front wheel, right front fender, roof
- top-up asked: Film these again, in this order: right front wheel (not filmed); right front fender (not filmed); roof (glimpsed, 2.5 s). The app then re-runs 9 of 16 nouns: wheel, fender, roof, headlight, tail light, side mirror, car, license plate, face. Also film the odometer once.

return


- left front door: filmed, 11.2 s
- left rear door: filmed, 10.9 s
- right front door: filmed, 17.5 s
- right rear door: filmed, 13.0 s
- left front fender: filmed, 10.5 s
- left rear fender: filmed, 5.2 s
- right front fender: not_filmed
- right rear fender: filmed, 9.5 s
- hood: filmed, 23.3 s
- roof: glimpsed, 2.5 s
- trunk lid: filmed, 9.0 s
- front bumper: filmed, 19.5 s
- rear bumper: filmed, 9.8 s
- left front wheel: filmed, 10.5 s
- left rear wheel: filmed, 5.2 s
- right front wheel: not_filmed
- right rear wheel: filmed, 9.5 s
- headlights: filmed, 20.8 s
- tail lights: filmed, 9.5 s
- mirrors: filmed, 19.9 s
- windshield: filmed, 24.9 s
- rear window: filmed, 9.1 s

left front door

coverage: pickup 16.5 s (filmed); return 11.2 s (filmed)



pickup: video time 4.80 s; wall clock 2026-11-02T19:46:33Z; marks pickup_left_front_door_kf1_m1, pickup_left_front_door_kf1_m2, pickup_left_front_door_kf1_m3, pickup_left_front_door_kf1_m4



return: video time 3.53 s; wall clock 2026-11-02T19:50:45Z; marks return_left_front_door_kf1_m1, return_left_front_door_kf1_m2, return_left_front_door_kf1_m3

how it was checked: compared on keyframes pickup_left_front_door_kf1 with return_left_front_door_kf1, the first pair tried; registration pickup_left_front_door_kf1 onto return_left_front_door_kf1 by matched edges and the outline (mask IoU 0.91, 24 of 45 matched points agree); pickup_left_front_door_kf1_m1: not at its spot in the return crop (NCC 0.34); recorded only; 2 marks could not be checked at their spot; pickup_left_front_door_kf1_m4: its box does not stand out from the paint around it in its own crop (contrast 1.5), so it is left off the list (K20)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_left_front_door_kf1_m2, return_left_front_door_kf1_m1` `scuff S`	already there	L3	0.10 units, about 4 cm	Stays Put: drift 0.01, b1 0.19, b2 0.12, not panned; neighbour test: moves with its 4 neighbours, 0.6x their wobble over the clip and 0.2x within 0.5 s; fixed; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26). pickup view flagged dirty: the mark is in the same place in both walks, so it was there at pickup, whatever it is

pickup_left_front_door_kf1_m3, return_left_front_door_kf1_m2 scratch S	already there	L3	0.05 units, about 2 cm	Stays Put: drift 0.06, b1 0.19, b2 0.12, not panned; neighbour test: 0.6x its 4 neighbours' wobble over the clip and 1.9x within 0.5 s; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark pickup view flagged dirty: the mark is in the same place in both walks, so it was there at pickup, whatever it is
pickup_left_front_door_kf1_m1 scuff S	needs your eye	L4, L1, K15	no pair	Stays Put: drift 0.04, b1 0.19, b2 0.12, not panned; neighbour test: moves with its 4 neighbours, 0.3x their wobble over the clip and 0.1x within 0.5 s; fixed; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26). pickup view flagged dirty: could be dirt
return_left_front_door_kf1_m3 scratch S	needs your eye	L4, L2, K15	no pair	Stays Put: drift 0.06, b1 0.23, b2 0.17, not panned; neighbour test: 1 neighbour tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark pickup view flagged dirty: could have hidden the mark


L3 already there: d < tau_pre_r
L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
L1 not seen at return: d is None for a pickup mark: not_seen_at_return
K15 view flagged: Muse Spark flagged the pickup or return view of the panel wet, dirty or glare, so a mark seen in one walk only may be dirt, water or a reflection, or may have been hidden in the other walk; a mark in the same place in both walks keeps its label with a note
L2 new or unseen: d is None for a return mark: new_or_unseen

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins


0b1d3a373eec / cc683f02ad13

left rear door

coverage: pickup 15.9 s (filmed); return 10.9 s (filmed)



pickup: video time 0.00 s; wall clock 2026-11-02T19:46:29Z



return: video time 3.27 s; wall clock 2026-11-02T19:50:45Z

how it was checked: compared on keyframes pickup_left_rear_door_kf1 with return_left_rear_door_kf1, the first pair tried

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right front door

coverage: pickup 24.8 s (filmed); return 17.5 s (filmed)



pickup: video time 39.53 s; wall clock 2026-11-02T19:47:08Z



return: video time 24.13 s; wall clock 2026-11-02T19:51:06Z

how it was checked: compared on keyframes pickup_right_front_door_kf1 with return_right_front_door_kf1, the first pair tried

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right rear door

coverage: pickup 23.1 s (filmed); return 13.0 s (filmed)



pickup: video time 40.07 s; wall clock 2026-11-02T19:47:09Z; marks pickup_right_rear_door_kf1_s1



return: video time 25.13 s; wall clock 2026-11-02T19:51:07Z; marks return_right_rear_door_kf1_m1

how it was checked: compared on keyframes pickup_right_rear_door_kf1 with return_right_rear_door_kf1, the first pair tried; second marks pass: looked again at pickup_right_rear_door_kf1 around return_right_rear_door_kf1_m1: found pickup_right_rear_door_kf1_s1; registration pickup_right_rear_door_kf1 onto return_right_rear_door_kf1 by matched edges and the outline (mask IoU 0.97, 44 of 69 matched points agree); return_right_rear_door_kf1_m1: not at its spot in the pickup crop (NCC 0.25); recorded only; 1 mark could not be checked at its spot

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_rear_door_kf1_s1` `unsure S`	**needs your eye**	L4, L5, K12, K3, K4	no pair	size not stated: no ruler within 0.6 m of this mark
`return_right_rear_door_kf1_m1` `scuff S`	**new or unseen**	L5	no pair	Stays Put: drift 0.05, b1 0.33, b2 0.01, not panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26). the second look saw damage in the box (2 of 3 answers) and not at the same spot in the pickup walk (3 of 3 answers), so the label stands

L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
L5 beyond the band: d >= tau_eye_r: both marks keep their unmatched labels
K12 low confidence: Spark confidence low on either mark
K3 tiny mark: size under 0.03 units or bbox under 12 px
K4 uncertain type: type dirt, reflection or unsure

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins	`0b1d3a373eec / cc683f02ad13`

left front fender

coverage: pickup 15.5 s (filmed); return 10.5 s (filmed)



pickup: video time 5.07 s; wall clock 2026-11-02T19:46:34Z



return: video time 4.00 s; wall clock 2026-11-02T19:50:46Z

how it was checked: compared on keyframes pickup_left_front_fender_kf1 with return_left_front_fender_kf1; tried first: pickup_left_front_fender_kf1 with return_left_front_fender_kf2 (G4 mask IoU 0.52)

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

left rear fender

coverage: pickup 0.0 s (not_filmed); return 5.2 s (filmed)

no pickup frame for this panel



return: video time 0.00 s; wall clock 2026-11-02T19:50:42Z; marks return_left_rear_fender_kf1_m1, return_left_rear_fender_kf2_m2

Verdicts

marks	verdict	rule ids	distance	detail
`return_left_rear_fender_kf1_m1, return_left_rear_fender_kf2_m2` `chip S`	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right front fender

coverage: pickup 8.9 s (filmed); return 0.0 s (not_filmed)



no return frame for this panel

pickup: video time 35.27 s; wall clock 2026-11-02T19:47:04Z; marks pickup_right_front_fender_kf1_m2, pickup_right_front_fender_kf1_m1

how it was checked: left out: pickup_right_front_fender_kf1_m1 sits 5.5% of the crop's long side off the right front fender and on no other panel tracked in that frame, so it was not matched

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_front_fender_kf1_m2` `chip S`	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right rear fender

coverage: pickup 12.7 s (filmed); return 9.5 s (filmed)



pickup: video time 42.33 s; wall clock 2026-11-02T19:47:11Z; marks pickup_right_rear_fender_kf1_m1



return: video time 25.60 s; wall clock 2026-11-02T19:51:07Z; marks return_right_rear_fender_kf1_m1

how it was checked: not compared: keyframes pickup_right_rear_fender_kf1 with return_right_rear_fender_kf1 (G4 mask IoU 0.69, the registration did not vouch: the fit was refused (mask IoU after the warp 0.83)), and the panel has no other keyframe pair; not called reshaped: keyframes pickup_right_rear_fender_kf1 with return_right_rear_fender_kf1, IoU 0.69, box aspect ratios 2.090 and 2.038 (2.5% apart), largest blob 42% of the mask difference

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_rear_fender_kf1_m1, return_right_rear_fender_kf1_m1` `chip S`	**not comparable**	L6, G4	no pair	Stays Put: drift 0.16, b1 0.22, b2 0.09, not panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label


L6 not comparable: a G rule failed for the panel; both best frames still show
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

hood

coverage: pickup 38.3 s (filmed); return 23.3 s (filmed)



pickup: video time 22.13 s; wall clock 2026-11-02T19:46:51Z; marks pickup_hood_kf1_m1, pickup_hood_kf1_m2, pickup_hood_kf1_m3, pickup_hood_kf1_m4, pickup_hood_kf1_m5, pickup_hood_kf1_m6, pickup_hood_kf1_m7, pickup_hood_kf1_m8, pickup_hood_kf1_m9, pickup_hood_kf1_m10, pickup_hood_kf1_m11, pickup_hood_kf1_m12, pickup_hood_kf1_m13, pickup_hood_kf1_m14, pickup_hood_kf2_m1



return: video time 12.27 s; wall clock 2026-11-02T19:50:54Z; marks return_hood_kf1_m1

how it was checked: compared on keyframes pickup_hood_kf2 with return_hood_kf2, the first pair tried; registration pickup_hood_kf2 onto return_hood_kf2 by matched edges and the outline (mask IoU 0.98, 39 of 61 matched points agree); pickup_hood_kf1_m3: the return crop shows the same patch at its spot (NCC 0.81) and no mark there, so needs your eye (K18); pickup_hood_kf1_m5: the return crop shows the same patch at its spot (NCC 0.84) and no mark there, so needs your eye (K18); pickup_hood_kf1_m8: the return crop shows the same patch at its spot (NCC 0.94) and no mark there, so needs your eye (K18); pickup_hood_kf1_m9: the return crop shows the same patch at its spot (NCC 0.96) and no mark there, so needs your eye (K18); pickup_hood_kf1_m11: the return crop shows the same patch at its spot (NCC 0.97) and no mark there, so needs your eye (K18); pickup_hood_kf1_m13: the return crop shows the same patch at its spot (NCC 0.78) and no mark there, so needs your eye (K18); 5 marks could not be checked at their spot; same walk: pickup_hood_kf1_m1 is pickup_hood_kf2_m1 seen again in pickup_hood_kf1 (registered onto pickup_hood_kf2, features); pickup_hood_kf1_m2 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m3 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m4 is pickup_hood_kf1_m3 seen again in pickup_hood_kf1 (registered onto pickup_hood_kf2, features); pickup_hood_kf1_m5 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m6 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m7 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m8 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m9 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m10 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m11 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m12 is pickup_hood_kf2_m1 seen again in pickup_hood_kf1 (registered onto pickup_hood_kf2, features); pickup_hood_kf1_m13 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); pickup_hood_kf1_m14 carried from pickup_hood_kf1 onto pickup_hood_kf2 (features); return_hood_kf1_m1 carried from return_hood_kf1 onto return_hood_kf2 (features); pickup_hood_kf1_m2: its box does not stand out from the paint around it in its own crop (contrast 0.6), so it is left off the list (K20); pickup_hood_kf1_m6: its box does not stand out from the paint around it in its own crop (contrast 0.7), so it is left off the list (K20); pickup_hood_kf1_m7: its box does not stand out from the paint around it in its own crop (contrast 0.2), so it is left off the list (K20); pickup_hood_kf1_m10: its box does not stand out from the paint around it in its own crop (contrast 1.2), so it is left off the list (K20); pickup_hood_kf1_m14: its box does not stand out from the paint around it in its own crop (contrast 0.6), so it is left off the list (K20)

Check by eye: debris on this panel; check by eye (6 spots Muse Spark typed dirt, not listed one by one)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_hood_kf2_m1, return_hood_kf1_m1` `dirt M`	already there	L3	0.20 units, about 7 cm	size not stated: no ruler within 0.6 m of this mark; no license plate measured on that frame pickup view flagged dirty, return view flagged dirty and glare: the mark is in the same place in both walks, so it was there at pickup, whatever it is Muse Spark typed the pickup mark dirt and the return mark scratch (K4), two kinds that disagree (K5): a note here, since the mark sits in the same place in both walks and the

second look compared the two crops and said same (2 of 2 answers)

L3 already there: d < tau_pre_r

Groups

- 2 dirt marks here at pickup, 0 at return, 0 new or unseen

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins


`0b1d3a373eec / cc683f02ad13`

roof

coverage: pickup 3.1 s (glimpsed); return 2.5 s (glimpsed)



pickup: video time 26.13 s; wall clock 2026-11-02T19:46:55Z; marks pickup_roof_kf1_m1, pickup_roof_kf1_m2, pickup_roof_kf1_m3, pickup_roof_kf1_m4



return: video time 30.93 s; wall clock 2026-11-02T19:51:12Z; marks return_roof_kf1_m1, return_roof_kf1_m2, return_roof_kf2_m1, return_roof_kf2_m2

how it was checked: not compared: keyframes pickup_roof_kf1 with return_roof_kf2 (G1 not filmed, G4 mask IoU: not measured, G6 side uncertain); G1 and G6 are panel gates, so no other pair was tried

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_roof_kf1_m1, pickup_roof_kf1_m2, pickup_roof_kf1_m3, pickup_roof_kf1_m4, return_roof_kf1_m1, return_roof_kf1_m2, return_roof_kf2_m1, return_roof_kf2_m2` dirt S	not comparable	L6, G1, G4, G6	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G6 side uncertain: side_uncertain, or front_sign null, on either walk

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

trunk lid

coverage: pickup 10.3 s (filmed); return 9.0 s (filmed)



pickup: video time 51.07 s; wall clock 2026-11-02T19:47:20Z



return: video time 33.87 s; wall clock 2026-11-02T19:51:15Z

how it was checked: compared on keyframes pickup_trunk_lid_kf1 with return_trunk_lid_kf1, the first pair tried

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

front bumper



pickup: video time 20.80 s; wall clock 2026-11-02T19:46:49Z; marks pickup_front_bumper_kf1_m1, pickup_front_bumper_kf1_m2, pickup_front_bumper_kf1_m3, pickup_front_bumper_kf2_m1, pickup_front_bumper_kf2_m3, pickup_front_bumper_kf2_m4, pickup_front_bumper_kf2_m5



return: video time 12.27 s; wall clock 2026-11-02T19:50:54Z; marks return_front_bumper_kf1_m1, return_front_bumper_kf1_m2, return_front_bumper_kf1_m3, return_front_bumper_kf1_m4

coverage: pickup 33.1 s (filmed); return 19.5 s (filmed)

how it was checked: compared on keyframes pickup_front_bumper_kf3 with return_front_bumper_kf1, the first pair tried; registration pickup_front_bumper_kf3 onto return_front_bumper_kf1 by the panel outline (mask IoU 0.92, 40 of 227 matched points agree); registration pickup_front_bumper_kf2 onto return_front_bumper_kf1 by the panel outline (mask IoU 0.69, 2 of 69 matched points agree), refused: mask IoU after the warp 0.69; 7 marks could not be checked at their spot; same walk: pickup_front_bumper_kf1_m1 carried from pickup_front_bumper_kf1 onto pickup_front_bumper_kf3 (features); pickup_front_bumper_kf1_m2 carried from pickup_front_bumper_kf1 onto pickup_front_bumper_kf3 (features); pickup_front_bumper_kf1_m3 carried from pickup_front_bumper_kf1 onto pickup_front_bumper_kf3 (features);
pickup_front_bumper_kf1_m2: its box does not stand out from the paint around it in its own crop (contrast 0.7), so it is left off the list (K20);
pickup_front_bumper_kf1_m3: its box does not stand out from the paint around it in its own crop (contrast 0.6), so it is left off the list (K20);
pickup_front_bumper_kf2_m3: its box does not stand out from the paint around it in its own crop (contrast 0.3), so it is left off the list (K20);
pickup_front_bumper_kf2_m4: its box does not stand out from the paint around it in its own crop (contrast 0.3), so it is left off the list (K20);
pickup_front_bumper_kf2_m5: its box does not stand out from the paint around it in its own crop (contrast 0.8), so it is left off the list (K20);
return_front_bumper_kf1_m3: its box does not stand out from the paint around it in its own crop (contrast 1.4), so it is left off the list (K20);
return_front_bumper_kf1_m4: its box does not stand out from the paint around it in its own crop (contrast 0.4), so it is left off the list (K20)

Check by eye: debris on this panel; check by eye (4 spots Muse Spark typed dirt, not listed one by one)


Groups

- 5 dirt marks here at pickup, 2 at return, 0 new or unseen

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

rear bumper



pickup: video time 49.80 s; wall clock 2026-11-02T19:47:18Z; marks pickup_rear_bumper_kf1_m1, pickup_rear_bumper_kf1_m2, pickup_rear_bumper_kf1_m3, pickup_rear_bumper_kf1_m4, pickup_rear_bumper_kf2_m1, pickup_rear_bumper_kf2_m2, pickup_rear_bumper_kf2_m3, pickup_rear_bumper_kf2_m4



return: video time 33.67 s; wall clock 2026-11-02T19:51:15Z; marks return_rear_bumper_kf1_m1, return_rear_bumper_kf1_m2, return_rear_bumper_kf2_m1, return_rear_bumper_kf2_m2

coverage: pickup 11.3 s (filmed); return 9.8 s (filmed)

how it was checked: compared on keyframes pickup_rear_bumper_kf2 with return_rear_bumper_kf1, the first pair tried; left out: return_rear_bumper_kf2_m2 sits where return_rear_bumper_kf2 is blurred for privacy (52% of its box), so it was not matched; registration pickup_rear_bumper_kf2 onto return_rear_bumper_kf1 by the panel outline (mask IoU 0.86, 1 of 47 matched points agree), refused: mask IoU after the warp 0.86; registration pickup_rear_bumper_kf1 onto return_rear_bumper_kf1 by matched edges and the outline (mask IoU 0.89, 99 of 170 matched points agree); pickup_rear_bumper_kf1_m2: paired with return_rear_bumper_kf1_m2, the same patch at the same spot in the return crop (NCC 0.95); 8 marks could not be checked at their spot; same walk: return_rear_bumper_kf2_m1 carried from return_rear_bumper_kf2 onto return_rear_bumper_kf1 (outline); copies: pickup_rear_bumper_kf2_m1 is pickup_rear_bumper_kf1_m1 seen again in pickup_rear_bumper_kf2, by an outline fit that was refused on its own but put this and another mark of pickup_rear_bumper_kf2 inside the paired marks (4 px), so it has no line of its own (already decided with return_rear_bumper_kf1_m1); pickup_rear_bumper_kf2_m2 is pickup_rear_bumper_kf1_m2 seen again in pickup_rear_bumper_kf2, by an outline fit that was refused on its own but put this and another mark of pickup_rear_bumper_kf2 inside the paired marks (18 px), so it has no line of its own (already decided with return_rear_bumper_kf1_m2); pickup_rear_bumper_kf1_m3: its box does not stand out from the paint around it in its own crop (contrast 1.7), so it is left off the list (K20); return_rear_bumper_kf2_m1: its box does not stand out from the paint around it in its own crop (contrast 0.0), so it is left off the list (K20)

Check by eye: debris on this panel; check by eye (3 spots Muse Spark typed dirt, not listed one by one)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_rear_bumper_kf1_m1, return_rear_bumper_kf1_m1` `scuff S`	already there	L3	0.09 units, about 3 cm	Stays Put: drift 0.19, b1 0.14, b2 1.00, panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label about 2.1 in, between 1.7 and 2.9 in (ruler: the license plate, 12 in; no wheel measured on that frame; return view flagged dirty: the size may include dirt) Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26). pickup view flagged dirty: the mark is in the same place in both walks, so it was there at pickup, whatever it is
`pickup_rear_bumper_kf1_m2, return_rear_bumper_kf1_m2` `scuff S`	already there	L3	0.01 units, about 0 cm	Stays Put: drift 0.22, b1 0.14, b2 1.00, panned; neighbour test: 0 neighbours tracked through the clip, 4 needed; inconclusive; recorded only: Stays Put is not calibrated yet and changes no label

	about 0.9 in, between 0.5 and 1.5 in (ruler: the license plate, 12 in; no wheel measured on that frame; return view flagged dirty: the size may include dirt) Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26). pickup view flagged dirty: the mark is in the same place in both walks, so it was there at pickup, whatever it is

L3 already there: d < tau_pre_r

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins	`0b1d3a373eec / cc683f02ad13`

left front wheel



pickup: video time 3.40 s; wall clock 2026-11-02T19:46:32Z; marks pickup_left_front_wheel_kf1_m1, pickup_left_front_wheel_kf1_m2



return: video time 3.40 s; wall clock 2026-11-02T19:50:45Z

coverage: pickup 15.5 s (filmed); return 10.5 s (filmed)

how it was checked: compared on keyframes pickup_left_front_wheel_kf3 with return_left_front_wheel_kf2, the first pair tried;
pickup_left_front_wheel_kf1_m1: its box does not stand out from the paint around it in its own crop (contrast 2.3), so it is left off the list (K20);
pickup_left_front_wheel_kf1_m2: its box does not stand out from the paint around it in its own crop (contrast 2.8), so it is left off the list (K20)

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

left rear wheel

no pickup frame for this panel



return: video time 0.80 s; wall clock 2026-11-02T19:50:42Z

coverage: pickup 0.0 s (not_filmed); return 5.2 s (filmed)

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right front wheel



no return frame for this panel

pickup: video time 36.67 s; wall clock 2026-11-02T19:47:05Z; marks pickup_right_front_wheel_kf1_m1, pickup_right_front_wheel_kf1_m2

coverage: pickup 8.9 s (filmed); return 0.0 s (not_filmed)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_front_wheel_kf1_m1, pickup_right_front_wheel_kf1_m2` `dirt M`	not comparable	L6, G1	no pair	

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

right rear wheel



pickup: video time 43.40 s; wall clock 2026-11-02T19:47:12Z; marks pickup_right_rear_wheel_kf1_m1



return: video time 25.93 s; wall clock 2026-11-02T19:51:07Z; marks return_right_rear_wheel_kf3_m2, return_right_rear_wheel_kf2_m1, return_right_rear_wheel_kf3_m1

coverage: pickup 12.7 s (filmed); return 9.5 s (filmed)

how it was checked: compared on keyframes pickup_right_rear_wheel_kf1 with return_right_rear_wheel_kf1, the first pair tried; left out: pickup_right_rear_wheel_kf1_m1 sits 5.6% of the crop's long side off the right rear wheel and on no other panel tracked in that frame, so it was not matched; left out: return_right_rear_wheel_kf2_m1 sits 8.1% of the crop's long side off the right rear wheel and on no other panel tracked in that frame, so it was not matched; left out: return_right_rear_wheel_kf3_m1 sits 6.1% of the crop's long side off the right rear wheel and on no other panel tracked in that frame, so it was not matched

Verdicts

marks	verdict	rule ids	distance	detail
`return_right_rear_wheel_kf3_m2` `scuff S`	**needs your eye**	L4, L2, K12, K15, K2	no pair	size not stated: tire size not given return view flagged dirty: could be dirt; pickup view flagged dirty: could have hidden the mark

L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
L2 new or unseen: d is None for a return mark: new_or_unseen
K12 low confidence: Spark confidence low on either mark
K15 view flagged: Muse Spark flagged the pickup or return view of the panel wet, dirty or glare, so a mark seen in one walk only may be dirt, water or a reflection, or may have been hidden in the other walk; a mark in the same place in both walks keeps its label with a note
K2 single frame: the mark appears in 1 of 3 keyframes while the other two were complete and sharp

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

headlights

coverage: pickup 33.3 s (filmed); return 20.8 s (filmed)



pickup: video time 11.53 s; wall clock 2026-11-02T19:46:40Z



return: video time 9.20 s; wall clock 2026-11-02T19:50:51Z

how it was checked: compared on keyframes pickup_headlights_kf1 with return_headlights_kf3; tried first: pickup_headlights_kf1 with return_headlights_kf2 (G13 the other one of the pair)

No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

tail lights

coverage: pickup 11.7 s (filmed); return 9.5 s (filmed)



pickup: video time 47.73 s; wall clock 2026-11-02T19:47:16Z



return: video time 29.87 s; wall clock 2026-11-02T19:51:11Z; marks return_tail_lights_kf1_m1

how it was checked: compared on keyframes pickup_tail_lights_kf1 with return_tail_lights_kf1, the first pair tried; second marks pass: looked again at pickup_tail_lights_kf1 around return_tail_lights_kf1_m1: no mark there; registration pickup_tail_lights_kf1 onto return_tail_lights_kf1 by matched edges and the outline (mask IoU 0.94, 26 of 42 matched points agree); 1 mark could not be checked at its spot; return_tail_lights_kf1_m1: its box does not stand out from the paint around it in its own crop (contrast 1.0), so it is left off the list (K20)


No marks compared on this panel.

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

mirrors

coverage: pickup 31.1 s (filmed); return 19.9 s (filmed)



pickup: video time 28.07 s; wall clock 2026-11-02T19:46:57Z; marks pickup_mirrors_kf1_m1, pickup_mirrors_kf1_m2, pickup_mirrors_kf2_m1, pickup_mirrors_kf2_m2, pickup_mirrors_kf2_m3, pickup_mirrors_kf3_m1, pickup_mirrors_kf3_m2, pickup_mirrors_kf3_m3



return: video time 18.53 s; wall clock 2026-11-02T19:51:00Z; marks return_mirrors_kf1_m1, return_mirrors_kf1_m2, return_mirrors_kf2_m1, return_mirrors_kf2_m2, return_mirrors_kf2_m3, return_mirrors_kf3_m1, return_mirrors_kf3_m2

how it was checked: compared on keyframes pickup_mirrors_kf3 with return_mirrors_kf3, the first pair tried; registration pickup_mirrors_kf3 onto return_mirrors_kf3 by the panel outline (mask IoU 0.97, 1 of 8 matched points agree); return_mirrors_kf2_m3: the pickup crop shows the same patch at its spot (NCC 0.85) and no mark there, so needs your eye (K18); 7 marks could not be checked at their spot; same walk: pickup_mirrors_kf1_m1 is pickup_mirrors_kf3_m3 seen again in pickup_mirrors_kf1 (registered onto pickup_mirrors_kf3, features); pickup_mirrors_kf1_m2 is pickup_mirrors_kf3_m2 seen again in pickup_mirrors_kf1 (registered onto pickup_mirrors_kf3, features); pickup_mirrors_kf2_m1 is pickup_mirrors_kf3_m3 seen again in pickup_mirrors_kf2 (registered onto pickup_mirrors_kf3, outline); pickup_mirrors_kf2_m2 is pickup_mirrors_kf3_m3 seen again in pickup_mirrors_kf2 (registered onto pickup_mirrors_kf3, outline); pickup_mirrors_kf2_m3 carried from pickup_mirrors_kf2 onto pickup_mirrors_kf3 (outline); return_mirrors_kf1_m1 is return_mirrors_kf3_m1 seen again in return_mirrors_kf1 (registered onto return_mirrors_kf3, outline); return_mirrors_kf1_m2 carried from return_mirrors_kf1 onto return_mirrors_kf3 (outline); return_mirrors_kf2_m1 is return_mirrors_kf3_m1 seen again in return_mirrors_kf2 (registered onto return_mirrors_kf3, features); return_mirrors_kf2_m2 is return_mirrors_kf1_m2 seen again in return_mirrors_kf2 (registered onto return_mirrors_kf3, features); return_mirrors_kf2_m3 carried from return_mirrors_kf2 onto return_mirrors_kf3 (features); pickup_mirrors_kf3_m1: its box does not stand out from the paint around it in its own crop (contrast 0.3), so it is left off the list (K20); pickup_mirrors_kf3_m2: its box does not stand out from the paint around it in its own crop (contrast 1.0), so it is left off the list (K20); pickup_mirrors_kf3_m3: its box does not stand out from the paint around it in its own crop (contrast -0.3), so it is left off the list (K20); pickup_mirrors_kf2_m3: its box does not stand out from the paint around it in its own crop (contrast 0.2), so it is left off the list (K20); return_mirrors_kf3_m1: its box does not stand out from the paint around it in its own crop (contrast 2.6), so it is left off the list (K20); return_mirrors_kf3_m2: its box does not stand out from the paint around it in its own crop (contrast 0.6), so it is left off the list (K20); return_mirrors_kf1_m2: its box does not stand out from the paint around it in its own crop (contrast 0.7), so it is left off the list (K20); no front sign on this panel, so each keyframe's side comes from its own track: pickup_mirrors_kf1 right, pickup_mirrors_kf2 right, pickup_mirrors_kf3 right, return_mirrors_kf1 right, return_mirrors_kf2 right, return_mirrors_kf3 right

Verdicts

marks	verdict	rule ids	distance	detail
`return_mirrors_kf2_m3` `unsure S`	**needs your eye**	L4, L2, K12, K18, K3, K4	no pair	size not stated: no ruler within 0.6 m of this mark


L4 needs your eye: tau_pre_r <= d < tau_eye_r, or any K flag lowered the label
L2 new or unseen: d is None for a return mark: new_or_unseen
K12 low confidence: Spark confidence low on either mark
K18 the other walk shows the same patch: registration (11/2): the pickup and return crops of the panel were aligned from the panel outline and its rigid edges, and at this mark's mapped spot the other walk's crop shows the same patch (normalized cross-correlation and the same contrast against its surroundings) with no mark of the other walk there, so the mark is not new or gone; needs your eye
K3 tiny mark: size under 0.03 units or bbox under 12 px
K4 uncertain type: type dirt, reflection or unsure

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

windshield

coverage: pickup 40.9 s (filmed); return 24.9 s (filmed)



pickup: video time 27.73 s; wall clock 2026-11-02T19:46:56Z; marks pickup_windshield_kf2_m1, pickup_windshield_kf2_m2, pickup_windshield_kf2_m3, pickup_windshield_kf2_m4



return: video time 15.80 s; wall clock 2026-11-02T19:50:57Z; marks return_windshield_kf1_m1

how it was checked: not compared: none of the 6 keyframe pairs passed every gate; tried: pickup_windshield_kf1 with return_windshield_kf2 (G12 view mostly blurred for privacy); pickup_windshield_kf1 with return_windshield_kf1 (G12 view mostly blurred for privacy); pickup_windshield_kf2 with return_windshield_kf2 (G3 blurry keyframe, G12 view mostly blurred for privacy); pickup_windshield_kf1 with return_windshield_kf3 (G3 blurry keyframe, G12 view mostly blurred for privacy); pickup_windshield_kf2 with return_windshield_kf1 (G3 blurry keyframe); pickup_windshield_kf2 with return_windshield_kf3 (G3 blurry keyframe, G12 view mostly blurred for privacy)


Check by eye: glass: check by eye; reflections make marks on glass unreliable (5 spots Muse Spark boxed on it, not judged)

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins


`0b1d3a373eec / cc683f02ad13`

rear window

coverage: pickup 12.0 s (filmed); return 9.1 s (filmed)



pickup: video time 51.07 s; wall clock 2026-11-02T19:47:20Z; marks pickup_rear_window_kf1_m1, pickup_rear_window_kf1_m2, pickup_rear_window_kf1_m3, pickup_rear_window_kf1_m4, pickup_rear_window_kf1_m5



return: video time 34.27 s; wall clock 2026-11-02T19:51:16Z; marks return_rear_window_kf1_m1, return_rear_window_kf1_m2, return_rear_window_kf1_m3, return_rear_window_kf1_m4, return_rear_window_kf1_m5, return_rear_window_kf1_m6, return_rear_window_kf1_m7, return_rear_window_kf2_m1, return_rear_window_kf2_m4, return_rear_window_kf2_m5

how it was checked: compared on keyframes pickup_rear_window_kf1 with return_rear_window_kf2, the first pair tried

Check by eye: glass: check by eye; reflections make marks on glass unreliable (15 spots Muse Spark boxed on it, not judged)

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`

Panels without frames

Every canonical panel has a frame.

Not comparable

panel	rule ids	why
left rear fender	G1	G1 not filmed: the panel is not 'filmed' in either walk
right front fender	G1	G1 not filmed: the panel is not 'filmed' in either walk
right rear fender	G4	G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
roof	G1, G4, G6	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G6 side uncertain: side_uncertain, or front_sign null, on either walk
left rear wheel	G1	G1 not filmed: the panel is not 'filmed' in either walk
right front wheel	G1	G1 not filmed: the panel is not 'filmed' in either walk
windshield	G12	G12 view mostly blurred for privacy: more than view_max of the panel's area in a keyframe crop is blurred for privacy (a face or plate over it), so that crop gives no verdict (thresholds matching.privacy_blur, R27)

Method and limits

Every verdict on the panel pages was decided by code from the numbers below. The thresholds were frozen into this run under config hash `f9bb1ca339d97887886fe182bb4dd4a02f079cfd799565057148412f8277a775`. Rebuilding the derived files from the stored model answers and these thresholds gives the same bytes when the line below says so.

rebuild	event chain verified to the head on page 1 and any original still in quarantine re-hashed at sheet time; run walkaround verify to compare a rebuild
storage	Model requests were sent with storage off and the models accepted it; nothing was kept after the run. Files API upload deleted: 2026-11-02T23:55:14.219Z; quarantine deleted: 2026-11-02T23:55:14.219Z.
Hertz thresholds	Example thresholds Hertz published (REV 7.2025), illustrative only, quoted from its Damage Charges support page saved 2026-10-26: a body scratch is billable when it cannot be covered by a credit card (2 in x 3.5 in), or when scratches over 1 in together exceed that area; a dent with a diameter over 1 in, or multiple dents; a wheel, rim or hubcap scratch or scuff over 1 in; any crack or chip in glass. Paint transfer or scuffs that do not break the paint are listed as Ordinary Wear and not charged.

Eval numbers

No eval run is attached to this sheet; the README carries the eval tables with their N.

Calibration

tau_pre (already there below)	`0.4`
tau_eye (needs your eye below)	`0.8`
tau_fix (Stays Put fixed below)	`0.08`
sigma_frame / sigma_spark / sigma_view / sigma_within	`None / 0.117 / 0.057935 / 0.130558`
calibrated	no: tau_pre hit its cap, so the matcher is not calibrated for this run

Model calls (from runs/ledger.jsonl)

kind	calls	dollars	quantity
total	`0`	`0.0000`	

What was blurred

- pickup: SAM image checks on 32 keyframes found a plate on 12 and faces on 4; the display proxy was pixelated from the plate and face tracks
- return: SAM image checks on 39 keyframes found a plate on 13 and faces on 6; the display proxy was pixelated from the plate and face tracks

What was deleted and when

kind	target	sha256	bytes	deleted at	reason	receipt
file	`media/pickup.proxy.mp4`	`528821187478`	`24418081`	2026-11-02T23:46:56Z	unblurred proxy deleted at blur.done	

file	media/return.proxy.mp4	bacf28269939	18943280	2026-11-02T23:47:03Z	unblurred proxy deleted at blur.done	
files_api	file-4530081803925934	528821187478		2026-11-02T23:55:14.219Z	run end (pickup proxy)	{'deleted': True, 'id': 'file-4530081803925934', 'object': 'file'}
files_api	file-2492105111280233	bacf28269939		2026-11-02T23:55:14.219Z	run end (return proxy)	{'deleted': True, 'id': 'file-2492105111280233', 'object': 'file'}
quarantine	quarantine/pickup.orig	0b1d3a373eec	58008058	2026-11-02T23:55:14.219Z	run end	
quarantine	quarantine/return.orig	cc683f02ad13	37568726	2026-11-02T23:55:14.219Z	run end	

What the seal does not prove

- which car was filmed, unless the plate was kept on this sheet at the renter's request
- that the walk was not staged before the upload; the seal dates the bytes, not the events in them
- anything about the pickup condition when the seal was made after the return

The seal is offered as a process record under FRE 901(b)(9): the same inputs through the same code give the same output, and the method page states that code's inputs.

Thresholds frozen into this run

claim.align_landmark_fit	False
claim.dark_v_max	0.15
claim.drawn_box_inside_saturated_max	0.1
claim.drawn_box_perimeter_saturated_min	0.3
claim.drawn_box_saturation_min	0.5
claim.full_panel_area_min	0.03
claim.full_panel_border_max	0.15
claim.landmark_fit_min_landmarks	3
claim.landmark_fit_residual_max_frac	0.1
claim.low_res_px	480
claim.on_panel_frac	0.025
claim.passenger_side_is	right
claim.photo_flag_caps_one_walk_only	True
claim.r_claim_full_panel	0.1
claim.r_claim_two_landmarks	0.2
claim.roi_pad_frac	0.25
claim.roi_region_max_panel_frac	0.4
claim.sam_vote_requests	14
claim.scanner_style_saturation_max	0.08
claim.view_flag_caps	True
cost.d1_budget_usd	25
cost.pair_estimate_usd_10fps	4.9

cost.pair_estimate_usd_15fps	6.2
cost.pickup_check_estimate_usd	2.6
cost.sam_image_usd	0.0025
cost.sam_video_min_frames	50
cost.sam_video_usd_per_frame	0.0002
cost.voice_usd_per_hour	0.18
coverage.area_only_box_area_frac_min	0.01
coverage.c_present_floor	0.5
coverage.filmed_area_frac_min	0.03
coverage.filmed_area_frac_min_by_panel.headlights	0.01
coverage.filmed_area_frac_min_by_panel.mirrors	0.005
coverage.filmed_area_frac_min_by_panel.tail_lights	0.01
coverage.filmed_completeness_min	0.85
coverage.filmed_sharpness_rel_min	0.4
coverage.glimpsed_c_percentile	25
coverage.odometer_ask_once	True
coverage.topup_order	['wheels', 'lower_bumpers', 'rest']
dedup.cluster_radius_units	0.2
dedup.collinear_angle_deg	10
dedup.collinear_gap_units	0.1
dedup.count_mode_new_point_min_units	0.1
dedup.droplet_max_size_units	0.03
dedup.droplet_min_marks	8
dedup.group_min_marks	3
dedup.group_radius_units	0.5
dedup.marks_on_panel.enabled	True
dedup.road_spray_band_bottom_frac	0.25
dedup.road_spray_min_marks	3
dedup.sam_box_refine.enabled	True
dedup.sam_box_refine.fills_box_min	0.8
dedup.sam_box_refine.margin_frac	0.25
dedup.sam_box_refine.margin_px	4
dedup.sam_box_refine.max_area_ratio	3.0
dedup.sam_box_refine.max_crop_frac	0.02
dedup.sam_box_refine.max_objects	16
dedup.sam_box_refine.min_inside	0.5
dedup.sam_box_refine.min_mask_px	4
dedup.sam_box_refine.pad_px	2
dedup.small_mark_px	12
dedup.small_mark_units	0.03
dedup.spark_zoom_refine.enabled	True
dedup.spark_zoom_refine.min_px	96
dedup.spark_zoom_refine.out_h	720
dedup.spark_zoom_refine.out_w	1280
dedup.spark_zoom_refine.patch_sent_px	28
dedup.spark_zoom_refine.prefer_kind	True
dedup.spark_zoom_refine.window_patches	3
eval.billable_buckets_mm	[10, 20, 25.4]

eval.false_mark_radius_units	0.35
eval.recall_radius_units	0.25
eval.report_pairs	['p2xr2', 'cross', 'multi_day']
eval.threshold_fit_pairs	['pseudo', 'p1xr1']
geometry.bumper_arc_fallback_tau_factor	1.5
geometry.carried_moments_check_frames	5
geometry.carried_moments_residual_max_units	0.02
geometry.hood_depth_thirds	3
geometry.perspective_residual_center_max	0.08
geometry.perspective_residual_corner_max	0.25
geometry.unit_cm_along_door	35
geometry.unit_cm_vertical_door	29
geometry.whiten_affine_invariance_tol	1e-06
matching.band_radius_factor	0.5
matching.chance_match_density_formula	pi * tau_pre^2 / 12 * mark_density
matching.cm_per_unit_for_print	35
matching.colour_on_paint.enabled	True
matching.compatible_types	['scratch', 'scuff', 'chip']
matching.conditions_on_panel.enabled	True
matching.counter_confirms_mark	True
matching.counter_looks_max	8
matching.debris_by_eye.any_view	True
matching.debris_by_eye.enabled	True
matching.debris_by_eye.types	['dirt']
matching.faint_left_off.enabled	True
matching.fixture_half_grid.badge	[50, 40]
matching.fixture_half_grid.handle	[90, 30]
matching.fixture_half_grid.hub	[60, 60]
matching.fixture_half_grid.lock	[30, 30]
matching.fixture_half_grid.plate_corner_bl	[30, 30]
matching.fixture_half_grid.plate_corner_br	[30, 30]
matching.fixture_half_grid.plate_corner_tl	[30, 30]
matching.fixture_half_grid.plate_corner_tr	[30, 30]
matching.fixture_half_grid.sensor	[30, 30]
matching.fixture_half_grid.valve	[30, 30]
matching.fixture_half_grid.washer_nozzle	[30, 30]
matching.fixture_overlap_min	0.5
matching.fixtures_not_damage	True
matching.glass_by_eye.enabled	True
matching.glass_by_eye.panels	['windshield', 'rear_window']
matching.hood_mask_iou_min	0.8
matching.inside_other_box.enabled	True
matching.look_majority.agree	2
matching.look_majority.asks_max	3
matching.look_majority.enabled	True
matching.margin_min_tau_pre_factor	0.5
matching.mask_iou_min	0.7
matching.next_keyframe_pair	True

matching.one_walk_counter_look	True
matching.pair_scale.enabled	True
matching.pair_scale.max_ratio	2.0
matching.pair_scale.prefer_ratio	1.5
matching.privacy_blur.enabled	True
matching.privacy_blur.mark_max	0.5
matching.privacy_blur.view_max	0.2
matching.pseudo_pair_percentile	90
matching.pseudo_pair_share_min	0.9
matching.ratio_test_min	1.5
matching.registration.enabled	True
matching.registration_vouches.enabled	True
matching.registration_vouches.max_reproj_px	2.0
matching.registration_vouches.min_fit_iou	0.85
matching.registration_vouches.min_inliers	40
matching.registration_vouches.min_spread	0.3
matching.registration_vouches.models	['features']
matching.reshape_aspect_tol	0.02
matching.reshape_blob_share_min	0.5
matching.reshape_iou_min	0.5
matching.reshape_open_px	5
matching.reshaped_panel	True
matching.same_walk_copies.enabled	True
matching.same_walk_copies.into_labels	['already_there']
matching.same_walk_copies.refused_fit_min_hits	2
matching.same_walk_copies.refused_fit_min_mask_iou	0.85
matching.same_walk_register.enabled	True
matching.seams_not_marks	False
matching.second_marks_pass.enabled	True
matching.second_marks_pass.max_asks	12
matching.second_marks_pass.on_panel	True
matching.sharpness_rel_min	0.4
matching.side_from_track.enabled	True
matching.side_from_track.min_share	0.8
matching.side_from_track.min_shared_frames	15
matching.side_from_track.panels	['mirrors']
matching.sigma_spark	0.117
matching.size_cost_factor	0.1
matching.stands_out.enabled	True
matching.stands_out.max_panel_share	0.1
matching.stands_out.min_contrast	3.0
matching.tau_eye_factor	2.0
matching.tau_pre0_floor	0.25
matching.tau_pre0_sigma_factor	3.535534
matching.tau_pre_cap	0.4
matching.tight_pair_k5	True
matching.tight_pair_second_look	True
matching.twin_mirror.enabled	True

matching.twin_mirror.grid	64
matching.twin_mirror.margin	0.1
matching.type_cost_compatible	0.1
matching.type_cost_incompatible	0.4
matching.wheel_min_marks_for_shift	2
matching.wheel_radius_tolerance	0.1
matching.wheel_size_factor_max	2.0
media.anchor_clip_frames	180
media.anchor_clip_half_window_s	6.0
media.chunk_bytes	8388608
media.chunk_route_max_body_bytes	9437184
media.chunks_in_flight	3
media.clip_crf	18
media.clip_frames	91
media.clip_half_window_s	1.5
media.clip_prompt_frame	45
media.clip_size_px	1008
media.files_expires_after_s	3600
media.inline_data_url_max_bytes	52428800
media.other_route_max_body_bytes	1048576
media.proxy_codec	libx264
media.proxy_crf	20
media.proxy_fps	15
media.proxy_fps_fallbacks	[10, 30]
media.proxy_max_edge	960
media.proxy_preset	medium
media.source_fps_assumed	30
media.upload_max_bytes	1073741824
media.upload_warn_bytes	524288000
media.wav_rate	24000
nouns.d1_text_prompts	['scuff']
nouns.door_handle_image_requests_per_pair	24
nouns.image_only	['door handle']
nouns.lanes	['car', 'license plate', 'face', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window']
nouns.never_prompt	['front bumper', 'rear bumper']
nouns.privacy	['license plate', 'face']
nouns.topup_always	['car', 'license plate', 'face']
nouns.voice_keywords	['car', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window', 'scuff', 'scratch', 'chip', 'dent', 'crack', 'tape', 'odometer']
orchestrator.baseten_rpm	30
orchestrator.baseten_semaphore	1
orchestrator.caps_if_no_card_ceiling.pair_runs_per_day	0
orchestrator.caps_if_no_card_ceiling.pickup_runs_per_day	3
orchestrator.daily_card_ceiling_cents	7500

orchestrator.decode_workers	2
orchestrator.health_probe_failures_to_pause	3
orchestrator.health_probe_interval_s	300
orchestrator.judging_card_ceiling_cents	5000
orchestrator.max_concurrent_runs	2
orchestrator.media_workers	2
orchestrator.pair_runs_per_day	1
orchestrator.pdf_timeout_s	60
orchestrator.pickup_runs_per_day	6
orchestrator.priority_wave_size	6
orchestrator.queue_eta_from_last_runs	3
orchestrator.rate_limit_backoff_base_s	0.5
orchestrator.rate_limit_retries	6
orchestrator.replay_fixed_total_s_estimate	35
orchestrator.replay_recorded_delay_cap_ms	2000
orchestrator.request_retries	1
orchestrator.request_timeout_s	240
orchestrator.run_deadline_s	1200
orchestrator.run_spend_ceiling_cents	1200
orchestrator.sam_image_semaphore	16
orchestrator.sam_video_semaphore_global	32
orchestrator.sam_video_semaphore_per_run	16
orchestrator.spark_semaphore	12
orchestrator.sse_ping_s	15
orchestrator.sweeper_interval_s	3600
orchestrator.volume_min_free_bytes	524288000
panels.anchor_absorb_iou_min	0.5
panels.anchor_max_frames_per_panel	3
panels.anchor_negative_point_seam_offset_box_widths	0.1
panels.anchor_pass_coverage_below	0.7
panels.area_floor_default	0.02
panels.area_floor_small	0.005
panels.border_frac_keyframe_max	0.15
panels.c_floor	None
panels.car_box_containment_min	0.8
panels.car_mask_containment_min	0.8
panels.crop_long_edge_px	1280
panels.crop_pad_frac	0.1
panels.direction_min_px_per_frame	2.0
panels.direction_phase_corr	False
panels.door_check.dir_share_min	0.75
panels.door_check.end_light_inside_min	0.5
panels.door_check.margin_min	2
panels.door_check.min_frames	5
panels.door_check.mirror_band_door_heights	0.25
panels.door_check.mirror_far_door_widths	0.4
panels.door_check.mirror_near_door_widths	0.15
panels.door_check.mirror_side_gap_min	0.1

panels.door_check.photo_margin_min	2
panels.door_check.same_door_iou_min	0.5
panels.door_check.side_view_aspect_min	0.5
panels.door_check.weights.lid_side	2
panels.door_check.weights.mirror	2
panels.door_check.weights.mirror_side	2
panels.door_check.weights.pair	1
panels.door_check.weights.walk	1
panels.door_check.weights.wheel	2
panels.door_check.wheel_overlap_min	0.3
panels.door_check.wheel_rear_share_min	0.5
panels.door_glass_edge	True
panels.edge_on_floor.car door	0.4
panels.edge_on_floor.fender	0.4
panels.edge_on_floor.wheel	0.36
panels.fast_mask_decode	True
panels.fender_from_wheels.above_d	0.75
panels.fender_from_wheels.below_side_d	0.5
panels.fender_from_wheels.box_above_d	0.6
panels.fender_from_wheels.box_side_d	0.35
panels.fender_from_wheels.door_gap_d	0.6
panels.fender_from_wheels.min_frames	5
panels.fender_from_wheels.open_px	5
panels.fender_from_wheels.reach_d	1.6
panels.fragment_gap_split_frames	2.5
panels.fragment_gap_split_s	0.5
panels.fragment_min_frames	2
panels.fragment_min_s	0.5
panels.glare_s_max	40
panels.glare_v_min	250
panels.keyframe_box_pass_candidates	9
panels.keyframe_decode_budget_s_per_video	60
panels.keyframe_min_gap_s	0.5
panels.keyframe_panels_in_flight	4
panels.keyframe_score_exponents.area	1.0
panels.keyframe_score_exponents.completeness	1.0
panels.keyframe_score_exponents.frontality	1.0
panels.keyframe_score_exponents.one_minus_glare	1.0
panels.keyframe_score_exponents.sharpness	1.0
panels.keyframe_top_k	3
panels.keyframe_top_k_under_budget	2
panels.merge_area_ratio	[0.6, 1.6]
panels.merge_aspect_tolerance	0.2
panels.merge_gap_max_s	1.0
panels.merge_pred_dist_box_widths	0.5
panels.off_car_tracks.enabled	True
panels.off_car_tracks.frames	3
panels.off_car_tracks.grid	10

panels.off_car_tracks.min_inside	0.25
panels.part_check.adjacent_sizes	0.5
panels.part_check.dir_share_min	0.75
panels.part_check.door_gap_d	0.6
panels.part_check.margin_min	2
panels.part_check.min_frames	5
panels.part_check.mirror_near_sizes	0.25
panels.part_check.offset_min_d	0.5
panels.part_check.presence_margin	0.3
panels.part_check.weights.bumper	1
panels.part_check.weights.door_side	2
panels.part_check.weights.lid	2
panels.part_check.weights.lid_side	2
panels.part_check.weights.light_side	2
panels.part_check.weights.lights	2
panels.part_check.weights.mirror	1
panels.prompt_box_pad_px	2
panels.side_vote_margin_min	1
panels.side_vote_weights.R1	2
panels.side_vote_weights.R2	1
panels.side_vote_weights.R3	1
panels.side_vote_weights.R4	1
panels.small_nouns	['side mirror', 'headlight', 'tail light', 'license plate', 'face']
panels.twin_check.adjacent_lid_sizes	0.25
panels.twin_check.margin_min	3
panels.twin_check.min_frames	5
panels.twin_check.mirror_far_lid_sizes	1.5
panels.twin_check.mirror_near_lid_sizes	1.0
panels.twin_check.neighbour_majority	2.0
panels.twin_check.neighbour_share_min	0.5
panels.twin_check.photo_margin_min	2
panels.twin_check.plate_inside_min	0.8
panels.twin_check.plate_share_min	0.5
panels.twin_check.presence_margin	0.4
panels.twin_check.weights.glass	1
panels.twin_check.weights.lights	1
panels.twin_check.weights.mirror	2
panels.twin_check.weights.plate	2
panels.uncertain_per_track	True
panels.view_match_return	True
privacy.box_blocks_across	4
privacy.files_delete_retries	3
privacy.image_check_nouns	['license plate', 'face']
privacy.image_checks_in_flight	16
privacy.keep_plate_default	False
privacy.mask_blur.dilate_frac	0.03
privacy.mask_blur.dilate_px_at_4k	12

privacy.mask_blur.enabled	True
privacy.mask_blur.on_car_frames	5
privacy.mask_blur.on_car_min	0.6
privacy.mask_blur.plate_carry_grow_max	0.5
privacy.mask_blur.samples_across	4.0
privacy.pixel_block_px_at_4k	20
privacy.run_retention_hours	24
privacy.track_box_dilation_frac	0.1
privacy.track_box_dilation_px	24
privacy.track_box_union_s	0.1
privacy.track_carry_fit_s	0.4
privacy.track_carry_grow_per_s	0.5
privacy.track_carry_s	3.0
privacy.track_carry_speed_max_frac_per_s	1.0
privacy.track_flow_cover_max_frac	0.1
privacy.track_flow_cover_path	True
privacy.track_flow_grow_per_s	0.2
privacy.track_gap_bridge_s	0.5
privacy.unblurred_temp_max_minutes	30
ruler.axis_tilt_correction_max_deg	30
ruler.body_scuff_ordinary_wear	True
ruler.bound_px_per_side	2
ruler.camera_hfov_deg	70
ruler.d1_plate_wheel_ppi_agreement	0.15
ruler.mark_min_px	8
ruler.plate_c_min	0.5
ruler.plate_hw_min	0.35
ruler.plate_long_side_in	12
ruler.plate_min_px	60
ruler.plate_tilt_max_deg	30
ruler.ruler_max_distance_m	0.6
ruler.threshold_body_scratch_in	3.5
ruler.threshold_dent_in	1.0
ruler.threshold_wheel_in	1.0
ruler.tire_diameter_formula	D = 2 * (SW * AR / 2540 + RD / 2)
ruler.view_flag_sizes	True
ruler.wheel_c_min	0.5
ruler.wheel_min_px	120
sheet.footage_credit	True
spark.confidence_levels	['low', 'medium', 'high']
spark.d1_jaccard_pass	0.7
spark.d1_sigma_pass_frac_of_crop_width	0.02
spark.effort	low
spark.grid	1000
spark.grid_slack	20
spark.image_long_edge_px	1280
spark.input_tokens_per_1280_crop_estimate	1400
spark.jpeg_quality	90

spark.landmarks.bumper	['plate_corner_tl', 'plate_corner_tr', 'plate_corner_bl', 'plate_corner_br', 'fog_lamp', 'grille_corner', 'sensor']
spark.landmarks.door	['handle', 'lock', 'mirror_base', 'window_front_corner', 'window_rear_corner', 'wheel_arch', 'lower_trim', 'badge']
spark.landmarks.hood	['badge', 'washer_nozzle', 'front_corner_left', 'front_corner_right']
spark.landmarks.wheel	['hub', 'rim_lip', 'valve']
spark.landmarks_max	4
spark.mark_types	['scratch', 'scuff', 'chip', 'dent', 'crack', 'dirt', 'reflection', 'unsure']
spark.max_output_tokens	4000
spark.model	muse-spark-1.3
spark.retry_max_output_tokens	8000
spark.schema_names	['marks_v1', 'count_v1', 'look_v1', 'seed_v1', 'claim_name_v1', 'timeline_v1', 'note_prefill_v1', 'counter2_v1']
spark.schema_retry_count	1
spark.second_look_engine	spark_open
spark.second_looks_per_pair_max	25
spark.size_classes	['S', 'M', 'L']
spark.store	False
spark.stream_when_expected_over_s	30
staysput.b1_floor	0.15
staysput.b2_floor	0.05
staysput.cap_enabled	False
staysput.check_box_covered_min	0.9
staysput.clip_blur_dilation_frac	0.3
staysput.clip_frames_max	181
staysput.control_blob_max_frac	0.15
staysput.control_blob_min_px	9
staysput.curvature_boundary_units	0.15
staysput.d1_pass_box_share	0.8
staysput.d1_pass_drift_max	0.08
staysput.d1_reflection_drift_min	0.16
staysput.highlight_s_percentile	10
staysput.highlight_v_percentile	95
staysput.max_clips_per_walk	16
staysput.max_objects_per_clip	16
staysput.min_bbox_px_at_4k	12
staysput.min_drift_frames	10
staysput.neighbour_dedupe_iou	0.5
staysput.neighbour_fixed_below	1.5
staysput.neighbour_handle_half_h_frac	0.02
staysput.neighbour_handle_half_w_frac	0.08
staysput.neighbour_mark_min_clip_px	16
staysput.neighbour_near_half_window_s	0.5
staysput.neighbour_part_max_window_frac	0.5
staysput.neighbour_residual_floor_px	0.5

staysput.neighbour_sliding_above	2.5
staysput.neighbour_track_share_min	0.8
staysput.neighbour_window_margin	1.15
staysput.neighbour_window_max_growth	2.0
staysput.neighbour_window_max_panel_frac	1.5
staysput.neighbours_enabled	True
staysput.neighbours_max	12
staysput.neighbours_min	4
staysput.neighbours_target	6
staysput.no_track_box_share_below	0.8
staysput.panned_inconclusive_share_caption_threshold	0.5
staysput.reflection_control_from_hood_glare	True
staysput.sign_agreement_min	0.8
staysput.sign_pair_gap_frames	5
staysput.sign_pairs_min	8
staysput.sign_panel_dx_min_px_per_frame	2.0
staysput.sliding_factor	2.0
staysput.tau_fix_floor	0.08
staysput.tau_fix_sigma_factor	3.0
staysput.window_frac_of_panel_width	0.3
staysput.window_mark_margin	1.5
staysput.window_min_px	400
staysput.window_share_overlap_min	0.5
voice.chip_min_ms	100
voice.max_audio_s	600
voice.max_body_bytes	33554432
voice.mode	ENDPOINTING
voice.model	muse-voice-transcribe-1.0
voice.modes_allowed	['PUSH_TO_TALK', 'ENDPOINTING', 'DIARIZATION']
voice.pin_fallback	turn_start_panel
voice.seeds_per_walk_max	16

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

0b1d3a373eec / cc683f02ad13

Appendix A certification

```
Renter's certification

I, [name], state that:
1. I recorded the videos listed below myself, at pickup on [date] and at return on [date], of the
vehicle under
   rental agreement [number].
2. I uploaded them to Walkaround without editing them, and the sha256 hashes on page 1 match the files
on my phone.
3. I understand this sheet is evidence support, not legal advice, and that it was produced by code from
my videos.

- pickup: IMG_2678.mov (sha256 0b1d3a373eec...)
- return: IMG_2679.mov (sha256 cc683f02ad13...)

Signed: _____________________   Date: ___________

This is a signed statement, not a notarized affidavit.
```

Appendix B glossary

```
Glossary

already there: the same mark was found at pickup within tau_pre of its return position (rule L3).
needs your eye: a human should look; the pair sat in the band between tau_pre and tau_eye, or a cap (K1
to K15) applied (L4).
new or unseen: a return mark with no pickup mark near it; new, or not filmed at pickup (L2).
not seen at return: a pickup mark with no return mark near it (L1).
not comparable: a panel gate failed (G1, G3 to G10); both best frames still show with the reason (L6).
view flagged: Muse Spark said a frame shows water, dirt or glare. That is a model's judgment, so it no
longer blocks a panel (gate G2 did that until Oct 31). A mark seen in one walk only is capped at needs
your eye (K15); a mark in the same place in both walks keeps its label, with a note.
tight pair: a pair inside tau_pre is already there because the mark sits in the same place in both
walks, whatever Muse Spark called it. So Spark's type (dirt, reflection or unsure, K4), the two types
disagreeing (K5) and its low confidence (K12) are notes on that pair, and the second look compares the
two crops and may lower it (K7). If the second look gives no answer, K4, K5 and K12 cap the pair at
needs your eye as before. A mark seen in one walk only, or a pair in the band, keeps them as caps.
keyframe pair: each panel is compared on one pickup keyframe and one return keyframe. When that pair
fails a gate of the pair (G3, G4, G5, G8 or G9), the panel's other keyframe pairs are tried in a fixed
order (clean views first, then the two keyframe scores, then keyframe number) and the first that passes
every gate is used. The panel page says which pair was used and what each pair tried failed. G1, G6, G7
and G10 belong to the panel, so no other pair can pass them.
outline changed in place: a panel that fails only the mask IoU gate (G4) on every keyframe pair tried,
with the best IoU from 0.5 to under 0.7, is needs your eye (L7) instead of not comparable when the two
keyframes' box shapes agree within 2% and the outline difference sits in one place (its largest blob
holds at least half of it). A turned camera changes the box shape or spreads the difference along the
whole outline; a crushed panel does neither. No marks are compared, so it never says already there or
new.
counter-look: a mark seen in one walk only would be new or unseen (or not seen at return) on distance
alone. If no cap already lowers it, the second look is shown the mark in its own walk and the other
walk's view of the same panel with the spot where it would sit outlined (carried through the panel
frame), and answers two questions: is there a damage mark (scratch, scuff, chip, dent, crack) in the box
around the mark, and does the other walk show the same mark at the spot. The label stands only when it
says yes to the first and no to the second. Anything else is needs your eye: K17 (the second look saw no
damage in the box) when the first answer is no or unsure, K16 (the other walk may show it) when the
second is yes or unsure. If it gives no answer, the label stands. A model can only lower a label.
factory fixture: parking sensors, badges, door handles and locks, washer nozzles, the tire valve, the
wheel hub and the plate corners are part of the car, not damage. Muse Spark is asked not to box them,
and a mark whose box still sits mostly on one the run found in the same view (a point Muse Spark named,
or the door handle SAM found) is left out of matching. It gets no label; the panel page names it under
how it was checked.
registration: on a compared panel the pickup crop is mapped onto the return crop from the panel's
outline (the two SAM masks) and, where there are enough, matched edges of its rigid parts; the fit is
refused when the outlines disagree. Each mark's box is then carried to the other crop and the two
patches are compared pixel by pixel. If the other walk shows the same patch there and has no mark there,
the mark is not new or gone: needs your eye (K18). If it has an unmatched mark there, the two are paired
and measured at that spot. Nothing here is a model's answer, and a refused fit changes nothing.
glass: the windshield and rear window get one line, check by eye. Reflections of trees, sky and
buildings move with the camera and Muse Spark boxes them as marks, so marks on glass are not compared.
The boxes it drew there are kept and counted on the line.
debris: on a compared panel, the needs-your-eye lines whose every mark Muse Spark typed dirt, on a view
it flagged wet, dirty or glare, become one line for the panel, debris on this panel; check by eye. A
line holding a mark typed as damage or unsure stays as its own line.
colour on the paint: Muse Spark is also asked to box a stripe or patch of a clearly different colour on
the paint, such as paint transferred from another car, tape or a sticker, as a scuff. The second look
counts one as a mark in the box.
inside the other walk's box: a mark seen in one walk only whose box lies at least half inside a box Muse
Spark drew in the other walk's view (often one large box, such as a crush, dirt or a reflection) is not
called new or gone, since the other walk did not show clean paint there: needs your eye (K19).
```

stands out: a mark seen in one walk only must stand out from the paint around it in its own crop, in plain pixels, to be called new or not seen at return. A box that does not (Muse Spark may have boxed clean paint) is needs your eye (K20). A box covering much of its panel, such as a crush, is not tested.
registration vouches: gate G4 asks whether the two walks' views show the same part of the panel by comparing SAM's two outlines. When no keyframe pair passes every gate and G4 is the only gate one fails, a strong registration of the two crops on matched edges (many matched points spread over the panel, small error) shows it directly, and the panel is compared on that pair. A weak or refused fit leaves G4 as it is.
majority look: the second look's answers vary from one ask to the next, so the pair look (K7) and the counter-look (K17 and K16) are asked up to three times, stopping once two answers agree, and the label follows the majority. A split is unsure, so a model can still only lower a label. Every answer is kept.
the same mark seen again: a mark seen in one walk only, on another frame of the same panel and walk, that lands on a mark already called already there (close in the panel frame, or carried there by a fit of the two frames) is that mark seen again. It gets no line of its own; how it was checked names it.
debris on any view: a mark seen in one walk only that Muse Spark typed dirt joins the panel's debris line whether or not the view was flagged. A mark Muse Spark typed as damage, or could not type, never joins it.
left off the list: a mark seen in one walk only whose box does not stand out from the paint around it (K20) gets no line. How it was checked names it with its contrast, so you can still look.
mirror side: a side mirror has no front or back the way a door does, so gate G6 does not ask for one. Each mirror frame takes the side of the doors filmed with it; frames of the two different mirrors are not compared (G13).
units: panel-normalized distance; 1 unit is about 35 cm along a door (the about-cm beside it uses that).
tau_pre, tau_eye: the two distance thresholds, calibrated from the run's own repeat frames; printed on the method page.
Stays Put: a check that a mark moves with the panel through a short clip; a reflection slides, a scratch stays put.
sha256: the fingerprint of a file; one changed byte changes it.
sealed: the manifest of hashes was written and offered for time stamping before any model saw the video.
config hash: the fingerprint of every threshold the code used; it changes when a threshold changes.
rule id: the row of the decision table that produced a label; G gates a panel, K caps a mark, L names a label, E is a claim exit.

Appendix C verify it yourself

```
Verify it yourself (5 steps; none needs Walkaround's server)

This run's verdicts recomputed on Nov 2, 2026 with this version's rules (code d44edde) from the model
answers stored on Nov 2, 2026 by run hero_focus5; no new model calls. The originals' hashes and stamps
are that run's seal.

1. Hash the video file on your phone or computer and compare it with page 1:
   shasum -a 256 <your video file>     (Linux: sha256sum <your video file>)
   pickup: 0b1d3a373eeccd030eb8cc1eeadfa408d929a48cbabcf2f90481923bf4eca2cf
   return: cc683f02ad13d63d148fb5568724560f5c35e3d15202edcf7a21609cc23024f3
2. Read the OpenTimestamps proof (pip install opentimestamps-client):
   ots info bundle/manifest.json.ots
3. Verify it against the Bitcoin block, or drop the .ots file on https://opentimestamps.org :
   ots verify bundle/manifest.json.ots
4. Verify the RFC 3161 token from freetsa (2026-11-02T23:42:57Z) with freetsa's certificates (download
https://freetsa.org/files/cacert.pem and https://freetsa.org/files/tsa.crt):
   openssl ts -verify -data bundle/manifest.json -in bundle/manifest.json.tsr -CAfile cacert.pem -
untrusted tsa.crt
5. Re-hash every file in the bundle and rebuild the derived files from the stored model answers:
   walkaround verify hero_focus5b
```

Letter: write to the company first

```
Write to the company first

[date]

To: [rental company], damage claims
Re: rental agreement [number], picked up [date], returned [date]

I received a damage charge of [amount] for [description]. Before anything else I ask for the full damage
report,
the written repair estimate and every photograph or scan the company holds for this rental, including
the pickup
inspection images. Hertz's own support page says customers can request more images.

I recorded a walkaround video at pickup and at return. The files were hashed and sealed before any
analysis:
- pickup: IMG_2678.mov, 58008058 bytes, sha256
0b1d3a373eeccd030eb8cc1eeadfa408d929a48cbabcf2f90481923bf4eca2cf, camera time 2026-11-02T19:46:29Z,
received 2026-11-02T23:42:53.536Z
- return: IMG_2679.mov, 37568726 bytes, sha256
cc683f02ad13d63d148fb5568724560f5c35e3d15202edcf7a21609cc23024f3, camera time 2026-11-02T19:50:42Z,
received 2026-11-02T23:42:53.575Z
- sealed at 2026-11-02T23:42:53.709Z
- Walkaround run hero_focus5b; the panel-by-panel evidence sheet is attached
- verdicts recomputed on Nov 2, 2026 with this version's rules (code d44edde) from the model answers
stored on Nov 2, 2026 by run hero_focus5; no new model calls
- the frames on the sheet: Footage: filmed by us with the car owner's permission; the marks are blue
tape stand-ins

The attached sheet shows the panel in question at pickup and at return with the marks drawn on both
frames. The
sheet is evidence support, not legal advice, and I ask that it be read next to your own images.

If the charge stands after you have reviewed it, I will obtain an alternative written estimate within 10
business
days. Card network rules (Visa Core Rules 13.3 and 13.5; 15 USC 1666i) require that I first try to
resolve the
charge with you; this letter is that attempt. Please reply within 14 days to [email].

[name]
```

Walkaround run hero_focus5b. Footage: filmed by us with the car owner's permission; the marks are blue tape stand-ins

`0b1d3a373eec / cc683f02ad13`