Walkaround evidence sheet

Two walkaround videos of one rental car, compared panel by panel. Code decides every verdict; a model answer can only lower one.

evidence support, not legal advice

run id	`pairC_core1`
app commit	`9111529f6c6b50428ce942e68ef5691223e34c48`
config hash	`1cf41037cf2ed72ad3593312153cd6b572dc226f4e1f3f68c11dc345f84eacd3`
events head hash	`91773e3031d6efb6a1921a5a66c7278719602169cd74adf63bf156098dc89b65`
rental agreement number	_____ (fill in)
plate	plate blurred

The three clocks

sealed at	first model call at	sealed after the camera time
2026-10-31T22:50:50.063Z	**2026-10-31T22:51:10Z**	**camera time not present**

Originals

walk	file	bytes	sha256	camera says	received	hash on your phone = hash on receipt	proven to exist by
pickup	uco3d_7336_narrated.mp4	`96182720`	`25f68a8992c980976df1352c0d2894eca301a13b576bcac397e61952e1440efb`	not present	2026-10-31T22:50:49.676Z	match	2026-10-31T22:50:54Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)
return	uco3d_50152-5241-46685.mp4	`107096877`	`f49b432f2932d4a9ffeb59881c992c5054e09a2d7d6b816a41d5dd1df9c8646b`	not present	2026-10-31T22:50:49.806Z	match	2026-10-31T22:50:54Z (RFC 3161 token from freetsa); OpenTimestamps pending at the calendars (ots upgrade adds the Bitcoin block after a few hours)

Privacy

Processed with Meta's Model API in Standard mode, which Meta's documentation says is not used to train Meta models. Uploads were set to expire after one hour and were deleted by Walkaround when the run ended. Model requests were sent with storage off. Meta's terms allow it to retain content for abuse review and legal reasons; Walkaround does not control that. SAM 3.1 saw the unblurred proxy for the length of one segmentation pass to find the plates and faces it then blurred.

Files API upload deleted: 2026-10-31T22:57:26.030Z. Stored responses deleted: none stored or not yet. Quarantine (unblurred originals) deleted: 2026-10-31T22:57:26.030Z.

What to do with this sheet

1. Start with the dated pickup frames in this sheet: the camera says not present, the file was received 2026-10-31T22:50:49.676Z, and the file hashes (25f68a8992c9, f49b432f2932) are on page 1 and in the sealed manifest.
2. Ask the company in writing for the full damage report, the repair estimate and every image it holds for this rental, including the pickup inspection images; Hertz says customers can request more images.
3. Get an alternative written estimate from a body shop within 10 business days; card network rules compare two quotes (Visa Core Rules Table 5-19; Amex allows up to 115% of the estimate).
4. If the company does not answer, escalate to a named executive and file a complaint with your state consumer protection office; the one sourced renter win came by executive escalation with the company's own scans.
5. Last, the card dispute, with its clocks: 60 days from the statement under Regulation Z 1026.13, 120 days under Visa's rules, and the $50 cap of 15 USC 1666i; a dispute does not stop collections, so keep the paper trail.

Coverage per walk

pickup

- left front door: glimpsed, 1.1 s
- left rear door: not_filmed
- right front door: filmed, 9.0 s
- right rear door: glimpsed, 9.7 s
- left front fender: not_seen
- left rear fender: glimpsed, 5.3 s
- right front fender: glimpsed, 3.3 s
- right rear fender: filmed, 1.3 s
- hood: filmed, 18.1 s
- roof: not_filmed
- trunk lid: filmed, 6.6 s
- front bumper: filmed, 7.5 s
- rear bumper: filmed, 6.5 s
- left front wheel: glimpsed, 0.7 s
- left rear wheel: glimpsed, 6.7 s
- right front wheel: filmed, 4.5 s
- right rear wheel: glimpsed, 6.7 s
- headlights: glimpsed, 8.3 s
- tail lights: glimpsed, 7.7 s
- mirrors: glimpsed, 4.0 s
- windshield: filmed, 10.9 s
- rear window: filmed, 7.2 s
- missing at pickup: left front wheel, right front wheel, left rear door, left front fender, left rear fender, right front fender, right rear fender, roof, headlights, tail lights, mirrors, rear window
- top-up asked: Film these again, in this order: left front wheel (glimpsed, 2.5 s); right front wheel (not filmed); left rear door (glimpsed, 2.5 s); left front fender (not seen); left rear fender (glimpsed, 3.9 s); right front fender (not filmed); right rear fender (glimpsed, 2.3 s); roof (glimpsed, 7.5 s); headlights (glimpsed, 15.3 s); tail lights (glimpsed, 20.3 s); mirrors (glimpsed, 7.4 s); rear window (glimpsed, 4.9 s). The app then re-runs 11 of 16 nouns: wheel, car door, fender, roof, headlight, tail light, side mirror, rear window, car, license plate, face. Also film the odometer once.

return

- left front door: filmed, 1.1 s
- left rear door: glimpsed, 2.5 s
- right front door: filmed, 10.4 s
- right rear door: filmed, 11.1 s
- left front fender: not_seen
- left rear fender: glimpsed, 3.9 s
- right front fender: not_filmed
- right rear fender: glimpsed, 2.3 s
- hood: filmed, 19.1 s
- roof: glimpsed, 7.5 s
- trunk lid: filmed, 13.9 s
- front bumper: filmed, 9.7 s
- rear bumper: filmed, 6.1 s
- left front wheel: glimpsed, 2.5 s
- left rear wheel: filmed, 6.9 s
- right front wheel: not_filmed
- right rear wheel: filmed, 8.8 s
- headlights: glimpsed, 15.3 s
- tail lights: glimpsed, 20.3 s
- mirrors: glimpsed, 7.4 s
- windshield: filmed, 15.7 s
- rear window: glimpsed, 4.9 s

left front door

coverage: pickup 1.1 s (glimpsed); return 1.1 s (filmed)




m2 reflection M
m1 dirt M



pickup: video time 0.53 s; marks pickup_left_front_door_kf2_m1



return: video time 19.73 s; marks return_left_front_door_kf1_m1, return_left_front_door_kf1_m2

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_left_front_door_kf2_m1`, `return_left_front_door_kf1_m1`, `return_left_front_door_kf1_m2` `scuff M`	**not comparable**	L6, G1, G2, G4	no pair	size not stated: no ruler within 0.6 m of this mark Hertz's page lists scuffs that do not break paint as ordinary wear (REV 7.2025, illustrative only; page saved 2026-10-26).


L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

left rear door

coverage: pickup 0.0 s (not_filmed); return 2.5 s (glimpsed)

no pickup frame for this panel





return: video time 19.47 s; marks return_left_rear_door_kf2_m1, return_left_rear_door_kf2_m2

Verdicts

marks	verdict	rule ids	distance	detail
return_left_rear_door_kf2_m1, return_left_rear_door_kf2_m2 dirt S	not comparable	L6, G1	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

right front door

coverage: pickup 9.0 s (filmed); return 10.4 s (filmed)





return: video time 7.67 s; marks return_right_front_door_kf1_m1, return_right_front_door_kf2_m1



pickup: video time 19.20 s; marks pickup_right_front_door_kf1_m1

Verdicts

marks	verdict	rule ids	distance	detail

`pickup_right_front_door_kf1_m1,`
`return_right_front_door_kf1_m1,`
`return_right_front_door_kf2_m1`
`unsure S`
	not comparable	L6, G4, G9	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G9 mask definition differs: window_subtracted differs between the paired keyframes

What was said

- `0 to 16140 ms`: front door like scratch near the handle <|speaker_

right rear door

coverage: pickup 9.7 s (glimpsed); return 11.1 s (filmed)





return: video time 7.00 s



pickup: video time 19.07 s; marks pickup_right_rear_door_kf1_m1, pickup_right_rear_door_kf2_m1, pickup_right_rear_door_kf2_m2

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_rear_door_kf1_m1, pickup_right_rear_door_kf2_m1, pickup_right_rear_door_kf2_m2` `dent M`	**not comparable**	L6, G1, G4, G9	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G9 mask definition differs: window_subtracted differs between the paired keyframes

left rear fender

coverage: pickup 5.3 s (glimpsed); return 3.9 s (glimpsed)



pickup: video time 13.13 s



return: video time 6.47 s

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G3, G4, G6	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G6 side uncertain: side_uncertain, or front_sign null, on either walk

right front fender

coverage: pickup 3.3 s (glimpsed); return 0.0 s (not_filmed)



pickup: video time 8.53 s

no return frame for this panel

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

right rear fender

coverage: pickup 1.3 s (filmed); return 2.3 s (glimpsed)



pickup: video time 18.40 s



return: video time 7.80 s


Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G2, G4	no pair	size not stated: no ruler within 0.6 m of this mark


L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

hood

coverage: pickup 18.1 s (filmed); return 19.1 s (filmed)



pickup: video time 2.00 s; marks pickup_hood_kf1_m1, pickup_hood_kf1_m2, pickup_hood_kf1_m3, pickup_hood_kf1_m4, pickup_hood_kf1_m5, pickup_hood_kf1_m6, pickup_hood_kf1_m7, pickup_hood_kf1_m8, pickup_hood_kf1_m9, pickup_hood_kf1_m10, pickup_hood_kf2_m1, pickup_hood_kf2_m3, pickup_hood_kf2_m4, pickup_hood_kf2_m5, pickup_hood_kf2_m6, pickup_hood_kf2_m7



return: video time 3.27 s; marks return_hood_kf1_m1, return_hood_kf1_m2, return_hood_kf1_m3, return_hood_kf2_m1, return_hood_kf2_m2, return_hood_kf2_m3

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_hood_kf1_m1, pickup_hood_kf1_m10, pickup_hood_kf1_m2, pickup_hood_kf1_m3, pickup_hood_kf1_m4, pickup_hood_kf1_m5, pickup_hood_kf1_m6, pickup_hood_kf1_m7, pickup_hood_kf1_m8, pickup_hood_kf1_m9, pickup_hood_kf2_m1, pickup_hood_kf2_m3, pickup_hood_kf2_m4, pickup_hood_kf2_m5, pickup_hood_kf2_m6, pickup_hood_kf2_m7, return_hood_kf1_m1, return_hood_kf1_m2, return_hood_kf1_m3, return_hood_kf2_m1, return_hood_kf2_m2, return_hood_kf2_m3` dirt S	**not comparable**	L6, G2, G4, G8	no pair	Stays Put: drift 0.05, b1 0.10, b2 0.09, panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G8 hood IoU: hood pair with whitened mask IoU under 0.8

What was said

- `0 to 16140 ms`: hood looks clean,

roof

coverage: pickup 0.0 s (not_filmed); return 7.5 s (glimpsed)

no pickup frame for this panel



return: video time 19.33 s; marks return_roof_kf1_m1, return_roof_kf1_m2, return_roof_kf1_m3, return_roof_kf1_m4, return_roof_kf1_m5, return_roof_kf1_m6

Verdicts

marks	verdict	rule ids	distance	detail
return_roof_kf1_m1, return_roof_kf1_m2, return_roof_kf1_m3, return_roof_kf1_m4, return_roof_kf1_m5, return_roof_kf1_m6 dirt S	not comparable	L6, G1, G2, G6	no pair	Stays Put: drift 0.06, b1 0.03, b2 0.01, not panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark


L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G6 side uncertain: side_uncertain, or front_sign null, on either walk

trunk lid

coverage: pickup 6.6 s (filmed); return 13.9 s (filmed)



pickup: video time 15.47 s; marks pickup_trunk_lid_kf1_m1, pickup_trunk_lid_kf1_m2, pickup_trunk_lid_kf1_m3, pickup_trunk_lid_kf1_m4, pickup_trunk_lid_kf1_m5, pickup_trunk_lid_kf1_m6



return: video time 19.07 s; marks return_trunk_lid_kf1_m1, return_trunk_lid_kf1_m2, return_trunk_lid_kf1_m3, return_trunk_lid_kf1_m4, return_trunk_lid_kf1_m5, return_trunk_lid_kf1_m6, return_trunk_lid_kf2_m1, return_trunk_lid_kf2_m2, return_trunk_lid_kf2_m3, return_trunk_lid_kf2_m4, return_trunk_lid_kf2_m5, return_trunk_lid_kf2_m7, return_trunk_lid_kf2_m8, return_trunk_lid_kf2_m9, return_trunk_lid_kf2_m10, return_trunk_lid_kf2_m11, return_trunk_lid_kf2_m12

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_trunk_lid_kf1_m1, pickup_trunk_lid_kf1_m2, pickup_trunk_lid_kf1_m3, pickup_trunk_lid_kf1_m4, pickup_trunk_lid_kf1_m5, pickup_trunk_lid_kf1_m6, return_trunk_lid_kf1_m1, return_trunk_lid_kf1_m2, return_trunk_lid_kf1_m3, return_trunk_lid_kf1_m4, return_trunk_lid_kf1_m5, return_trunk_lid_kf1_m6, return_trunk_lid_kf2_m1, return_trunk_lid_kf2_m10, return_trunk_lid_kf2_m11, return_trunk_lid_kf2_m12, return_trunk_lid_kf2_m2, return_trunk_lid_kf2_m3, return_trunk_lid_kf2_m4, return_trunk_lid_kf2_m5, return_trunk_lid_kf2_m7, return_trunk_lid_kf2_m8, return_trunk_lid_kf2_m9` `chip S`	not comparable	L6, G2, G4	no pair	Stays Put: drift 0.07, b1 0.16, b2 0.09, not panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

What was said

- `0 to 16140 ms`: A|> trunk lid two small chips by the edge

front bumper



pickup: video time 3.60 s; marks pickup_front_bumper_kf1_m1, pickup_front_bumper_kf1_m2



return: video time 17.60 s

coverage: pickup 7.5 s (filmed); return 9.7 s (filmed)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_front_bumper_kf1_m1, pickup_front_bumper_kf1_m2` `dirt M`	**not comparable**	L6, G2, G4	no pair	Stays Put: drift 0.77, b1 0.18, b2 0.79, not panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

What was said

- `0 to 16140 ms`: pick up work, starting at the front bumper,

rear bumper



pickup: video time 17.67 s; marks pickup_rear_bumper_kf1_m1, pickup_rear_bumper_kf1_m2, pickup_rear_bumper_kf2_m1



return: video time 2.00 s; marks return_rear_bumper_kf1_m1

coverage: pickup 6.5 s (filmed); return 6.1 s (filmed)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_rear_bumper_kf1_m1, pickup_rear_bumper_kf1_m2, pickup_rear_bumper_kf2_m1, return_rear_bumper_kf1_m1` `dirt M`	**not comparable**	L6, G2, G4	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7

What was said

- `16700 to 18540 ms`: rear bumper looks fine

left front wheel





return: video time 18.40 s; marks return_left_front_wheel_kf1_m1



pickup: video time 0.33 s; marks pickup_left_front_wheel_kf1_m1

coverage: pickup 0.7 s (glimpsed); return 2.5 s (glimpsed)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_left_front_wheel_kf1_m1`, `return_left_front_wheel_kf1_m1` `dirt S`	**not comparable**	L6, G1, G2	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop

left rear wheel



pickup: video time 10.80 s



return: video time 6.87 s

coverage: pickup 6.7 s (glimpsed); return 6.9 s (filmed)

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G2, G4, G6	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G6 side uncertain: side_uncertain, or front_sign null, on either walk

right front wheel



no return frame for this panel

pickup: video time 7.87 s; marks pickup_right_front_wheel_kf1_m1

coverage: pickup 4.5 s (filmed); return 0.0 s (not_filmed)

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_right_front_wheel_kf1_m1` `dirt S`	**not comparable**	L6, G1, G2	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop

right rear wheel

no pickup frame for this panel



return: video time 9.20 s

coverage: pickup 6.7 s (glimpsed); return 8.8 s (filmed)

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1, G2	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop

headlights

coverage: pickup 8.3 s (glimpsed); return 15.3 s (glimpsed)



pickup: video time 3.87 s; marks pickup_headlights_kf1_m1



return: video time 18.07 s; marks return_headlights_kf1_m1

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_headlights_kf1_m1, return_headlights_kf1_m1` `reflection M`	**not comparable**	L6, G1, G2	no pair	Stays Put: drift 0.22, b1 0.49, b2 0.16, not panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop

tail lights

coverage: pickup 7.7 s (glimpsed); return 20.3 s (glimpsed)



pickup: video time 19.67 s



return: video time 7.80 s

Verdicts

marks	verdict	rule ids	distance	detail
	not comparable	L6, G1	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk

mirrors

coverage: pickup 4.0 s (glimpsed); return 7.4 s (glimpsed)



pickup: video time 6.67 s



return: video time 5.93 s; marks return_mirrors_kf2_m1

Verdicts

marks	verdict	rule ids	distance	detail
`return_mirrors_kf2_m1` `reflection S`	**not comparable**	L6, G1, G2, G3, G4, G6	no pair	size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe
G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
G6 side uncertain: side_uncertain, or front_sign null, on either walk

windshield

coverage: pickup 10.9 s (filmed); return 15.7 s (filmed)



pickup: video time 18.73 s; marks pickup_windshield_kf1_m1, pickup_windshield_kf1_m2, pickup_windshield_kf1_m3, pickup_windshield_kf1_m4, pickup_windshield_kf2_m1, pickup_windshield_kf2_m2, pickup_windshield_kf2_m3



return: video time 18.07 s; marks return_windshield_kf1_m1, return_windshield_kf1_m2, return_windshield_kf1_m3, return_windshield_kf1_m4

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_windshield_kf1_m1, pickup_windshield_kf1_m2, pickup_windshield_kf1_m3, pickup_windshield_kf1_m4, pickup_windshield_kf2_m1, pickup_windshield_kf2_m2, pickup_windshield_kf2_m3, return_windshield_kf1_m1, return_windshield_kf1_m2, return_windshield_kf1_m3, return_windshield_kf1_m4` `reflection S`	**not comparable**	L6, G2	no pair	Stays Put: drift 0.13, b1 0.07, b2 0.12, panned; recorded only: Stays Put is not calibrated yet and changes no label size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G2 crop condition: wet, dirty or glare flag from Spark on either crop

rear window

coverage: pickup 7.2 s (filmed); return 4.9 s (glimpsed)



pickup: video time 18.73 s; marks pickup_rear_window_kf1_m1, pickup_rear_window_kf1_m2, pickup_rear_window_kf1_m3, pickup_rear_window_kf1_m4



return: video time 0.07 s; marks return_rear_window_kf1_m1, return_rear_window_kf1_m2, return_rear_window_kf1_m3, return_rear_window_kf1_m4, return_rear_window_kf2_m1, return_rear_window_kf2_m2, return_rear_window_kf2_m3, return_rear_window_kf2_m4

Verdicts

marks	verdict	rule ids	distance	detail
`pickup_rear_window_kf1_m1, pickup_rear_window_kf1_m2, pickup_rear_window_kf1_m3, pickup_rear_window_kf1_m4, return_rear_window_kf1_m1, return_rear_window_kf1_m2, return_rear_window_kf1_m3, return_rear_window_kf1_m4, return_rear_window_kf2_m1, return_rear_window_kf2_m2, return_rear_window_kf2_m3, return_rear_window_kf2_m4` dirt M	**not comparable**	L6, G1, G2, G3	no pair	Stays Put: no track (SAM did not follow the mark through the clip) size not stated: no ruler within 0.6 m of this mark

L6 not comparable: a G rule failed for the panel; both best frames still show
G1 not filmed: the panel is not 'filmed' in either walk
G2 crop condition: wet, dirty or glare flag from Spark on either crop
G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe

Panels without frames

panel	coverage
left front fender	pickup: not_seen (0.0 s); return: not_seen (0.0 s)

Not comparable

panel	rule ids	why
left front door	G1, G2, G4	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
left rear door	G1	G1 not filmed: the panel is not 'filmed' in either walk
right front door	G4, G9	G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G9 mask definition differs: window_subtracted differs between the paired keyframes
right rear door	G1, G4, G9	G1 not filmed: the panel is not 'filmed' in either walk G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G9 mask definition differs: window_subtracted differs between the paired keyframes
left rear fender	G1, G3, G4, G6	G1 not filmed: the panel is not 'filmed' in either walk G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G6 side uncertain: side_uncertain, or front_sign null, on either walk
right front fender	G1	G1 not filmed: the panel is not 'filmed' in either walk
right rear fender	G1, G2, G4	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
hood	G2, G4, G8	G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G8 hood IoU: hood pair with whitened mask IoU under 0.8
roof	G1, G2, G6	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G6 side uncertain: side_uncertain, or front_sign null, on either walk
trunk lid	G2, G4	G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
front bumper	G2, G4	G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
rear bumper	G2, G4	G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7
left front wheel	G1, G2, K10	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop K10 one-mark wheel: one-mark wheel outside the radius, type and size rule

left rear wheel	G1, G2, G4, G6	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G6 side uncertain: side_uncertain, or front_sign null, on either walk
right front wheel	G1, G2	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop
right rear wheel	G1, G2	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop
headlights	G1, G2	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop
tail lights	G1	G1 not filmed: the panel is not 'filmed' in either walk
mirrors	G1, G2, G3, G4, G6	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe G4 mask IoU: whitened mask IoU of the paired keyframes under 0.7 G6 side uncertain: side_uncertain, or front_sign null, on either walk
windshield	G2	G2 crop condition: wet, dirty or glare flag from Spark on either crop
rear window	G1, G2, G3	G1 not filmed: the panel is not 'filmed' in either walk G2 crop condition: wet, dirty or glare flag from Spark on either crop G3 blurry keyframe: sharpness below 0.4 of the candidates' max on either keyframe

Method and limits

Every verdict on the panel pages was decided by code from the numbers below. The thresholds were frozen into this run under config hash `1cf41037cf2ed72ad3593312153cd6b572dc226f4e1f3f68c11dc345f84eacd3`. Rebuilding the derived files from the stored model answers and these thresholds gives the same bytes when the line below says so.

rebuild	event chain verified to the head on page 1 and any original still in quarantine re-hashed at sheet time; run walkaround verify to compare a rebuild
storage	Model requests were sent with storage off and the models accepted it; nothing was kept after the run. Files API upload deleted: 2026-10-31T22:57:26.030Z; quarantine deleted: 2026-10-31T22:57:26.030Z.
Hertz thresholds	Example thresholds Hertz published (REV 7.2025), illustrative only, quoted from its Damage Charges support page saved 2026-10-26: a body scratch is billable when it cannot be covered by a credit card (2 in x 3.5 in), or when scratches over 1 in together exceed that area; a dent with a diameter over 1 in, or multiple dents; a wheel, rim or hubcap scratch or scuff over 1 in; any crack or chip in glass. Paint transfer or scuffs that do not break the paint are listed as Ordinary Wear and not charged.

Eval numbers

No eval run is attached to this sheet; the README carries the eval tables with their N.

Calibration

tau_pre (already there below)	`0.4`
tau_eye (needs your eye below)	`0.8`
tau_fix (Stays Put fixed below)	`0.08`
sigma_frame / sigma_spark / sigma_view / sigma_within	`None / 0.117 / 0.064602 / 0.13365`
calibrated	no: tau_pre hit its cap, so the matcher is not calibrated for this run

Model calls (from runs/ledger.jsonl)

kind	calls	dollars	quantity
sam_image	170	0.4250	170 images
sam_video	64	2.4896	12448 frames
spark	63	0.3144	121834 tokens
voice	1	0.0009	19.76 s
total	298	3.2299	

What was blurred

- pickup: SAM image checks on 27 keyframes found a plate on 14 and faces on 0; the display proxy was pixelated from the plate and face tracks
- return: SAM image checks on 34 keyframes found a plate on 11 and faces on 0; the display proxy was pixelated from the plate and face tracks

What was deleted and when

kind	target	sha256	bytes	deleted at	reason	receipt

file	media/pickup.proxy.mp4	a5327b83fd9f	16354164	2026-10-31T22:55:10Z	unblurred proxy deleted at blur.done	
file	media/return.proxy.mp4	095b907b280c	15180664	2026-10-31T22:55:11Z	unblurred proxy deleted at blur.done	
files_api	file-2203878920160465	a5327b83fd9f		2026-10-31T22:57:26.030Z	run end (pickup proxy)	{'deleted': True, 'id': 'file-2203878920160465', 'object': 'file'}
files_api	file-3478672575647355	095b907b280c		2026-10-31T22:57:26.030Z	run end (return proxy)	{'deleted': True, 'id': 'file-3478672575647355', 'object': 'file'}
quarantine	quarantine/pickup.orig	25f68a8992c9	96182720	2026-10-31T22:57:26.030Z	run end	
quarantine	quarantine/return.orig	f49b432f2932	107096877	2026-10-31T22:57:26.030Z	run end	

What the seal does not prove

- which car was filmed, unless the plate was kept on this sheet at the renter's request
- that the walk was not staged before the upload; the seal dates the bytes, not the events in them
- anything about the pickup condition when the seal was made after the return

The seal is offered as a process record under FRE 901(b)(9): the same inputs through the same code give the same output, and the method page states that code's inputs.

Thresholds frozen into this run

claim.align_landmark_fit	False
claim.dark_v_max	0.15
claim.drawn_box_inside_saturated_max	0.1
claim.drawn_box_perimeter_saturated_min	0.3
claim.drawn_box_saturation_min	0.5
claim.full_panel_area_min	0.03
claim.full_panel_border_max	0.15
claim.landmark_fit_min_landmarks	3
claim.landmark_fit_residual_max_frac	0.1
claim.low_res_px	480
claim.on_panel_frac	0.025
claim.passenger_side_is	right
claim.r_claim_full_panel	0.1
claim.r_claim_two_landmarks	0.2
claim.roi_pad_frac	0.25
claim.roi_region_max_panel_frac	0.4
claim.sam_vote_requests	14

claim.scanner_style_saturation_max	0.08
cost.d1_budget_usd	25
cost.pair_estimate_usd_10fps	4.9
cost.pair_estimate_usd_15fps	6.2
cost.pickup_check_estimate_usd	2.6
cost.sam_image_usd	0.0025
cost.sam_video_min_frames	50
cost.sam_video_usd_per_frame	0.0002
cost.voice_usd_per_hour	0.18
coverage.area_only_box_area_frac_min	0.01
coverage.c_present_floor	0.5
coverage.filmed_area_frac_min	0.03
coverage.filmed_completeness_min	0.85
coverage.filmed_sharpness_rel_min	0.4
coverage.glimpsed_c_percentile	25
coverage.odometer_ask_once	True
coverage.topup_order	['wheels', 'lower_bumpers', 'rest']
dedup.cluster_radius_units	0.2
dedup.collinear_angle_deg	10
dedup.collinear_gap_units	0.1
dedup.count_mode_new_point_min_units	0.1
dedup.droplet_max_size_units	0.03
dedup.droplet_min_marks	8
dedup.group_min_marks	3
dedup.group_radius_units	0.5
dedup.road_spray_band_bottom_frac	0.25
dedup.road_spray_min_marks	3
dedup.small_mark_px	12
dedup.small_mark_units	0.03
eval.billable_buckets_mm	[10, 20, 25.4]
eval.false_mark_radius_units	0.35
eval.recall_radius_units	0.25
eval.report_pairs	['p2xr2', 'cross', 'multi_day']
eval.threshold_fit_pairs	['pseudo', 'p1xr1']
geometry.bumper_arc_fallback_tau_factor	1.5
geometry.carried_moments_check_frames	5
geometry.carried_moments_residual_max_units	0.02
geometry.hood_depth_thirds	3
geometry.perspective_residual_center_max	0.08
geometry.perspective_residual_corner_max	0.25
geometry.unit_cm_along_door	35
geometry.unit_cm_vertical_door	29
geometry.whiten_affine_invariance_tol	1e-06
matching.band_radius_factor	0.5
matching.chance_match_density_formula	pi * tau_pre^2 / 12 * mark_density
matching.cm_per_unit_for_print	35
matching.compatible_types	['scratch', 'scuff', 'chip']
matching.hood_mask_iou_min	0.8

matching.margin_min_tau_pre_factor	0.5
matching.mask_iou_min	0.7
matching.pseudo_pair_percentile	90
matching.pseudo_pair_share_min	0.9
matching.ratio_test_min	1.5
matching.sharpness_rel_min	0.4
matching.sigma_spark	0.117
matching.size_cost_factor	0.1
matching.tau_eye_factor	2.0
matching.tau_pre0_floor	0.25
matching.tau_pre0_sigma_factor	3.535534
matching.tau_pre_cap	0.4
matching.type_cost_compatible	0.1
matching.type_cost_incompatible	0.4
matching.wheel_min_marks_for_shift	2
matching.wheel_radius_tolerance	0.1
matching.wheel_size_factor_max	2.0
media.anchor_clip_frames	180
media.anchor_clip_half_window_s	6.0
media.chunk_bytes	8388608
media.chunk_route_max_body_bytes	9437184
media.chunks_in_flight	3
media.clip_crf	18
media.clip_frames	91
media.clip_half_window_s	1.5
media.clip_prompt_frame	45
media.clip_size_px	1008
media.files_expires_after_s	3600
media.inline_data_url_max_bytes	52428800
media.other_route_max_body_bytes	1048576
media.proxy_codec	libx264
media.proxy_crf	20
media.proxy_fps	15
media.proxy_fps_fallbacks	[10, 30]
media.proxy_max_edge	960
media.proxy_preset	medium
media.source_fps_assumed	30
media.upload_max_bytes	1073741824
media.upload_warn_bytes	524288000
media.wav_rate	24000
nouns.d1_text_prompts	['scuff']
nouns.door_handle_image_requests_per_pair	24
nouns.image_only	['door handle']
nouns.lanes	['car', 'license plate', 'face', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window']
nouns.never_prompt	['front bumper', 'rear bumper']
nouns.privacy	['license plate', 'face']

nouns.topup_always	['car', 'license plate', 'face']
nouns.voice_keywords	['car', 'car door', 'bumper', 'wheel', 'hood', 'trunk lid', 'fender', 'roof', 'headlight', 'tail light', 'side mirror', 'windshield', 'rear window', 'car window', 'scuff', 'scratch', 'chip', 'dent', 'crack', 'tape', 'odometer']
orchestrator.baseten_rpm	30
orchestrator.baseten_semaphore	1
orchestrator.caps_if_no_card_ceiling.pair_runs_per_day	0
orchestrator.caps_if_no_card_ceiling.pickup_runs_per_day	3
orchestrator.daily_card_ceiling_cents	2000
orchestrator.decode_workers	2
orchestrator.health_probe_failures_to_pause	3
orchestrator.health_probe_interval_s	300
orchestrator.judging_card_ceiling_cents	5000
orchestrator.max_concurrent_runs	2
orchestrator.media_workers	2
orchestrator.pair_runs_per_day	1
orchestrator.pdf_timeout_s	60
orchestrator.pickup_runs_per_day	6
orchestrator.priority_wave_size	6
orchestrator.queue_eta_from_last_runs	3
orchestrator.rate_limit_backoff_base_s	0.5
orchestrator.rate_limit_retries	6
orchestrator.replay_fixed_total_s_estimate	35
orchestrator.replay_recorded_delay_cap_ms	2000
orchestrator.request_retries	1
orchestrator.request_timeout_s	240
orchestrator.run_deadline_s	720
orchestrator.run_spend_ceiling_cents	800
orchestrator.sam_image_semaphore	16
orchestrator.sam_video_semaphore_global	32
orchestrator.sam_video_semaphore_per_run	16
orchestrator.spark_semaphore	12
orchestrator.sse_ping_s	15
orchestrator.sweeper_interval_s	3600
orchestrator.volume_min_free_bytes	524288000
panels.anchor_absorb_iou_min	0.5
panels.anchor_max_frames_per_panel	3
panels.anchor_negative_point_seam_offset_box_widths	0.1
panels.anchor_pass_coverage_below	0.7
panels.area_floor_default	0.02
panels.area_floor_small	0.005
panels.border_frac_keyframe_max	0.15
panels.c_floor	None
panels.car_box_containment_min	0.8
panels.car_mask_containment_min	0.8
panels.crop_long_edge_px	1280
panels.crop_pad_frac	0.1

panels.direction_min_px_per_frame	2.0
panels.direction_phase_corr	False
panels.fragment_gap_split_frames	2.5
panels.fragment_gap_split_s	0.5
panels.fragment_min_frames	2
panels.fragment_min_s	0.5
panels.glare_s_max	40
panels.glare_v_min	250
panels.keyframe_box_pass_candidates	9
panels.keyframe_decode_budget_s_per_video	60
panels.keyframe_min_gap_s	0.5
panels.keyframe_score_exponents.area	1.0
panels.keyframe_score_exponents.completeness	1.0
panels.keyframe_score_exponents.frontality	1.0
panels.keyframe_score_exponents.one_minus_glare	1.0
panels.keyframe_score_exponents.sharpness	1.0
panels.keyframe_top_k	3
panels.keyframe_top_k_under_budget	2
panels.merge_area_ratio	[0.6, 1.6]
panels.merge_aspect_tolerance	0.2
panels.merge_gap_max_s	1.0
panels.merge_pred_dist_box_widths	0.5
panels.prompt_box_pad_px	2
panels.side_vote_margin_min	1
panels.side_vote_weights.R1	2
panels.side_vote_weights.R2	1
panels.side_vote_weights.R3	1
panels.side_vote_weights.R4	1
panels.small_nouns	['side mirror', 'headlight', 'tail light', 'license plate', 'face']
privacy.files_delete_retries	3
privacy.image_check_nouns	['license plate', 'face']
privacy.image_checks_in_flight	16
privacy.keep_plate_default	False
privacy.pixel_block_px_at_4k	20
privacy.run_retention_hours	24
privacy.track_box_dilation_frac	0.1
privacy.track_box_dilation_px	24
privacy.track_gap_bridge_s	0.5
privacy.unblurred_temp_max_minutes	30
ruler.axis_tilt_correction_max_deg	30
ruler.body_scuff_ordinary_wear	True
ruler.bound_px_per_side	2
ruler.camera_hfov_deg	70
ruler.d1_plate_wheel_ppi_agreement	0.15
ruler.mark_min_px	8
ruler.plate_c_min	0.5
ruler.plate_long_side_in	12
ruler.plate_min_px	60

ruler.plate_tilt_max_deg	30
ruler.ruler_max_distance_m	0.6
ruler.threshold_body_scratch_in	3.5
ruler.threshold_dent_in	1.0
ruler.threshold_wheel_in	1.0
ruler.tire_diameter_formula	D = 2 * (SW * AR / 2540 + RD / 2)
ruler.wheel_c_min	0.5
ruler.wheel_min_px	120
spark.confidence_levels	['low', 'medium', 'high']
spark.d1_jaccard_pass	0.7
spark.d1_sigma_pass_frac_of_crop_width	0.02
spark.effort	low
spark.grid	1000
spark.grid_slack	20
spark.image_long_edge_px	1280
spark.input_tokens_per_1280_crop_estimate	1400
spark.jpeg_quality	90
spark.landmarks.bumper	['plate_corner_tl', 'plate_corner_tr', 'plate_corner_bl', 'plate_corner_br', 'fog_lamp', 'grille_corner', 'sensor']
spark.landmarks.door	['handle', 'lock', 'mirror_base', 'window_front_corner', 'window_rear_corner', 'wheel_arch', 'lower_trim', 'badge']
spark.landmarks.hood	['badge', 'washer_nozzle', 'front_corner_left', 'front_corner_right']
spark.landmarks.wheel	['hub', 'rim_lip', 'valve']
spark.landmarks_max	4
spark.mark_types	['scratch', 'scuff', 'chip', 'dent', 'crack', 'dirt', 'reflection', 'unsure']
spark.max_output_tokens	4000
spark.model	muse-spark-1.3
spark.retry_max_output_tokens	8000
spark.schema_names	['marks_v1', 'count_v1', 'look_v1', 'seed_v1', 'claim_name_v1', 'timeline_v1', 'note_prefill_v1']
spark.schema_retry_count	1
spark.second_look_engine	spark_open
spark.second_looks_per_pair_max	25
spark.size_classes	['S', 'M', 'L']
spark.store	False
spark.stream_when_expected_over_s	30
staysput.b1_floor	0.15
staysput.b2_floor	0.05
staysput.cap_enabled	False
staysput.check_box_covered_min	0.9
staysput.clip_blur_dilation_frac	0.3
staysput.clip_frames_max	181
staysput.control_blob_max_frac	0.15
staysput.control_blob_min_px	9
staysput.curvature_boundary_units	0.15
staysput.d1_pass_box_share	0.8

staysput.d1_pass_drift_max	0.08
staysput.d1_reflection_drift_min	0.16
staysput.highlight_s_percentile	10
staysput.highlight_v_percentile	95
staysput.max_clips_per_walk	16
staysput.max_objects_per_clip	16
staysput.min_bbox_px_at_4k	12
staysput.min_drift_frames	10
staysput.no_track_box_share_below	0.8
staysput.panned_inconclusive_share_caption_threshold	0.5
staysput.reflection_control_from_hood_glare	True
staysput.sign_agreement_min	0.8
staysput.sign_pair_gap_frames	5
staysput.sign_pairs_min	8
staysput.sign_panel_dx_min_px_per_frame	2.0
staysput.sliding_factor	2.0
staysput.tau_fix_floor	0.08
staysput.tau_fix_sigma_factor	3.0
staysput.window_frac_of_panel_width	0.3
staysput.window_mark_margin	1.5
staysput.window_min_px	400
staysput.window_share_overlap_min	0.5
voice.chip_min_ms	100
voice.max_audio_s	600
voice.max_body_bytes	33554432
voice.mode	ENDPOINTING
voice.model	muse-voice-transcribe-1.0
voice.modes_allowed	['PUSH_TO_TALK', 'ENDPOINTING', 'DIARIZATION']
voice.pin_fallback	turn_start_panel
voice.seeds_per_walk_max	16

Appendix A certification

```
Renter's certification

I, [name], state that:
1. I recorded the videos listed below myself, at pickup on [date] and at return on [date], of the vehicle
under
   rental agreement [number].
2. I uploaded them to Walkaround without editing them, and the sha256 hashes on page 1 match the files on
my phone.
3. I understand this sheet is evidence support, not legal advice, and that it was produced by code from
my videos.

- pickup: uco3d_7336_narrated.mp4 (sha256 25f68a8992c9...)
- return: uco3d_50152-5241-46685.mp4 (sha256 f49b432f2932...)

Signed: _____   Date: _____

This is a signed statement, not a notarized affidavit.
```

Appendix B glossary

```
Glossary

already there: the same mark was found at pickup within tau_pre of its return position (rule L3).
needs your eye: a human should look; the pair sat in the band between tau_pre and tau_eye, or a cap (K1
to K14) applied (L4).
new or unseen: a return mark with no pickup mark near it; new, or not filmed at pickup (L2).
not seen at return: a pickup mark with no return mark near it (L1).
not comparable: a panel gate failed (G1 to G10); both best frames still show with the reason (L6).
units: panel-normalized distance; 1 unit is about 35 cm along a door (the about-cm beside it uses that).
tau_pre, tau_eye: the two distance thresholds, calibrated from the run's own repeat frames; printed on
the method page.
Stays Put: a check that a mark moves with the panel through a short clip; a reflection slides, a scratch
stays put.
sha256: the fingerprint of a file; one changed byte changes it.
sealed: the manifest of hashes was written and offered for time stamping before any model saw the video.
config hash: the fingerprint of every threshold the code used; it changes when a threshold changes.
rule id: the row of the decision table that produced a label; G gates a panel, K caps a mark, L names a
label, E is a claim exit.
```

Appendix C verify it yourself

```
Verify it yourself (5 steps; none needs Walkaround's server)

1. Hash the video file on your phone or computer and compare it with page 1:
   shasum -a 256 <your video file>     (Linux: sha256sum <your video file>)
   pickup: 25f68a8992c980976df1352c0d2894eca301a13b576bcac397e61952e1440efb
   return: f49b432f2932d4a9ffeb59881c992c5054e09a2d7d6b816a41d5dd1df9c8646b
2. Read the OpenTimestamps proof (pip install opentimestamps-client):
   ots info bundle/manifest.json.ots
3. Verify it against the Bitcoin block, or drop the .ots file on https://opentimestamps.org :
   ots verify bundle/manifest.json.ots
4. Verify the RFC 3161 token from freetsa (2026-10-31T22:50:54Z) with freetsa's certificates (download
https://freetsa.org/files/cacert.pem and https://freetsa.org/files/tsa.crt):
   openssl ts -verify -data bundle/manifest.json -in bundle/manifest.json.tsr -CAfile cacert.pem -
untrusted tsa.crt
5. Re-hash every file in the bundle and rebuild the derived files from the stored model answers:
   walkaround verify pairC_core1
```

Letter: write to the company first

```
Write to the company first

[date]

To: [rental company], damage claims
Re: rental agreement [number], picked up [date], returned [date]

I received a damage charge of [amount] for [description]. Before anything else I ask for the full damage
report,
the written repair estimate and every photograph or scan the company holds for this rental, including the
pickup
inspection images. Hertz's own support page says customers can request more images.

I recorded a walkaround video at pickup and at return. The files were hashed and sealed before any
analysis:
- pickup: uco3d_7336_narrated.mp4, 96182720 bytes, sha256
25f68a8992c980976df1352c0d2894eca301a13b576bcac397e61952e1440efb, camera time not present, received 2026-
10-31T22:50:49.676Z
- return: uco3d_50152-5241-46685.mp4, 107096877 bytes, sha256
f49b432f2932d4a9ffeb59881c992c5054e09a2d7d6b816a41d5dd1df9c8646b, camera time not present, received 2026-
10-31T22:50:49.806Z
- sealed at 2026-10-31T22:50:50.063Z
- Walkaround run pairC_core1; the panel-by-panel evidence sheet is attached

The attached sheet shows the panel in question at pickup and at return with the marks drawn on both
frames. The
sheet is evidence support, not legal advice, and I ask that it be read next to your own images.

If the charge stands after you have reviewed it, I will obtain an alternative written estimate within 10
business
days. Card network rules (Visa Core Rules 13.3 and 13.5; 15 USC 1666i) require that I first try to
resolve the
charge with you; this letter is that attempt. Please reply within 14 days to [email].

[name]
```