




APIS – 2026 YTD

EHS MONTHLY REPORT




June 30, 2026

APIS - 2026 YTD EHS MONTHLY REPORT

▶ ACCIDENT AND INCIDENT of Body Plant



▶ ACCIDENT AND INCIDENT of End Plant



APIS - 2026 FIRST AID REPORT

▶ INFORMATION

Name of victim: Nguyen Nhut Huy – Technician

Time: 09:30 AM, date: June 23th 2026

Place: Inker workshop

Situation:

Lúc 09:30 ngày 23 tháng 06 năm 2026, Nhân viên kỹ thuật inker đang thao tác đưa shape vào bên trong Fountain roll, thì fountain tuột nhanh từ trên xuống trúng vị trí ngón tay trở phải của bạn nhân viên đang đặt vào vị trí lỗ hở trên cây shape gây ra vết thương.

At 9:30 AM on June 23, 2026, while an inker technician was inserting the formwork into the fountain roll, the fountain roll slipped rapidly from above and struck the technician's right index finger, which was positioned over the cooling water inlet hole on the formwork, causing injury.

Kết luận sau khi đi khám tại bệnh viện: vết thương nhẹ tại ngón tay trở bàn tay phải; không gãy xương.

Conclusion after examination at the hospital: minor injury to the index finger of the right hand; no fracture.


Direct cause:

Thao tác công việc không tuân thủ yêu cầu an toàn lắp đặt cấu kiện cơ khí.

The work procedures did not comply with the safety requirements for installing mechanical components.



APIS - 2026 FIRST AID REPORT




APIS - 2026 YTD EHS MONTHLY REPORT

▶ NEARMISS ACCIDENT


APIS – 2026 NEARMISS ACCIDENT of Body Plant

■ Total ■ Target



APIS - 2026 NEARMISS ACCIDENT of End Plant


■ Total ■ Target




APIS - 2026 YTD EHS MONTHLY REPORT

► 5S AUDIT RESULT

APIS - 2026 5S AUDIT RESULT of Body Plant




APIS – 2026 5S AUDIT RESULT of End Plant




APIS - 2026 YTD EHS MONTHLY REPORT

► COST FOR WASTE TREATMENT

APIS - 2026 COST FOR WASTE TREATMENT of Body Plant




APIS - 2026 COST FOR WASTE TREATMENT of End Plant




APIS - 2026 YTD EHS MONTHLY REPORT

WASTE TREATMENT of Body Plant


APIS – 2026 YTD TRAMP OIL WASTE




APIS – 2026 YTD LACQUER & VARNISH MIX WATER WASTE



APIS – 2026 YTD GLOVES AND RAGS STICK OIL & CHEMICAL WASTE




APIS – 2026 YTD SLUDGE WASTE FROM WWTP




APIS - 2026 YTD EHS MONTHLY REPORT

▶ WASTE TREATMENT of End Plant

APIS – 2026 YTD COMPOUND MIX WATER WASTE




APIS – 2026 YTD GLOVES AND RAGS STICK OIL & CHEMICAL WASTE




APIS - 2026 YTD EHS MONTHLY REPORT

WASTE RECYCLE – Body Plant


2026 – YTD LAYER PAD DISPOSAL




PALLET ALUMINUM COIL (Ton)




COIL COVER STRAPPING BAND (Ton)




CARTON AND PAPER (Ton)



STEEL DRUM (Ton)




OTHER WOODS (Ton)




APIS - 2026 YTD EHS MONTHLY REPORT

WASTE RECYCLE – End Plant


2026 – YTD LAYER PAD DISPOSAL




PALLET ALUMINUM COIL (Ton)




COIL COVER STRAPPING BAND (Ton)




CARTON AND PAPER (Ton)



STEEL DRUM (Ton)




OTHER WOODS (Ton)




APIS - 2026 YTD EHS MONTHLY REPORT

WASTE WATER TREATMENT - BODYLINE


FLUORIDE (mg/l)



COD (mg/l)



pH



APIS - 2026 YTD EHS MONTHLY REPORT

THANK YOU!

