
## Results for GRAPPA implementation:




Ground Truth Coil Images

Before Reconstruction


After


After, Coil Combined

R= 2:










R = 6:



Artifacts begin to become noticeable at R = 6R = 6 with additional lines of calibration space:

