A-SAFE



Alarm Bar

PRH-1036-A-SAFE-20122024-4

Alarm Bar is for internal use only

Production

Dimensions (mm/inches)

- **A** 2000 / 78¾
- **B** 130 / 5⅛
- **C** Standard - Max 3m / 118⅛
  Option - Max 15m / 590⅝



Colour Combination

Standard

Rail
Standard Yellow
RAL 1007*
PANTONE 7548*

*Please note that the RAL and PANTONE colours listed are the closest match to standard A-SAFE colours, but may not be exact matches of the actual product colour and should be used for guidance only.

Product Material

Rail

MEMAPLEX™

Ultimate strength polymer created from an exclusive composition of the most sophisticated polyolefins and rubber additives, expertly blended for unequalled strength and flexibility.

Weight of product

Per Alarm Bar
9.45 Kg / 20.83 lbs

Minimum order quantities

Not applicable on this product

Suitability

Environment

Internal use only

ATEX Suitability

Not suitable in an explosive atmosphere

Vehicle Suitability

High Rack Stacker

Electric Reach Truck

Fit for purpose application

Building and equipment protection

Industrial door protection

Impact Zone
Height dependant

Material Properties	MEMAPLEX™
Temperature Range	-10°C to 50°C
Ignition Temperature	370°C to 390°C
Flash Point	350°C to 370°C
Toxicity	Not Hazardous
Chemical Resistance	Excellent - ISO/TR 10358
Weathering Stability (Grey Scale)	5/5*
Light Stability (Blue Wool Scale)	7/8**
Static Rating (Surface Resistivity)	10^{15} - 10^{16} Ω
Hygiene Seals	No

* Weathering scale 1 is very poor and 5 is excellent ** Light stability scale 1 is very poor and 8 is excellent

Fire information

Manufactured from polypropylene. Polypropylene has an ignition temperature of 370º Celsius which is significantly higher than materials such as wooden pallets or polymers such as flexible PVC. This means that for combustion of an A-SAFE Alarm Bar to occur, a facility fire would need to be both large and well advanced, by which time any personnel would have already been evacuated to safety.

Polymer has been engineered to remain stable up to a temperature of 350º Celsius. In contrast, PVC starts breaking down at between 249º Celsius and 273º Celsius, and materials such as wood will burn instantly.

Our material has been specially developed to minimise the release of smoke during combustion. Furthermore, unlike environmentally hazardous polymers like PVC, it does not release harmful dioxins, hydrogen cyanide or hydrogen chloride when burnt.

Environmental information

Research conducted by a leading plastic solutions company* showed that producing one metric tonne of polymer generates less carbon emissions than producing a tonne of steel**. Therefore, from the very outset of raw material production, polymer provides a significant CO_2 saving over steel.

For more information visit A-SAFE.com

* http://www.borealisgroup.com ** www.liloontheweb.org.uk/handbook/carbonfootprint

Recycling Information		
Packaging	Rail	Electrical Components
Mixed Recycled	5	

Part Codes

1. M-01-01-0001 - Cap
2. B-04-01-0062 - Foam Insert
3. S-02-02-0024 - Battery Pack
4. B-02-02-0143 - Wire and Gripple - 3m Standard
   B-02-02-0144 - Wire and Gripple - 15m (Option)
5. B-04-01-0067 - Screw Cap
6. B-02-02-0065 - Screw (4.2 x 12.7)

Items below will not be sent out as replacements

7. P-03-03-0001 Alarm Bar and LED Strip
8. B-06-02-0006 - Loom Wire
9. B-02-02-0048 - Captive Nut
10. B-06-02-0002 - Buzzer
11. B-06-02-0001 - PCB
12. B-03-02-0071 - Bracket



Trouble Shooting

Trouble shooting guide for the Alarm Bar LED and/or Buzzer failure

Perform manual impact test by impacting the Alarm Bar with you hand **Fig1**.
If the Alarm Bar is operating properly, it should flash and bleep for 20 seconds and reset.
If this does not happen refer to the options below to help resolve any issue.

Item		Problem	Options
One or both sides of the alarm bar LED does not flash, buzzer does not sound	1	LED and or buzzer connector not clipped into the PCB. **Fig 2**.	Check the connections, clip into place and re test. if okay, follow 2,3,4,5
	2	PCB's not same revision **Fig 3**.	Check revision number on both PCB's. If they are the same, follow step 3, 4, 5. If they are different, contact A-SAFE Quality Control.
	3	Connecting wire loom not clipped in to the PCB or damaged **Fig 4**.	Check the loom connection, connect if necessary or replace if damaged, re test. If not okay check 4 and 5
	4	The battery pack is not full or batteries correct orientation **Fig 5**.	Check the battery pack is full and batteries correct orientation on both sides of the battery pack, make correct if necessary. Re test
	5	The battery pack is not plugged in to the PCB **Fig 6**.	Check the battery pack is plugged in to the PCB and insert if necessary. Re test
Continuous flashing and alarming after completing test procedure		The alarm bar (PCB) is not level	Make sure the alarm bar is positioned as in the SOP, fixing screws facing straight up

Photos

Fig 1


Fig 2

Fig 3


Fig 4

Fig 5

Fig 6

Data Sheets

Testing Videos

CAD

Install Documents

Certificates

If you have any questions please contact
the product management team at A-SAFE HQ
Product.Management@asafe.com

A-SAFE
PIONEERING WORKPLACE SAFETY

PRODUCTHUB

Document Reference	PRH-1036-A-SAFE-20122024-4
Document Description	Alarm Bar
Date Created	November 2023
Author/s	Matthew Briggs
Checked by	Alex Dougherty
Approved by	Ben Allen
Revision	Version 4 - December 2024