Crash Summary

Unannotated Image

Annotated Image



Incident Information

Incident Detected	True
Status	active
Types	collision
Confidence	1.0
Why	Two vehicles, a white commercial van and a yellow passenger car, are involved in a collision near the median barrier. The yellow car is partially off the roadway, against the barrier, with the white van stopped next to it, partially in the lane.
Actual Accident Verified By Gemini	True
Accident Verification Status	confirmed_by_both
Accident Verification Note	Both the unannotated image and video clip confirm a true accident. Image note: A white van and a yellow car are positioned on the side of the highway, with the yellow car partially off the road and against the median barrier. The front right of the white van appears to be in contact with the rear left of the yellow car, suggesting a collision. The abnormal position and apparent contact of the vehicles indicate an accident. Video note: A yellow car swerves off the road into the median, colliding with the barrier/dirt and coming to a stop. A white van is also stopped nearby in the left lane.

Verification Details

Image Verification	True
Image Verification Note	A white van and a yellow car are positioned on the side of the highway, with the yellow car partially off the road and against the median barrier. The front right of the white van appears to be in contact with the rear left of the yellow car, suggesting a collision. The abnormal position and apparent contact of the vehicles indicate an accident.
Video Verification	True
Video Verification Note	A yellow car swerves off the road into the median, colliding with the barrier/dirt and coming to a stop. A white van is also stopped nearby in the left lane.

Severity Assessment



Score: 21 **Category:** MINOR

Severity Criteria

Lane Blockage Score	1
Lane Blockage Evidence	The white van is partially intruding into one lane (rightmost lane next to the median).

Lane Blockage Confidence	1.0
Vehicle Count Score	1
Vehicle Count Evidence	Two vehicles are involved: one white commercial van and one yellow passenger car.
Vehicle Count Confidence	1.0
Vehicle Type Score	1
Vehicle Type Evidence	A commercial van is one of the involved vehicles, representing the highest risk type.
Vehicle Type Confidence	1.0
Hazards Score	0
Hazards Evidence	No fire, smoke, or large fluid spill is clearly visible.
Hazards Confidence	0.9
Vehicle Orientation Score	1
Vehicle Orientation Evidence	Both vehicles are upright, but the yellow car is angled against the median barrier, and the van is slightly angled.
Vehicle Orientation Confidence	1.0
Damage / Deformation Score	1
Damage / Deformation Evidence	The front/side of the yellow car shows moderate crumpling.
Damage / Deformation Confidence	0.9
Debris Extent Score	1
Debris Extent Evidence	Small, localized debris appears to be present immediately around the impact area of the yellow car.
Debris Extent Confidence	0.8
Fire Visible Trigger	NO
Rollover Confirmed Trigger	NO
Major Structural Collapse Trigger	NO
Full Roadway Blocked Trigger	NO
Large Debris Field Across Multiple Lanes Trigger	NO
Critical Unknown Count	0
Should Return Unknown	NO
Severity Notes / Uncertainty	

General Information

Camera ID	
Camera Name	
Description	
Public URL	
Latitude	
Longitude	
City	
Categories	
Route	
Milepost	
Direction	
Direction Confidence	
Weather	
Lane Count	
Operational Status	
Camera IP	

Vehicle Summary

Vehicle Count	2
Count Confidence	1.0
Type Confidence	1.0

People

People Visible	0
Injuries	UNKNOWN
Signs	
Confidence	0.0

Hazards

Fire	NO

Smoke	NO
Debris	YES
Fluid Spill	UNKNOWN
Notes	No fire or smoke is visible. Minor localized debris is present near the vehicles.
Confidence	0.9

Lane Impact

Lanes Affected	rightmost lane
Shoulder	YES
Traffic Flow	slow
Confidence	0.9
Notes	The white van is partially in the rightmost lane next to the median. The yellow car is off the roadway against the median barrier, impacting the shoulder.

Location in View

Region	center
Distance	near
Lane	rightmost lane
Shoulder	median shoulder
Median	YES
Statement	An incident involving two vehicles is located near the median barrier, partially impacting the rightmost lane of traffic and the median shoulder.

Media Inputs

Unannotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_088662ff4c7c/best_accident_frame_raw.jpg
Annotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_088662ff4c7c/best_accident_frame_annotated.jpg
Video	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_088662ff4c7c/accident_context_clip_raw.mp4