## University of Victoria

### **ELEC 340**

APPLIED ELECTROMAGNETICS AND PHOTONICS

## Lab 3 - Normal Incidence and Reflection Transmission

Instructor:
Dr. Poman So

Teaching Assistant: Farzeen IQBAL

A.K. Blanken V00809798 T. Stephen V00812021 A01 - B03

March 9, 2016



### 1 Objective

Upon completion of the lab you should be able to:

- 1. Have a good understanding of the electromagnetic theory that governs the reflection and transmission of uniform plane waves at normal incidence.
- 2. Use computer software and smith charts to solve reflection and transmission problems.
- 3. Design electromagnetic impedance transformers.

### 2 Introduction

This lab uses a parallel plate wave guide filled with two different dielectrics to investigate reflection and transmission. When a uniform plane waves hits the boundary between two different dielectrics part of it is transmitted into the second medium and part of it is reflected back. The reflected wave interferes with in incident wave and creates a standing wave. This process is shown in Fig. 1.




Figure 1: Reflection and transmission of a uniform plane wave at a normal material boundary

The reflection and transmission coefficients,  $\Gamma$  and T, are given by:

$$\Gamma = \frac{E_{x0}^r}{E_{x0}^i} \qquad T = \frac{E_{x0}^t}{E_{x0}^i}$$
 (1)

The total electric and magnetic fields in the first material will be the sums of their incident and

reflected components. If the phase of the reflected wave is not  $\pm 90^{\circ}$ , the total field will have both a traveling and a standing component. The magnitude of the total wave will be bounded by  $E_{x0}^{i}$   $(1 \pm |\Gamma|)$ .

For multiple boundaries, this analysis can be applied recursively starting at the medium furthest from the incident wave and working towards it.

#### 3 Procedure

A waveguide was constructed in MEFiSTo and filled with two dielectric media, as shown in Fig. 2.




Figure 2: Parallel plate waveguide

Initially, we made both dielectrics identical and changed the right end to a perfect electrical boundary. The source generated a 10 GHz plane wave through the structure. By observing the wave envelope in the structure we were able to determine the standing wave amplitudes,  $E_{max}$  and  $E_{min}$ , and positions of  $l_{max}$  and  $l_{min}$ . The type of right boundary (absorbing, electric, magnetic) was changed, as well as the dielectric properties  $\epsilon_r$  and  $\sigma$ . See Section 4 for the effect of these variations of the wave patterns.

A third material was added to study the use of dielectrics as impedance transformers. The structure is shown in Fig. 3




Figure 3: Waveguide with three dielectric regions

By choosing the length of the second dielectric region as  $\lambda_2/4$  and  $\epsilon_2 = \sqrt{\epsilon_1 \epsilon_3}$ , we were able to create several impedance transformers by varying the length of the second medium and by using different pairs of input frequency and medium size.

#### 4 Discussion

#### 4.1 Traveling standing waves at normal incidence

Change the absorbing boundary in the second medium to a perfect electric boundary.

Task 2a Identify the standing and traveling wave in the structure.





Figure 4: Standing wave pattern for waveguide with electric boundary at right end

**Task 2b** What is the amplitude of the wave at the probe? Is it  $2 \mathrm{V m}^{-1}$ ? Why?



The amplitude of the standing wave is  $1.675 \,\mathrm{V}\,\mathrm{m}^{-1}$  because the probe is not located at a standing wave antinode: odd integer multiples of  $l_{max}$ .

**Task 2c** What is the amplitude of the wave to the left of the source region? Is it  $2 \mathrm{V m}^{-1}$ ? Why?

Fig. 4 shows that the wave has an amplitude of  $2 \,\mathrm{V}\,\mathrm{m}^{-1}$ . This is because the reflected wave is in phase with the source wave and constructive interference occurs.

**Task 2d** What are:  $E_{max}$ ,  $E_{min}$ ,  $l_{max}$ ,  $l_{min}$ ,  $|\Gamma|$ ,  $\phi_{\Gamma}$ ? What are possible sources of error between the simulation and expected values?

Parameter	Expected	Actual
$E_{max}$	$2\mathrm{V}\mathrm{m}^{-1}$	$1.969{ m Vm^{-1}}$
$E_{min}$	$0\mathrm{Vm^{-1}}$	$0.3478\mathrm{Vm^{-1}}$
$l_{max}$	$62.5\mathrm{mm}$	$< 62.5 \mathrm{mm}$
$l_{min}$	$55\mathrm{mm}$	$< 55 \mathrm{mm}$
$ \Gamma $	1/3	1/3
$\phi_{\Gamma}$	$-\pi$ rad	$-\pi$ rad

The values of E differ from the expected values because the probes for those measurements were placed at the positions of  $l_{max}$  and  $l_{min}$  as determined by calculating the wavelength for  $c_0 = 3.0 \times 10^8 \,\mathrm{m\,s^{-1}}$ .

**Task 5a** Set  $\epsilon_{r2} = 4$ ,  $\sigma_2 = 1 \,\mathrm{S}\,\mathrm{m}^{-1}$  and repeat Task 2 with an absorbing right boundary.





Figure 5:  $\epsilon_{r2} = 4$ ,  $\sigma_2 = 1 \, \mathrm{S \, m^{-1}}$ , absorbing right boundary

A standing wave envelope is produced between the source and dielectric boundary. As the wave enters the second medium it is attenuated.

**Task 5b** What is the amplitude of the wave at the probe? Is it  $2 \text{V m}^{-1}$ ? Why?




The amplitude is  $0.263\,\mathrm{V\,m^{-1}}$ . As noted in 2b, the source is not placed at an antinode. Also, the wave attenuates as it enters the second medium because  $\sigma_2 \neq 0$ .

**Task 5c** What is the amplitude of the wave to the left of the source region? Is it  $2 \mathrm{V m}^{-1}$ ? Why? The amplitude is  $0.639 \mathrm{V m}^{-1}$  I think this value is wrong. Reading the (x,y) pair in the top of the graph it's the same for all graphs...

**Task 5d** What are:  $E_{max}$ ,  $E_{min}$ ,  $l_{max}$ ,  $l_{min}$ ,  $|\Gamma|$ ,  $\phi_{\Gamma}$ ? What are possible sources of error between the simulation and expected values?

Again, error comes from approximating  $c_0$ .



Parameter	Expected	Actual
$E_{max}$	$1.33{ m V}{ m m}^{-1}$	$1.365{ m Vm^{-1}}$
$E_{min}$	$0.67{ m V}{ m m}^{-1}$	$0.685{ m Vm^{-1}}$
$l_{max}$	$42.5\mathrm{mm}$	$>42.5\mathrm{mm}$
$l_{min}$	$50\mathrm{mm}$	$> 50 \mathrm{mm}$
$ \Gamma $	$\frac{1}{7}$	1/7
$\phi_\Gamma$	0  rad	0  rad

Task 6a Set  $\epsilon_{r1} = 9$ ,  $\sigma_1 = 0.5 \, \mathrm{S \, m^{-1}}$  and repeat Task 5.





Figure 6:  $\epsilon_{r1} = 9$ ,  $\sigma_1 = 0.5 \,\mathrm{S}\,\mathrm{m}^{-1}$ ,  $\epsilon_{r2} = 4$ ,  $\sigma_2 = 1 \,\mathrm{S}\,\mathrm{m}^{-1}$ 


The wave attenuates in the first dielectric because  $\sigma_1 \neq 0$ .

**Task 6b** What is the amplitude of the wave at the probe? Is it  $2 V m^{-1}$ ? Why?



The amplitude is  $0.1879\,\mathrm{V\,m^{-1}}$ . It is smaller than in 5b because the wave attenuated in the first medium.

Task 6c What is the amplitude of the wave to the left of the source region? Is it  $2 \,\mathrm{V}\,\mathrm{m}^{-1}$ ? Why? The amplitude is  $0.7345 \,\mathrm{V}\,\mathrm{m}^{-1}$  at the location of the leftmost probe in Fig. 6. It does



not receive constructive interference from the reflection and is attenuated by the dielectric.

**Task 6d** What are:  $E_{max}$ ,  $E_{min}$ ,  $l_{max}$ ,  $l_{min}$ ,  $|\Gamma|$ ,  $\phi_{\Gamma}$ ? What are possible sources of error between the simulation and expected values?

Parameter	Expected	Actual
$E_{max}$	??	$0.6587\mathrm{Vm^{-1}}$
$E_{min}$	??	$0.4573\mathrm{V}\mathrm{m}^{-1}$
$l_{max}$	$42.5\mathrm{mm}$	$>42.5\mathrm{mm}$
$l_{min}$	$50\mathrm{mm}$	$> 50 \mathrm{mm}$
$ \Gamma $	??	??
$\phi_{\Gamma}$	??	??

# 5 Conclusion

Summarize the entire report and note any unresolved issues. This section will usually repeat the abstract.