



State Farm
P.O. Box 106169
Atlanta, GA 30348-6169
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

Structural Damage Claim Policy

This estimate is priced based on estimated market pricing for the cost of materials, labor, and other factors at the time of the loss.

Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, please contact us. If your contractor's estimate is higher than ours, you should contact us prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy terms, conditions and limits.

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you - not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.



Building Estimate Summary Guide

This summary guide is based on a sample estimate and is provided for reference only.

Please refer to the estimate for specifics of your claim.

State Farm Insurance

Insured: Smith, Joe & Jane	Estimate: 00-0000-000
Property: 1 Main Street	Claim number: 00-0000-000
Anywhere, IL 00000-0000	Policy Number: 00-00-0000-0
Type of Loss: Other	Price List: ILBL8F_MAR 13
Deductible: \$1,000.00	Restoration/Service/ Remodel
	F = Factored In, D = Do Not Apply

Summary for Dwelling

Line Item Total [1]		5,953.10
Material Sales Tax	@ 10.000% x 1,520.00	
Subtotal		6,105.10
General Contractor Overhead [2]	@ 10.0% x 6,105.10	610.51
General Contractor Profit	@ 10.0% x 6,105.10	
Replacement Cost Value (Including General Contractor Overhead and Profit [3])		7,326.12
Less Depreciation (Including Taxes) [4]		(832.50)
Less General Contractor Overhead & Profit on Recoverable & Non - recoverable Depreciation		(166.50)
Less Deductible [5]		
Net Actual Cash Value Payment [6]		

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes) [4]	832.50	
Less Non - recoverable Depreciation (Including Taxes) [7]		
Subtotal		312.50
General Contractor O&P on Depreciation	166.50	
Less General Contractor O&P on Non - recoverable Depreciation		
Subtotal		
Total Maximum Additional Amounts Available If Incurred [8]		
Total Amount of Claim If Incurred [9]		

Claim Representative

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

- 1. Line Item Total** – Total value of all line items in the estimate plus possible adjustments for *labor minimums*. *Labor Minimum* is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
- 2. General Contractor's Overhead and Profit** – General contractor's charge for coordinating your repairs.
- 3. Replacement Cost Value (RCV)** – Estimated cost to repair or replace damaged property.
- 4. Depreciation** – The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
- 5. Deductible** – The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
- 6. Net Actual Cash Value Payment (ACV)** – The repair or replacement cost of the damaged part of the property less *depreciation* and *deductible*.
- 7. Non Recoverable Depreciation** – *Depreciation* applied to items that are not eligible for replacement cost benefits.
- 8. Total Maximum Additional Amount if Incurred** – Total amount of recoverable depreciation after actual repair or replacement of the property.
- 9. Total Amount of Claim if Incurred** – Total amount of the claim, including *net actual cash value payment* and *total maximum additional amount available if incurred*.

State Farm

CHEN, KENNETH

75-79J8-65X

Insured:	CHEN, KENNETH	Estimate:	75-79J8-65X
Property:	1115 LACHMAN LN	Claim Number:	7579J865X
	PACIFIC PLSDS, CA 90272-2227	Policy Number:	75C9A1815
Home:	310-717-7288	Price List:	CALA28_JAN25
Cellular:	310-717-7288		Restoration/Service/Remodel
Type of Loss:	Smoke		
Deductible:	\$0.00		
Date of Loss:	1/8/2025		
Date Inspected:	2/18/2025		

Summary for Coverage A - Dwelling - 39 Smoke

Line Item Total	69,914.45
Material Sales Tax	674.52
Replacement Cost Value	70,588.97
Less Deductible	(0.00)
Net Payment	\$70,588.97

Longmeyer,Bill
866-787-8676 x 12160

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

State Farm

CHEN, KENNETH

75-79J8-65X

Insured:	CHEN, KENNETH	Estimate:	75-79J8-65X
Property:	1115 LACHMAN LN	Claim Number:	7579J865X
	PACIFIC PLSDS, CA 90272-2227	Policy Number:	75C9A1815
Home:	310-717-7288	Price List:	CALA28_JAN25
Cellular:	310-717-7288		Restoration/Service/Remodel
Type of Loss:	Smoke		
Deductible:	\$0.00		
Date of Loss:	1/8/2025		
Date Inspected:	2/18/2025		

Summary for Coverage A - Dwelling - 39 Smoke - Trees, Shrubs, and Landscaping

Line Item Total	3,572.27
Material Sales Tax	160.81
Replacement Cost Value	3,733.08
Less Deductible	(0.00)
Net Payment	\$3,733.08

Longmeyer,Bill
866-787-8676 x 12160

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

State Farm

CHEN, KENNETH

75-79J8-65X

Insured:	CHEN, KENNETH	Estimate:	75-79J8-65X
Property:	1115 LACHMAN LN	Claim Number:	7579J865X
	PACIFIC PLSDS, CA 90272-2227	Policy Number:	75C9A1815
Home:	310-717-7288	Price List:	CALA28_JAN25
Cellular:	310-717-7288		Restoration/Service/Remodel
Type of Loss:	Smoke		
Deductible:	\$1,395.58		
Date of Loss:	1/8/2025		
Date Inspected:	2/18/2025		

Summary for Coverage A - Dwelling Extension - 39 Smoke

Line Item Total	1,262.69
Material Sales Tax	1.43
Replacement Cost Value	1,264.12
Less Deductible	(1,395.58)
Replacement Cost Value Total	(131.46)
Net Payment	\$0.00

Longmeyer,Bill
866-787-8676 x 12160

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND
LIMITS OF YOUR POLICY.

Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

State Farm

CHEN, KENNETH

75-79J8-65X

Insured:	CHEN, KENNETH	Estimate:	75-79J8-65X
Property:	1115 LACHMAN LN	Claim Number:	7579J865X
	PACIFIC PLSDS, CA 90272-2227	Policy Number:	75C9A1815
Home:	310-717-7288	Price List:	CALA28_JAN25
Cellular:	310-717-7288		Restoration/Service/Remodel
Type of Loss:	Smoke		
Deductible:	\$0.00		
Date of Loss:	1/8/2025		
Date Inspected:	2/18/2025		

Summary for Coverage A - Dwelling - 35 Windstorm and Hail

Line Item Total	827.11
Material Sales Tax	30.41
Replacement Cost Value	857.52
Less Deductible	(0.00)
Net Payment	\$857.52

Longmeyer,Bill
866-787-8676 x 12160

**ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND
LIMITS OF YOUR POLICY.**

Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

State Farm

CHEN, KENNETH

75-79J8-65X

Insured:	CHEN, KENNETH	Estimate:	75-79J8-65X
Property:	1115 LACHMAN LN	Claim Number:	7579J865X
	PACIFIC PLSDS, CA 90272-2227	Policy Number:	75C9A1815
Home:	310-717-7288	Price List:	CALA28_JAN25
Cellular:	310-717-7288		Restoration/Service/Remodel
Type of Loss:	Smoke		
Deductible:	\$0.00		
Date of Loss:	1/8/2025		
Date Inspected:	2/18/2025		

Summary for Coverage A - Dwelling - 33 Fire, Lightning, & Removal


Line Item Total	10,836.87
California Lumber Assessment Fee	11.59
Material Sales Tax	441.08
Replacement Cost Value	11,289.54
Less Deductible	(0.00)
Net Payment	\$11,289.54

Longmeyer,Bill
866-787-8676 x 12160

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

Source - EagleView Roof & Walls
Exterior




Dwelling Roof

4,558.71 Surface Area
428.35 Total Perimeter Length

45.59 Number of Squares

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
1. Clean the surface area	4,558.71 SF	0.55	4.33	2,511.62
2. R&R Solar electric panel - up to 200 watt	1.00 EA	827.11	30.41	857.52
Far back solar panel is shattered				
Totals: Dwelling Roof			34.74	3,369.14

Ext_Surfaces



3,581.77 SF Walls
3,581.77 SF Walls & Ceiling

486.22 LF Floor Perimeter

Window	8' X 5' 6"	Opens into Exterior
Window	5' X 5' 6"	Opens into Exterior
Door	3' X 7'	Opens into Exterior
Window	1' X 7'	Opens into Exterior
Window	5' X 2'	Opens into Exterior
Window	4' 6" X 3'	Opens into Exterior
Window	5' X 10' 6"	Opens into Exterior
Window	5' X 10' 6"	Opens into Exterior
Window	4' 6" X 4' 6"	Opens into Exterior
Door	3' X 9'	Opens into Exterior
Door	3' X 9'	Opens into Exterior
Door	3' X 9'	Opens into Exterior
Door	3' X 9'	Opens into Exterior
Window	3' 6" X 9'	Opens into Exterior
Window	3' X 9'	Opens into Exterior
Window	4' 6" X 9'	Opens into Exterior
Window	2' 6" X 9'	Opens into Exterior
Window	3' 6" X 9'	Opens into Exterior
Window	2' X 9'	Opens into Exterior
Door	3' X 7' 6"	Opens into Exterior
Window	5' X 7' 6"	Opens into Exterior
Window	2' X 7' 6"	Opens into Exterior
Door	3' X 7'	Opens into Exterior
Window	5' X 3' 6"	Opens into Exterior
Window	2' X 4'	Opens into Exterior
Window	2' X 4'	Opens into Exterior
Window	2' 6" X 4' 6"	Opens into Exterior
Door	3' X 7'	Opens into Exterior
Door	3' X 7'	Opens into Exterior
Window	2' X 7'	Opens into Exterior
Door	3' X 6' 11 5/8"	Opens into Exterior
Door	17' 6" X 8' 6 1/8"	Opens into Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
3. Clean the surface area	4,354.00 SF	0.55	4.14	2,398.84

State Farm

CHEN, KENNETH

75-79J8-65X

CONTINUED - Ext_Surfaces

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
Includes cleaning for home and garage				
Totals: Ext_Surfaces			4.14	2,398.84

Front Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
4. Clean with pressure/chemical spray	411.15 SF	0.51	0.39	210.08
includes stairs, landings and patio				
Totals: Front Elevation			0.39	210.08

Right Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
5. Clean soffit - wood	48.00 SF	0.60	0.05	28.85
entry soffit				
* 6. Clean with pressure/chemical spray - Concrete wall	405.24 SF	0.51	0.38	207.05
Both sides				
* 7. Clean with pressure/chemical spray- Driveway	1,144.00 SF	0.51	1.09	584.53
Totals: Right Elevation			1.52	820.43

State Farm

CHEN, KENNETH

75-79J8-65X

Rear Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
8. Clean with pressure/chemical spray	670.56 SF	0.51	0.64	342.63
Both sides				
9. Wood fence 5'- 6' high - cedar or equal	70.00 LF	63.16	179.55	4,600.75
10. R&R Tile floor covering - High grade	100.00 SF	23.50	75.34	2,425.34
Replace the tile burned on the back patio				
Totals: Rear Elevation			255.53	7,368.72

Left Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
11. Clean soffit - wood	97.17 SF	0.60	0.09	58.39
* 12. Clean with pressure/chemical spray- Patio	733.96 SF	0.51	0.70	375.02
Tile patio				
13. Tile / Cultured Marble - General Laborer - per hour	3.00 HR	61.77	0.00	185.31
Labor to fix the tile on the outdoor fireplace				
14. Clean with pressure/chemical spray	431.12 SF	0.51	0.41	220.28
Clean backside of concrete wall at pool				
Totals: Left Elevation			1.20	839.00


Area Totals: Exterior

3,581.77 SF Walls	486.22 Exterior Perimeter	3,581.77 SF Walls and Ceiling
3,581.77 Exterior Wall Area	of Walls	486.22 LF Floor Perimeter
4,558.71 Surface Area	45.59 Number of Squares	428.35 Total Perimeter Length

Total: Exterior			297.52	15,006.21
------------------------	--	--	---------------	------------------

CONTINUED - Guest Room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
21. Clean door - bypass set (per side)	2.00 EA	23.29	0.10	46.68
22. Clean door hardware	5.00 EA	10.72	0.10	53.70
23. Clean window unit (per side) 10 - 20 SF	1.00 EA	24.40	0.00	24.40
24. Clean register - heat / AC	2.00 EA	9.13	0.00	18.26
** CEILING **				
25. HEPA Vacuuming - Detailed - (PER SF)	285.34 SF	0.81	0.00	231.13
26. Clean the ceiling	285.34 SF	0.57	0.27	162.91
27. Clean recessed light fixture	7.00 EA	17.15	0.06	120.11
28. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
<u>CONTENT MANIPULATION</u>				
29. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Guest Room			1.58	2,360.75




Guest Bathroom		Height: 8'
177.90 SF Walls	98.98 SF Ceiling	
276.88 SF Walls & Ceiling	76.20 SF Floor	
34.75 LF Ceil. Perimeter	21.56 LF Floor Perimeter	
Window	4' X 3'	Opens into Exterior
Door	3' 1 1/16" X 8' 2 1/16"	Opens into GUEST_ROOM
Door	2' 2" X 7' 11"	Opens into GUEST_BEDRO4

State Farm

CHEN, KENNETH

75-79J8-65X



Subroom: Guest Bathroom (1)

Height: 8'

61.82 SF Walls
75.21 SF Walls & Ceiling
7.49 LF Ceil. Perimeter
13.39 SF Ceiling

Missing Wall - Goes to Ceiling

4' 6 9/16" X 7' 9"

Opens into GUEST_BATHRO

Missing Wall - Goes to Ceiling


2' 11 5/16" X 7' 9"

Opens into GUEST_BATHRO


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
30. HEPA Vacuuming - Detailed - (PER SF)	76.20 SF	0.81	0.00	61.72
31. Clean floor - tile	76.20 SF	0.95	0.51	72.90
** WALLS **				
32. HEPA Vacuuming - Detailed - (PER SF)	239.72 SF	0.81	0.00	194.17
33. Clean the walls	239.72 SF	0.57	0.23	136.87
34. Clean door / window opening (per side)	3.00 EA	21.03	0.01	63.10
35. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
36. Clean window unit (per side) 10 - 20 SF	1.00 EA	24.40	0.00	24.40
37. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
** FIXTURES **				
38. Clean vanity - inside and out	12.43 LF	21.36	0.13	265.63
39. Clean countertop	24.86 SF	1.19	0.05	29.63
40. Clean sink	2.00 EA	21.03	0.01	42.07
41. Clean sink faucet	2.00 EA	15.65	0.00	31.30
42. Clean mirror	25.00 SF	1.15	0.02	28.77
43. Clean light bar	2.00 EA	29.78	0.02	59.58
44. Clean toilet	1.00 EA	35.35	0.00	35.35
45. Clean toilet seat	1.00 EA	7.62	0.00	7.62
46. Clean toilet paper dispenser	1.00 EA	11.40	0.00	11.40

CONTINUED - Guest Bathroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
47. Clean towel bar	1.00 EA	11.38	0.00	11.38
48. Clean shower	1.00 EA	70.11	0.01	70.12
49. Clean tub / shower faucet	1.00 EA	22.77	0.00	22.77
50. Clean shower door	1.00 EA	28.79	0.01	28.80
** CEILING **				
51. HEPA Vacuuming - Detailed - (PER SF)	112.37 SF	0.81	0.00	91.02
52. Clean the ceiling	112.37 SF	0.57	0.11	64.16
53. Clean recessed light fixture	2.00 EA	17.15	0.02	34.32
54. Clean bathroom fan	1.00 EA	45.53	0.00	45.53
Totals: Guest Bathroom			1.15	1,513.82



Office Bath		Height: 8'
139.64 SF Walls	51.09 SF Ceiling	
190.74 SF Walls & Ceiling	42.39 SF Floor	
25.07 LF Ceil. Perimeter	19.24 LF Floor Perimeter	
Door	2' 11 13/16" X 8' 1/16"	Opens into OFFICE
Door	3' 7/16" X 8' 1 1/4"	Opens into FOYER



Subroom: Office Bath (4)		Height: 8'
29.16 SF Walls	0.99 SF Ceiling	
30.15 SF Walls & Ceiling		
3.65 LF Ceil. Perimeter		
Missing Wall	3' 4 3/16" X 8'	Opens into OFFICE_BATH2
Missing Wall	3 9/16" X 8'	Opens into OFFICE_BATH1

State Farm

CHEN, KENNETH

75-79J8-65X

Subroom: Office Bath (3)

Height: 8'



3.58 SF Walls
4.61 SF Walls & Ceiling
0.31 LF Ceil. Perimeter

1.03 SF Ceiling

Missing Wall - Goes to Ceiling

3' 4 3/16" X 7' 8"

Opens into OFFICE_BATH

Missing Wall


3 11/16" X 8'

Opens into OFFICE_BATH1

Missing Wall

3' 4 3/16" X 8'

Opens into OFFICE_BATH2



Subroom: Office Bath (2)

Height: Tray

21.33 SF Walls
33.50 SF Walls & Ceiling
2.67 LF Ceil. Perimeter

12.17 SF Ceiling

Missing Wall

2' 8" X 8'

Opens into OFFICE_BATH1

Missing Wall


3' 4 3/16" X 8'

Opens into OFFICE_BATH3

Missing Wall

3' 4 3/16" X 8'

Opens into OFFICE_BATH4



Subroom: Office Bath (1)

Height: 8'

20.78 SF Walls
25.08 SF Walls & Ceiling
1.32 LF Ceil. Perimeter

4.30 SF Ceiling

Missing Wall - Goes to Ceiling

3' 3 1/4" X 5'

Opens into OFFICE_BATH

Missing Wall - Goes to Ceiling

1' 3 13/16" X 7' 8"

Opens into OFFICE_BATH

Missing Wall

3 11/16" X 8'

Opens into OFFICE_BATH3

Missing Wall

2' 8" X 8'

Opens into OFFICE_BATH2

Missing Wall

3 9/16" X 8'

Opens into OFFICE_BATH4

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

** FLOORING **

55. HEPA Vacuuming - Detailed - (PER SF)	42.39 SF	0.81	0.00	34.34
--	----------	------	------	-------

56. Clean floor - tile	42.39 SF	0.95	0.28	40.55
------------------------	----------	------	------	-------

** WALLS **

57. HEPA Vacuuming - Detailed - (PER SF)	214.49 SF	0.81	0.00	173.74
--	-----------	------	------	--------


State Farm

CHEN, KENNETH

75-79J8-65X

CONTINUED - Office Bath

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
58. Clean the walls	214.49 SF	0.57	0.20	122.46
59. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
60. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
** FIXTURES **				
61. Clean vanity - inside and out	4.75 LF	21.36	0.05	101.51
62. Clean countertop	9.50 SF	1.19	0.02	11.33
63. Clean sink	1.00 EA	21.03	0.00	21.03
64. Clean sink faucet	1.00 EA	15.65	0.00	15.65
65. Clean mirror	12.00 SF	1.15	0.01	13.81
66. Clean light bar	1.00 EA	29.78	0.01	29.79
67. Clean toilet	1.00 EA	35.35	0.00	35.35
68. Clean toilet seat	1.00 EA	7.62	0.00	7.62
69. Clean toilet paper dispenser	1.00 EA	11.40	0.00	11.40
70. Clean shower	1.00 EA	70.11	0.01	70.12
71. Clean tub / shower faucet	1.00 EA	22.77	0.00	22.77
72. Clean shower door	1.00 EA	28.79	0.01	28.80
** CEILING **				
73. HEPA Vacuuming - Detailed - (PER SF)	69.58 SF	0.81	0.00	56.36
74. Clean the ceiling	69.58 SF	0.57	0.07	39.73
75. Clean recessed light fixture	2.00 EA	17.15	0.02	34.32
76. Clean bathroom fan	1.00 EA	45.53	0.00	45.53
77. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
Totals: Office Bath			0.71	1,039.49



Height: Tray

8.74 SF Walls
169.32 SF Walls & Ceiling
48.66 LF Ceil. Perimeter

160.58 SF Ceiling
114.75 SF Floor



Height: Sloped

17.71 SF Walls
34.79 SF Walls & Ceiling
16.44 LF Ceil. Perimeter

17.07 SF Ceiling
13.72 SF Floor
1.13 LF Floor Perimeter

Missing Wall
Missing Wall
Missing Wall
Missing Wall - Goes to Floor

2' 4" X 10' 11 1/4"

Opens into KITCHEN

Missing Wall **9' 3 15/16" X 10' 11 1/4"**


Opens into KITCHEN2

Missing Wall **2' 4" X 10' 11 1/4"**

Opens into KITCHEN3

Missing Wall - Goes to Floor **14' X 11'**

Opens into GREAT_ROOM_2



Height: Sloped

73.57 SF Walls
91.44 SF Walls & Ceiling
9.99 LF Ceil. Perimeter

17.88 SF Ceiling
17.31 SF Floor
7.42 LF Floor Perimeter

Missing Wall **2' 4" X 9'**


Opens into KITCHEN1

Missing Wall 2' 4" X 9'

Opens into KITCHEN4

Missing Wall **7' 5" X 9'**

Opens into KITCHEN2



Height: Sloped

26.74 SF Walls
44.61 SF Walls & Ceiling
9.99 LF Ceil. Perimeter

17.88 SF Ceiling
3.71 SF Floor

Missing Wall **7' 5" X 9'**

Opens into KITCHEN2

Missing Wall **2' 4" X 9'**

Opens into KITCHEN1

Window 4' 11 1/16" X 3' 9 11/16"

Opens into Exterior


Missing Wall **2' 4" X 9'**

Opens into KITCHEN4

State Farm

CHEN, KENNETH

75-79J8-65X



Subroom: Kitchen (2)

Height: Sloped


187.56 SF Walls	49.22 SF Ceiling
236.78 SF Walls & Ceiling	25.80 SF Floor
35.88 LF Ceil. Perimeter	11.25 LF Floor Perimeter

Missing Wall	7' 7" X 9'	Opens into KITCHEN2
Missing Wall	9' 3 15/16" X 9'	Opens into KITCHEN2
Missing Wall	7' 7" X 9'	Opens into KITCHEN2
Missing Wall	2' 4" X 9'	Opens into KITCHEN3
Window	5' 11 1/8" X 3' 5 3/4"	Opens into Exterior
Missing Wall	2' 4" X 9'	Opens into KITCHEN

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
78. HEPA Vacuuming - Detailed - (PER SF)	175.29 SF	0.81	0.00	141.98
79. Clean floor - tile	175.29 SF	0.95	1.17	167.70
** WALLS **				
80. HEPA Vacuuming - Detailed - (PER SF)	314.32 SF	0.81	0.00	254.60
81. Clean the walls	314.32 SF	0.57	0.30	179.46
82. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
83. Clean window unit (per side) 10 - 20 SF	2.00 EA	24.40	0.00	48.80
** CABINETRY / HARDWARE / ACCESORIES **				
84. Clean cabinetry - lower - inside and out	53.07 LF	23.84	0.55	1,265.74
85. Clean cabinetry - upper - inside and out	25.00 LF	23.84	0.26	596.26
86. Clean cabinetry - full height - inside and out	3.83 LF	41.64	0.05	159.53
* 87. Clean cabinetry - upper - top of cabinet	25.00 LF	23.27	0.26	582.01
88. Clean countertop	114.99 SF	1.19	0.22	137.06
89. Clean sink	2.00 EA	21.03	0.01	42.07
90. Clean sink faucet	2.00 EA	15.65	0.00	31.30
91. Clean dishwasher - exterior	1.00 EA	25.34	0.00	25.34

CONTINUED - Kitchen

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
92. Clean range - exterior	1.00 EA	51.02	0.05	51.07
93. Clean range hood	1.00 EA	27.41	0.01	27.42
** CEILING **				
94. HEPA Vacuuming - Detailed - (PER SF)	262.62 SF	0.81	0.00	212.72
95. Clean the ceiling	262.62 SF	0.57	0.25	149.94
96. Clean recessed light fixture	18.00 EA	17.15	0.15	308.85
97. Clean register - heat / AC	2.00 EA	9.13	0.00	18.26
Totals: Kitchen			3.29	4,442.18




Hallway **Height: 8'**

282.10 SF Walls	120.61 SF Ceiling
402.71 SF Walls & Ceiling	120.61 SF Floor
50.57 LF Ceil. Perimeter	34.10 LF Floor Perimeter

Door	3' 1 8/8" X 7' 5/8"	Opens into GUEST_ROOM1
Door	2' 11 9/16" X 6' 11 1/16"	Opens into GUEST_BEDROO
Door	2' 10 13/16" X 6' 11 7/8"	Opens into UTILITY_ROOM
Door	3' 1 3/8" X 7' 10 7/8"	Opens into BEDROOM

Subroom: Hallway (2) **Height: Sloped**

102.42 SF Walls	13.23 SF Ceiling
115.65 SF Walls & Ceiling	11.74 SF Floor
12.18 LF Ceil. Perimeter	9.27 LF Floor Perimeter



Missing Wall	9' 1 5/16" X 10' 5"	Opens into HALLWAY2
Missing Wall - Goes to Floor	1' 3 7/16" X 8'	Opens into HALLWAY_2
Missing Wall - Goes to Floor	1' 3 7/16" X 9'	Opens into HALLWAY


State Farm

CHEN, KENNETH

75-79J8-65X

Subroom: Hallway (3)

Height: Sloped



16.75 SF Walls
25.89 SF Walls & Ceiling
11.12 LF Ceil. Perimeter

9.14 SF Ceiling
6.07 SF Floor


Missing Wall
Missing Wall - Goes to Floor
Missing Wall
Missing Wall - Goes to Floor

9' 1 5/16" X 12' 6"
8" X 8"
9' 1 5/16" X 12' 6"
8" X 9'

Opens into HALLWAY_1
Opens into HALLWAY_2
Opens into HALLWAY1
Opens into HALLWAY

Subroom: Hallway (1)

Height: Peaked



153.82 SF Walls
217.96 SF Walls & Ceiling
25.43 LF Ceil. Perimeter

64.13 SF Ceiling
63.02 SF Floor
14.38 LF Floor Perimeter


Missing Wall
Missing Wall - Goes to Ceiling
Missing Wall
Missing Wall - Goes to Floor
Missing Wall - Goes to Floor
Missing Wall - Goes to Floor
Missing Wall - Goes to Floor

7' 2 7/8" X 12'
5' 5 7/8" X 9'
4' 5 11/16" X 12'
6' 1 15/16" X 9' 10"
1' 3 7/16" X 9'
8" X 9'
2' 8 1/4" X 9'

Opens into GREAT_ROOM1
Opens into FIREPLACE
Opens into GREAT_ROOM_2
Opens into FOYER
Opens into HALLWAY1
Opens into HALLWAY2
Opens into HALLWAY_1

Subroom: Hallway 2 (4)

Height: Sloped



129.72 SF Walls
154.66 SF Walls & Ceiling
23.69 LF Ceil. Perimeter

24.95 SF Ceiling
22.96 SF Floor
9.11 LF Floor Perimeter

Missing Wall
Missing Wall - Goes to Floor
Missing Wall - Goes to Floor

9' 1 5/16" X 12'
2' 6 1/4" X 8'
2' 6 1/4" X 9'

Opens into HALLWAY2
Opens into HALLWAY_2
Opens into HALLWAY


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

** FLOORING **

98. HEPA Vacuuming - Detailed - (PER SF)	224.40 SF	0.81	0.00	181.76
99. Clean floor - tile	224.40 SF	0.95	1.49	214.67

CONTINUED - Hallway

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** WALLS **				
100. HEPA Vacuuming - Detailed - (PER SF)	684.81 SF	0.81	0.00	554.70
101. Clean the walls	684.81 SF	0.57	0.65	390.99
102. Clean door / window opening (per side)	4.00 EA	21.03	0.02	84.14
103. Clean door (per side)	4.00 EA	11.59	0.08	46.44
104. Clean door hardware	4.00 EA	10.72	0.08	42.96
105. Clean thermostat	1.00 EA	20.69	0.00	20.69
** CEILING **				
106. HEPA Vacuuming - Detailed - (PER SF)	232.06 SF	0.81	0.00	187.97
107. Clean the ceiling	232.06 SF	0.57	0.22	132.49
108. Clean recessed light fixture	5.00 EA	17.15	0.04	85.79
109. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
110. Clean cold air return cover	1.00 EA	14.08	0.01	14.09
111. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
112. Clean roof window or skylight	1.00 EA	54.66	0.01	54.67
Totals: Hallway			2.60	2,042.51



Master Bathroom

Height: 8'


189.65 SF Walls	109.47 SF Ceiling
299.12 SF Walls & Ceiling	90.54 SF Floor
30.24 LF Ceil. Perimeter	26.91 LF Floor Perimeter

Door 2' 10 13/16" X 7' 10 7/8" Opens into BEDROOM

State Farm

CHEN, KENNETH

75-79J8-65X



Subroom: Master Bathroom (2)

Height: 8'

102.01 SF Walls
129.98 SF Walls & Ceiling
10.65 LF Ceil. Perimeter

27.97 SF Ceiling

Missing Wall - Goes to Ceiling

4' 1 1/8" X 4' 5"

Opens into MASTER_BATH1

Missing Wall - Goes to Ceiling


1' 10" X 7' 8"

Opens into MASTER_BATHR

Missing Wall - Goes to Ceiling

4' 8 11/16" X 7' 8"

Opens into MASTER_BATHR



Subroom: Master Bathroom (1)

Height: 8'

51.47 SF Walls
77.06 SF Walls & Ceiling
10.45 LF Ceil. Perimeter

25.59 SF Ceiling

Window

5' 1/8" X 5' 1/4"

Opens into Exterior

Missing Wall - Goes to Ceiling

6' 6 1/4" X 6' 5"

Opens into MASTER_BATHR

Missing Wall - Goes to Ceiling

3' 11 1/8" X 4' 5"

Opens into MASTER_BATH2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

** FLOORING **

113. HEPA Vacuuming - Detailed - (PER SF)	90.54 SF	0.81	0.00	73.34
114. Clean floor - tile	90.54 SF	0.95	0.60	86.61

** WALLS **

115. HEPA Vacuuming - Detailed - (PER SF)	343.13 SF	0.81	0.00	277.94
116. Clean the walls	343.13 SF	0.57	0.33	195.91
117. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
118. Clean door - French (per side)	1.00 EA	36.03	0.01	36.04
119. Clean window unit (per side) 10 - 20 SF	1.00 EA	24.40	0.00	24.40

** FIXTURES **

120. Clean vanity - inside and out	10.33 LF	21.36	0.11	220.76
121. Clean countertop	10.33 SF	1.19	0.02	12.31
122. Clean sink	2.00 EA	21.03	0.01	42.07

State Farm

CHEN, KENNETH

75-79J8-65X


CONTINUED - Master Bathroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
123. Clean sink faucet	2.00 EA	15.65	0.00	31.30
124. Clean mirror	24.00 SF	1.15	0.02	27.62
125. Clean light bar	3.00 EA	29.78	0.03	89.37
126. Clean toilet	1.00 EA	35.35	0.00	35.35
127. Clean toilet seat	1.00 EA	7.62	0.00	7.62
128. Clean toilet paper dispenser	1.00 EA	11.40	0.00	11.40
129. Clean towel bar	1.00 EA	11.38	0.00	11.38
130. Clean tub	1.00 EA	34.18	0.01	34.19
131. Clean shower	1.00 EA	70.11	0.01	70.12
132. Clean tub / shower faucet	2.00 EA	22.77	0.01	45.55
133. Clean shower door	2.00 EA	28.79	0.02	57.60
** CEILING **				
134. HEPA Vacuuming - Detailed - (PER SF)	163.04 SF	0.81	0.00	132.06
135. Clean the ceiling	163.04 SF	0.57	0.15	93.08
136. Clean recessed light fixture	4.00 EA	17.15	0.03	68.63
137. Clean bathroom fan	1.00 EA	45.53	0.00	45.53
138. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
139. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
140. Clean door (per side)	1.00 EA	11.59	0.02	11.61
Totals: Master Bathroom			1.39	1,814.02

State Farm

CHEN, KENNETH

75-79J8-65X



Office

Height: Sloped


308.03 SF Walls
442.44 SF Walls & Ceiling
32.79 LF Ceil. Perimeter

134.41 SF Ceiling
133.36 SF Floor
32.66 LF Floor Perimeter

Window

8' 7 1/8" X 5'

Opens into Exterior



Subroom: Office (1)

Height: Sloped

209.62 SF Walls
299.34 SF Walls & Ceiling
43.75 LF Ceil. Perimeter

89.73 SF Ceiling
89.45 SF Floor
18.20 LF Floor Perimeter

Door

3' 7/8" X 7' 11 11/16"

Opens into FOYER

Door

2' 11 13/16" X 8' 1/16"

Opens into OFFICE_BATH

Door

3' 5/8" X 7' 11 1/4"

Opens into OFFICE_CLOSE

Missing Wall


16' 4 13/16" X 10'

Opens into OFFICE1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
141. HEPA Vacuuming - Detailed - (PER SF)	222.81 SF	0.81	0.00	180.48
142. Clean floor	222.81 SF	0.69	0.21	153.95
** WALLS **				
143. HEPA Vacuuming - Detailed - (PER SF)	517.65 SF	0.81	0.00	419.30
144. Clean the walls	517.65 SF	0.57	0.49	295.55
145. Clean door / window opening (per side)	4.00 EA	21.03	0.02	84.14
146. Clean door - French (per side)	3.00 EA	36.03	0.03	108.12
147. Clean door hardware	2.00 EA	10.72	0.04	21.48
148. Clean window unit (per side) 10 - 20 SF	3.00 EA	24.40	0.01	73.21
149. Clean register - heat / AC	2.00 EA	9.13	0.00	18.26
150. Clean thermostat	1.00 EA	20.69	0.00	20.69
** CEILING **				
151. HEPA Vacuuming - Detailed - (PER SF)	224.13 SF	0.81	0.00	181.55

CONTINUED - Office

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
152. Clean the ceiling	224.13 SF	0.57	0.21	127.96
153. Clean recessed light fixture	6.00 EA	17.15	0.05	102.95
154. Clean light fixture	1.00 EA	17.13	0.01	17.14
<u>CONTENT MANIPULATION</u>				
155. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Office			1.07	1,866.55

**Linen Closet****Height: 8'**

49.63 SF Walls	3.67 SF Ceiling
53.30 SF Walls & Ceiling	3.67 SF Floor
7.89 LF Ceil. Perimeter	5.87 LF Floor Perimeter

Door 2' 3/16" X 6' 8 5/16" Opens into MASTER_CLOS5


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
156. HEPA Vacuuming - Detailed - (PER SF)	3.67 SF	0.81	0.00	2.97
157. Clean floor	3.67 SF	0.69	0.00	2.53
** WALLS **				
158. HEPA Vacuuming - Detailed - (PER SF)	49.63 SF	0.81	0.00	40.20
159. Clean the walls	49.63 SF	0.57	0.05	28.34
160. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
161. Clean door (per side)	1.00 EA	11.59	0.02	11.61

CONTINUED - Linen Closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
162. Clean closet shelf and rod per lineal foot	2.45 LF	1.73	0.01	4.25
** CEILING **				
163. HEPA Vacuuming - Detailed - (PER SF)	3.67 SF	0.81	0.00	2.97
164. Clean the ceiling	3.67 SF	0.57	0.00	2.09
Totals: Linen Closet			0.08	115.99

Great Room 2

Height: Peaked




301.64 SF Walls	235.69 SF Ceiling
537.33 SF Walls & Ceiling	228.34 SF Floor
72.82 LF Ceil. Perimeter	22.78 LF Floor Perimeter

Door	4' 7 1/2" X 7' 8"	Opens into Exterior
Window	4' 7" X 1' 10"	Opens into Exterior
Missing Wall - Goes to Floor	14' X 11'	Opens into KITCHEN4
Missing Wall	4' 5 11/16" X 11' 6"	Opens into HALLWAY


Subroom: Great Room 2 (5)

Height: Sloped




13.87 SF Walls	179.72 SF Ceiling
193.59 SF Walls & Ceiling	179.20 SF Floor
36.72 LF Ceil. Perimeter	0.38 LF Floor Perimeter

Missing Wall	5' 7 5/8" X 11'	Opens into GREAT_ROOM
Missing Wall	30' 10 13/16" X 11'	Opens into GREAT_ROOM_3
Door	5' 5" X 7' 8"	Opens into Exterior
Window	5' 5" X 1' 10"	Opens into Exterior
Missing Wall	30' 8 13/16" X 11'	Opens into GREAT_ROOM_2

**Subroom: Great Room (2)****Height: Sloped**

107.27 SF Walls
 186.50 SF Walls & Ceiling
 26.36 LF Ceil. Perimeter

79.23 SF Ceiling
 79.00 SF Floor
 12.53 LF Floor Perimeter

Missing Wall**7' 2 7/8" X 11'****Opens into GREAT_ROOM1****Missing Wall - Goes to neither Floor/Ceiling****5' 5 7/8" X 6' 4"****Opens into FIREPLACE****Missing Wall****5' 7 5/8" X 11'****Opens into GREAT_ROOM_1****Missing Wall****13' 9 11/16" X 11'****Opens into GREAT_ROOM2****Subroom: Great Room (3)****Height: Sloped**

58.04 SF Walls
 79.55 SF Walls & Ceiling
 20.78 LF Ceil. Perimeter

21.51 SF Ceiling
 20.01 SF Floor
 5.86 LF Floor Perimeter

Missing Wall**7' 2 7/8" X 11' 6"****Opens into GREAT_ROOM****Missing Wall****8 7/16" X 11' 6"****Opens into GREAT_ROOM1****Missing Wall - Goes to Ceiling****1' 3 3/4" X 8' 6"****Opens into FIREPLACE****Missing Wall****7' 2 7/8" X 11' 6"****Opens into HALLWAY**

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

**** FLOORING ****


165. HEPA Vacuuming - Detailed - (PER SF)	785.21 SF	0.81	0.00	636.02
166. Clean floor - tile	785.21 SF	0.95	5.22	751.17

**** WALLS ****

167. HEPA Vacuuming - Detailed - (PER SF)	835.67 SF	0.81	0.00	676.89
168. Clean the walls	835.67 SF	0.57	0.79	477.12
169. Clean door / window opening (per side)	7.00 EA	21.03	0.03	147.24
170. Clean patio door (sliding glass) (per side)	6.00 EA	63.28	0.71	380.39
171. Clean door - French double door set (per side)	1.00 EA	72.01	0.02	72.03
172. Clean door hardware	14.00 EA	10.72	0.29	150.37
173. Clean window unit (per side) 10 - 20 SF	4.00 EA	24.40	0.01	97.61

CONTINUED - Great Room 2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
174. Clean window unit (per side) 3 - 9 SF	9.00 EA	17.07	0.01	153.64
175. Clean thermostat	3.00 EA	20.69	0.00	62.07
176. Clean cold air return cover	1.00 EA	14.08	0.01	14.09
177. Clean fireplace screen	2.00 EA	48.77	0.00	97.54
** CEILING **				
178. HEPA Vacuuming - Detailed - (PER SF)	797.58 SF	0.81	0.00	646.04
179. Clean the ceiling	797.58 SF	0.57	0.76	455.38
180. Clean recessed light fixture	34.00 EA	17.15	0.29	583.39
CONTENT MANIPULATION				
181. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Great Room 2			8.14	5,462.76



Office Closet

Height: 8'

190.41 SF Walls	44.84 SF Ceiling
235.25 SF Walls & Ceiling	44.84 SF Floor
26.83 LF Ceil. Perimeter	23.78 LF Floor Perimeter

Door


3' 5/8" X 7' 11 1/4"

Opens into OFFICE

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
182. HEPA Vacuuming - Detailed - (PER SF)	44.84 SF	0.81	0.00	36.32
183. Clean floor	44.84 SF	0.69	0.04	30.98

CONTINUED - Office Closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** WALLS **				
184. HEPA Vacuuming - Detailed - (PER SF)	190.41 SF	0.81	0.00	154.23
185. Clean the walls	190.41 SF	0.57	0.18	108.71
186. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
187. Clean door - French (per side)	1.00 EA	36.03	0.01	36.04
188. Clean shelving - wood	11.89 LF	1.45	0.06	17.30
** CEILING **				
189. HEPA Vacuuming - Detailed - (PER SF)	44.84 SF	0.81	0.00	36.32
190. Clean the ceiling	44.84 SF	0.57	0.04	25.60
191. Clean light fixture	1.00 EA	17.13	0.01	17.14
Totals: Office Closet			0.34	483.67




Bedroom		Height: Sloped
282.67 SF Walls	171.12 SF Ceiling	
453.78 SF Walls & Ceiling	166.44 SF Floor	
61.28 LF Ceil. Perimeter	20.59 LF Floor Perimeter	
Door	2' 10 13/16" X 7' 10 7/8"	Opens into MASTER_BATHR
Door	3' 1 3/8" X 7' 10 7/8"	Opens into HALLWAY_2
Door	4' 11 1/2" X 8' 1/16"	Opens into MASTER_CLOS5
Door	6' 5/16" X 7' 11 1/4"	Opens into MASTER_CLOSE
Window	3' 6" X 3' 6"	Opens into Exterior


75-79J8-65X



Opens into Exterior



Opens into BEDROOM4




Opens into BEDROOM2

Page: 32

CONTINUED - Bedroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
198. Clean patio door (sliding glass) (per side)	1.00 EA	63.28	0.12	63.40
199. Clean door hardware	7.00 EA	10.72	0.15	75.19
200. Clean window unit (per side) 10 - 20 SF	2.00 EA	24.40	0.00	48.80
201. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
202. Clean light fixture	2.00 EA	17.13	0.01	34.27
** CEILING **				
203. HEPA Vacuuming - Detailed - (PER SF)	414.84 SF	0.81	0.00	336.02
204. Clean the ceiling	414.84 SF	0.57	0.39	236.85
205. Clean recessed light fixture	10.00 EA	17.15	0.09	171.59
206. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
<u>CONTENT MANIPULATION</u>				
207. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Bedroom			1.84	2,896.56



Master Closet

Height: 8'

233.13 SF Walls	74.80 SF Ceiling
307.92 SF Walls & Ceiling	74.80 SF Floor
35.79 LF Ceil. Perimeter	28.81 LF Floor Perimeter

Door	4' 11 1/2" X 8' 1/16"	Opens into BEDROOM
Door	2' 3/16" X 6' 8 5/16"	Opens into LINEN_CLOSE2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

**** FLOORING ****

State Farm

CHEN, KENNETH

75-79J8-65X


CONTINUED - Master Closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
208. HEPA Vacuuming - Detailed - (PER SF)	74.80 SF	0.81	0.00	60.59
209. Clean floor	74.80 SF	0.69	0.07	51.68
** WALLS **				
210. HEPA Vacuuming - Detailed - (PER SF)	233.13 SF	0.81	0.00	188.84
211. Clean the walls	233.13 SF	0.57	0.22	133.10
212. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
213. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
214. Clean door (per side)	1.00 EA	11.59	0.02	11.61
215. Clean door hardware	1.00 EA	10.72	0.02	10.74
216. Clean closet organizer and rod	3.00 EA	60.69	0.44	182.51
** CEILING **				
217. HEPA Vacuuming - Detailed - (PER SF)	74.80 SF	0.81	0.00	60.59
218. Clean the ceiling	74.80 SF	0.57	0.07	42.71
219. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
220. Clean recessed light fixture	4.00 EA	17.15	0.03	68.63
221. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
<u>CONTENT MANIPULATION</u>				
222. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Master Closet			0.90	1,006.17

State Farm

CHEN, KENNETH


75-79J8-65X



Master Closet Hers Height: Tray

172.02 SF Walls	81.70 SF Ceiling
253.72 SF Walls & Ceiling	75.72 SF Floor
27.48 LF Ceil. Perimeter	21.46 LF Floor Perimeter

Door 6' 5/16" X 7' 11 1/4" Opens into BEDROOM



Subroom: Master Closet Hers (1) Height: 8'

89.78 SF Walls	13.68 SF Ceiling
103.46 SF Walls & Ceiling	13.68 SF Floor
11.22 LF Ceil. Perimeter	11.22 LF Floor Perimeter

Missing Wall 7' 3 3/4" X 8' Opens into MASTER_CLOSE

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

**** FLOORING ****

223. HEPA Vacuuming - Detailed - (PER SF)	89.40 SF	0.81	0.00	72.41
224. Clean floor	89.40 SF	0.69	0.08	61.77

**** WALLS ****


225. HEPA Vacuuming - Detailed - (PER SF)	261.80 SF	0.81	0.00	212.06
226. Clean the walls	261.80 SF	0.57	0.25	149.48
227. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
228. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
229. Clean closet organizer and rod	3.00 EA	60.69	0.44	182.51

**** CEILING ****

230. HEPA Vacuuming - Detailed - (PER SF)	95.38 SF	0.81	0.00	77.26
231. Clean the ceiling	95.38 SF	0.57	0.09	54.46
232. Clean recessed light fixture	4.00 EA	17.15	0.03	68.63
233. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
234. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03

CONTINUED - Master Closet Hers


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
235. Clean door (per side)	1.00 EA	11.59	0.02	11.61
CONTENT MANIPULATION				
236. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Master Closet Hers			0.93	1,076.22



Guest Bedroom Height: Sloped

211.79 SF Walls	134.00 SF Ceiling
345.79 SF Walls & Ceiling	133.65 SF Floor
33.59 LF Ceil. Perimeter	24.85 LF Floor Perimeter

Door	2' 10" X 6' 8"	Opens into Exterior
Door	2' 11 9/16" X 6' 11 1/16"	Opens into HALLWAY_2
Door	2' 10 13/16" X 6' 11 7/8"	Opens into GUEST_BEDRO1



Subroom: Guest Bedroom (1) Height: Sloped

282.97 SF Walls	125.07 SF Ceiling
408.04 SF Walls & Ceiling	120.00 SF Floor
53.25 LF Ceil. Perimeter	27.64 LF Floor Perimeter

Door	2' 2" X 7' 11"	Opens into GUEST_BATHRO
Missing Wall	20' 6 3/8" X 9' 4"	Opens into GUEST_BEDRO3
Door	2' 5" X 6' 8"	Opens into Exterior
Window	2' 6" X 5' 8"	Opens into Exterior
Window	2' 6" X 5' 8"	Opens into Exterior


State Farm

CHEN, KENNETH

75-79J8-65X

Subroom: Guest Bedroom (2)

Height: Sloped



57.69 SF Walls
161.67 SF Walls & Ceiling
30.66 LF Ceil. Perimeter

103.98 SF Ceiling
102.66 SF Floor
5.33 LF Floor Perimeter

Missing Wall 20' 6 3/8" X 8' 6" Opens into GUEST_BEDRO4
Door 4' 8" X 6' 8" Opens into Exterior
Missing Wall 20' 6 3/8" X 8' 6" Opens into GUEST_BEDROO

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

** FLOORING **

237. HEPA Vacuuming - Detailed - (PER SF)	356.32 SF	0.81	0.00	288.62
238. Clean floor	356.32 SF	0.69	0.34	246.20

** WALLS **

239. HEPA Vacuuming - Detailed - (PER SF)	552.45 SF	0.81	0.00	447.48
240. Clean the walls	552.45 SF	0.57	0.52	315.42
241. Clean door / window opening (per side)	6.00 EA	21.03	0.02	126.20
242. Clean door - French (per side)	3.00 EA	36.03	0.03	108.12
243. Clean patio door (sliding glass) (per side)	1.00 EA	63.28	0.12	63.40
244. Clean door hardware	4.00 EA	10.72	0.08	42.96
245. Clean window unit (per side) 10 - 20 SF	2.00 EA	24.40	0.00	48.80
246. Clean register - heat / AC	2.00 EA	9.13	0.00	18.26
247. Clean thermostat	1.00 EA	20.69	0.00	20.69


** CEILING **

248. HEPA Vacuuming - Detailed - (PER SF)	363.05 SF	0.81	0.00	294.07
249. Clean the ceiling	363.05 SF	0.57	0.34	207.28
250. Clean recessed light fixture	10.00 EA	17.15	0.09	171.59
251. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12

CONTENT MANIPULATION

CONTINUED - Guest Bedroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
252. Content Manipulation charge - per hour	1.00 HR	61.77	0.00	61.77
to facilitate cleaning of the room by moving things in place				
Totals: Guest Bedroom			1.54	2,470.98



Guest Bedroom Closet

Height: 8'


166.65 SF Walls	33.51 SF Ceiling
200.16 SF Walls & Ceiling	33.51 SF Floor
23.36 LF Ceil. Perimeter	20.46 LF Floor Perimeter

Door 2' 10 13/16" X 6' 11 7/8" Opens into GUEST_BEDROO


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				
253. HEPA Vacuuming - Detailed - (PER SF)	33.51 SF	0.81	0.00	27.14
254. Clean floor	33.51 SF	0.69	0.03	23.15
** WALLS **				
255. HEPA Vacuuming - Detailed - (PER SF)	166.65 SF	0.81	0.00	134.99
256. Clean the walls	166.65 SF	0.57	0.16	95.15
257. Clean door / window opening (per side)	1.00 EA	21.03	0.00	21.03
258. Clean door - French (per side)	1.00 EA	36.03	0.01	36.04
259. Clean shelving - wood	10.23 LF	1.45	0.05	14.88
** CEILING **				
260. HEPA Vacuuming - Detailed - (PER SF)	33.51 SF	0.81	0.00	27.14
261. Clean the ceiling	33.51 SF	0.57	0.03	19.13

CONTINUED - Guest Bedroom Closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
262. Clean light fixture	1.00 EA	17.13	0.01	17.14
Totals: Guest Bedroom Closet			0.29	415.79

**Foyer****Height: Sloped**

228.01 SF Walls	75.29 SF Ceiling
303.29 SF Walls & Ceiling	75.05 SF Floor
37.49 LF Ceil. Perimeter	19.65 LF Floor Perimeter

Missing Wall - Goes to Floor**5' 9 15/16" X 9' 10"****Opens into HALLWAY****Door****3' 7/16" X 8' 1 1/4"****Opens into OFFICE_BATH****Door****3' 7/8" X 7' 11 11/16"****Opens into OFFICE****Subroom: Foyer (1)****Height: Sloped**

63.25 SF Walls	13.21 SF Ceiling
76.46 SF Walls & Ceiling	13.12 SF Floor
10.36 LF Ceil. Perimeter	5.10 LF Floor Perimeter

Missing Wall**5' 9 15/16" X 10'****Opens into FOYER****Door****5' 2 3/4" X 8' 7/16"****Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

**** FLOORING ****


263. HEPA Vacuuming - Detailed - (PER SF)	88.17 SF	0.81	0.00	71.42
264. Clean floor - tile	88.17 SF	0.95	0.59	84.35

**** WALLS ****

265. HEPA Vacuuming - Detailed - (PER SF)	291.25 SF	0.81	0.00	235.91
266. Clean the walls	291.25 SF	0.57	0.28	166.29

CONTINUED - Foyer

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
267. Clean door / window opening (per side)	4.00 EA	21.03	0.02	84.14
268. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
269. Clean exterior door (per side)	2.00 EA	22.98	0.05	46.01
270. Clean door hardware	4.00 EA	10.72	0.08	42.96
271. Clean window unit (per side) 10 - 20 SF	1.00 EA	24.40	0.00	24.40
** CEILING **				
272. HEPA Vacuuming - Detailed - (PER SF)	88.50 SF	0.81	0.00	71.69
273. Clean the ceiling	88.50 SF	0.57	0.08	50.53
274. Clean recessed light fixture	6.00 EA	17.15	0.05	102.95
275. Clean smoke/carbon monoxide detector	1.00 EA	10.12	0.00	10.12
Totals: Foyer			1.17	1,062.85



Utility Room

Height: 8'

210.29 SF Walls	85.78 SF Ceiling
296.07 SF Walls & Ceiling	66.54 SF Floor
42.16 LF Ceil. Perimeter	24.01 LF Floor Perimeter

Door	2' 10 15/16" X 6' 7 1/8"	Opens into Exterior
Door	2' 10 13/16" X 6' 11 7/8"	Opens into HALLWAY_2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
** FLOORING **				

276. HEPA Vacuuming - Detailed - (PER SF)	66.54 SF	0.81	0.00	53.90
277. Clean floor - tile	66.54 SF	0.95	0.44	63.65

**** WALLS ****

State Farm

CHEN, KENNETH

75-79J8-65X

CONTINUED - Utility Room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
278. HEPA Vacuuming - Detailed - (PER SF)	210.29 SF	0.81	0.00	170.33
279. Clean the walls	210.29 SF	0.57	0.20	120.07
280. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
281. Clean door - French (per side)	2.00 EA	36.03	0.02	72.08
282. Clean door hardware	1.00 EA	10.72	0.02	10.74
283. Clean electrical breaker panel	1.00 EA	17.17	0.01	17.18
** FIXTURES **				
284. Clean cabinetry - lower - inside and out	9.33 LF	23.84	0.10	222.53
285. Clean cabinetry - upper - inside and out	14.41 LF	23.84	0.15	343.68
286. Clean cabinetry - full height - inside and out	1.83 LF	41.64	0.02	76.22
* 287. Clean cabinetry - upper - top of cabinet	14.41 LF	23.27	0.15	335.47
288. Clean countertop	18.66 SF	1.19	0.04	22.25
289. Clean sink	1.00 EA	21.03	0.00	21.03
290. Clean sink faucet	1.00 EA	15.65	0.00	15.65
** CEILING **				
291. HEPA Vacuuming - Detailed - (PER SF)	85.78 SF	0.81	0.00	69.48
292. Clean the ceiling	85.78 SF	0.57	0.08	48.97
293. Clean register - heat / AC	1.00 EA	9.13	0.00	9.13
294. Clean recessed light fixture	4.00 EA	17.15	0.03	68.63
Totals: Utility Room			1.27	1,783.06
Area Totals: Main Level				
6,612.05 SF Walls	3,364.13 SF Ceiling	9,976.18 SF Walls and Ceiling		
3,079.70 SF Floor	3,983.96 Total Area	623.44 LF Floor Perimeter		
3,524.15 Floor Area	383.40 Exterior Perimeter	1,286.84 LF Ceil. Perimeter		
3,109.95 Exterior Wall Area	of Walls	7,181.46 Interior Wall Area		

State Farm

CHEN, KENNETH

75-79J8-65X

Total: Main Level

28.29

31,853.37

General Provisions

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

****SITE PROTECTION****

**** EQUIPMENT ****

295. Negative air fan/Air scrubber (24 hr period) - No monit.	35.00 DA	73.02	0.00	2,555.70
---	----------	-------	------	----------

296. Add for HEPA filter (for negative air exhaust fan)	1.75 EA	217.22	32.60	412.74
---	---------	--------	-------	--------

297. Carbon vapor filter (for air scrubber) - 16" x 16"	7.00 EA	78.11	37.91	584.68
---	---------	-------	-------	--------

298. Equipment setup, take down, and monitoring (hourly charge)	5.00 HR	95.00	0.00	475.00
---	---------	-------	------	--------

Totals: General Provisions			70.51	4,028.12
-----------------------------------	--	--	--------------	-----------------

Attic

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

299. R&R Batt insulation - 12" - R38 - unfaced batt	3,527.02 SF	2.93	562.91	10,897.08
---	-------------	------	--------	-----------

Totals: Attic			562.91	10,897.08
----------------------	--	--	---------------	------------------

HVAC

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

State Farm

CHEN, KENNETH

75-79J8-65X

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
300. Clean furnace - forced air - Large	1.00 EA	134.20	0.08	134.28
301. Clean ductwork - Interior (PER REGISTER)	1.00 EA	40.74	0.01	40.75

Totals: HVAC			0.09	175.03
---------------------	--	--	-------------	---------------

Area Totals: Source - EagleView Roof & Walls

10,193.82 SF Walls	3,364.13 SF Ceiling	13,557.95 SF Walls and Ceiling
3,079.70 SF Floor	3,983.96 Total Area	1,109.66 LF Floor Perimeter
3,524.15 Floor Area	869.63 Exterior Perimeter of Walls	1,286.84 LF Ceil. Perimeter
6,691.72 Exterior Wall Area		7,181.46 Interior Wall Area
4,558.71 Surface Area	45.59 Number of Squares	428.35 Total Perimeter Length

Total: Source - EagleView Roof & Walls			959.32	61,959.81
---	--	--	---------------	------------------

Other Structures

Pool

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

CLEAN POOL

302. Swimming Pool - General Laborer - per hour	8.00 HR	61.77	0.00	494.16
---	---------	-------	------	--------

To clean the pool after the wildfire

303. R&R Swimming pool pump, 2 hp	1.00 EA	2,332.94	66.03	2,398.97
-----------------------------------	---------	----------	-------	----------


Totals: Pool			66.03	2,893.13
---------------------	--	--	--------------	-----------------

Garage

State Farm

CHEN, KENNETH

75-79J8-65X



Garage interior

Height: 9'


569.41 SF Walls
1,003.38 SF Walls & Ceiling
79.06 LF Ceil. Perimeter

433.98 SF Ceiling
433.98 SF Floor
61.31 LF Floor Perimeter

Door

17' 9" X 8' 1/16"

Opens into Exterior



Subroom: Stairs (1)

Height: 9'

30.80 SF Walls
35.67 SF Walls & Ceiling
6.46 LF Ceil. Perimeter

4.87 SF Ceiling
10.47 SF Floor
6.60 LF Floor Perimeter

Missing Wall

3' 6 13/16" X 9'

Opens into GARAGE_INTER

Door

2' 11 7/8" X 6' 8"

Opens into Exterior

Missing Wall

1' 7" X 9'

Opens into GARAGE_INTER

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
-------------	----------	------------	-----	-----

** FLOORING **

304. HEPA Vacuuming - Detailed - (PER SF)	444.45 SF	0.81	0.00	360.00
305. Clean floor	444.45 SF	0.69	0.42	307.09

** WALLS **


306. HEPA Vacuuming - Detailed - (PER SF)	600.21 SF	0.81	0.00	486.17
307. Clean the walls	600.21 SF	0.57	0.57	342.69
308. Clean door / window opening (per side)	2.00 EA	21.03	0.01	42.07
309. Clean door - French (per side)	1.00 EA	36.03	0.01	36.04
310. Clean door hardware	1.00 EA	10.72	0.02	10.74
311. Clean electrical breaker panel	1.00 EA	17.17	0.01	17.18
312. Clean outlet or switch	3.00 EA	5.61	0.00	16.83

** CEILING **

313. HEPA Vacuuming - Detailed - (PER SF)	438.85 SF	0.81	0.00	355.47
314. Clean the ceiling	438.85 SF	0.57	0.42	250.56

CONTINUED - Garage interior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
315. Clean light fixture - fluorescent	4.00 EA	22.79	0.02	91.18
316. Clean overhead (garage) door opener	1.00 EA	42.65	0.00	42.65
Totals: Garage interior			1.48	2,358.67

**Garage Roof**

475.01 Surface Area	4.75 Number of Squares
87.73 Total Perimeter Length	

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
317. Clean the surface area	475.01 SF	0.55	0.45	261.71
Totals: Garage Roof			0.45	261.71

Garage Exterior Door

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
318. R&R Overhead door & hardware - 16' x 7'	1.00 EA	1,732.73	120.16	1,852.89
Totals: Garage Exterior Door			120.16	1,852.89

Area Totals: Garage

600.21 SF Walls	438.85 SF Ceiling	1,039.06 SF Walls and Ceiling
444.45 SF Floor		67.90 LF Floor Perimeter
		85.51 LF Ceil. Perimeter
475.01 Surface Area	4.75 Number of Squares	87.73 Total Perimeter Length

Total: Garage			122.09	4,473.27
----------------------	--	--	---------------	-----------------

State Farm

CHEN, KENNETH

75-79J8-65X

Area Totals: Other Structures

600.21 SF Walls

438.85 SF Ceiling

1,039.06 SF Walls and Ceiling

444.45 SF Floor

67.90 LF Floor Perimeter

85.51 LF Ceil. Perimeter

475.01 Surface Area

4.75 Number of Squares

87.73 Total Perimeter Length

Total: Other Structures**188.12****7,366.40****Landscaping**

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
319. Plants - shrubs - deciduous - 5 gallon	3.00 EA	103.53	9.91	320.50
Shrubs/bushes on top of garage				
320. Plants - shrubs - evergreen - 5 gallon	8.00 EA	126.76	44.08	1,058.16
Trees at rear elevation				
321. R&R Artificial grass / turf	120.00 SF	18.73	106.82	2,354.42
Totals: Landscaping			160.81	3,733.08

Debris Removal

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
322. Haul debris - per pickup truck load - including dump fees	1.00 EA	200.79	0.00	200.79
Totals: Debris Removal			0.00	200.79

PRC RESTORATION INC.

0.00 SF Walls

0.00 SF Ceiling

0.00 SF Walls & Ceiling

0.00 SF Floor

0.00 SF Short Wall

0.00 LF Floor Perimeter

0.00 SF Long Wall

0.00 LF Ceil. Perimeter

State Farm

CHEN, KENNETH

75-79J8-65X

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
323. Cleaning (Bid Item)	1.00 EA	14,137.76 *EN	0.00	14,137.76
Totals: PRC RESTORATION INC.			0.00	14,137.76

Labor Minimums Applied

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
324. Tile / marble labor minimum	1.00 EA	323.80	0.00	323.80
Totals: Labor Minimums Applied			0.00	323.80

Line Item Totals: 75-79J8-65X	1,308.25	87,721.64
--------------------------------------	-----------------	------------------

COVERAGE	TAX	RCV
Coverage A - Dwelling - 39 Smoke	674.52	70,588.97
Coverage A - Dwelling - 39 Smoke - Trees, Shrubs, and Landscaping	160.81	3,733.08
Coverage A - Dwelling Extension - 39 Smoke	1.43	1,264.12
Coverage A - Dwelling - 35 Windstorm and Hail	30.41	857.52
Coverage A - Dwelling - 33 Fire, Lightning, & Removal	441.08	11,277.95
Total	1,308.25	87,721.64

Grand Total Areas:

10,794.02 SF Walls	3,802.98 SF Ceiling	14,597.00 SF Walls and Ceiling
3,524.15 SF Floor		1,177.57 LF Floor Perimeter
		1,372.35 LF Ceil. Perimeter
3,524.15 Floor Area	3,983.96 Total Area	7,181.46 Interior Wall Area
6,691.72 Exterior Wall Area	869.63 Exterior Perimeter of Walls	
5,033.71 Surface Area	50.34 Number of Squares	516.08 Total Perimeter Length

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION		LINE ITEM	REPL. COST	ACV	NON-REC.	MAX ADDL.
		QTY	TOTAL		DEPREC.	AMT AVAIL.
CLN	CLEANING					
	Clean {V}	10,912.33 SF	\$6,230.35	\$6,230.35	\$0.00	\$0.00
	Clean {V}	9,387.72 SF	\$5,172.17	\$5,172.17	\$0.00	\$0.00
	Clean light bar	6.00 EA	\$178.74	\$178.74	\$0.00	\$0.00
	Clean bathroom fan	3.00 EA	\$136.59	\$136.59	\$0.00	\$0.00
	Cleaning (Bid Item)	1.00 EA	\$14,137.76	\$14,137.76	\$0.00	\$0.00
	Clean door - bypass set (per side)	2.00 EA	\$46.68	\$46.68	\$0.00	\$0.00
	Clean electrical breaker panel	2.00 EA	\$34.36	\$34.36	\$0.00	\$0.00
	Clean cold air return cover	2.00 EA	\$28.18	\$28.18	\$0.00	\$0.00
	Clean closet organizer and rod	6.00 EA	\$365.02	\$365.02	\$0.00	\$0.00
	Clean closet shelf and rod per lineal foot	2.45 LF	\$4.25	\$4.25	\$0.00	\$0.00
	Clean countertop	178.34 SF	\$212.58	\$212.58	\$0.00	\$0.00
	Clean ductwork - Interior (PER REGISTER)	1.00 EA	\$40.75	\$40.75	\$0.00	\$0.00
	Clean door (per side)	8.00 EA	\$92.88	\$92.88	\$0.00	\$0.00
	Clean door hardware	43.00 EA	\$461.84	\$461.84	\$0.00	\$0.00
	Clean dishwasher - exterior	1.00 EA	\$25.34	\$25.34	\$0.00	\$0.00
	Clean floor	1,963.30 SF	\$1,356.53	\$1,356.53	\$0.00	\$0.00
	Clean sink faucet	8.00 EA	\$125.20	\$125.20	\$0.00	\$0.00
	Clean floor - tile	1,548.74 SF	\$1,481.60	\$1,481.60	\$0.00	\$0.00
	Clean cabinetry - full height - inside and out	5.66 LF	\$235.75	\$235.75	\$0.00	\$0.00
	Clean light fixture - fluorescent	4.00 EA	\$91.18	\$91.18	\$0.00	\$0.00
	Clean door - French (per side)	29.00 EA	\$1,045.16	\$1,045.16	\$0.00	\$0.00
	Clean door - French double door set (per side)	1.00 EA	\$72.03	\$72.03	\$0.00	\$0.00
	Clean furnace - forced air - Large	1.00 EA	\$134.28	\$134.28	\$0.00	\$0.00
	Clean range hood	1.00 EA	\$27.42	\$27.42	\$0.00	\$0.00
	HEPA Vacuuming - Detailed - (PER SF)	14,424.37 SF	\$11,683.76	\$11,683.76	\$0.00	\$0.00
	Clean light fixture	5.00 EA	\$85.69	\$85.69	\$0.00	\$0.00
	Clean cabinetry - lower - inside and out	62.40 LF	\$1,488.27	\$1,488.27	\$0.00	\$0.00
	Clean mirror	61.00 SF	\$70.20	\$70.20	\$0.00	\$0.00
	Clean overhead (garage) door opener	1.00 EA	\$42.65	\$42.65	\$0.00	\$0.00
	Clean door / window opening (per side)	58.00 EA	\$1,219.97	\$1,219.97	\$0.00	\$0.00
	Clean outlet or switch	3.00 EA	\$16.83	\$16.83	\$0.00	\$0.00
	Clean patio door (sliding glass) (per side)	8.00 EA	\$507.19	\$507.19	\$0.00	\$0.00

Note: Slight variances may be found within report sections due to rounding

Date: 4/15/2025 7:27 AM

Page: 48

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION		LINE ITEM	REPL. COST	ACV	NON-REC.	MAX ADDL.
		QTY	TOTAL		DEPREC.	AMT AVAIL.
CLN	CLEANING					
	Clean with pressure/chemical spray	411.15 SF	\$210.08	\$210.08	\$0.00	\$0.00
	Clean with pressure/chemical spray	431.12 SF	\$220.28	\$220.28	\$0.00	\$0.00
	Clean with pressure/chemical spray	670.56 SF	\$342.63	\$342.63	\$0.00	\$0.00
	Clean with pressure/chemical spray - Concrete wall	405.24 SF	\$207.05	\$207.05	\$0.00	\$0.00
	Clean with pressure/chemical spray- Patio	733.96 SF	\$375.02	\$375.02	\$0.00	\$0.00
	Clean with pressure/chemical spray- Driveway	1,144.00 SF	\$584.53	\$584.53	\$0.00	\$0.00
	Clean recessed light fixture	116.00 EA	\$1,990.38	\$1,990.38	\$0.00	\$0.00
	Clean register - heat / AC	14.00 EA	\$127.82	\$127.82	\$0.00	\$0.00
	Clean range - exterior	1.00 EA	\$51.07	\$51.07	\$0.00	\$0.00
	Clean fireplace screen	2.00 EA	\$97.54	\$97.54	\$0.00	\$0.00
	Clean shower door	4.00 EA	\$115.20	\$115.20	\$0.00	\$0.00
	Clean soffit - wood	145.17 SF	\$87.24	\$87.24	\$0.00	\$0.00
	Clean shelving - wood	22.12 LF	\$32.18	\$32.18	\$0.00	\$0.00
	Clean roof window or skylight	1.00 EA	\$54.67	\$54.67	\$0.00	\$0.00
	Clean smoke/carbon monoxide detector	7.00 EA	\$70.84	\$70.84	\$0.00	\$0.00
	Clean sink	8.00 EA	\$168.27	\$168.27	\$0.00	\$0.00
	Clean shower	3.00 EA	\$210.36	\$210.36	\$0.00	\$0.00
	Clean towel bar	2.00 EA	\$22.76	\$22.76	\$0.00	\$0.00
	Clean toilet	3.00 EA	\$106.05	\$106.05	\$0.00	\$0.00
	Clean toilet seat	3.00 EA	\$22.86	\$22.86	\$0.00	\$0.00
	Clean toilet paper dispenser	3.00 EA	\$34.20	\$34.20	\$0.00	\$0.00
	Clean thermostat	6.00 EA	\$124.14	\$124.14	\$0.00	\$0.00
	Clean tub / shower faucet	4.00 EA	\$91.09	\$91.09	\$0.00	\$0.00
	Clean tub	1.00 EA	\$34.19	\$34.19	\$0.00	\$0.00
	Clean cabinetry - upper - inside and out	39.41 LF	\$939.94	\$939.94	\$0.00	\$0.00
	Clean cabinetry - upper - top of cabinet	39.41 LF	\$917.48	\$917.48	\$0.00	\$0.00
	Clean vanity - inside and out	27.51 LF	\$587.90	\$587.90	\$0.00	\$0.00
	Clean window unit (per side) 10 - 20 SF	17.00 EA	\$414.82	\$414.82	\$0.00	\$0.00
	Clean window unit (per side) 3 - 9 SF	9.00 EA	\$153.64	\$153.64	\$0.00	\$0.00
	Clean exterior door (per side)	2.00 EA	\$46.01	\$46.01	\$0.00	\$0.00
	TOTAL CLEANING		\$55,291.44	\$55,291.44	\$0.00	\$0.00
CON	CONTENT MANIPULATION					

Note: Slight variances may be found within report sections due to rounding

Date: 4/15/2025 7:27 AM

Page: 49

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION	LINE ITEM QTY	REPL. COST TOTAL	ACV	NON-REC. DEPREC.	MAX ADDL. AMT AVAIL.
CON CONTENT MANIPULATION					
Content Manipulation charge - per hour	7.00 HR	\$432.39	\$432.39	\$0.00	\$0.00
TOTAL CONTENT MANIPULATION		\$432.39	\$432.39	\$0.00	\$0.00
DMO GENERAL DEMOLITION					
Haul debris - per pickup truck load - including dump fees	1.00 EA	\$200.79	\$200.79	\$0.00	\$0.00
TOTAL GENERAL DEMOLITION		\$200.79	\$200.79	\$0.00	\$0.00
DOR DOORS					
R&R Overhead door & hardware - 16' x 7'	1.00 EA	\$1,852.89	\$1,852.89	\$0.00	\$0.00
TOTAL DOORS		\$1,852.89	\$1,852.89	\$0.00	\$0.00
ELS ELECTRICAL - SPECIAL SYSTEMS					
R&R Solar electric panel - up to 200 watt	1.00 EA	\$857.52	\$857.52	\$0.00	\$0.00
TOTAL ELECTRICAL - SPECIAL SYSTEMS		\$857.52	\$857.52	\$0.00	\$0.00
EQC MISC. EQUIPMENT - COMMERCIAL					
R&R Artificial grass / turf	120.00 SF	\$2,354.42	\$2,354.42	\$0.00	\$0.00
TOTAL MISC. EQUIPMENT - COMMERCIAL		\$2,354.42	\$2,354.42	\$0.00	\$0.00
FCT FLOOR COVERING - CERAMIC TILE					
R&R Tile floor covering - High grade	100.00 SF	\$2,425.34	\$2,425.34	\$0.00	\$0.00
TOTAL FLOOR COVERING - CERAMIC TILE		\$2,425.34	\$2,425.34	\$0.00	\$0.00
FEN FENCING					
Wood fence 5'- 6' high - cedar or equal	70.00 LF	\$4,600.75	\$4,600.75	\$0.00	\$0.00
TOTAL FENCING		\$4,600.75	\$4,600.75	\$0.00	\$0.00
HMR HAZARDOUS MATERIAL REMEDIATION					
Equipment setup, take down, and monitoring (hourly charge)	5.00 HR	\$475.00	\$475.00	\$0.00	\$0.00
Add for HEPA filter (for negative air exhaust fan)	1.75 EA	\$412.74	\$412.74	\$0.00	\$0.00
Carbon vapor filter (for air scrubber) - 16" x 16"	7.00 EA	\$584.68	\$584.68	\$0.00	\$0.00
Negative air fan/Air scrubber (24 hr period) - No monit.	35.00 DA	\$2,555.70	\$2,555.70	\$0.00	\$0.00
TOTAL HAZARDOUS MATERIAL REMEDIATION		\$4,028.12	\$4,028.12	\$0.00	\$0.00
INS INSULATION					
R&R Batt insulation - 12" - R38 - unfaced batt	3,527.02 SF	\$10,897.08	\$10,897.08	\$0.00	\$0.00
TOTAL INSULATION		\$10,897.08	\$10,897.08	\$0.00	\$0.00

Note: Slight variances may be found within report sections due to rounding

Date: 4/15/2025 7:27 AM

Page: 50

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION		LINE ITEM	REPL. COST	ACV	NON-REC.	MAX ADDL.
		QTY	TOTAL		DEPREC.	AMT AVAIL.
LND	LANDSCAPING					
	Plants - shrubs - deciduous - 5 gallon	3.00 EA	\$320.50	\$320.50	\$0.00	\$0.00
	Plants - shrubs - evergreen - 5 gallon	8.00 EA	\$1,058.16	\$1,058.16	\$0.00	\$0.00
	TOTAL LANDSCAPING		\$1,378.66	\$1,378.66	\$0.00	\$0.00
POL	SWIMMING POOLS & SPAS					
	Swimming Pool - General Laborer - per hour	8.00 HR	\$494.16	\$494.16	\$0.00	\$0.00
	R&R Swimming pool pump, 2 hp	1.00 EA	\$2,398.97	\$2,398.97	\$0.00	\$0.00
	TOTAL SWIMMING POOLS & SPAS		\$2,893.13	\$2,893.13	\$0.00	\$0.00
TIL	TILE					
	Tile / Cultured Marble - General Laborer - per hour	3.00 HR	\$185.31	\$185.31	\$0.00	\$0.00
	Tile / marble labor minimum	1.00 EA	\$323.80	\$323.80	\$0.00	\$0.00
	TOTAL TILE		\$509.11	\$509.11	\$0.00	\$0.00
TOTALS			\$87,721.64	\$87,721.64	\$0.00	\$0.00

Note: Slight variances may be found within report sections due to rounding

Date: 4/15/2025 7:27 AM

Page: 51

Recap of Taxes, Overhead and Profit

	GC Overhead (0%)	GC Profit (0%)	Material Sales Tax (9.5%)	Storage Rental Tax (9.5%)
Line Items	0.00	0.00	1,308.25	0.00
Permit	0.00	0.00	0.00	0.00
Total	0.00	0.00	1,308.25	0.00

State Farm

CHEN, KENNETH

75-79J8-65X

Recap by Category


Items	Total	%
CLEANING	55,248.91	62.97%
Coverage: Coverage A - Dwelling - 39 Smoke @ 98.61% =	54,480.38	
Coverage: Coverage A - Dwelling Extension - 39 Smoke @ 1.39% =	768.53	
CONTENT MANIPULATION	432.39	0.49%
Coverage: Coverage A - Dwelling - 39 Smoke @ 100.00% =	432.39	
GENERAL DEMOLITION	200.79	0.23%
Coverage: Coverage A - Dwelling - 39 Smoke @ 100.00% =	200.79	
DOORS	1,732.73	1.97%
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal @ 100.00% =	1,732.73	
ELECTRICAL - SPECIAL SYSTEMS	827.11	0.94%
Coverage: Coverage A - Dwelling - 35 Windstorm and Hail @ 100.00% =	827.11	
MISC. EQUIPMENT - COMMERCIAL	2,247.60	2.56%
Coverage: Coverage A - Dwelling - 39 Smoke - Trees, Shrubs, and Landscaping @ 100.00% =	2,247.60	
FLOOR COVERING - CERAMIC TILE	2,350.00	2.68%
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal @ 100.00% =	2,350.00	
FENCING	4,421.20	5.04%
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal @ 100.00% =	4,421.20	
HAZARDOUS MATERIAL REMEDIATION	3,957.61	4.51%
Coverage: Coverage A - Dwelling - 39 Smoke @ 100.00% =	3,957.61	
INSULATION	10,334.17	11.78%
Coverage: Coverage A - Dwelling - 39 Smoke @ 100.00% =	10,334.17	
LANDSCAPING	1,324.67	1.51%
Coverage: Coverage A - Dwelling - 39 Smoke - Trees, Shrubs, and Landscaping @ 100.00% =	1,324.67	
SWIMMING POOLS & SPAS	2,827.10	3.22%
Coverage: Coverage A - Dwelling Extension - 39 Smoke @ 17.48% =	494.16	
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal @ 82.52% =	2,332.94	
TILE	509.11	0.58%
Coverage: Coverage A - Dwelling - 39 Smoke @ 100.00% =	509.11	
Subtotal	86,413.39	98.50%
Permits and Fees	11.59	0.01%
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal @ 100.00% =	11.59	
Material Sales Tax	1,308.25	1.49%
Coverage: Coverage A - Dwelling - 39 Smoke @ 51.56% =	674.52	

State Farm



CHEN, KENNETH

75-79J8-65X

Coverage: Coverage A - Dwelling - 39 Smoke - Trees, Shrubs, and Landscaping	@	12.29% =	160.81	
Coverage: Coverage A - Dwelling Extension - 39 Smoke	@	0.11% =	1.43	
Coverage: Coverage A - Dwelling - 35 Windstorm and Hail	@	2.32% =	30.41	
Coverage: Coverage A - Dwelling - 33 Fire, Lightning, & Removal	@	33.72% =	441.08	
Total			87,733.23	100.00%



Date: 4/15/2025 7:27 AM



Exterior