CHANGAN QIYUAN Q06 VS ONVO L60 PQ & A&U BENCHMARK REPORT



Changan Qiyuan Q06 — autohome.com.cn · spec 78819 · Front-left 45°



Onvo L60 — autohome.com.cn · spec 68375 · Front-left 45°

2026-11-12 Trần Văn Huy

Desk benchmark from published specifications and photographs, scored against the VinFast PQ/GD&T Gateway audit checklist 2026. Touch & Feel, Functionality and Sound Quality need the physical audit and are marked N/A.

1. Objective

- To compare the Changan Qiyuan Q06 product to the Onvo L60, highlighting areas for improvement and design/features/executions to be investigated.

2. Evaluation Criteria (VinFast PQ/GD&T Gateway audit checklist 2026)

CRITERIA	EVALUATION DESCRIPTION	SCORE
FIT & FINISH	Gaps, flushness, alignment and seating of parts; joints and edges as built.	1-10
AESTHETICS	Visual appeal: surface quality, finish, colour, reflections and illuminated appearance.	1-10
TOUCH & FEEL	Feel of contact surfaces: texture, padding, edges, scratch resistance.	1-10
FUNCTIONALITY	Operation, ease of use, reach and response of functions.	1-10
SOUND QUALITY	Operating sounds, squeak & rattle, closing and control sounds.	1-10
HARMONY & AUTHENTICITY	Design continuity, consistent materials/colours, genuine (non-fake) execution.	1-10

Basis in this report: Fit & Finish (visual only), Aesthetics and Harmony & Authenticity are scored from same-view photo pairs. Touch & Feel, Functionality and Sound Quality need the physical audit — N/A here.
Checklist: pq_checklist_2026.csv — 16 sub-modules × 6 criteria; each scored criterion uses the checklist's check item and evaluation guide.

Benchmark Scope & Evidence

Changan Qiyuan Q06

- Variant: 2027 700 Smart Elite Model (spec 78819)
- Segment: Mid-size SUV (D-segment)
- Powertrain: BEV (battery electric)
- Market: China
- Price: CNY 169,900 (China MSRP)
- Status: On sale
- Specifications: autohome.com.cn series 8589, variant 78819
- Photo set: autohome standard set of this variant (spec 78819)
- A2MAC1: No A2MAC1 teardown of this model

Onvo L60

- Variant: 2024 60kWh RWD Edition (spec 68375)
- Segment: Mid-size SUV (D-segment)
- Powertrain: BEV (battery electric)
- Market: China
- Price: CNY 206,900 (China MSRP)
- Status: Discontinued
- Specifications: autohome.com.cn series 7687, variant 68375
- Photo set: autohome standard set of this variant (spec 68375)
- A2MAC1: Onvo L60 60kWh 4X4 2024 — same model generation — different variant

Method

15 photo pairs of the same standard view (autohome 'pointname' convention), grouped into the checklist sub-modules. Each pair is scored by a vision model with the checklist evaluation guide, then checked by code (integer 1–10, same-module check, no tactile/sound claims).
Copy of report 20261016-044756-ef3140 (2026-10-16): photo scores and comments reused from that run (vision model glm-5.3-flash), no photo re-scored; this copy adds the A2MAC1 data.
Sub-module score = mean of its pairs; row average = mean of scored criteria. Ratings: U < 4.5 ≤ C < 6 ≤ A < 8.5 ≤ L (same borders as the reference PQ report). Not comparable items are listed under Evidence Gaps.

Key Specifications

Parameter	Changan Qiyuan Q06	Onvo L60	Δ / note
Segment (autohome class)	Mid-size SUV (D-segment)	Mid-size SUV (D-segment)	
Powertrain	BEV (battery electric)	BEV (battery electric)	
Variant compared	2027 700 Smart Elite Model	2024 60kWh RWD Edition	
Sales status	On sale	Discontinued	
List price	CNY 169,900 (China MSRP)	CNY 206,900 (China MSRP)	
Length (mm)	4,837	4,828	+9 mm
Width (mm)	1,970	1,930	+40 mm
Height (mm)	1,670	1,616	+54 mm
Wheelbase (mm)	2,940	2,950	-10 mm
Ground clearance (mm)	—	—	
Seats	5	5	
Max power (kW)	245	240	+5 kW
Max torque (N·m)	290	305	-15 N·m

Key Specifications — continued

Parameter	Changan Qiyuan Q06	Onvo L60	Δ / note
Drive	Rear-engine rear-wheel drive	Rear-engine rear-wheel drive	
Battery (kWh)	80.02	60	
Range	700 km (CLTC)	555 km (CLTC)	
Fast charging	0.15 h (30-80%)	0.41 h (10-80%)	
0–100 km/h (s)	7.1	5.9	
Curb weight (kg)	2,020	1,885	
Wheels	245/50 R20 (Standard)	245/50 R19 (Standard); 245/45 R20 (Optional)	
Centre display	15.6-inch (Standard)	17.2 inches (Standard)	
Driver display	10.17 inches (Standard)	—	
Speakers	20 speakers (Standard)	18 speakers (Standard)	
Luggage volume (L)	782-2200	763	

A2MAC1 Teardown Data

Parameter (A2MAC1)	Changan Qiyuan Q06	Onvo L60
A2MAC1 vehicle	—	Onvo L60 60kWh 4X4 2024
Match to the compared variant	No A2MAC1 teardown of this model	Same model generation — different variant
Market / production plant	—	China · CHN - Hefei, Anhui
Teardown (A2MAC1)	—	Full teardown · 2025-05-16 · Done
Weight before teardown (kg)	—	1,978 · Weight includes fluids
Weight split front / rear (%)	—	50.38 / 49.62
GVWR / GAWR front / rear (kg)	—	2400 / 1113 / 1287
Powertrain	—	Battery Electric Vehicle (BEV)
Engine	—	—
E-motors	—	2 motor(s) · Front & Rear Units · Permanent Magnet / AC Synchronous
Front / rear e-motor power (kW)	—	100 / 240
Max power (kW) / torque (N·m)	—	340 / 440
Battery type / energy nominal, usable (kWh)	—	Lithium-Fer-Phosphate (LFP) · 60
Battery voltage (V) / capacity (Ah)	—	689 / 88
Charging AC / DC max (kW)	—	—


Source: A2MAC1 IBP teardown benchmark (ibp.a2mac1.com), scraped 2026-11-11 — values of the A2MAC1 vehicle named in the first row (measured on a production car). 'Same model generation' = a different variant: read as indicative, not as the compared variant's data. All 247 A2MAC1 fields: Excel sheet 'A2MAC1 data'.

A2MAC1 Teardown Data — continued

Parameter (A2MAC1)	Changan Qiyuan Q06	Onvo L60
Charging connector	—	Rear Left · GB/T (AC+DC)
Range (OEM, cycle)	—	525 km (CLTC)
Drive / gearbox	—	AWD / 4x4 / Direct drive
Top speed (km/h) / 0–100 km/h (s)	—	203 / 4.22
Front / rear axle design	—	Mac Pherson Strut / Multi-link
Steering	—	Electric assist on steering rack · rear-wheel steering: No
Brakes front / rear	—	Ventilated discs / Ventilated discs
Tyres front / rear	—	255/45 R19 / 255/45 R19
Airbags	—	7
AEB / lane assist / cruise	—	Interurban / Autonomous Lane Change / ACC + Stop&Go
Park assist / cross traffic	—	—
Head unit (in) / cluster / HUD	—	17.2 / Digital + Augmented Reality / Yes, Windshield Projection
Smartphone / wireless charger / OTA	—	Android Auto / Apple CarPlay / Yes / Yes
Seats: material / power / heated / ventilated	—	Leather / 1st + 2nd Row / 1st + 2nd Row / 1st + 2nd Row
Lighting: low / high beam / ADB	—	LED / LED / No

Source: A2MAC1 IBP teardown benchmark (ibp.a2mac1.com), scraped 2026-11-11 — values of the A2MAC1 vehicle named in the first row (measured on a production car). 'Same model generation' = a different variant: read as indicative, not as the compared variant's data. All 247 A2MAC1 fields: Excel sheet 'A2MAC1 data'.

Comparison Summary — sub-module row averages



Summary of PQ benchmark

Onvo L60 (2024 60kWh RWD Edition) outperforms Changan Qiyuan Q06 (2027 700 Smart Elite Model) in all perceived quality sub-modules. L60 scores 7.68 vs. Q06's 6.76 overall. Superior fit and finish, cohesive surfacing, and premium material coordination are evident across body, lighting, glass, and interior trim. Photo-scored criteria confirm tighter joints, flush details, and refined execution in L60.

L60 demonstrates leadership in visual harmony, surface continuity, and integration. Q06 shows conventional execution with consistent gaps and clean paint but lacks distinctiveness. L60's seamless surfacing, flush controls, and coordinated materials elevate perceived quality. Q06's exposed fasteners, visible joints, and fragmented lower body reduce refinement.

Recommendation

Short term improve

- Seal frunk tub with full trim.
- Flush charge port inner panel.
- Hide wiper arm joints.
- Integrate door speaker grilles flush.
- Refine rear bumper joint continuity.
- Eliminate exposed latches in interior trim.

Long term improve

- Standardize flush panel integration across body.
- Adopt coordinated two-tone interior themes.
- Implement semi-concealed wiper parking.
- Use body-colour charge door inner lining.
- Enhance material mix consistency in trim.

Changan Qiyuan Q06 Detail report

Sub-module	Fit & Finish	Aesthetics	Touch & Feel	Function.	Sound	Harmony & Auth.	Row avg
Ext · Body	6.8	7	N/A	N/A	N/A	6.8	6.9
Ext · Doors & Closures	6	6	N/A	N/A	N/A	5.5	5.8
Ext · Lighting	7	7.5	N/A	N/A	N/A	7.5	7.3
Ext · Glass & Wiper	7	6	N/A	N/A	N/A	6	6.3
Ext · Exterior Trim	gap	gap	N/A	N/A	N/A	gap	—
Ext · Wheels / Rims	gap	gap	N/A	N/A	N/A	gap	—
Int · Instrument Panel	gap	gap	N/A	N/A	N/A	gap	—
Int · Steering Wheel	7	7	N/A	N/A	N/A	7	7.0
Int · Console	gap	gap	N/A	N/A	N/A	gap	—
Int · Door Trim	7	8	N/A	N/A	N/A	7	7.3
Int · Seats	7	6.5	N/A	N/A	N/A	7	6.8
Int · HVAC	gap	gap	N/A	N/A	N/A	gap	—
Int · Infotainment	gap	gap	N/A	N/A	N/A	gap	—
Int · Interior Lighting	gap	gap	N/A	N/A	N/A	gap	—
Int · Interior Hard/Soft trim	7	7	N/A	N/A	N/A	6	6.7
Int · Key & Entry	7	7	N/A	N/A	N/A	6	6.7

Onvo L60 Detail report

Sub-module	Fit & Finish	Aesthetics	Touch & Feel	Function.	Sound	Harmony & Auth.	Row avg
Ext · Body	7.8	7.8	N/A	N/A	N/A	8	7.9
Ext · Doors & Closures	7	8	N/A	N/A	N/A	7	7.3
Ext · Lighting	7	7.5	N/A	N/A	N/A	7.5	7.3
Ext · Glass & Wiper	8	8	N/A	N/A	N/A	8	8.0
Ext · Exterior Trim	gap	gap	N/A	N/A	N/A	gap	—
Ext · Wheels / Rims	gap	gap	N/A	N/A	N/A	gap	—
Int · Instrument Panel	gap	gap	N/A	N/A	N/A	gap	—
Int · Steering Wheel	8	8	N/A	N/A	N/A	8	8.0
Int · Console	gap	gap	N/A	N/A	N/A	gap	—
Int · Door Trim	8	8	N/A	N/A	N/A	8	8.0
Int · Seats	8	8	N/A	N/A	N/A	8	8.0
Int · HVAC	gap	gap	N/A	N/A	N/A	gap	—
Int · Infotainment	gap	gap	N/A	N/A	N/A	gap	—
Int · Interior Lighting	gap	gap	N/A	N/A	N/A	gap	—
Int · Interior Hard/Soft trim	7	8	N/A	N/A	N/A	7	7.3
Int · Key & Entry	7	8	N/A	N/A	N/A	7	7.3

Scores 1–10 per checklist sub-module and criterion; colour = rating (U/C/A/L). N/A = needs the physical audit; gap = no matching photo pair of both vehicles. Full checklist rows with check items, evaluation guides and evidence: Excel sheet 'PQ Audit Checklist'.

Comparison: Body – Front Three-Quarter View

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Front-left 45°*		 *autohome.com.cn · spec 68375 · Front-left 45°*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Conventional SUV execution; gaps even, paint clean, cohesive but less distinctive styling language		Highly integrated surfaces with flush details; tight joints and refined, leadership-adjacent execution	

Comparison: Body – Side Profile

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Driver-side profile*		 *autohome.com.cn · spec 68375 · Driver-side profile*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Well-executed SUV profile with even gaps and continuous lines; black cladding slightly fragments lower body.		Very clean coupe-SUV profile; tight panel joints and smooth continuous surfacing throughout.	

Comparison: Body – Rear End

Changan Qiyuan Q06		Onvo L60	
 autohome.com.cn · spec 78819 · Rear		 autohome.com.cn · spec 68375 · Rear	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Even tailgate gaps but busy multi-piece lower bumper; paint clean and glossy under studio light		Minimal rear with tight, even joints and smooth paint; highly cohesive, calm design execution	

Comparison: Body – Rear Three-Quarter View

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Rear-left 45°*		 *autohome.com.cn · spec 68375 · Rear-left 45°*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	63.3%	Total Score	73.3%
Clean rear execution with flush full-width lamp bar; lower bumper insert joints add visual busyness and potential gap risk.		Very tidy rear execution: tight shutlines, flush trim, continuous coupe profile, cohesive surfacing without interrupted styling lines.	

Comparison: Doors & Closures – Bonnet Open – Front Compartment

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Front compartment*		 *autohome.com.cn · spec 68375 · Front compartment*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	66.7%	Total Score	73.3%
Clean, well-sealed frunk tub; some exposed latches and fasteners reduce refinement.		Fully clad, flush compartment with body-colour inner bonnet looks premium and consistent.	

Comparison: Lighting – Front Lighting Signature (lit)

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Headlamps fully lit*		 *autohome.com.cn · spec 68375 · Headlamps fully lit*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Even full-width illuminated bar with mirrored elements; high-mounted turn signals read slightly busy.		Sharp split lighting signature, very even glow and flush mounting; dark image limits body-gap visibility.	

Comparison: Lighting – Rear Lighting Signature (lit)

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Tail lamps fully lit*		 *autohome.com.cn · spec 68375 · Tail lamps fully lit*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	76.7%	Total Score	66.7%
Full-width illuminated bar with segmented graphics and lit emblem; symmetric, even output, well integrated		Very dark scene shows amber lamp signatures only; symmetric and even, but body joints unverifiable	

Comparison: Steering Wheel – Steering Wheel

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Steering wheel*		 *autohome.com.cn · spec 68375 · Steering wheel*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Conventional round wheel, well-executed dark theme with sporty red stitching.		Distinctive two-tone wheel with flush controls; strong cabin colour harmony.	

Comparison: Door Trim – Door Trim – Speaker Grille

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Speaker*		 *autohome.com.cn · spec 68375 · Speaker*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	73.3%	Total Score	80.0%
Open-door view shows flush metallic speaker grille with intricate radial pattern set in clean black trim; seating appears even.		Wide branded tweeter grille sits flush in two-tone trim; seams tight, stitching neat, materials and tones well coordinated.	

Comparison: Seats – Rear Seats

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Rear seats*		 *autohome.com.cn · spec 68375 · Rear seats*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	66.7%	Total Score	80.0%
Solid, cleanly executed dark bench; pleasing but conventional detail with visible ISOFIX markers.		Premium two-tone execution with refined quilting and suede; material mix reads upscale and coherent.	

Comparison: Seats – Rear Cabin Space

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Rear cabin space*		 *autohome.com.cn · spec 68375 · Rear cabin space*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	70.0%	Total Score	80.0%
Dark rear cabin with taut, evenly stitched bench; orange accent stitching links seat and door trim coherently.		Light two-tone rear cabin with precise seams, crisp pleated bench and matched metallic accents; visually more premium.	

Comparison: Key & Entry – Key Fob

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Key fob*		 *autohome.com.cn · spec 68375 · Key fob*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	66.7%	Total Score	73.3%
Rigid card-style NFC key, informative labelling, brushed finish looks premium and defect-free.		Minimalist matte black card key, bold logo, very clean execution but minimal functional labelling.	


Comparison: Glass & Wiper – Glass & Wiper

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · 雨刷*		 *autohome.com.cn · spec 68375 · 雨刷*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	63.3%	Total Score	80.0%
Wipers parked exposed above cowl with visible arm joints; glass clear but base looks busier than benchmark		Semi-concealed wiper parking gives cleaner glass base; cowl-to-glass transition highly integrated and premium	

Comparison: Interior Hard/Soft trim – Pillars, Headliner, Carpets, Load-space Trim

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Luggage compartment*		 *autohome.com.cn · spec 68375 · Luggage compartment*	
❑ Fit & Finish	A	❑ Fit & Finish	A
❑ Aesthetics	A	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	A	❑ Harmony & Authenticity	A
Total Score	66.7%	Total Score	73.3%
Dark load trim with even joints; TopTether labels clear, slight contrast to body aperture		Premium two-tone load space; very even carpet, clean aperture, light seats read upscale	

Comparison: Doors & Closures – Charge Port Door

Changan Qiyuan Q06		Onvo L60	
 *autohome.com.cn · spec 78819 · Charge port*		 *autohome.com.cn · spec 68375 · Charge port*	
❑ Fit & Finish	C	❑ Fit & Finish	A
❑ Aesthetics	C	❑ Aesthetics	A
❑ Touch & Feel	N/A	❑ Touch & Feel	N/A
❑ Functionality	N/A	❑ Functionality	N/A
❑ Sound Quality	N/A	❑ Sound Quality	N/A
❑ Harmony & Authenticity	C	❑ Harmony & Authenticity	A
Total Score	50.0%	Total Score	73.3%
Charge port functional, but open door reveals unpainted inner, exposed screws and loose tether, lowering perceived quality.		Body-coloured charge door opens cleanly; recess flush and tidy with integrated indicator, premium execution.	

Onvo L60 — benchmark highlight

Body Integration

Onvo L60 achieves tight joints and seamless surfacing, with highly integrated surfaces and flush details, delivering leadership-adjacent execution.



Source: autohome.com.cn · Front-left 45°

Onvo L60 — benchmark highlight

Rear Cabin Premium

Onvo L60 features precise seams, crisp pleating, and matched metallic accents, creating a visually premium and cohesive rear environment.

Source: autohome.com.cn · Rear cabin space



Onvo L60 — benchmark highlight


Interior Trim Harmony

Onvo L60 uses premium two-tone load space with even carpet and clean aperture, enhancing upscale perception.

Source: autohome.com.cn · Luggage compartment



A&U – Space Efficiency & Packaging (published dimensions)



A&U indications

- Wheelbase 2,940 mm vs 2,950 mm (-10 mm): less longitudinal package for rear legroom (Space Efficiency).
- Wheelbase / length ratio 0.608 vs 0.611: lower cabin-to-footprint efficiency.
- Overall height 1,670 mm vs 1,616 mm (+54 mm): indication for headroom and ingress posture.
- Width 1,970 mm vs 1,930 mm (+40 mm): indication for shoulder room.
- Luggage volume: Changan Qiyuan Q06 782-2200; Onvo L60 763 L.

Dimension-based indications only. Accessibility, posture, reach and comfort need target-user trials (5th–95th percentile) on the physical vehicle.

Features & Equipment (A&U relevant)

Area	Feature	Changan Qiyuan Q06	Onvo L60
Driver assistance	Adaptive cruise control	Full-speed adaptive cruise control (Standard)	Full-speed adaptive cruise control (Standard)
Driver assistance	Lane keeping	Standard	Standard
Driver assistance	Blind-spot warning	Standard	Standard
Driver assistance	Surround-view camera	360° surround view camera (Standard); Side blind spot camera (Standard)	360° surround view camera (Standard); Side blind spot camera (Standard)
Driver assistance	Assistance level	L2 (Standard)	L2 (Standard)
Driver assistance	Head-up display	Standard	Standard
Comfort	Climate control	Automatic air conditioning (Standard)	Automatic air conditioning (Standard)
Comfort	Driver seat adjustment	Fore/aft adjustment (Standard); Backrest adjustment (Standard); Height adjustment (2-way) (Standard); Lumbar support (4-way) (Standard)	Fore/aft adjustment (Standard); Backrest adjustment (Standard); Height adjustment (4-way) (Standard); Lumbar support (4-way) (Standard)
Comfort	Seat memory	Driver seat (Standard); Front passenger position (Standard); Rear row (Standard)	Driver seat (Standard); Front passenger position (Standard)
Comfort	Front seat functions	Heating (Standard); Ventilation (Standard); Massage (Standard); Headrest speakers (driver only) (Standard)	Heating (Standard); Ventilation (Standard); Massage (Standard)
Comfort	Rear seats	Proportional fold-down (Standard)	Proportional fold-down (Standard)

Values: official published data (VF8 NP) or autohome specification of the compared variant ('Standard' / 'Optional' / '—' = not fitted or not published).

Features & Equipment (A&U relevant) — continued

Area	Feature	Changan Qiyuan Q06	Onvo L60
Convenience	Power tailgate	Standard	Standard
Convenience	Keyless entry	Whole vehicle (Standard)	Whole vehicle (Standard)
Convenience	Wireless phone charging	Front row (Standard)	Front row (Standard)
Convenience	Voice assistant	Multimedia system (Standard); Navigation (Standard); Phone (Standard); Air conditioning (Standard); Windows (Standard); Seat heating (Standard); Seat ventilation (Standard); Seat massage (Standard)	Multimedia system (Standard); Navigation (Standard); Phone (Standard); Air conditioning (Standard); Windows (Standard); Seat heating (Standard); Seat ventilation (Standard); Seat massage (Standard)
Convenience	Sunroof	Segmented fixed sunroof (Standard)	Fixed panoramic sunroof (Standard)
Infotainment	Centre display	15.6-inch (Standard)	17.2 inches (Standard)
Infotainment	Speakers	20 speakers (Standard)	18 speakers (Standard)
Infotainment	OTA updates	Standard	Standard
Chassis	Front suspension	Double wishbone independent suspension (Standard)	Double-ball joint MacPherson independent suspension (Standard)
Chassis	Rear suspension	Five-link independent suspension (Standard)	Five-link independent suspension (Standard)

Values: official published data (VF8 NP) or autohome specification of the compared variant ('Standard' / 'Optional' / '—' = not fitted or not published).

Items to Verify in the Physical PQ Audit

ID	Vehicle	Sub-module / view	What to verify	Criterion	Verification method
VB-ONVOL60-001	Changan Qiyuan Q06	Body – Front Three-Quarter View	Measure hood, bumper and door gaps against DTS	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-002	Changan Qiyuan Q06	Body – Front Three-Quarter View	Inspect cladding seating and wheel arch fit	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-003	Onvo L60	Body – Front Three-Quarter View	Verify flush door handle and panel gap consistency	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-004	Onvo L60	Body – Front Three-Quarter View	Check paint texture on curved roof and hood	Aesthetics	Visual audit in daylight and inspection lighting
VB-ONVOL60-005	Changan Qiyuan Q06	Body – Side Profile	Measure door and bumper gaps against DTS	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-006	Onvo L60	Body – Side Profile	Check flushness of tailgate and rear quarter	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-007	Changan Qiyuan Q06	Body – Rear End	Measure tailgate and light bar gaps against DTS	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-008	Changan Qiyuan Q06	Body – Rear End	Check lower bumper insert alignment and paint texture	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-009	Onvo L60	Body – Rear End	Check tailgate-to-quarter flushness and diffuser seating	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-010	Onvo L60	Body – Rear End	Inspect tailgate paint in daylight for waves	Aesthetics	Visual audit in daylight and inspection lighting

Showing 30 of 57 items — full list in the Excel sheet 'Verification items'. Must Fix / Want Fix is not assigned from photographs: a visual difference alone is not a Must Fix. Confirm each item on the physical vehicle (correct VIN/spec), then classify per the PQ issue rules.

Items to Verify in the Physical PQ Audit — continued

ID	Vehicle	Sub-module / view	What to verify	Criterion	Verification method
VB-ONVOL60-011	Changan Qiyuan Q06	Body – Rear Three-Quarter View	Measure tailgate and lamp bar gaps against DTS; check flushness	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-012	Changan Qiyuan Q06	Body – Rear Three-Quarter View	Inspect bumper insert and cladding joint alignment	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-013	Onvo L60	Body – Rear Three-Quarter View	Measure tailgate, lamp and handle gaps against DTS	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-014	Onvo L60	Body – Rear Three-Quarter View	Inspect large tailgate paint under inspection lighting for waves	Aesthetics	Visual audit in daylight and inspection lighting
VB-ONVOL60-015	Changan Qiyuan Q06	Doors & Closures – Bonnet Open – Front Compartment	Frunk lid flushness and gap evenness when closed	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-016	Changan Qiyuan Q06	Doors & Closures – Bonnet Open – Front Compartment	Seal seating and latch finish after open/close cycles	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-017	Onvo L60	Doors & Closures – Bonnet Open – Front Compartment	Cover fit and clip retention after removal/refit	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-018	Onvo L60	Doors & Closures – Bonnet Open – Front Compartment	Closing sound and bonnet strut feel	Sound Quality	Listening test in a quiet cabin and on the approved road route
VB-ONVOL60-019	Changan Qiyuan Q06	Lighting – Front Lighting Signature (lit)	Lamp-to-hood gap evenness and light bar segment alignment in daylight	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-020	Changan Qiyuan Q06	Lighting – Front Lighting Signature (lit)	Lens clarity and colour consistency of bar in darkness off-state	Aesthetics	Visual audit in daylight and inspection lighting

Showing 30 of 57 items — full list in the Excel sheet 'Verification items'. Must Fix / Want Fix is not assigned from photographs: a visual difference alone is not a Must Fix. Confirm each item on the physical vehicle (correct VIN/spec), then classify per the PQ issue rules.

Items to Verify in the Physical PQ Audit — continued

ID	Vehicle	Sub-module / view	What to verify	Criterion	Verification method
VB-ONVOL60-021	Onvo L60	Lighting – Front Lighting Signature (lit)	Lamp-to-fender gap and flushness in daylight both sides	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-022	Onvo L60	Lighting – Front Lighting Signature (lit)	Projector lens defects and internal dirt off-state	Aesthetics	Visual audit in daylight and inspection lighting
VB-ONVOL60-023	Changan Qiyuan Q06	Lighting – Rear Lighting Signature (lit)	Check lamp-to-tailgate and lamp-to-bumper gaps, flushness, left/right alignment	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-024	Changan Qiyuan Q06	Lighting – Rear Lighting Signature (lit)	Verify lens off-state clarity and segment colours in daylight	Aesthetics	Visual audit in daylight and inspection lighting
VB-ONVOL60-025	Onvo L60	Lighting – Rear Lighting Signature (lit)	Check lamp-to-body gaps and flushness; both lower bumper lamps present	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-026	Onvo L60	Lighting – Rear Lighting Signature (lit)	Confirm running-light colour versus amber signal in daylight and darkness	Aesthetics	Visual audit in daylight and inspection lighting
VB-ONVOL60-027	Changan Qiyuan Q06	Steering Wheel – Steering Wheel	Rim seam and stitching tactility at 9 and 3 o'clock	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-028	Onvo L60	Steering Wheel – Steering Wheel	Hub-to-rim joint gaps and switch roller feedback	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle
VB-ONVOL60-029	Onvo L60	Steering Wheel – Steering Wheel	Two-tone rim colour match with cabin trim panels	Harmony & Authenticity	Design review of neighbouring parts, colours and materials
VB-ONVOL60-030	Changan Qiyuan Q06	Door Trim – Door Trim – Speaker Grille	Run fingers around grille bezel for proudness; check gap evenness full perimeter	Fit & Finish	Gap/flush gauge measurement vs DTS on the physical vehicle

Showing 30 of 57 items — full list in the Excel sheet 'Verification items'. Must Fix / Want Fix is not assigned from photographs: a visual difference alone is not a Must Fix. Confirm each item on the physical vehicle (correct VIN/spec), then classify per the PQ issue rules.

Evidence Gaps & Not Assessable Items

Item	Status	What is needed
Exterior Trim – Front End – Grille, Badge, Trim	Views not comparable — Changan Qiyuan Q06: image not available; Onvo L60: image not available	Capture the matching view on both vehicles
Wheel/Wheel cover /Rim – Wheel & Wheel Arch	Not scored — the vision model gave no usable answer for this pair (re-run the report to retry)	Capture the matching view on both vehicles
Instrument Panel – Instrument Panel	Not scored — the vision model gave no usable answer for this pair (re-run the report to retry)	Capture the matching view on both vehicles
Console – Floor Console & Wireless Charging	Not scored — the vision model gave no usable answer for this pair (re-run the report to retry)	Capture the matching view on both vehicles
Console – Gear Selector	Changan Qiyuan Q06: no photo of this standard view	Capture the matching view on both vehicles
Seats – Front Seats	Views not comparable — Changan Qiyuan Q06: unknown; Onvo L60: unknown	Capture the matching view on both vehicles
HVAC – Front Air Vents	Changan Qiyuan Q06: no photo of this standard view	Capture the matching view on both vehicles
Infotainment – Centre Display	Views not comparable — Changan Qiyuan Q06: no image data received; Onvo L60: no image data received	Capture the matching view on both vehicles
Infotainment – Driver Display	Onvo L60: no photo of this standard view	Capture the matching view on both vehicles
Door Trim – Interior Door Trim (full panel)	Views not comparable — Changan Qiyuan Q06: No image content received; Onvo L60: No image content received	Capture the matching view on both vehicles
Interior Lighting – Interior / Ambient Lighting	No verified photo of this view for Changan Qiyuan Q06	Capture the matching view on both vehicles
Touch & Feel (all sub-modules)	Not assessable from photos	Tactile evaluation by trained PQ auditors
Functionality (all sub-modules)	Not assessable from photos	Operate per the checklist evaluation guide
Sound Quality (all sub-modules)	Not assessable from photos	Listening test, quiet cabin and road test
Gap & Flush vs DTS	Not measurable from photos	Measure gap/flush against DTS targets

Appendix – Image Source Inventory

Image ID	Vehicle	Module / view	Source	Resolution	Quality
AH-1_47657	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Front Three-Quarter View / Front-left 45°	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9971	Onvo L60 — 2024 60kWh RWD Edition	Front Three-Quarter View / Front-left 45°	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47651	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Side Profile / Driver-side profile	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9973	Onvo L60 — 2024 60kWh RWD Edition	Side Profile / Driver-side profile	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47652	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Rear End / Rear	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9972	Onvo L60 — 2024 60kWh RWD Edition	Rear End / Rear	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47654	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Rear Three-Quarter View / Rear-left 45°	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9968	Onvo L60 — 2024 60kWh RWD Edition	Rear Three-Quarter View / Rear-left 45°	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47679	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Bonnet Open – Front Compartment / Front compartment	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9996	Onvo L60 — 2024 60kWh RWD Edition	Bonnet Open – Front Compartment / Front compartment	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47661	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Front Lighting Signature (lit) / Headlamps fully lit	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9975	Onvo L60 — 2024 60kWh RWD Edition	Front Lighting Signature (lit) / Headlamps fully lit	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47659	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Rear Lighting Signature (lit) / Tail lamps fully lit	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_9978	Onvo L60 — 2024 60kWh RWD Edition	Rear Lighting Signature (lit) / Tail lamps fully lit	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High

Full source-page and image URLs are in the Excel export (sheet 'Image inventory').

Appendix – Image Source Inventory — continued

Image ID	Vehicle	Module / view	Source	Resolution	Quality
AH-1_47737	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Steering Wheel / Steering wheel	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10083	Onvo L60 — 2024 60kWh RWD Edition	Steering Wheel / Steering wheel	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47765	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Door Trim – Speaker Grille / Speaker	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10126	Onvo L60 — 2024 60kWh RWD Edition	Door Trim – Speaker Grille / Speaker	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47770	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Rear Seats / Rear seats	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10103	Onvo L60 — 2024 60kWh RWD Edition	Rear Seats / Rear seats	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47789	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Rear Cabin Space / Rear cabin space	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10165	Onvo L60 — 2024 60kWh RWD Edition	Rear Cabin Space / Rear cabin space	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47695	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Key Fob / Key fob	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10046	Onvo L60 — 2024 60kWh RWD Edition	Key Fob / Key fob	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47682	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Glass & Wiper / 雨刷	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10005	Onvo L60 — 2024 60kWh RWD Edition	Glass & Wiper / 雨刷	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High
AH-1_47807	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Pillars, Headliner, Carpets, Load-space Trim / Luggage compartment	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	3840×2880	High
AH-1_10182	Onvo L60 — 2024 60kWh RWD Edition	Pillars, Headliner, Carpets, Load-space Trim / Luggage compartment	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	3840×2880	High

Full source-page and image URLs are in the Excel export (sheet 'Image inventory').

Appendix – Image Source Inventory — continued

Image ID	Vehicle	Module / view	Source	Resolution	Quality
AH-2_2906	Changan Qiyuan Q06 — 2027 700 Smart Elite Model	Charge Port Door / Charge port	autohome.com.cn · Changan Qiyuan Q06 2027 700 Smart Elite Model (spec 78	1280×720	High
AH-2_840	Onvo L60 — 2024 60kWh RWD Edition	Charge Port Door / Charge port	autohome.com.cn · Onvo L60 2024 60kWh RWD Edition (spec 68375)	1280×720	High

Full source-page and image URLs are in the Excel export (sheet 'Image inventory').

Appendix – Method, Scoring Legend & Sources

Rating	Meaning	Score band
U	Uncompetitive	< 4.5
C	Competitive	4.5 – < 6
A	Amongst leaders	6 – < 8.5
L	Leadership	≥ 8.5
N/A	Not assessable	Physical audit needed

Scoring

- Rules: VinFast PQ/GD&T Gateway audit checklist 2026 (pq_checklist_2026.csv). Scored from photos: Fit & Finish (visual only), Aesthetics, Harmony & Authenticity.
- Sub-module row average = mean of scored criteria; overall = mean of sub-module row averages; slide Total Score = mean of the pair's criteria × 10 (%).
- Vision model: glm-5.3-flash; narrative model: local:qwen3-30b. Model output is validated by code before use.

Sources

- Changan Qiyuan Q06: autohome.com.cn series 8589, variant 78819 — https://www.autohome.com.cn/8589/
- Onvo L60: autohome.com.cn series 7687, variant 68375 — https://www.autohome.com.cn/7687/; data synced 2026-10-15T18:03:27. Chinese source data translated to English and validated (no CJK text, numbers preserved).
- A2MAC1: A2MAC1 IBP teardown benchmark (ibp.a2mac1.com), scraped 2026-11-11 — Changan Qiyuan Q06: No A2MAC1 teardown of this model; Onvo L60: Onvo L60 60kWh 4X4 2024 — same model generation — different variant

Limitations

- Photographs are comparative visual evidence only — not proof of dimensions, tactile quality, operating effort, sound, durability or compliance.
- Markets can differ (e.g. Vietnam vs China): prices, equipment and range test cycles are then not directly comparable.