

CPT & DPSH TEST LOG

Job Number:

Test Label:

18261

115T1

Client:

Miyamoto

Project:

115 Taranaki Street

Operator: Ben Wilson

Piezocone (Rig): MKJ365 (P001249)

Hole Depth: 15.4m
EOH Reason: DPSH Refusal

Test Date: 27/08/2018

Coordinates: -41.295312, 174.77794 (WGS84)

Supervisor: Shokoufeh Sadeghifard

Site Location: Te Aro, Wellington

Tip Sleeve Pore Friction Depth (m) Dynamic Probe Super Heavy (DPSH-B) Pressure (kPa) Ratio (%) Resistance Friction (MPa) (kPa) 20 30 200 300 909 20 15 16 16 16 15 19 18 17 14 17 15 15 13 15 17 18 7 4

Remarks
One O one

CPTu testing carried out to ASTM Standard D5778-12

10cm-sq piezocone used for each CPTu test

CPTu sefued at 50Mpc on the tip, 50Mpc on the friction places or

CPTu refusal at 50MPa on the tip, 500kPa on the friction sleeve or at 2500kPa pore pressure Torque readings taken before the addition of each new DPSH rod DPSH-B refusal at two consecutive increments of 40 blows or over

P 001245: 95% P 001249: 90% Calibration performed on 4th November 2014

1013I Ferry Road, Ferrymead, Christchurch 8023, New Zealand

0800 TESTER (837837)

www.landtest.co.nz

Average Energy Transfer Ratio for the DPSH-B hammer on each rig:

Hole Depth: 15.4m Page 1 of 2

Created: 28/08/2018 8:53:50 AM



CPT & DPSH TEST LOG

Job Number:

Test Label:

18261

115T1

Client: Project: Miyamoto 115 Taranaki Street


Site Location: Te Aro, Wellington Test Date: 27/08/2018 Coordinates:


-41.295312, 174.77794 (WGS84)

Operator: Ben Wilson

MKJ328 (P001249) Piezocone (Rig):

Hole Depth: 15.4m





Remarks

CPTu testing carried out to ASTM Standard D5778-12

10cm-sq piezocone used for each CPTu test
CPTu refusal at 50MPa on the tip, 500kPa on the friction sleeve or at 2500kPa pore pressure
Torque readings taken before the addition of each new DPSH rod
DPSH-B refusal at two consecutive increments of 40 blows or over

Average Energy Transfer Ratio for the DPSH-B hammer on each rig:

P 001245: 95% P 001249: 90%

Calibration performed on 4th November 2014

1013I Ferry Road, Ferrymead, Christchurch 8023, New Zealand

0800 TESTER (837837)

www.landtest.co.nz

Hole Depth: 15.4m

Page 2 of 2 Created: 28/08/2018 8:53:54 AM