

## **CPT & DPSH TEST LOG**

17154

Project:

Wellington City Council Wellington Town Hall

Test Label:

Job Number:

**CPT202** 

Site Location: 109 Wakefield St, Wellington

Test Date: 10/03/2017

Coordinates: 1748840.5, 5427561.8 (NZTM)


Supervisor: Shirley Wang

Reduced Level: 2.16m (Wellington Datum 1953) Operator: Logan Allan

Piezocone (Rig): MKJ364 (P001249)

> 10.6m Hole Depth: Pre-drill: 2.7m

EOH Reason: Friction Refusal



CPTu testing carried out to ASTM Standard D5778-12
10cm-sq piezocone used for each CPTu test
CPTu refusal at 50MPa on the tip, 500kPa on the friction sleeve or at 2500kPa pore pressure
DPSH-B refusal at two consecutive increments of 20 blows or over

P 001245: 95% P 001249: 90%

Calibration performed on 4th November 2014

Average Energy Transfer Ratio for the DPSH-B hammer on each rig:

300 Cashel St, Christchurch Central, Christchurch 8011, New Zealand 0800 TESTER (837837) www.landtest.co.nz Hole Depth:

10.6m



## **CPT & DPSH TEST LOG**

ıncil

17154

Project:

Wellington City Council
Wellington Town Hall

Test Label:

Job Number:

**CPT202** 

Site Location: 109 Wakefield St, Wellington

Test Date: 10/03/2017

**Coordinates:** 1748840.5, 5427561.8 (NZTM)

Supervisor: Shirley Wang

Reduced Level: 2.16m (Wellington Datum 1953)

Operator: Logan Allan

Piezocone (Rig): MKJ364 (P001249)

Hole Depth: 10.6m Pre-drill: 2.5m

EOH Reason: Friction Refusal

	Tip Resistance (MPa)	Sleeve Friction (kPa)	Pore Pressure (kPa)	Friction Ratio (%)	pth (m)	Dynamic Probe Super Heavy (DPSH-B) (Blows / 100mm)									
	- 10 - 20 - 30 - 40	- 100 - 200 - 300 - 400	- 0 -200 -400 -600	2 4 9 8	De	4	8	12	16	20	24	28	32	36	
-				EOH: 10.6m	  	4		13	18	20	23				-

Remarks

CPTu testing carried out to ASTM Standard D5778-12
10cm-sq piezocone used for each CPTu test
CPTu refusal at 50MPa on the tip, 500kPa on the friction sleeve or at 2500kPa pore pressure
DPSH-B refusal at two consecutive increments of 20 blows or over

Average Energy Transfer Ratio for the DPSH-B hammer on each rig:

P 001245: 95% P 001249: 90%

Calibration performed on 4th November 2014

Generated with Core-GS by Geroc

Hole Depth: