Problem report for:

Merriweather[opsz,wdth,wght].ttf

sha1: 0dda02202fe5c69a7d916d8da150fcf99184bf01
Family name: Merriweather

Version: Version 2.100

Parameters:

Error tolerance: 0.95

Kink—reporting aggressiveness: 0.5

Legend:

► Contour start point and direction

● Contour start point when the first two points overlap

► Contour start point in contours with wrong direction

● Suggested new contour start point

● Point causing kink in the contour

○ Kink artifact

🟥 Colored contours: contours with the wrong order

⬛ Underweight contours

Tolerance: badness; closer to zero the worse

Summary of problems

**kink: 4**
    Eng
    Q
   uni0494
    uni04A6

Glyph name: Eng

Problems: kink

'wdth=112.0'

midway interpolation

'wght=900.0'

proposed fix

Glyph name: uni0494

Problems: kink

'wdth=112.0'

midway interpolation

'wght=900.0'

proposed fix

4

Glyph name: uni0494

Problems: kink

'wght=900.0'

midway interpolation

'opsz=144.0 wdth=87.0'

proposed fix

Glyph name: uni0494

Problems: kink

'opsz=144.0 wdth=112.0'

midway interpolation

'opsz=144.0 wght=900.0'

proposed fix

Glyph name: uni0494

Problems: kink

'opsz=144.0 wght=900.0'

midway interpolation

'wdth=87.0 wght=900.0'

proposed fix

Glyph name: uni04A6

Problems: kink

'wght=900.0'

midway interpolation

'opsz=144.0 wdth=87.0'

proposed fix

Glyph name: Q

Problems: kink

'opsz=144.0 wdth=112.0'

midway interpolation

'opsz=144.0 wght=900.0'

proposed fix

Index

Table of contents