



Permit dredge sites within 2 km of an MV1007 dredge that recovered no glass or no rock

D7: 0.9 km from MV1007 D14 (NO GLASS)
0.45 km from its dredge track




MV1007 D14: Top of seamount near Pseudofault on WDL. Recovery: 1/4 bag; altered basalt fragments. Depth 1423 m (permit site 1388 m). Nearest glass-bearing dredge: MV1007 D13, 2.7 km.

D25: 0.9 km from MV1007 D22 (NO GLASS)




MV1007 D22: Big Round Seamount, second seamount from north on Lineament 2. Recovery: 150 kg; pillow and flow fragments with green/blue alteration. Depth 1130 m (permit site 1123 m). Nearest glass-bearing dredge: SO158 DR46-A, 14.2 km.

D26: 0.9 km from MV1007 D23 (NO ROCK)



MV1007 D23: Small seamount, third from north on lineament 2. Recovery: sediment only; no rock recovery. Depth 1946 m (permit site 1774 m). Nearest glass-bearing dredge: SO158 DR41-A, 17.3 km.

Where they are (all 30 permit sites)



AT53-04 permit site (flagged: yellow ring)



previous dredge: glass



previous dredge: no glass



previous dredge: no rock



MV1007 dredge track (on- to off-bottom)



link to the repeated MV1007 dredge (distance in title)