



Company: EPS SERVICES PTE LTD
Contact: Gage Yong

Phone: 82744647
Title: 38 Lim Tua Tow road

Created: Fri, 3/6/2026
No. Items: 8

Fans currently all kdk

L1 put door x 2
L1 Indoor x 5
L2 5 each room & living area

2 sty+ 1 attc
L1 room + bath
L2 4 room x 3 bath
4500sqf




Kitchen

Drawer cannot close properly due to gas tank pipe



Gas tank

Move the tank reduce the pipe access at the drawer area



Kitchen bathroom

Replace shower mixer



Ariston oven

Oven tripped ncb when turn on



Company: EPS SERVICES PTE LTD
Contact: Gage Yong


Phone: 82744647
Title: 38 Lim Tua Tow road

Created: Fri, 3/6/2026
No. Items: 8



L1 Walkway

Replace 2- way 1 gang x 1 + wall light / remove switch
+ light, replace 3 gang 2- way at L2



Porch area

Loose tiles



L2 2 way for wall light at staircase



Shower rubber seal