

12043 W ALAMEDA PKWY

LAKEWOOD CO 80228


PROPERTY TYPE
Commercial 2112

YEAR BUILT
-

BUILDING AREA
75,951 SF

ROOF SQUARES
760

PARCEL ID
4917105011



OVERALL ROOF CONDITION SCORE

58 /100
POOR

RISK LEVEL

HIGH



ROOF INFORMATION

ROOF TYPE	Mixed roof types
ROOF SYSTEM	Primary: TPO
VISIBLE CONCERNS	dark staining/color variation; many penetrations/units; Upper white roof shows scattered discoloration and small stains but no clear widespread ponding.
ROOF AGE EST.	Likely mid-life to older on the dark roof sections; the bright white upper membrane appears newer or restored. Exact age cannot be determined from aerial imagery alone.
ROOF AREA	75,951 SF
ROOF PITCH	Low-slope / flat
CONFIDENCE	60%

SELECTED AERIAL IMAGE - ESRI WORLD IMAGERY

ROOF CONDITION BREAKDOWN

Membrane Condition		57/100
Ponding		55/100
Flashing & Seals		56/100
Penetrations		52/100
Overall Maintenance		55/100

AERIAL ROOF OBSERVATIONS

1. Visible risk factors include dark staining or inconsistent roof color, high penetration or rooftop-unit density.
2. Large dominant upper roof field is bright white and smooth, consistent with a single-ply membrane or coated surface; TPO is the conservative label from aerial evidence.
3. Mid/lower central roof block is darker, matte, and visually distinct from the upper roof, supporting a separate dark membrane or asphaltic roof zone.
4. Small attached east/southeast roof strip shows straighter panel-like divisions and rigid geometry, supporting a separate metal section.
5. Scattered small stains/discoloration are visible on the white roof; no clear extensive ponding signature is resolved.

BUILDING CHARACTERISTICS

LAND AREA	8.26 acres
STORIES	-
CONSTRUCTION TYPE	Commercial
TAX DISTRICT	-
LAND VALUE	\$4,498,025

REPORT SUMMARY

Aerial imagery dated not provided shows a mixed commercial roof with a dominant bright white low-slope membrane field, a separate dark low-slope roof section, and a small attached metal roof strip. Visible risk factors include dark staining or inconsistent roof color, high penetration or rooftop-unit density.

Recommendation:

Have a qualified commercial roof-coating contractor or roof consultant perform an onsite inspection, moisture testing where warranted, confirm the exact systems, document repairs, and provide a reliable project-price proposal. If the dominant white low-slope roof is otherwise restorable and not asphalt shingle, evaluate whether a silicone roof restoration is appropriate before a costlier overlay or replacement; a properly designed silicone system can reduce tear-off waste, cost, and disruption, create a seamless monolithic white reflective cool-roof surface, improve resistance to UV exposure and hail, withstand ponding water when properly designed and installed, and may qualify for a manufacturer warranty of up to 20 years. If inspection reveals widespread moisture, failed insulation, deck deterioration, or an incompatible substrate, pursue overlay or replacement evaluation instead.

ROOF REPAIR OPTIONS

Roof Replacement Cost Estimate

TOTAL PROJECT COST

\$2,227,263

\$25.50 / SF

COST SUMMARY

Replacement Subtotal	\$1,936,750
Contingency (15%)	\$290,513
Total Project Cost	\$2,227,263

Roof Overlay Cost Estimate

TOTAL PROJECT COST

\$835,461

\$10.00 / SF

COST SUMMARY

Overlay Subtotal	\$759,510
Contingency (10%)	\$75,951
Total Project Cost	\$835,461

Roof Coating Estimate

TOTAL PROJECT COST

\$265,828 - \$455,706

\$3.50 - \$6.00 / SF

WARRANTY TERM

10 Year Warranty	\$265,828 - \$303,804
15 Year Warranty	\$341,780 - \$379,755
20 Year Warranty	\$417,730 - \$455,706

Cost estimates are derived from publicly available information and proprietary commercial roofing analysis models and are intended for preliminary budgeting and planning purposes only. Roof-area measurements do not include the vertical surface area of parapet walls. They should not be considered a contractor quote, engineering assessment, or guarantee of actual project costs. Estimates do not include additional repairs or unforeseen conditions that may be identified during an on-site inspection.