

Fault Code: 219


Make-Up Tank Oil Level Low Fault

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 219 PID(P): S153 SPN: 1380 FMI: 1 Lamp: Engine Protection SRT:	Low oil level detected in the remote oil reservoir used in the Centinel™ system.	Centinel™ system is disabled.

©Cummins Inc



19400659

Make-up Tank Oil Level Low Sensor

Circuit Description

The make-up tank oil level low sensor monitors the oil level in the make-up oil tank and reports to the ECM when the oil drops below the specified level.

Component Location

The make-up tank oil level low sensor is located on the lower portion of the Centinel™ system make-up oil tank.

Shoptalk

Verify that the make-up tank has the appropriate level of oil.

Refer to Troubleshooting Fault Code t05-219 (</qs3/pubsys2/xml/en/procedures/19/19-t05-219.html>)

Last Modified: 01-Mar-2011
