



Technical Service Bulletin

Technical Service Bulletin: TSB140133

Released Date: 28-Oct-2015

New Rear Gear Camshaft Idler Shaft

New Rear Gear Camshaft Idler Shaft

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a replacement rear gear camshaft idler shaft and associated parts.

Product Affected


QSK23 CM500

QSK23 CM2250 K109

QSK23 PG CM850

Description of Change


Replacement idler gear with bushing and idler gear retainer released with replacement rear gear camshaft idler shaft. See Figure 1 and 2.



01d00870

Figure 1, Obsolete Design

1. Camshaft idler shaft
2. Idler gear (large)
3. Idler gear with bushing
4. Gear retainer



01d00871

Figure 2, Replacement Design

1. Camshaft idler shaft
2. Idler gear (large)
3. Idler gear with bushing
4. Gear retainer

Reason for Change

New design includes improved clamp load for rear gear camshaft idler shaft and improved idler gear bushing lubrication.

Service Instructions

⚠ CAUTION ⚠

Obsolete rear gear camshaft idler shaft and idler gear with bushing not compatible with replacement parts. Component oil lubrication will be affected, engine damage will result.

Replacement part numbers recommended for use.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Rear Gear Camshaft Idler Shaft and Gear Part Numbers		
Part Name	Obsolete Part Number	Replacement Part Number
Camshaft Idler Shaft	4097269	4365225
Idler Gear with Bushing	4096764	4365226
Gear Retainer	4096709	4365229

Part Structure

Camshaft idler shaft, idler gear with bushing, and gear retainer part numbers have been obsoleted. When replacing any of these parts, all must be replaced.

Part Inventory Action

None.

Production Status

Implemented for production. See Table 2.

Table 2, Plant Information		
ESN First	Build Date*	Plant
00327150	29-Sep-14	Cummins Komatsu Engine Company
85000848	13-Dec-14	Phaltan Plant

*Engine build date can be found on the engine dataplate.

Document History

Date	Details
2014-9-28	Module Created
2014-11-11	Updated part number information.
2015-2-16	Updated parts table, format, and added production table.
2015-10-26	Corrected ESN first.