


Fault Code: 379

Fueling Actuator Number 1 - Grounded Circuit (Front)

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 379 PID(P): SPN: FMI: Lamp: Shutdown SRT:	Fueling actuator Number 1 circuit - grounded circuit. (front)	Engine will shut down.



Fueling Actuator Number 1 Circuit

Circuit Description

The fueling actuators are actuated by the ECM to control fuel metering. Each fueling actuator is connected to the ECM by a supply and a return wire. An electrical pulse is sent to the fueling actuator from the ECM on the supply wire and returns to the ECM on the return wire. Each solenoid valve is normally closed, and it is **only** opened by an electrical pulse from the ECM during metering.

Component Location

The front fueling actuator is mounted on the fuel delivery housing. It is the actuator closest to the front of the QSX15 engine.

Shoptalk

The possible failure modes are short to battery, low actuator resistance, or short between supply and return wires.

Refer to Troubleshooting Fault Code t05-379 (</qs3/pubsys2/xml/en/procedures/01/01-t05-379.html>)

Last Modified: 29-Jul-2010
