
Flood Situation Report

Area: 35.180°N 25.470°E (112.7 km²) Flood date: 2026-10-04 Generated: 2026-10-11 06:02 UTC

Flood / debris impact detected

Educational prototype generated automatically from satellite data. Not an official emergency map.

4.86 km²	1.74 km²	4	51.5 km	21	0
Flood water	Debris / mud	Buildings likely hit	Roads affected	Bridges hit	Settlements cut off



Settlements that lost or changed road access to a hospital

#	Settlement	Road access now	Buildings	Nearest hospital (before)	Before	Now
1	Καμινάκι	Likely cut off	213	hospital #3	6.0 km, 10 min	no route
2	Άγιος Κωνσταντίνος	Likely cut off	112	hospital #3	4.0 km, 5 min	no route
3	Πλάτη	Likely cut off	106	hospital #3	6.4 km, 10 min	no route
4	Κάτω Μετόχι	Likely cut off	74	hospital #3	5.6 km, 7 min	no route
5	Άγιος Χαράλαμπος	Long detour	62	hospital #3	5.9 km, 9 min	8.8 km, 18 min

Can we get there? Roads and bridges

Blocked or damaged roads (names from the pre-event map)

- Περιμετρική Οδός Οροπεδίου: 0.78 km affected, 35.195°N 25.448°E
- Ψυχρό - Άγιος Γεώργιος: 0.26 km affected, 35.166°N 25.466°E
- unnamed tertiary: 0.69 km affected, 35.162°N 25.473°E
- unnamed unclassified: 20.96 km affected, 35.191°N 25.458°E
- + 5 more

Bridges likely hit

- Περιμετρική Οδός Οροπεδίου, 35.192°N 25.432°E
- bridge on unnamed unclassified, 35.187°N 25.441°E
- bridge on unnamed unclassified, 35.194°N 25.441°E
- bridge on unnamed unclassified, 35.188°N 25.448°E
- + 17 more

Helicopter access for settlements cut off by road

- Καμινάκι [Likely cut off]: mapped helipad: none within 5 km; flat open ground 0.3 km (35.156°N 25.463°E)
- Άγιος Κωνσταντίνος [Likely cut off]: mapped helipad: none within 5 km; flat open ground 0.5 km (35.178°N 25.498°E)
- Πλάτη [Likely cut off]: mapped helipad: none within 5 km; flat open ground 0.2 km (35.171°N 25.436°E)
- Κάτω Μετόχι [Likely cut off]: mapped helipad: none within 5 km; flat open ground 0.3 km (35.184°N 25.429°E)

Flat open ground = slope at most 7°, at least 60 m clear, away from detected flood or debris and mapped buildings or power lines. Not checked: trees, unmapped wires or buildings, soft ground, debris the map missed. Confirm from the air. Distances are straight-line.

Data used

- Sentinel-1 radar: before 2026-09-28, after 2026-10-04 (track asc-102, 6 days apart)
- Sentinel-1 radar: before 2026-09-29, after 2026-10-05 (track asc-029, 6 days apart)
- Sentinel-2 optical: second sensor (92% of area cloud-free); confirms radar and adds what only it sees (low confidence)
- OpenStreetMap as of 2026-07-27 (before the event)
- AI segmentation model: used, combined with rule-based detection
- Debris class only in mountain terrain (UNEP-WCMC definition); 100% of this area is mountain

Confidence and limits

- 3.66 km² of the flood/debris area is medium or high confidence.
- Sentinel satellites revisit an area only every few days: this system maps damage after the fact and cannot warn of a sudden glacier or lake outburst. Areas marked grey were hidden from the radar and are unknown, not safe. Road access uses mapped roads only. 'Likely cut off' rests on low-confidence detections (debris counts as confident only when a second radar pass or Sentinel-2 confirms it); 'Unknown' means the last route crosses roads the radar could not see. Travel times use nominal speeds per road class. Rows are ranked by priority: certainty, settlement size (mapped buildings), extra time.
- Before-images taken on or before 2026-09-30 (set by the operator: the area was still dry then). Change between that date and the after-image includes the whole build-up of the flood, and also any other change in that period (crops, construction).

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Model trained on Kuro Siwo: Bountos et al., 2024 (NeurIPS Datasets & Benchmarks). Run crete_lasithi_2026.